



PORTSMOUTH, NEW HAMPSHIRE

JULY 2019

# Wastewater Pump Station Master Plan



# PUMP STATION MASTER PLAN

## TABLE OF CONTENTS

| <b>SECTION</b> | <b>DESCRIPTION</b>                                       | <b>PAGE</b> |
|----------------|--|-------------|
| 1              | Executive Summary .....                                  | 1-1         |
| 1.1            | Introduction .....                                       | 1-1         |
| 1.2            | Recommendations .....                                    | 1-1         |
| 2              | Introduction   |             |
| 2.1            | Scope of Work.....                                       | 2-1         |
| 2.2            | Report Background Information .....                      | 2-3         |
| 2.2.1          | Pump Station Historical Information .....                | 2-3         |
| 2.2.2          | Pump Station Force Main Information .....                | 2-4         |
| 2.2.3          | Pump Station Flooding Assessment.....                    | 2-4         |
| 2.2.4          | Applicable Fire Code .....                               | 2-4         |
| 3              | Pump Station Evaluations – Wet Pit/Dry Pit Pump Stations |             |
| 3.1            | Mechanic Street .....                                    | 3-1         |
| 3.1.1          | Existing Conditions.....                                 | 3-1         |
| 3.1.1.1        | Equipment .....  | 3-1         |
| 3.1.1.2        | Building .....   | 3-4         |
| 3.1.1.3        | Site.....  | 3-5         |
| 3.1.1.4        | Force Main .....   | 3-5         |
| 3.1.2          | Capacity Review .....                                    | 3-6         |
| 3.1.3          | Emergency Bypass Plan.....                               | 3-7         |
| 3.1.4          | Recommendations.....                                     | 3-7         |
| 3.2            | Deer Street .....  | 3-8         |
| 3.2.1          | Existing Conditions.....                                 | 3-8         |
| 3.2.1.1        | Equipment .....  | 3-9         |
| 3.2.1.2        | Building .....   | 3-10        |
| 3.2.1.3        | Site.....  | 3-11        |
| 3.2.1.4        | Force Main .....   | 3-12        |
| 3.2.2          | Capacity Review .....                                    | 3-13        |
| 3.2.3          | Emergency Bypass Plan.....                               | 3-13        |
| 3.2.4          | Recommendations.....                                     | 3-14        |
| 3.3            | Lafayette Road .....                                     | 3-14        |
| 3.3.1          | Existing Conditions.....                                 | 3-14        |
| 3.3.1.1        | Site.....  | 3-15        |
| 3.3.1.2        | Force Main .....   | 3-15        |

|     |                                  |      |
|-----|----------------------------------|------|
|     | 3.3.2 Recommendations.....       | 3-16 |
| 3.4 | Heritage Avenue.....             | 3-16 |
|     | 3.4.1 Existing Conditions.....   | 3-16 |
|     | 3.4.1.1 Force Main.....          | 3-16 |
|     | 3.4.2 Recommendations.....       | 3-17 |
| 3.5 | Gosling Road .....               | 3-17 |
|     | 3.5.1 Existing Conditions.....   | 3-17 |
|     | 3.5.1.1 Equipment.....           | 3-17 |
|     | 3.5.1.2 Building .....           | 3-19 |
|     | 3.5.1.3 Site.....                | 3-19 |
|     | 3.5.1.4 Force Main.....          | 3-20 |
|     | 3.5.2 Capacity Review .....      | 3-20 |
|     | 3.5.3 Emergency Bypass Plan..... | 3-21 |
|     | 3.5.4 Recommendations.....       | 3-21 |
| 3.6 | Ryeline .....                    | 3-22 |
|     | 3.6.1 Existing Conditions.....   | 3-22 |
|     | 3.6.1.1 Equipment.....           | 3-22 |
|     | 3.6.1.2 Building .....           | 3-23 |
|     | 3.6.1.3 Site.....                | 3-25 |
|     | 3.6.1.4 Force Main.....          | 3-25 |
|     | 3.6.2 Capacity Review .....      | 3-26 |
|     | 3.6.3 Emergency Bypass Plan..... | 3-26 |
|     | 3.6.4 Recommendations.....       | 3-26 |

#### 4 Pump Station Evaluations – Suction Lift Pump Stations

|     |                                  |      |
|-----|----------------------------------|------|
| 4.1 | Constitution Avenue .....        | 4-1  |
|     | 4.1.1 Existing Conditions.....   | 4-1  |
|     | 4.1.1.1 Equipment.....           | 4-1  |
|     | 4.1.1.2 Building .....           | 4-3  |
|     | 4.1.1.3 Site.....                | 4-4  |
|     | 4.1.1.4 Force Main.....          | 4-5  |
|     | 4.1.2 Capacity Review .....      | 4-6  |
|     | 4.1.3 Emergency Bypass Plan..... | 4-6  |
|     | 4.1.4 Recommendations.....       | 4-6  |
| 4.2 | West Road .....                  | 4-7  |
|     | 4.2.1 Existing Conditions.....   | 4-7  |
|     | 4.2.1.1 Equipment.....           | 4-7  |
|     | 4.2.1.2 Building .....           | 4-10 |
|     | 4.2.1.3 Site.....                | 4-11 |
|     | 4.2.1.4 Force Main.....          | 4-11 |
|     | 4.2.2 Capacity Review .....      | 4-12 |
|     | 4.2.3 Emergency Bypass Plan..... | 4-12 |
|     | 4.2.4 Recommendations.....       | 4-13 |
| 4.3 | Woodlands I .....                | 4-14 |
|     | 4.3.1 Existing Conditions.....   | 4-14 |
|     | 4.3.1.1 Equipment.....           | 4-14 |

|     |                                  |      |
|-----|----------------------------------|------|
|     | 4.3.1.2 Building .....           | 4-17 |
|     | 4.3.1.3 Site.....                | 4-18 |
|     | 4.3.1.4 Force Main.....          | 4-18 |
|     | 4.3.2 Capacity Review .....      | 4-18 |
|     | 4.3.3 Emergency Bypass Plan..... | 4-19 |
|     | 4.3.4 Recommendations.....       | 4-19 |
| 4.4 | Woodlands II .....               | 4-20 |
|     | 4.4.1 Existing Conditions.....   | 4-20 |
|     | 4.4.1.1 Equipment .....          | 4-20 |
|     | 4.4.1.2 Building .....           | 4-23 |
|     | 4.4.1.3 Site.....                | 4-24 |
|     | 4.4.1.4 Force Main.....          | 4-24 |
|     | 4.4.2 Capacity Review .....      | 4-25 |
|     | 4.4.3 Emergency Bypass Plan..... | 4-25 |
|     | 4.4.4 Recommendations.....       | 4-25 |
| 4.5 | Atlantic Heights.....            | 4-26 |
|     | 4.5.1 Existing Conditions.....   | 4-26 |
|     | 4.5.1.1 Equipment .....          | 4-26 |
|     | 4.5.1.2 Building .....           | 4-29 |
|     | 4.5.1.3 Site.....                | 4-30 |
|     | 4.5.1.4 Force Main.....          | 4-30 |
|     | 4.5.2 Capacity Review .....      | 4-31 |
|     | 4.5.3 Emergency Bypass Plan..... | 4-31 |
|     | 4.5.4 Recommendations.....       | 4-32 |
| 4.6 | Leslie Drive .....               | 4-32 |
|     | 4.6.1 Existing Conditions.....   | 4-32 |
|     | 4.6.1.1 Equipment.....           | 4-33 |
|     | 4.6.1.2 Building .....           | 4-35 |
|     | 4.6.1.3 Site.....                | 4-36 |
|     | 4.6.1.4 Force Main.....          | 4-37 |
|     | 4.6.2 Capacity Review .....      | 4-38 |
|     | 4.6.3 Emergency Bypass Plan..... | 4-38 |
|     | 4.6.4 Recommendations.....       | 4-39 |
| 4.7 | Marcy Street .....               | 4-39 |
|     | 4.7.1 Existing Conditions.....   | 4-40 |
|     | 4.7.1.1 Equipment .....          | 4-40 |
|     | 4.7.1.2 Building .....           | 4-42 |
|     | 4.7.1.3 Site.....                | 4-43 |
|     | 4.7.1.4 Force Main.....          | 4-44 |
|     | 4.7.2 Capacity Review .....      | 4-45 |
|     | 4.7.3 Emergency Bypass Plan..... | 4-45 |
|     | 4.7.4 Recommendations.....       | 4-45 |
| 4.8 | Corporate Drive.....             | 4-46 |
|     | 4.8.1 Existing Conditions.....   | 4-46 |
|     | 4.8.1.1 Equipment .....          | 4-46 |
|     | 4.8.1.2 Building .....           | 4-48 |

|      |  |      |
|------|--|------|
|      | 4.8.1.3 Site.....  | 4-48 |
|      | 4.8.1.4 Force Main.....  | 4-48 |
|      | 4.8.2 Capacity Review.....   | 4-49 |
|      | 4.8.3 Recommendations.....   | 4-49 |
| 4.9  | Griffin Park .....   | 4-49 |
|      | 4.9.1 Existing Conditions.....   | 4-49 |
|      | 4.9.1.1 Equipment.....   | 4-49 |
|      | 4.9.1.2 Building .....   | 4-52 |
|      | 4.9.1.3 Site.....  | 4-52 |
|      | 4.9.1.4 Force Main.....  | 4-53 |
|      | 4.9.2 Capacity Review.....   | 4-53 |
|      | 4.9.3 Emergency Bypass Plan.....   | 4-54 |
|      | 4.9.4 Recommendations.....   | 4-54 |
| 4.10 | Tuckers Cove .....   | 4-54 |
|      | 4.10.1 Existing Conditions.....  | 4-54 |
|      | 4.10.1.1 Equipment.....  | 4-55 |
|      | 4.10.1.2 Building .....  | 4-57 |
|      | 4.10.1.3 Site.....   | 4-57 |
|      | 4.10.1.4 Force Main.....   | 4-58 |
|      | 4.10.2 Capacity Review.....  | 4-58 |
|      | 4.10.3 Emergency Bypass Plan.....  | 4-58 |
|      | 4.10.4 Recommendations.....  | 4-59 |
| 4.11 | Combined Project Recommendations .....                                   | 4-59 |
|      | 4.11.1 Combined Electrical, Standby Generator, and<br>HVAC Upgrades..... | 4-59 |
|      | 4.11.2 Combined Pump Station Conversion or Building<br>Replacement ..... | 4-60 |

5 Pump Station Evaluations – Submersible Pump Stations

|     |                                |     |
|-----|--------------------------------|-----|
| 5.1 | Clough Drive .....             | 5-1 |
|     | 5.1.1 Existing Conditions..... | 5-1 |
|     | 5.1.1.1 Equipment.....         | 5-1 |
|     | 5.1.1.2 Site.....              | 5-2 |
|     | 5.1.1.3 Force Main.....        | 5-3 |
|     | 5.1.2 Capacity Review.....     | 5-3 |
|     | 5.1.3 Recommendations.....     | 5-3 |
|     | 5.1.3.1 High Priority .....    | 5-3 |
|     | 5.1.3.2 Medium Priority.....   | 5-4 |
|     | 5.1.3.3 Low Priority.....      | 5-4 |
| 5.2 | Marsh Lane .....               | 5-4 |
|     | 5.2.1 Existing Conditions..... | 5-4 |
|     | 5.2.1.1 Equipment.....         | 5-4 |
|     | 5.2.1.2 Site.....              | 5-5 |
|     | 5.2.1.3 Force Main.....        | 5-6 |
|     | 5.2.2 Capacity Review.....     | 5-6 |
|     | 5.2.3 Recommendations.....     | 5-6 |

|     |   |      |
|-----|---|------|
|     | 5.2.3.1 High Priority .....             | 5-7  |
|     | 5.2.3.2 Medium Priority .....           | 5-7  |
|     | 5.2.3.3 Low Priority .....              | 5-7  |
| 5.3 | Mill Pond Way .....                     | 5-7  |
|     | 5.3.1 Existing Conditions.....          | 5-7  |
|     | 5.3.1.1 Equipment .....                 | 5-7  |
|     | 5.3.1.2 Site.....                       | 5-8  |
|     | 5.3.1.3 Force Main.....                 | 5-9  |
|     | 5.3.2 Capacity Review .....             | 5-9  |
|     | 5.3.3 Recommendations.....              | 5-9  |
|     | 5.3.3.1 High Priority .....             | 5-10 |
|     | 5.3.3.2 Medium Priority .....           | 5-10 |
|     | 5.3.3.3 Low Priority .....              | 5-10 |
| 5.4 | Northwest Street.....                   | 5-10 |
|     | 5.4.1 Existing Conditions.....          | 5-10 |
|     | 5.4.1.1 Equipment .....                 | 5-10 |
|     | 5.4.1.2 Site.....                       | 5-11 |
|     | 5.4.1.3 Force Main.....                 | 5-11 |
|     | 5.4.2 Capacity Review .....             | 5-12 |
|     | 5.4.3 Recommendations.....              | 5-12 |
|     | 5.4.3.1 High Priority .....             | 5-12 |
|     | 5.4.3.2 Medium Priority .....           | 5-12 |
|     | 5.4.3.3 Low Priority .....              | 5-12 |
| 5.5 | Combined Project Recommendations .....  | 5-13 |
|     | 5.5.1 Combined Electrical Upgrade ..... | 5-13 |

**APPENDICES**

- A PUMP STATION EVALUATIONS FORMS
- B RECOMMENDED FACILITIES IMPROVEMENT PLAN COSTS BY YEAR
- C COASTAL RESILIENCY MEMO
- D FIGURES

**LIST OF TABLES**

| <b><u>TABLE</u></b> | <b><u>DESCRIPTION</u></b>                        | <b><u>PAGE</u></b> |
|---------------------|--|--------------------|
| 1-1                 | SUMMARY RECOMMENDED FACILITIES IMPROVEMENTS PLAN | 1-3                |



## **SECTION 1**

### **EXECUTIVE SUMMARY**

#### **1.1 INTRODUCTION**

The City of Portsmouth owns, operates, and maintains wastewater collection and treatment systems that provide service to the City of Portsmouth, the Town of New Castle, and portions of the Towns of Greenland and Rye. The systems include approximately 110 miles of sewer, 9 miles of force main, and 20 municipally operated pumping stations. The City's wastewater pump stations are a critical component to the City's sewer collection system.

Since the majority of the pump stations were originally installed, many stations have undergone upgrades including pump and equipment replacement, electrical improvements, and Supervisory Control and Data Acquisition (SCADA) control integration. Fourteen of the City's pump stations are over 15 years old, with ten of them originally constructed over 30 years ago. This infrastructure is a critical City asset and many of the pumps or equipment may be reaching (or have reached) the end of its useful life. As a proactive means of addressing this aging infrastructure and preparing for capital improvements, the City has chosen to develop a Pump Station Master Plan. This Master Plan will be an key part of managing and maintaining the City's Wastewater Pump Station and Forcemain infrastructure moving forward.

Physical pump station evaluations were performed, in addition to reviewing historical plans, operating data, and maintenance reports. Pump Station Evaluation forms were developed and completed for each pump station, and recommendations for improvements were made based on an analysis of the pump station's current physical condition, historical records, current codes and input from City staff.

#### **1.2 RECOMMENDATIONS**

Recommendations for improvements at each pump station were broken into three categories, based on the level of priority: Low, Medium, and High. Planning-level cost estimates were developed for each recommendation and assigned a year of completion based on the priority level. The following table summarizes the recommended improvements for each pump station by year

in a 10-year Recommended Facilities Improvement Plan (RFIP). A total of \$20.5 M of pump station improvements are recommended over the next 10 years. The full RFIP is available in **Appendix B**.

**TABLE 1-1  
SUMMARY RECOMMENDED FACILITIES IMPROVEMENT PLAN**

| <b>RECOMMENDED FACILITIES IMPROVEMENT PLAN COSTS - BY YEAR (20% CONTINGENCY, 20% DESIGN)</b> |                            |                  |                  |                  |                     |                  |                    |                  |                  |                 |                  |                  |                     |
|--|----------------------------|------------------|------------------|------------------|---------------------|------------------|--------------------|------------------|------------------|-----------------|------------------|------------------|---------------------|
| <b>Pump Station</b>  |                            | <b>Year 0</b>    | <b>Year 1</b>    | <b>Year 2</b>    | <b>Year 3</b>       | <b>Year 4</b>    | <b>Year 5</b>      | <b>Year 6</b>    | <b>Year 7</b>    | <b>Year 8</b>   | <b>Year 9</b>    | <b>Year 10</b>   | <b>TOTAL</b>        |
|  |                            | <b>2019</b>      | <b>2020</b>      | <b>2021</b>      | <b>2022</b>         | <b>2023</b>      | <b>2024</b>        | <b>2025</b>      | <b>2026</b>      | <b>2027</b>     | <b>2028</b>      | <b>2029</b>      |                     |
| <b>1</b>   | <b>Mechanic St PS</b>      | \$484,600        | \$8,600          | \$0              | \$14,400,000        | \$0              | \$0                | \$0              | \$0              | \$0             | \$0              | \$0              | \$14,893,200        |
| <b>2</b>   | <b>Deer Street PS</b>      | \$98,600         | \$385,200        | \$23,000         | \$53,300            | \$0              | \$0                | \$32,400         | \$100,800        | \$25,900        | \$1,400          | \$496,800        | \$1,217,400         |
| <b>3</b>   | <b>Lafayette Street PS</b> | -                | -                | -                | -                   | -                | -                  | -                | -                | -               | -                | -                | -                   |
| <b>4</b>   | <b>Heritage Street PS</b>  | -                | -                | -                | -                   | -                | -                  | -                | -                | -               | -                | -                | -                   |
| <b>5</b>   | <b>Gosling Road PS</b>     | \$14,400         | \$3,600          | \$0              | \$41,000            | \$0              | \$118,800          | \$0              | \$50,400         | \$0             | \$0              | \$21,600         | \$249,800           |
| <b>6</b>   | <b>Ryeline PS</b>          | \$16,600         | \$0              | \$5,000          | \$28,800            | \$14,400         | \$85,700           | \$0              | \$0              | \$0             | \$115,200        | \$223,200        | \$488,900           |
| <b>7</b>   | <b>Constitution Ave PS</b> | \$15,100         | \$21,600         | \$28,800         | \$115,900           | \$0              | \$144,000          | \$37,400         | \$0              | \$0             | \$0              | \$0              | \$362,800           |
| <b>8</b>   | <b>West Road PS</b>        | \$19,400         | \$2,900          | \$7,200          | \$112,300           | \$136,100        | \$149,800          | \$37,400         | \$0              | \$0             | \$0              | \$0              | \$465,100           |
| <b>9</b>   | <b>Woodlands I PS</b>      | \$28,100         | \$25,200         | \$0              | \$127,400           | \$86,400         | \$144,000          | \$28,800         | \$0              | \$0             | \$0              | \$0              | \$439,900           |
| <b>10</b>  | <b>Woodlands II PS</b>     | \$19,400         | \$2,900          | \$0              | \$28,100            | \$17,300         | \$144,000          | \$36,000         | \$0              | \$0             | \$0              | \$0              | \$247,700           |
| <b>11</b>  | <b>Atlantic Heights PS</b> | \$49,700         | \$2,900          | \$28,800         | \$257,800           | \$0              | \$86,400           | \$1,400          | \$0              | \$0             | \$0              | \$0              | \$427,000           |
| <b>12</b>  | <b>Marcy Street PS</b>     | \$67,100         | \$8,600          | \$14,400         | \$213,800           | \$0              | \$70,600           | \$0              | \$0              | \$0             | \$0              | \$14,400         | \$388,900           |
| <b>13</b>  | <b>Corporate Drive PS</b>  | \$0              | \$2,900          | \$0              | \$3,600             | \$1,400          | \$21,600           | \$0              | \$14,400         | \$0             | \$0              | \$0              | \$43,900            |
| <b>14</b>  | <b>Griffin Park PS</b>     | \$20,200         | \$23,800         | \$0              | \$17,300            | \$28,800         | \$0                | \$169,900        | \$0              | \$0             | \$108,000        | \$0              | \$368,000           |
| <b>15</b>  | <b>Tuckers Cove PS</b>     | \$21,600         | \$14,400         | \$0              | \$0                 | \$10,800         | \$0                | \$15,800         | \$21,600         | \$0             | \$0              | \$0              | \$84,200            |
| <b>16</b>  | <b>Leslie Drive PS</b>     | \$53,300         | \$20,600         | \$57,600         | \$265,700           | \$0              | \$28,800           | \$23,000         | \$0              | \$0             | \$0              | \$0              | \$449,000           |
| <b>17</b>  | <b>Clough Drive PS</b>     | \$9,800          | \$1,400          | \$7,200          | \$11,500            | \$26,600         | \$0                | \$0              | \$0              | \$0             | \$0              | \$0              | \$56,500            |
| <b>18</b>  | <b>Marsh Lane PS</b>       | \$3,600          | \$4,300          | \$0              | \$69,100            | \$0              | \$0                | \$0              | \$21,600         | \$0             | \$0              | \$0              | \$98,600            |
| <b>19</b>  | <b>Mill Pond Way PS</b>    | \$3,600          | \$7,200          | \$0              | \$11,500            | \$0              | \$64,800           | \$0              | \$0              | \$0             | \$0              | \$0              | \$87,100            |
| <b>20</b>  | <b>North West Road PS</b>  | \$3,600          | \$8,600          | \$0              | \$69,100            | \$0              | \$0                | \$0              | \$21,600         | \$0             | \$0              | \$0              | \$102,900           |
| <b>TOTAL</b>   |                            | <b>\$928,700</b> | <b>\$544,700</b> | <b>\$172,000</b> | <b>\$15,826,200</b> | <b>\$321,800</b> | <b>\$1,058,500</b> | <b>\$382,100</b> | <b>\$230,400</b> | <b>\$25,900</b> | <b>\$224,600</b> | <b>\$756,000</b> | <b>\$20,470,900</b> |

2

## SECTION 2

### INTRODUCTION

#### 2.1 SCOPE OF WORK

In 2018, Wright-Pierce was retained by the City of Portsmouth, NH to develop a Wastewater Pumping Stations Master Plan. This report will be a key part of the City's management and maintenance of the wastewater pump station and force main infrastructure moving forward. The Master Plan report consists of the following main components:

- Pump Station evaluation
- Force Main evaluation
- Pump Station capacity assessment
- Pump Station and Force Main improvement recommendations
- Pump Station Evaluation summary sheets (**Appendix A**)
- Recommended Facilities Improvement Plan (**Appendix B**)

The City of Portsmouth owns, operates, and maintains wastewater collection and treatment systems that provide service to the City of Portsmouth, the Town of New Castle, and portions of the Towns of Greenland and Rye. There are two separate collection and treatment systems, one conveying wastewater to the Peirce Island Wastewater Treatment Facility (WWTF) and one conveying wastewater to the Pease International Tradeport WWTF. Combined, the two systems include approximately 110 miles of sewer, 9 miles of force main, and 20 municipally operated pumping stations. The City's wastewater pump stations are a critical component to the City's sewer collection system. Overview maps of the pump stations and their sewer sheds are available in **Appendix D**.

The City's twenty pump stations consist of three pump station types:

- **Wet Pit/Dry Pit Pump Station (6 total):** These medium to large capacity pump stations consist of a below grade wet well and adjacent dry well. The dry well contains centrifugal pumps which draw wastewater from the wet well through suction piping which penetrates from the dry well to the wet well.

- Mechanic Street
- Deer Street
- Lafayette Road
- Heritage Avenue
- Gosling Road
- Ryeline

- **Suction Lift Pump Stations (10 total):** These medium to large capacity pump stations consist of a pump station dry side (above or below-grade) equipped with self-priming pumps. The pumps are installed in a suction lift configuration situated above the wet well water surface.

- Constitution Avenue
- West Road
- Woodlands I
- Woodlands II
- Atlantic Heights
- Leslie Drive
- Marcy Street
- Corporate Drive
- Griffin Park
- Tuckers Cove

- **Submersible Pump Stations (4 total):** Typically the smallest capacity of the three pump station types, this style largely consists of submersible duplex pump configurations located in a circular wet well structure.

- Clough Drive
- Marsh Lane
- Mill Pond Way
- Northwest Street

On-site pump station evaluations were performed by wastewater process engineers, in addition to reviewing historical plans, operating data, and maintenance reports for each pump station. Pump Station Evaluation forms (**Appendix A**) were developed for each pump station and the stations were photographed to document the current conditions. Additional on-site evaluations were performed by electrical, instrumentation, mechanical, architectural, and structural engineers for five of the City’s pump stations: Mechanic Street, Deer Street, Leslie Drive, Constitution Avenue, and Atlantic Heights.

Desktop evaluations were performed by electrical, instrumentation, mechanical, architectural, and structural engineers for 13 of the City’s pump stations: West Road, Woodlands I, Woodlands II, Marcy Street, Corporate Drive, Griffin Park, Gosling Road, Ryeline, Tuckers Cove, Marsh Lane, Clough Drive, Mill Pond Way, and Northwest Street. No evaluation was performed on Heritage

Avenue pump station as it is scheduled for a comprehensive upgrade in 2019. No evaluation was performed on Lafayette Road as it underwent a major upgrade in 2018. Historical records and pump station capacity information were reviewed for evaluation of the force mains.

A desktop review was performed to assess the City's pump station force main assets. This includes an evaluation of force main conditions including force main operation (i.e., operational velocity), pipe material type, force main bypass options, corrosion risk, and criticality. City-wide maps delineating the force main locations in relation to potential soil corrosivity are available in **Appendix D**.

## **2.2 REPORT BACKGROUND INFORMATION**

In addition to information gathered during the on-site pump station evaluations, the following background references were used to develop this report.

### **2.2.1 Pump Station Historical Information**

The City provided record drawings, operation and maintenance manuals, and selected pump data sheets for the 20 pump stations, when available. In addition, the City provided institutional knowledge for each of the pump stations for items which were not necessarily recorded. In some instances, specific pump station record data was not available in which case basic assumptions were required to complete the assessment. Assumptions that affected the pump station evaluation or recommendation were noted.

The City provided elapsed time meter (ETM) data for each pump station and totalized daily flow data for the pump stations equipped with flow meters. ETM data was used to evaluate general pump operation trends. Pump station drawdown testing was completed, and magnetic flow meter data was recorded during the on-site visits. This data was combined with the ETM data sets where practicable to estimate flow trends for each pump station. In addition, the City supplied historical totalized magnetic flow meter data (daily) for many of the larger pump stations.

### **2.2.2 Pump Station Force Main Information**

The City provided their current geographical information system (GIS) database for the pump station force mains which included attributes such as pipe length, pipe material, and pipe age. Where available, the GIS database was cross-referenced with pump station record drawings for confirmation. The available force main data was used to evaluate their current conditions, and to develop recommendations for future force main inspection, maintenance, and planning.

The force main locations were overlaid with Natural Resource Conservation Service (NRCS) soils survey data to identify soil-type areas where force mains may be more at risk for corrosion. Depending on pipe material, the installation of force mains in areas of poor or corrosive soils can lead to accelerated deterioration of pipes, and therefore a shorter than expected anticipated useful life. Corrosive soils for steel and concrete from NRCS soils survey data were used to develop this factor. Cast iron and ductile iron pipes were analyzed with the steel corrosivity data. PVC was not investigated due to the material's high resistance to natural degradation (i.e. deterioration caused by soil conditions). Important to note is that most of the urban area soils were generically identified by the NRCS soils survey as "low corrosivity risk soils."

### **2.2.3 Pump Station Flooding Assessment**

In 2013, the City of Portsmouth completed a Coastal Resiliency Initiative Climate Change Vulnerability Assessment and Adaptation Plan (Coastal Resiliency Plan). The Coastal Resiliency Plan provides an overview of sea level flooding elevations across the City for the years 2050 and 2100 based on projected future scenarios. The conclusions from the Coastal Resiliency Plan were used as a basis for flood protection and pump station siting recommendations in the Pump Station Master Plan (**Appendix C**).

### **2.2.4 Applicable Fire Code**

#### NFPA 37 – Standard for Installation of Combustion Engines

To comply with NFPA 37, facilities must have a 1-hour fire-rated separation between rooms containing a stationary combustion engine (i.e., standby generator) and any other adjacent rooms within the structure. This code applies to many of the City's existing pump stations. Unless the requirement is waived by the local authority having jurisdiction, any major alteration to pump

stations which do not comply with this code, would need to be upgraded in accordance with NFPA 37. The current New Hampshire State Fire Code, Saf-C 6000, adopts by reference NFPA 1 - 2009 edition, which in turn adopts by reference NFPA 37 - 2006 edition.

#### NFPA 820 – Standard for Fire Protection in Wastewater Treatment & Collection Facilities

NFPA 820 was first issued as a recommendation in 1990 and governs to safeguard against fire and explosion risks in wastewater facilities that, while infrequent, tend to be relatively severe when they do occur. The scope has been expanded and the requirements refined in subsequent editions. This code reference dictates National Electric Code (NEC) classifications of hazardous references and also provides guidance on mechanical ventilation requirements for hazard-specific areas within a pump station.

3

## SECTION 3

### PUMP STATION EVALUATIONS WET PIT/DRY PIT PUMP STATIONS

#### 3.1 MECHANIC STREET

##### 3.1.1 Existing Conditions

The Mechanic Street Pump Station was originally constructed in the 1970s. It is the City's largest pump station and conveys all the City's wastewater that is treated at the Peirce Island WWTF. The pump station has undergone the following major upgrades:

- Building Renovation and Pump Replacement (1991)
- Screenings Removal Upgrade (2000)
- Electrical upgrade and Odor Control System Upgrade (2008)

##### *3.1.1.1 Equipment*

The pump station houses two 450 horse power (HP) dry pit submersible pumps. The Davis-EMU pumps were installed in 1991 and are rated for 22 MGD (15,300 gpm). The pumps operate in a lead/standby configuration and operate as much as 24-hours a day. Each pump is driven by a variable frequency drive (VFD) with the pump speed controlled by wet well level. The pump station wet well is divided into two parts separated by a manual sluice gate. The City indicated that the sluice gate is not operational. If the wet well needs to be bypassed, the City utilizes a permanent pump station bypass pump system which is comprised of a bypass wetwell and 143 HP submersible pump rated for 11.5 MGD (8,000 gpm). The bypass pump system was upgraded in 2000 with the Screenings Removal Upgrade project. The flows to the bypass pump do not pass through the influent screen.

The City indicated that over the past several years they have experienced the following wear and age-related equipment failures in their main pumping system:

- **Pump No. 1:** A hole was worn into the side of the pump volute. In 2015, the City had to complete an emergency pump repair consisting of installation of a temporary wear ring in the volute, and application of a coating inside the pump casing for wear protection.
- **Pump No. 2:** The motor failed which resulted in rewinding. In addition, in 2016 the suction piping failed and required emergency coupling adapters in the dry well.

The Wet Well side of the pump stations contains a hydraulically powered climber-style mechanical bar screen and dual stage wash press for screenings cleaning and compaction. The City indicated that the climber style screen requires constant maintenance. The Wet Well also contains a motor actuated influent sluice gate which can be operated to divert influent flow to the bypass pump station wet well.

Much of the equipment at the Mechanic Street Pump Station, including the main pumps, influent climber screen, screenings wash press, and support equipment has reached the end of its useful life. The existing equipment will require consistence maintenance to remain operational until its planned replacement as part of the City's Capital Improvement Plan.

#### *3.1.1.1.1 Heating, Ventilation, and Air Conditioning*

A packaged rooftop air handling unit provides heating (gas), cooling, and ventilation to the Control Room and Pump Room on the dry side of the pump station. This unit only operates during the day due to noise complaints from the neighbors. A ductless split system air conditioning unit provides additional cooling and is the primary source of cooling at night, when the rooftop unit is offline. Air is exhausted from the Control Room and Pump Room by a roof-mounted centrifugal upblast exhaust fan. When the main rooftop unit is not operating, the Dry Well is not ventilated as required by NFPA 820 requirements to declassify the space as required for the current electrical equipment ratings.

The Wet Well's ventilation is provided by a filtered, explosion-proof roof-mounted fan with weather hood. Exhaust air is ducted from the Wet Well through an odor control scrubber located on an elevated platform and its associated enclosed utility set exhaust fan. A bypass exhaust fan and associated ductwork is located adjacent to the odor control equipment. The equipment appears

to be in good condition. Heating is provided by an explosion proof electric unit heater which appears to be in fair condition.

A majority of the ventilation, heating, and cooling equipment were upgraded in 2000, with the dry well ductless split and the odor control system installed in 2008. Overall the equipment appeared to be in good condition. However, much of the HVAC equipment is roof-mounted and cannot be accessed without a complete electrical shutdown to the pump station due to the proximity of pole mounted transformers. In addition, the roof is not adequately equipped with guardrails for fall protection, as required by code. These code restrictions present significant maintenance obstacles when work is required on any of the HVAC equipment at the Mechanic Street Pump Station.

#### *3.1.1.1.2 Electrical*

The pump station's electric service is fed from three pole-mounted transformers located in close proximity to the pump station roof. The high voltage proximity presents life-safety access issues with HVAC equipment maintenance. Replacement of the transformers may require the installation of a pad-mounted transformer given the proximity of the pole to the pump station roof.

The main pumps are powered by variable frequency drives (VFDs) which were replaced in 2007. The automatic transfer switches (ATS-1 and ATS-2) allocated to each main pump were replaced in 2016. Much of the remaining electrical equipment was installed as part of the 1990 pump station upgrade and has reached the end of its useful life.

The pump station's diesel standby generator (Cummins 950 HP) was originally installed in 1990. The diesel storage tank for the generator is above-ground dual-wall fuel tank with leak detection port, located directly adjacent to the generator. Capacity information was not available for the storage tank; however, it appeared to be approximately 660 gallons total storage. Based on similar size standby generators, this volume appears to be relatively small and should be evaluated against NHDES' standby generator storage tank requirements. The tank shows some signs of minor surface corrosion, but appears to be in relatively good condition.

Emergency lighting and exit signage was observed to be missing from the Wet Well/Screenings Room as well as the Dry Well.

#### *3.1.1.1.3 Instrumentation*

The pump station controls are located in a control panel in the Control Room. A backup float control system is also located in the control panel in case of PLC or level instrument failure. There is a main effluent flow meter, two wet well submersible level transmitters, two high level float switches, and a drywell flood alarm level float switch. The bypass pump system is controlled by its own dedicated control panel and instruments. The bypass system includes an effluent flow meter, ultrasonic wet well level, and wet well float switches. No deficiencies were noted with the wet well level instruments or float switches, but it is noted that the bypass wet well ultrasonic level instrument and magnetic flow meter are approaching the end of their useful life (estimated at 15 years) and should be planned for replacement. All instruments in the wet well should be installed with intrinsically safe relays or intrinsically safe barrier protection installed.

#### *3.1.1.2 Building*

##### *3.1.1.2.1 Exterior*

The building exterior is in fair condition; however, there is evidence the building has been subjected to flooding at times. The roof houses mechanical equipment which presents life safety code issues as discussed in previous sections. Equipment located within 10 feet of the roof edge may only be accessed with full fall protection equipment when maintenance is required.

##### *3.1.1.2.2 Dry Well/Electrical Room*

Interior masonry surfaces on the upper level appeared to be mostly in good condition. The concrete floor near the entrance door has delaminated and missing toe plates were noted on the guard around the stair openings. The concrete stair is open at all levels with a single-height top-mounted guardrail. The concrete is in poor condition with degradation in areas. Corrosion was noted on the mezzanine steel beams, handrails, grating, and welds. The overhead concrete slab from the

mezzanine is degraded and should be resurfaced. Loose, broken, and missing stair nosing was observed.

#### *3.1.1.2.3 Wet Well*

The upper level concrete floor surfaces and walls showed significant staining and a few areas of degradation, likely due to the age and environment associated with the wet well area. The stair concrete was in poor condition with several steps missing imbedded stair nosings. The stair deficiencies present a tripping hazard. Concrete beams in the wet well area showed signs of spalling and cracking and should be repaired as soon as possible to prevent further damage

#### *3.1.1.3 Site*

As previously noted, there is evidence the site and building have been subject to flooding conditions. The existing finished floor elevation is 8.7 feet (NAVD) and falls within the floodplain for year 2050 and 2100 flooding projection scenarios as described in the City's Climate Change Vulnerability Assessment. See **Appendix C** for additional information regarding vulnerability to potential future flooding scenarios. Future pump station upgrades should consider these elevations when planning all proposed modifications or upgrades at the pump station.

Site observations indicated that the standby generator diesel fuel tank is not protected in any form or fastened to its support. Given the low elevation of the area, tank flotation may be a risk in a severe flooding scenario.

#### *3.1.1.4 Force Main*

The pump station's force main was installed during original construction of the pump station in the 1970s and has undergone several upgrades since. The notable force main upgrades occurred in 1988, 1990, and 1998. The force main is primarily ductile iron (DI) with a cast iron (CI) segment along the bridge section. The force main exits the pump station in a 20-inch diameter DI pipe and is immediately upsized to 30-inch diameter before traveling down Mechanic Street and splitting into two force mains before the bridge. After the bridge, the 24-inch DI pipe connects to the existing 24-inch DI force main installed in 1988 and travels 2,100 LF. The 16-inch CI pipe

connects to the existing 18-inch CI pipe installed in 1973 after the bridge and travels down Peirce Island Road, parallel to the 24-inch DI force main. The 16-inch CI and 24-inch DI force mains combine into a 30-inch pipe and continue the last 300 LF before entering the WWTF.

The average useful lifespan of DI force main pipe depends on a variety of factors, including: soil conditions, pumping conditions, and installation methods. Under normal conditions and good engineering practice, DI pipe can have a service life of 50 to 100 years. The older portions of the force main pipe are currently 45-years old.

In 2016, a force main break occurred on the newer 24-inch DI pipe. The break was attributed to a piece of rock bedded under the pipe which cause a small corrosion hole. No other notable breaks have occurred.

The Mechanic Street force main is located in an area of soils identified as low corrosivity to ductile iron. Based on this data, it is unlikely that soil conditions alone would contribute to accelerated degradation of the force main pipe. However, it must be noted that a section of force main before the Peirce Island bridge is in a low elevation area in close proximity to the Piscataqua River. It is expected that the water table is high and has high salinity, which can lead to accelerated corrosion of the force mains. However, if significant exterior force main degradation was occurring, it is likely that more recent force main construction projects at the pump station (i.e., Bypass Pumping upgrade, 2000) would have identified any force main deterioration issues.

### **3.1.2 Capacity Review**

Based on a review of the pump station runtime data, the pumps are currently operating almost 24-hours a day. This average day operation equates to approximately 20 million gallons per day (MGD) of wastewater based on the provided totalized flow meter data. It is only under drought conditions that the pumps typically run less, around 10 to 15 hours a day. Under high flow scenarios when the pumps are not able to convey peak sanitary flows, the sewer system overflows via one of two combined sewer overflow (CSO) structures in South Mill Pond. The pump station capacity is adequate for the City's current combined system. As the City continues to separate stormwater from the combined sewer system, the volume of stormwater flows conveyed tied into

the system may be reduced in the future, potentially allowing the Mechanic Street pump station peak capacities to be reduced and minimizing CSOs.

### **3.1.3 Emergency Bypass Plan**

The Mechanic Street Pump Station includes a permanent submersible wet well bypass system which has a capacity of up to 11 MGD, which corresponds to half of the pump station's design flow (22 MGD). In an emergency, this bypass pump system can be used to divert flow from the main pump station, to the bypass pump station. If flows exceed the capacity of the bypass pump station and the main pumps cannot be operated, the result will be a combined sewer overflow event in South Mill pond.

Based on a review of the existing record drawings, there is no permanent system in place to bypass the Mechanic Street force main(s). The City does have the capability to isolate a section of the force main on the pump station side of the Peirce Island bridge. In the event that the City needed to isolate the common force main section (30-inch) or the dual force main sections, the City has several force main bypass options depending on where the force main needed to be accessed:

- 1) Install a force main bypass connection at the pump station and install a temporary force main to the WWTF. This approach allows the City to utilize existing pumps, but would require a significant capital investment for equipment, materials, and labor.
- 2) Coordinate force main maintenance efforts for a "low flow" time slot and utilize septage haulers combined with in-line collection system storage to provide a window for force main maintenance. If the City exceeds the in-line storage capacity of the collection system, this approach can result in a CSO event in South Mill Pond (NPDES permitted CSOs 10A and 10B).

### **3.1.4 Recommendations**

Recommendations for the Mechanic Street Pump Station have been broken into three categories based on the level of priority. Medium and Low Priority recommendations can be found in the Recommended Facilities Improvement Plan attached as **Appendix B**. It must be noted that the Mechanic Street Pump Station is recommended for a comprehensive upgrade/replacement within

3 years and as such, deficiencies which were not considered high priority were assumed to be addressed in the subsequent upgrade. The following discussion addresses high priority and high cost items (greater than \$50,000) identified as part of this evaluation:

- i. The Mechanic Street Pump Station equipment including pumps, influent screen, and wet well piping have surpassed their useful life. A comprehensive Pump Station replacement is recommended within 1 to 3 years to continue to provide reliable operation.
- ii. As a short-term measure, it is recommended that the City contract with an ultrasonic thickness testing agency to confirm the integrity of all piping within the dry well.
- iii. Continuously operate the dry well roof exhaust fan to properly de-rate the area per NFPA 820 requirements. If the City determines that the existing exhaust fan unit cannot be operated, the City may consider a higher cost alternative to dry well ventilation which includes installation of new heating, ventilation, and cooling mechanical systems in the dry well.
- iv. Provide a capital planning fund for possible emergency VFD replacement until comprehensive pump station upgrades.
- v. Several minor improvements are recommended to ensure continued safety and reliability of the existing pump station: install emergency lighting; complete a dry well pipe thickness test; fasten the fuel oil tank to the foundations; repair and sandblast the dry well and wet well piping penetrations; repair the wet well cracked and spalled beams; replace wet well stair nosings; and pressure wash and repair the wet well concrete channel.

## **3.2 DEER STREET**

### **3.2.1 Existing Conditions**

The Deer Street Pump Station was originally constructed in the 1970s. It is the City's second largest pump station. This pump station has the largest sewer shed (approximately 200,000 linear feet of pipe), which includes a large part of the commercial downtown district, the residential areas

around North Mill Pond and Woodbury Avenue, as well as several commercial properties around and including the Durgin Square plaza. The pump station has undergone the following major upgrades:

- Building Renovation and Pump Replacement (1991)
- Comprehensive Pump Station upgrade (2007)

### ***3.2.1.1 Equipment***

The pump station houses three 200 HP vertical centrifugal Morris pumps installed in 2007. Each pump is rated for 6.2 MGD (single pump), or a combined 12.7 MGD (two pumps, PLC pump speed limited to 10.5 MGD). The pumps operate in a lead/lag/standby configuration. Each pump is VFD driven with the pump speed controlled by wet well level.

The pump station wet well is divided into two parts, with stop gates installed for wet well isolation. The influent sewer to the wet well can be controlled via a sluice gate. Prior to entering the wet well, wastewater flows through a hydraulically powered grinder. The wet well exhaust air is treated using a granular activated carbon adsorption unit.

The City reported that the existing pump station equipment is in good condition and has operated well since installation in 2008.

#### ***3.2.1.1.1 Heating, Ventilation, and Air Conditioning***

The Electric Room and Pump Room are supplied with heating and cooling by an air handling unit (AHU) with associated gas fired duct furnace, located in the mezzanine/attic area. The equipment was installed in 2008 and appear to be in relatively good condition. The exterior condensing unit associated with the air handling unit is showing signs of corrosion and the insulation on the refrigerant piping has been severely degraded and has failed in several places. The dry well area does not have a means to positively exhaust air from this space, as is required by NFPA 820 requirements to declassify the space for the current electrical equipment ratings. The Wet Well is ventilated by a duct mounted supply fan located in the electrical room and an exhaust fan and odor control unit located on the ground floor of the wet well. Heating is provided by an explosion proof unit heater. The equipment was installed in 2008 and appear to be in good condition.

### *3.2.1.1.2 Electrical*

As part of the comprehensive upgrade completed in 2007, all of the electrical equipment and distribution systems were replaced. No major deficiencies were noted, although it is recommended that arc flash safety labeling be added.

The pump station's standby generator (Caterpillar 500kW) was installed in 2007 and includes a sub-base 650-gallon fuel tank. The generator (and tank) are housed in a separate room adjacent to the Wet Well. No deficiencies were noted with the standby generator system.

### *3.2.1.1.3 Instrumentation*

The pump station controls are located in a control panel in the Electrical Room. A backup float control system is also located in the control panel in case of PLC or level instrument failure. There is a main effluent flow meter, wet well submersible level transmitters, four level float switches (two are backup switches), and a drywell flood alarm level float switch. No major deficiencies were noted with the instrumentation or control equipment.

The pump station also includes a newly installed gas detection system in both the Pump Room and Wet Well.

## **3.2.1.2 Building**

### *3.2.1.2.1 Exterior*

The building exterior is in excellent condition. On the exterior, only minor graffiti was noted during the site visit. The access doors to the Standby Generator Room are equipped with an internal louver assembly and modified door handle, which present a life safety concern for egress from this room. Minimum egress clear width is 32 inches for code compliance and this access door provides only an 18-inch egress distance with the louvers.

### *3.2.1.2.2 Dry Well/Electrical Room*

The existing concrete stair in the lower level is open at all levels with a single height top-mounted guardrail. The dry well stair shows signs of minor concrete degradation. It was also noted that the

stair nosing is loose, broken, or missing in several locations. Overall the concrete surfaces appear to be in good condition.

#### *3.2.1.2.3 Wet Well*

The upper level concrete floor surfaces showed significant staining and a few areas of degradation, likely due to the age of the area. The aluminum stair predates the 1990 pump station upgrade and may date back to the 1970s. The stairs were in fair condition but showed a moderate degree of corrosion with some bent treads. The odor control unit floor supports were questionable and should be structurally evaluated based on the potential weight of the activated carbon unit. The wet well contains an influent grinder that is in good condition. The City should plan on replacing the cutter stacks and possibly the grinder body, depending on its condition, every 4 to 8 years.

#### *3.2.1.2.4 Generator Room*

The Generator Room was constructed as an addition in the 2008 upgrade. The room houses the generator as well as provides access to the mechanical equipment platform via an alternating tread staircase. A large crack (drying/shrinkage crack) was observed in the ground level slab near the entrance door. Based on NFPA 37 requirements, the Generator room should be constructed to provide a 1-hour fire rated separation from the rest of the building. Based on the observed construction materials (i.e., plywood), this room does not appear to be adequately fire rated.

#### *3.2.1.3 Site*

The pump station is located at the corner of Deer Street and Market Street in the City's commercial downtown area. The Pump Station has a dedicated access drive on the front side (Deer Street) of the station, with Market Street and a residential sidewalk located on the north side of the Pump Station. The site is situated between two commercial buildings with access to one of these buildings' parking areas located on the immediate eastern side of the pump station.

The pump station's finished floor elevation is 13.0 feet (NAVD) with the surrounding grade ranging between 11.0 and 12.0 feet. These elevations fall within the floodplain for projected tidal flooding scenarios in the 2100, based on the City's Climate Change Vulnerability Assessment

(**Appendix C**). While the Deer Street Pump Station is not considered to be in immediate flooding danger, all future pump station upgrades should consider these elevations when planning all proposed modifications or upgrades at the pump station.

#### **3.2.1.4 Force Main**

The pump station's force main was installed during original construction of the pump station in the 1970s and has undergone several upgrades since. The major notable force main upgrades occurred in the 1980s and 1990 as part of the major pump station renovation.

The force main for this pump station begins as a 16-inch ductile iron (DI) pipe which splits into two separate force mains. Each force main is equipped with a buried gate valve for force main isolation. The City has indicated that both of these valves are no longer operational. After the inoperable buried valve, the force main is a 14-inch DI pipe (1976) routed along Ceres Street and northeast on Bow Street before transitioning to 16-inch DI pipe. The second force main is a 16-inch DI pipe which is routed up Market Street to the intersection of Pen hallow and Commercial Alley (1990) before transitioning to a 12-inch ductile iron pipe. Both force mains combine into a 20-inch DI pipe (1990) before discharging into a sewer manhole which conveys flow to the Mechanic Street Pump Station.

The average useful lifespan of DI pipe depends on a variety of factors, including: soil conditions, pumping conditions, and installation methods. Under normal conditions and good engineering practice, DI pipe can have a service life of 50 to 100 years. The existing force main pipes are made up of several different construction phases; however, it is estimated that much of the force main alignment is 32-years old. With the exception of the inoperable force main isolation valves, the City has no records of pipe failure or recurring maintenance issues.

The Deer Street force mains are located in an area of soils that do not present a corrosive risk to the force mains. However, much of the force main alignments are in heavily developed areas where soils are likely non-native fill material. If native soils are intact, they may contribute to a reduction in the expected lifespan of the pipe. Based on this data, age, and the criticality of the Deer Street Pump station, the City should monitor/inspect the Deer Street force mains every

5-10 years for integrity. Prior to any force main inspection taking place, the City will need to replace the buried isolation valves immediately outside of the pump station.

### **3.2.2 Capacity Review**

Based on a review of the pump station runtime data, the pumps are currently operating around 21-hours a day. Typically, these pumps operate well below full speed (~30 Hz) for large portions of the day when influent flows are low, and speed up during diurnal higher flowrates and storms. The average day pump operation averages to approximately 2.0 - 2.5 million gallons per day (MGD) of wastewater based on the City's provided totalized flow meter data. It is only under drought conditions that the pumps typically run less, around 15 hours a day. Elapsed time meter data indicates that Pump No. 3 operates between 20-30% more often than Pump No. 1 or Pump No. 2. Pump testing confirmed that this pump has a reduced capacity (5800 vs. 6000 gpm) compared to Pump No. 1 and Pump No. 2. This reduced capacity could be due to the pump/piping layout, but could also be indicative of impeller wear or other pump maintenance items. Under high flow scenarios, the Pump Station is limited to discharging 10.5 MGD by the Control Panel PLC to avoid overwhelming the downstream collection system (i.e., sewers, Mechanic Street). During these instances, the sewer system overflows via a combined sewer overflow (CSO) structure located across Market Street in the Piscataqua River (NPDES permitted CSO 013). Based on the downstream flow limitations, the Deer Street pump station is adequately sized to handle the sewershed's combined wastewater flows.

### **3.2.3 Emergency Bypass Plan**

The Deer Street Pump Station includes 12-inch bypass pumping connection if the pump station needed to be bypassed. If required, pump station bypass is considered an extreme event and would require supplemental bypass pumping from either the pump station wet well, or from the sewer manhole immediately upstream of the wet well.

The Deer Street Pump Station is serviced by two force mains which are each equipped with isolation valves for force main isolation. The City has reported that these valves are inoperable, and therefore, the City does not have a means to isolate either force main for maintenance. In the

event that these valves are repaired, the City could utilize one force main temporarily while maintenance of the other force main was completed.

### **3.2.4 Recommendations**

Recommendations for the Deer Street Pump Station have been broken into three categories based on the level of priority. Medium and Low Priority recommendations can be found in the Recommended Facilities Improvement Plan attached as **Appendix B**. The following discussion addresses high priority and high cost (greater than \$50,000) items identified through this evaluation.

- i. Repair buried force main isolation valves to allow for force main maintenance, inspection, etc.
- ii. Complete dry well (Electric Room, Pump Room) HVAC upgrades to provide positive ventilation as required per NFPA 820.
- iii. Begin long-term planning for Pump rehabilitation/replacement (10 years).
- iv. Modify the Generator Room to provide a 1-hour fire rating per NFPA 37.
- v. Evaluate Odor Control Unit elevated supports and support connections for structural integrity. Repair/reinforce supports as necessary.
- vi. To address several code-related life safety concerns, the following modifications are recommended: modify the Generator Room egress door louvers to allow for adequate egress clearances; add fire dampers to all ductwork that penetrate the Generator Room; add arc-flash safety labeling to electrical equipment where required.

## **3.3 LAFAYETTE ROAD**

### **3.3.1 Existing Conditions**

The Lafayette Road Pump Station was originally installed in 1962 and has undergone several major upgrades in 1991, and 1999. This pump station provides service to a major portion of the

south end of the City. The pump station was completely upgrade in 2018 and as a result, was not evaluated in detail as part of this study.

### **3.3.1.1 Site**

The pump station is located in the parking lot of shopping center on Lafayette Road in the City's commercial area. The existing finished floor elevation is approximately 14.0 feet and falls within the floodplain for 2100 flooding projection scenarios as described in the City's Climate Change Vulnerability Assessment. See **Appendix C** for additional information regarding vulnerability to potential future flooding scenarios.

### **3.3.1.2 Force Main**

The pump station's force main was installed during original construction of the pump station in 1962. The 14-inch asbestos cement (AC) force main extends approximately 2,600 LF before discharging into a sewer manhole on Lafayette Road.

The average useful lifespan of AC force main pipe depends on a variety of factors, including: soil and environmental conditions, pumping conditions, and installation methods. Under normal conditions and good engineering practice, AC pipe can have a service life of 50 to 100 years. Based on discussions with the City and a review of existing plans, the existing AC force main pipe is 56-years old. During the 2017 Lafayette Road Pump Station upgrade, the City successfully pigged the force main to ensure it's reliable, continued use. No issues were reported during the pigging exercise.

The force main is located in an area of soils with a low corrosion index. Based on this data, it is unlikely that soil conditions alone would contribute to accelerated degradation of the force main pipe. However, it must be noted that section of force main close to the pump station the is in a low elevation area in close proximity to Sagamore Creek, a tidally influenced water body. It is expected that the water table is high and possibly saline, which can lead to accelerated corrosion of asbestos cement force mains.

Based on the success of recent force main pigging in 2018, the 14-inch AC pipe appear to be in good condition internally. However, based on the age of the force main, it is recommended that the City plan to complete a visual investigation (CCTV) of the force main alignment to provide further confirmation of the interior pipe condition.

### **3.3.2 Recommendations**

It is recommended that the City plan to complete a closed-circuit television (CCTV) investigation in 1 to 3 years along the force main alignment to provide visual indication of the interior pipe condition.

## **3.4 HERITAGE AVENUE**

### **3.4.1 Existing Conditions**

The Heritage Avenue Pump Station was originally constructed in 1976 and provides service to several commercial/industrial properties located on Heritage Avenue. Comprehensive upgrades to the pump station are scheduled for design in 2018-2019; therefore, the pump station's current condition was not evaluated as part of this study.

#### ***3.4.1.1 Force Main***

The pump station's force main was upgraded in 2010. The 6-inch high density polyethylene (HDPE) force main extends 1,200 LF before discharging into a sewer manhole at the intersection of Heritage Avenue and Post Road.

The average useful lifespan of HDPE force main pipe depends on a variety of factors, including: soil conditions, pumping conditions, and installation methods. Under normal conditions and good engineering practice, HDPE pipe can have a service life of well over 50 years. The force main pipe is currently 8-years old and the City has no records of pipe failure or maintenance issues. HDPE is a very corrosion resistant material, and thus, it is unlikely that the soil type would contribute to deterioration of the pipe.

### **3.4.2 Recommendations**

The City has indicated that the Heritage Avenue pump station will be upgraded in 2019/2020. Based on the capacity of the pump station and historical low pump run times (less than 1 hour per day), the City should consider potential cost savings that could be realized with the application of a submersible-type pump station in lieu of suction lift or dry pit pumps.

## **3.5 GOSLING ROAD**

### **3.5.1 Existing Conditions**

The Gosling Road Pump Station was originally constructed in the early 1970s and underwent a comprehensive upgrade in 2005. This pump station provides service to a portion of the business/commercial district along Woodbury Avenue and Gosling Road.

#### ***3.5.1.1 Equipment***

The pump station houses two 40 HP vertical centrifugal pumps. Each pump is rated for 900 GPM at 105 feet of total dynamic head. The pumps operate in a lead/standby configuration. Each pump is VFD driven with the pump speed controlled by wet well level. The City indicated that replacement parts for these pumps are no longer available from the manufacturer. While the City has been able to stockpile some spare pump parts for the existing pumps, it is recommended that the pumps be replaced within the next 5 to 7 years with pumps which are supported by the manufacturer. At that time, pumps will have reached their expected useful design life (20 years).

The pump station wet well is divided into two parts, with stop gates installed for wet well isolation. Prior to entering the wet well, wastewater flows through a hydraulically powered grinder. The influent channel grinder is approaching 15 years old, but was observed to be in good condition. Depending on the severity of the grinder application, the City should plan on replacing the cutter stacks every 4 to 8 years, and possibly the grinder body depending on the condition.

#### *3.5.1.1.1 Heating, Ventilation, and Air Conditioning*

Ventilation air is circulated through the dry well by an exhaust fan located on the intermediate level, ducted down to the pump room below, and up to a louver in the ground level sidewall. The exhaust fan, louver, damper, and ductwork appear to be in good condition. Heating in the Dry Well is provided by a separated combustion unit heater with high static fan, located on the ground level and ducted down to the pump room below. Exhaust and combustion air are vented through a concentric vent kit in the sidewall. The unit appears to be in good condition, but was installed in 2005 and is approaching the end of its expected useful life. The City indicated that the dry well side of the pump station gets hot in the summertime and is difficult to keep cool. This is likely due to the lack of air conditioning as well as heat rejection from the VFDs, transformers, and other electrical distribution equipment.

The Wet Well is ventilated by an explosion proof FRP sidewall centrifugal exhaust fan ducted down to the lower level of the wet well. The fan and ductwork appear to be in good condition.

#### *3.5.1.1.2 Electrical*

As part of the comprehensive upgrade completed in 2005, all of the electrical equipment and distribution systems were replaced. The existing dry well hazardous gas detection system was not operational at the time of the site visit, but the City was in the process of replacing this system. No major deficiencies were noted.

The pump station's standby generator (Onan 125kW) was installed in 2005 and includes a sub-base diesel fuel tank. The generator (and tank) are housed in an exterior skin enclosure within a fenced in area adjacent to the Pump Station. No deficiencies were noted with the standby generator system.

#### *3.5.1.1.3 Instrumentation*

The pump station controls are located in a control panel in the upper level of the dry well. A backup float control system is also located in the control panel in case of PLC or level instrument failure. There is a main effluent flow meter, wet well submersible level transmitters, and four level float

switches (two are backup switches). No major deficiencies were noted with the instrumentation or control equipment.

The pump station gas detection system was being upgraded in both the Dry Well and Wet Well.

### **3.5.1.2 Building**

#### *3.5.1.2.1 Exterior*

The building exterior is in good condition. The membrane roof age was not able to be verified but may be nearing the end of its useful design life based on observations. In addition, the exterior monorail shows signs of corrosion and should be sandblasted/painted to prevent further corrosion.

#### *3.5.1.2.2 Dry Well/Electrical Room*

The interior surfaces and stairs are in good condition. No deficiencies were noted.

#### *3.5.1.2.3 Wet Well*

The interior surfaces of the wet well were observed to be in fair condition. The City should replace wet well channel grating where missing on the influent channels.

### **3.5.1.3 Site**

The pump station is located in a commercial district in the back corner of a Ryder truck rental establishment. The City indicated that in 2007/2008, the pump station was hit by a Ryder truck, and brick repair was required. The building structure has since been protected via concrete bollards around the periphery.

The existing finished floor elevation is 31 feet (NAVD) which is greater than 10 feet above flooding elevations identified in the City's Climate Change Vulnerability Assessment. Based on this assessment, the Gosling Road Pump Station does not present a flooding concern (**Appendix C**).

#### **3.5.1.4 Force Main**

Based on the reviewed plans, the pump station's force main was installed during the original construction of the pump station in the 1970s. The 8-inch asbestos cement (AC) force main extends 1200 LF before discharging into a sewer manhole on Woodbury Avenue.

The average useful lifespan of AC force main pipe depends on a variety of factors, including: soil and environmental conditions, pumping conditions, and installation methods. Under normal conditions and good engineering practice, AC pipe can have a service life of 50 to 100 years.

Based on discussions with the City and a review of existing plans, the existing AC force main pipe is 48-years old. The City reported no records of pipe failure or maintenance issues with this force main.

The force main is located in an area of soils identified as medium corrosivity to concrete. It is possible that this may accelerate the rate of deterioration of the force main, reducing the pipes anticipated useful life. Based on the age of the force main, it is recommended that the City plan to complete a visual investigation (CCTV) of the force main to provide further confirmation of the interior pipe condition.

#### **3.5.2 Capacity Review**

Based on a review of the pump station runtime data, the pumps are currently operating an average of approximately 12 hours per day per pump. The City reported that the pumps are operated at low speeds (around 30 Hz) continuously. This average day operation equates to approximately 0.11 MGD of wastewater based on the provided totalized flow meter data. It must be noted that operating the pumps continuously at low speeds can result in solids settling and scouring issues within the force main due to low wastewater velocities (less than 1 ft/sec). The City should modify the minimum speed of the pump station to provide the minimum flushing velocities (300 GPM, 2 ft/sec) required for the 8-inch AC force main. Under peak conditions, the pumps may run up to 24 hours per day (total run info) and convey up to 0.5 MGD. Based on the low pump operation speed, and the maximum total daily flowrates, the pump station operates within capacity.

### 3.5.3 Emergency Bypass Plan

Based on review of the historical pump station drawings, the Gosling Road Pump Station does not contain a force main or pump station bypass connection. The dry well does contain a pig launching setup for future force main cleaning. In the event that the City needed to isolate the force main for maintenance, the City would coordinate maintenance efforts for a “low flow” time slot and utilize septage haulers to provide a window for force main maintenance. Based on the relatively low average day flows to the Gosling Road pump station (less than 0.15 MGD), temporary septage hauling from the upstream sewer manhole or from the pump station wet well is an acceptable bypass management approach for force main maintenance.

### 3.5.4 Recommendations

Recommendations for the Gosling Road Pump Station have been broken into three categories based on the level of priority. Medium and Low Priority recommendations can be found in the Recommended Facilities Improvement Plan attached as **Appendix B**. The following discussion addresses high priority and high cost (greater than \$50,000) items identified through this evaluation.

- i. It is recommended that the City plan to complete a force main pigging and closed-circuit television (CCTV) investigation in 1 to 3 years along the force main to provide visual indication of the interior pipe condition.
- ii. Begin capital planning for pump replacement to provide the City with manufacturer supported pumps;
- iii. To address several code-related life safety concerns, the following modifications are recommended: replace wet well grating; installing exit and emergency lighting; and repairing the hazardous gas detection system.

## **3.6 RYELINE**

### **3.6.1 Existing Conditions**

The Ryeline Pump Station was originally constructed in 1964 and underwent a comprehensive improvement in 2009. The pump station provides service to the southernmost portion of Portsmouth, including residential neighborhoods along Ocean Road as well as commercial properties.

#### ***3.6.1.1 Equipment***

The pump station houses two 20 HP vertical centrifugal Smith & Loveless pumps which were installed in 2009. Each pump is rated for 600 GPM at 85 feet of total dynamic head. The pumps operate in a lead/standby configuration. Each pump is VFD driven with the pump speed controlled by wet well level.

The pump station wet well is divided into two parts, with stop gates installed for wet well isolation. The wet well divider gate was broken during the site visit. Prior to entering the wet well, wastewater flows through a hydraulically powered grinder.

The City reported that the existing pump station equipment is in good condition and has operated well since upgrade in 2009.

##### ***3.6.1.1.1 Heating, Ventilation, and Air Conditioning***

The dry well, which also contains the standby generator, is ventilated by an inline supply fan located in the Generator Room. The supply fan capacity was noted to not have capacity to properly ventilate the dry well at 6 air changes per hour to declassify the space. During the site visit the supply fan was in AUTO, but the controls were not set up to run continuously, as required by NFPA 820. Heating is provided by a separate combustion unit heater with high static fan observed to be in good condition. The standby generator intake louver/dampers are designed to operate when the emergency generator is operating or when the room temperature exceeds an operator adjustable setpoint. City staff indicated the pump station is extremely hot in the summer time.

The standby generator exhaust piping was not insulated and needs to be insulated for operator safety. While not required, a ventilated generator exhaust wall thimble should be considered to avoid wall damage.

The Wet Well is ventilated by an explosion proof FRP sidewall centrifugal exhaust fan ducted down to the lower level. The fan and ductwork appear to be in good condition. There is no dedicated wet well air intake installed in the wet well meaning that the wet well exhaust fan creates a negative pressure on the influent sewer system.

### **3.6.1.2 Building**

#### *3.6.1.2.1 Exterior*

The building exterior is in good condition. A few areas on the building steel framing exhibited minor peeling paint and corrosion that should be sandblasted and repainted to prevent further deterioration.

#### *3.6.1.2.2 Dry Well*

The interior surfaces are all noted to be in good condition.

The magnetic flow meter for the pump station is located in an enclosed intermediate confined area, accessible only via a ladder located immediately adjacent to the standby generator. The flow meter area should be treated as a confined space when access is required. In addition, due to the proximity of the standby generator, the standby generator should be locked out of use when the flow meter confined area is entered.

The guard rails for the spiral stairs did not have toe guards installed. Toe guards help prevent tools or occupants from an area where a fall hazard exists from above.

The pump station's standby generator (Caterpillar 80 kW) was installed in 2009 and is supplied by natural gas. The generator is located in the dry well of the pump station. While no deficiencies were noted with the standby generator system, the generator is not provided with a 1-hour space separation. Based on NFPA 37 requirements, the Generator room should be constructed to provide a 1-hour fire rated separation from the rest of the building. The City should consider relocating

the standby generator to an area outside of the dry well (i.e., exterior) during the next major pump station upgrade in order to comply with NFPA 37 requirements.

#### *3.6.1.2.3 Wet Well*

The interior surfaces of the wet well were observed to be in fair condition with the exception of the entranceway coatings. The coatings in this area are failing and cracking off of the existing walls in small sectional sheets. Based on site observations, the coating failing could be due to misapplication of the product or incorrect surface preparation which is the most likely case. Based on the low degree of humidity and odors in this area and the high rate of ventilation, it is not considered necessary that the City replace this coating system in the entranceway. The City could continue to monitor the coatings failures and spot repair the areas with epoxy as needed.

The guard rails for the stairs did not have toe guards installed. Toe guards help prevent tools or occupants from an area where a fall hazard exists from above. The wet well second level elevated access area is protected with a chain guard which should be replaced with a rigid rail guard for safety.

#### *3.6.1.2.4 Electrical*

As part of the comprehensive upgrade completed in 2009, all of the electrical equipment and distribution systems were replaced. No deficiencies were noted.

#### *3.6.1.2.5 Instrumentation*

The pump station controls are located in a control panel in the upper level of the dry well. A backup float control system is also located in the control panel in case of PLC or level instrument failure. There is a main effluent flow meter, wet well radar level sensors, and four level float switches (two are backup switches). No major deficiencies were noted with the instrumentation or control equipment.

### **3.6.1.3 Site**

The station is located on a parcel of low-lying land surrounded by jurisdictional wetlands associated with Berry's Brook. The existing pump station facility was upgraded in 2009 to include a dry well area that is elevated from the original 1970s pump station. This was done in an effort to minimize the risk of flooding from the adjacent wetlands. Based on discussions with the City, the pump station has not had pump station flooding issues since the pump station was raised in 2009. No other issues were noted on-site.

Based on the proximity to tidal waters the Ryeline Pump Station is not at risk for tidal flooding as evaluated in the City's Climate Change Vulnerability Assessment (**Appendix C**).

### **3.6.1.4 Force Main**

Based on the reviewed plans, the pump station's force main was installed during the original construction of the pump station in the early 1970s. The 8-inch asbestos cement (AC) force main extends 4000 LF before discharging into a sewer manhole on Lafayette Road.

The average useful lifespan of AC force main pipe depends on a variety of factors, including: soil and environmental conditions, pumping conditions, and installation methods. Under normal conditions and good engineering practice, AC pipe can have a service life of 50 to 100 years.

Based on discussions with the City and a review of existing plans, the existing AC force main pipe is 48-years old. The City reported no records of pipe failure or maintenance issues with this force main.

The force main is located in an area of soils identified ranging from low to high corrosivity risk to concrete. However, the existing 8-inch AC force main was excavated as part of the 2009 pump station upgrade and no significant deterioration issues were noted by the City. Based on the age of the force main, it is recommended that the City plan to complete a visual investigation (CCTV) of the force main to provide further confirmation of the interior pipe condition.

### **3.6.2 Capacity Review**

Based on a review of the pump station runtime data, the pumps are currently operating an average of approximately 10.5 hours per day per pump. The City reported that the pumps are operated at low speeds (around 30 Hz) continuously. This average day operation equates to approximately 0.18 MGD of wastewater based on the provided totalized flow meter data. It must be noted that operating the pumps continuously at low speeds can result in solids settling and scouring issues within the force main due to low wastewater velocities (less than 1 ft/sec). The City should modify the minimum speed of the pump station to provide the minimum flushing velocities (300 GPM, 2 ft/sec) required for the 8-inch AC force main. Under peak conditions, the pumps may run up to 24 hours per day (total run info) and convey over 0.5 MGD. Based on the low pump operation speed, and the maximum total daily flowrates, the pump station operates within capacity.

### **3.6.3 Emergency Bypass Plan**

Based on review of the historical pump station drawings, the Ryeline Pump Station has an exterior above grade bypass connection to allow temporary force main bypassing using the existing dry well pumps. The arrangement also allows the City to isolate the existing dry well pumps and use temporary pumps to connect to the existing force main.

In the event that the City needed to isolate the force main for maintenance, the City would coordinate maintenance efforts for a “low flow” time slot and utilize septage haulers to provide a window for force main maintenance. Based on the relatively low average day flows to the Ryeline pump station (< 0.18 MGD), temporary septage hauling from the upstream sewer manhole or from the pump station wet well is an acceptable bypass management approach for force main maintenance.

### **3.6.4 Recommendations**

Recommendations for the Ryeline Pump Station have been broken into three categories based on the level of priority. Medium and Low Priority recommendations can be found in the Recommended Facilities Improvement Plan attached as **Appendix B**. The following discussion

addresses high priority and high cost (greater than \$50,000) items identified through this evaluation.

- i. Restrict access to the magnetic flow meter vault with a sign labeled for “confined space only”. In addition, the sign should indicate that the standby generator should be disconnected (locked out/tagged out) prior to entrance.
- ii. Upgrade the dry well HVAC system with proper ventilation controls and ventilation fan requirements per NFPA 820.
- iii. Begin long-term planning for Pump rehabilitation/replacement (10 years).
- iv. The current interior location of the standby generator does not meet current NFPA 37 code requirements. During the next major pump station upgrade, the City should evaluate relocating the standby generator outside, or to a new area with a 1-hour fire rating.
- v. Complete dry well (Electric Room, Pump Room) HVAC upgrades to provide positive ventilation as required per NFPA 820.
- vi. To address several code-related life safety concerns, the following modifications are recommended: install rigid handrail on elevated wet well platform; add toe plates to guardrail for dry well staircase.

4

## SECTION 4

### PUMP STATION EVALUATIONS SUCTION LIFT PUMP STATIONS

#### 4.1 CONSTITUTION AVENUE

##### 4.1.1 Existing Conditions

The Constitution Avenue Pump Station was originally constructed in 1985 and underwent a SCADA upgrade in 2005. The pump station consists of a pre-fabricated structure which contains the pumps, electrical equipment, and standby generator, along with a circular pre-cast wet well. The pump station provides service to several commercial and industrial properties, including the Southgate Plaza shopping center.

##### *4.1.1.1 Equipment*

The suction-lift pump station houses two recently installed (2016 and 2017) Gorman-Rupp T-4 self-priming centrifugal pumps with 15 HP motors. The pump motors date back to the original pump station construction and should be included in capital replacement planning in the near future. Based on the City's records, each pump was originally rated for 320 GPM. Each pump is driven by constant speed starter with the pump operation controlled by wet well level. The pumps operate in a lead/standby configuration and operate as much as 8-hours a day. The pumps are operated at constant speed from a pump station control panel located within the pump station. Pump station draw-down tests indicated that the pumps are operating at a capacity closer to 177 GPM. Observed pump head conditions were lower than the anticipated design pressures. It should be noted the sheave configuration of the pumps is unknown and may be contributing to the lower observed pump capacity.

The pump station's 8-foot diameter wet well structure was observed to be in good condition due to the City's biannual cleaning program. The wet well hatch was missing a safety net, but no structural deficiencies were noted. The City indicated that the pump suction piping was replaced

in the wet well in 2015 due to corrosion. Observations indicate that the wet well pump discharge pipe is also showing signs of corrosion and should also be replaced.

#### *4.1.1.1.1 Heating, Ventilation and Air Conditioning*

The pump station building is heated by two wall-mounted electric unit heaters which have both been replaced recently. The heaters appear to be in good condition. The building is not actively ventilated which is authorized per the Building Code, but a mechanism must be in place to allow the door to remain open while the pump station occupied. The City indicated the pump station can get very hot in the summertime due to the lack of ventilation and/or air conditioning. The City should consider installation of a split air conditioning unit or exhaust fan.

During the site visit, the pump and process area showed signs of condensation. To mitigate corrosion of process equipment and piping, a dehumidifier is recommended for this area.

#### *4.1.1.1.2 Electrical*

The existing electrical distribution equipment and pump motor starters date back to the original pump station construction in 1985. This equipment has surpassed its useful design life. Many of the components are obsolete, and considerations should be given to a comprehensive electrical upgrade, including panelboards, emergency power equipment, and other ancillary electrical components. A few minor deficiencies were noted, such as the lack of exit and emergency lighting, as well as missing arc-flash safety labeling.

A 45-kW Cummins Onan standby generator and automatic transfer switch (ATS) are located inside the pump station. The generator and ATS were installed in 1985 and operates on two 150-gallon propane storage tanks located outside of the building. The generator's exhaust piping should be insulated for safety purposes, and while not required, installation of a ventilated exhaust wall thimble should be considered to avoid continued wall damage.

#### *4.1.1.1.3 Instrumentation*

The pump station controls are located in a control panel in the Pump Room. The control panel was upgraded in 2005 to include PLC (Programmable Logic Controller) based controls. The control panel was found to be in good condition, but has an estimated lifespan of approximately 20 years. The City should plan to replace the pump control panel, or the major components, based on this timeframe or during the next major pump station upgrade.

The pump station's PLC, which is installed in the control panel, is connected to a pole-mounted microwave radio that communicates with the City's SCADA system for monitoring, control, and alarming. The radio uses an antenna mounted on the north side of the building. It is recommended the antenna must be grounded.

The wet well instruments include a submersible pressure transducer, differential level floats, and two backup alarm floats (high-high and low-low). Submersible level instruments in hazardous locations should be installed with an intrinsically safe barriers. For ease of operator maintenance, it is recommended that conduit seal-offs are installed on the instrument conduits outside of the wet well with a junction box on the wet well side of the seal off, but still outside the wet well to allow for instrument replacement without confined space entry.

Emergency/exit lighting was observed to be missing from the pump station.

#### **4.1.1.2 Building**

##### *4.1.1.2.1 Exterior*

The existing building consists of a precast concrete structure with a stone aggregate exterior finish. The exterior is missing aggregate in locations that require cosmetic repair. The pre-cast concrete slab is in good condition with the exception of a corner of the slab which needs to be rebuilt/patched. The building joint between the foundation and the superstructure should be pressure washed and the joint sealed to ensure moisture does not penetrate the building envelope. The membrane roof appears to be in good condition but has a relatively low slope which allows water to pool as evidenced by staining. If the roof is replaced, a higher sloped roof is recommended

to assist drainage. The double access door is missing miscellaneous hardware and should be painted to preserve longevity.

The existing pre-cast pump station superstructure is 33 years old. While this pre-fabricated structure has served the City well, the overall condition is deteriorating and building maintenance and improvement needs will only increase in the coming years. Based on the increased building maintenance costs, it is recommended the City evaluate the following options for the Constitution Avenue pump station in the future (7 to 10 years):

- **Option 1: Building Replacement** – Begin capital planning for replacement of the existing building structure.
- **Option 2: Pump Station Conversion** – Convert the suction lift pump station to a submersible style pump station with a small outbuilding electrical distribution equipment and control panels.

#### *4.1.1.2.2 Interior*

The interior floors and wall finish need to be recoated for continued use. Several open piping penetrations from the wet well to the interior building were observed. These penetrations should be sealed to mitigate transfer of gases between the wet well and the building and to maintain the proper NFPA 820 classification for the building space. The back wall of the interior structure has a visible crack where the standby generator exhaust penetrates the wall. This crack is likely due to excessive heat from the exhaust pipe, and a lack of a ventilated wall thimble for the exhaust pipe. The wall crack should be sealed to prevent air and water leakage.

#### *4.1.1.3 Site*

The pump station is located directly adjacent to Constitution Avenue in a primarily commercial district. The station has its own paved driveway and is abutted by undeveloped forest on three sides. A chain link fence surrounds the two generator propane storage tanks (vertical 150-gallon). Bollards protect the wet well hatch located just outside the pump station building.

The site's grade was raised 3 to 5 feet for construction of the pump station to avoid stormwater issues caused by sheet flow from the adjacent property and road. While the site does not currently show signs of erosion/damage from stormwater drainage/runoff, it is recommended the City periodically inspect the surrounding site to ensure that stormwater/erosion issues do not develop.

Based on the City's Climate Change Vulnerability Assessment, the pump station will not be impacted by flood elevations (**Appendix C**).

#### ***4.1.1.4 Force main***

Based on a review of the existing plans, the pump station's force main was installed during original construction of the original pump station in 1985. The ductile iron (DI) force main pipe is 6-inches in diameter and discharges to a sewer manhole located approximately 2,600 feet away at the corner of Constitution Avenue and Lafayette Road.

The average useful lifespan of DI force main pipe depends on a variety of factors, including: soil conditions, pumping conditions, and installation methods. Under normal conditions and good engineering practice, DI pipe can have a service life of 50 to 100 years. The older portions of the force main pipe are currently 32-years old. The City did not report any maintenance issues with the ductile iron force main; however, the exposed wet well portions of the force main were noted to be in poor condition.

The Constitution Avenue force main is located in an area of soils that are reported to cause moderate to high corrosivity of steel. Based on this data, this soil type could potentially lead to accelerated degradation of the force main pipe, reducing the pipe's anticipated useful life. Based on the age of the force main and the condition of the exposed wet well force main, it is recommended that the City plan to complete a visual investigation (CCTV) of the force main to provide further confirmation of the interior pipe condition.

Based on observed pump flowrates, the velocity of flow through the PVC force main is 1.9 feet per second, which is near the minimum scour velocity. Long-term low-velocity operation increases the risk of solids settling in the force main, and reduces the force main capacity. While

the City has not reported any issues with force main solids settling, it is recommended the force main is periodically jetted to ensure it remains at full capacity.

#### **4.1.2 Capacity Review**

Based on a review of the pump station runtime data, the pumps are currently operating an average of 2.75 hours per day (total run time for both pumps). Based on draw-down test observations, this equates to approximately 30,000 gallons per day. Under peak conditions, the pumps may run up to 17 hours per day (total run time for both pumps). Given the minimal operating times for the both pumps, the station appears to have adequate capacity to handle existing flows.

The pump station appears to have significant peaks in run times during the spring (March to May). This trend suggests the pump station experiences inflow and infiltration (I/I) during the spring season when groundwater levels and stormwater/meltwater runoff are peaking. The City should investigate the Constitution Avenue sewershed to identify and mitigate potential sources of I/I.

#### **4.1.3 Emergency Bypass Plan**

The Constitution Avenue Pump Station does not contain a force main or pump station bypass connection. In the event the City needed to isolate the force main for maintenance, the City would coordinate maintenance efforts for a “low flow” time slot and utilize septage haulers to provide a window for force main maintenance. Based on the relatively low average day flows to the pump station (less than 30,000 GPD), temporary septage hauling from the upstream sewer manhole or from the pump station wet well is an acceptable bypass management approach for force main or pump station maintenance.

#### **4.1.4 Recommendations**

Recommendations for the Constitution Avenue Pump Station have been broken into three categories based on the level of priority. Medium and Low Priority recommendations can be found in the Recommended Facilities Improvement Plan attached as **Appendix B**. The following

discussion addresses High Priority and high cost (greater than \$50,000) items identified through this evaluation.

- i. The existing superstructure is approaching the end of its useful life. The City should consider pump station superstructure replacement, or conversion to a submersible pump station within 7 to 10 years. It should be noted that depending on the City's preference for the future pump station structure upgrade (replacement vs. conversion) and timeline, some of the identified Low and Medium priority recommendations may not apply.
- ii. Complete comprehensive electrical upgrade concurrently with Item i including distribution equipment, starters, standby generator, and automatic transfer switch (ATS).
- iii. Complete the following modifications to address code-related life safety concerns and to prevent further building deterioration: install a mechanism to hold the building door open while occupied; install exit and emergency lighting; provide arc-flash safety labeling; and ground the antenna mast.
- iv. Complete a force main pigging and closed-circuit television (CCTV) investigation along the force main in 3 to 5 years to provide visual verification of the interior pipe condition.

## **4.2 WEST ROAD**

### **4.2.1 Existing Conditions**

The West Road Pump Station was originally constructed in 1984 and underwent a SCADA upgrade in 2005. The pump station consists of a pre-fabricated structure which contains the pumps, electrical equipment, and standby generator, along with a circular pre-cast wet well. The pump station provides service to over a dozen commercial developments along West Road in the southern part of Portsmouth.

#### ***4.2.1.1 Equipment***

The suction-lift pump station houses two 10 HP Gorman-Rupp T-4 self-priming centrifugal pumps which are original to the pump station (1984). Based on the City's records, each pump was originally rated for 400 GPM. Each pump is driven by a constant speed starter with the pump

operation controlled by wet well level. The pumps operate in a lead/standby configuration and operate as much as 5 hours a day (combined). The pumps are operated at constant speed from a pump station control panel located within the pump station. Pump station draw-down tests indicated that the pumps are operating at a capacity between 270 to 300 GPM. Observed head conditions were lower than the anticipated design pressures. It should be noted the sheave configuration of the pumps was unknown and may be contributing to the lower observed pump capacity. The reduced pump efficiency may also be due to wear attributed to the age of the pumps (33-years). Based on the age of the pumps and motors, this equipment has surpassed its expected useful design life. While the pumps were noted to run reliably and have relatively low operational hours, the City should begin to plan for replacement of these pumps in the next 3-5 years, or during the next significant pump station upgrade. Based on the low runtimes and pump flowrates, the City may also consider conversion of this pump station to a submersible pump station for a capital cost savings.

The pump station's 8-foot diameter wet well structure was observed to be in good condition due to the City's biannual cleaning program. The wet well hatch was missing a safety net, but no structural deficiencies were noted. The pump suction and pump discharge piping showed significant signs of corrosion and should be considered for replacement.

#### *4.2.1.1.1 Heating, Ventilation and Air Conditioning*

The pump station building is heated by one wall-mounted electric unit heater which was noted to be in good condition. The building is not actively ventilated which is authorized per the Building Code, but a mechanism must be in place to allow the door to remain open while the pump station occupied. The City indicated the pump station can get very hot in the summertime due to the lack of ventilation and/or air conditioning. The City should consider installation of a split air conditioning unit or exhaust fan.

During the site visit, the pump and process area showed signs of condensation. To mitigate corrosion of process equipment and piping, a dehumidifier is recommended for this area.

While not required, a ventilated exhaust wall thimble should also be considered to avoid wall damage. The exterior standby generator exterior intake and exhaust louvers are corroded and should be replaced/repared. In addition, the existing exterior propane vent should be relocated to be greater than 5 feet from any building air intake or exhaust.

#### *4.2.1.1.2 Electrical*

The existing electrical distribution equipment and pump motor starters date back to the original pump station construction in 1984. This equipment has surpassed its useful design life. Many of the components are obsolete, and considerations should be given to a comprehensive electrical upgrade, including panelboards, emergency power equipment, and other ancillary electrical components. A few minor deficiencies were noted, such as the lack of exit and emergency lighting, as well as missing arc-flash safety labeling.

A 30-kW Cummins Onan standby generator and automatic transfer switch (ATS) is located inside the pump station. The generator was installed in 1984 and operates on two 100-gallon propane storage tanks located outside of the building. The ATS was replaced more recently based on discussions with the City. The generator's exhaust piping should be re-insulated for safety purposes.

#### *4.2.1.1.3 Instrumentation*

The pump station controls are located in a control panel in the Pump Room. The control panel was upgraded in 2005 to include PLC (Programmable Logic Controller) based controls. The control panel was found to be in good condition, but has an estimated lifespan of approximately 20 years. The City should plan to replace the pump control panel, or the major components, based on this timeframe or during the next major pump station upgrade.

The pump station's PLC, which is installed in the control panel, is connected to a pole-mounted microwave radio that communicates with the City's SCADA system for monitoring, control, and alarming. The radio uses an antenna mounted on the side of the building.

The wet well instruments include a submersible pressure transducer, differential level floats, and two backup alarm floats (high-high and low-low). Submersible level instruments in hazardous locations should be installed with an intrinsically safe barriers. For ease of operator maintenance, it is recommended that conduit seal-offs are installed on the instrument conduits outside of the wet well with a junction box on the wet well side of the seal off, but still outside the wet well to allow for instrument replacement without confined space entry.

Emergency/exit lighting was observed to be missing from the pump station.

#### **4.2.1.2 Building**

##### *4.2.1.2.1 Exterior*

The existing building consists of a precast concrete structure with a stone aggregate exterior finish. The exterior of the building appears to be in good condition with the exception of degraded sealant between precast sections, which should be replaced. The membrane roof shows evidence of minor leaks and has a relatively low slope which allows water to pool. Although no obvious tears or open joints were observed on the roof membrane, it does appear to be faded and may be thinning and brittle as it is likely nearing the end of its design life. Replacement of the membrane should be anticipated within 5 years. When the roof is replaced, a higher sloped roof is recommended to assist drainage. The double access door and door frame are in poor condition and should be considered for replacement if long term use is anticipated.

The existing pre-cast pump station superstructure is 33 years old. While this pre-fabricated structure has served the City well, the overall condition is deteriorating and building maintenance and improvement needs will only increase in the coming years. Based on the increased building maintenance costs, it is recommended that the City evaluate the following options for the West Road pump station in the future (5 to 10 years):

- **Option 1: Building Replacement** – Begin capital planning for replacement of the existing building structure.

- **Option 2: Pump Station Conversion** – Convert the suction lift pump station to a submersible style pump station with a small outbuilding electrical distribution equipment and control panels.

#### *4.2.1.2.2 Interior*

The interior floors and wall finishes appear to have recently been refinished and are in good condition. Several open piping penetrations from the wet well to the interior building were observed. These penetrations should be sealed to mitigate transfer of gases between the wet well and the building, and to maintain the proper NFPA 820 classification for the building space. The pre-cast roof slab seam has been sealed with caulking to mitigate roof leaking. The precast concrete top slab has many pop-outs and a large crack that should be repaired.

#### *4.2.1.3 Site*

The pump station is located directly adjacent to West Road in a commercial district. A chain link fence surrounds the two generator propane storage tanks. No issues were noted with the exterior site.

Based on the City’s Climate Change Vulnerability Assessment, the pump station will not be impacted by tidal flood elevations (**Appendix C**).

#### *4.2.1.4 Force Main*

Based on a review of the Town’s GIS data, the existing force main is a 6-inch PVC pipe. However, the pump station’s original force main installed during original construction of the pump station in 1984 was ductile iron (DI). For the purposes of this evaluation, the force main is assumed to be PVC. The force main discharges to a sewer manhole located approximately 1,300 feet away on West Road.

The average useful lifespan of PVC force main pipe depends on a variety of factors, including: soil conditions, pumping conditions, and installation methods. Under normal conditions and good engineering practice, PVC pipe can have a service life of 50 to 75 years. The force main pipe is

currently 33 years old. The City did not report any maintenance issues with the force main; however, the exposed ductile iron wet well portions of the force main were noted to be in poor condition.

The West Road force main is located in an area of soils that are reported to have a low corrosivity index. Based on this data, soil corrosion is not expected to contribute to accelerated deterioration of the force main pipe, even if the material is ductile iron as the original pump station drawings indicate. However, based on the age of the force main and the condition of the exposed wet well force main, it is recommended that the City plan to complete a visual investigation (CCTV) of the force main to provide further confirmation of the interior pipe condition.

#### **4.2.2 Capacity Review**

Based on a review of the pump station runtime data, the pumps are currently operating an average of less than 2 hours per day (total run time for both pumps). Based on draw-down test observations, this equates to approximately 30,000 gallons per day. Under peak conditions, the pumps may run up to 5 hours per day (total run time for both pumps). Given the minimal operating times for both pumps, the station appears to have adequate capacity to handle existing flows. Pump runtime data for the pump station was consistent throughout the year, with minimal seasonal peaking. Therefore, the pump station does not appear to be significantly impacted by seasonal inflow and infiltration (I/I).

#### **4.2.3 Emergency Bypass Plan**

The West Road Pump Station does not contain a force main or pump station bypass connection. In the event the City needed to isolate the force main for maintenance, the City would coordinate maintenance efforts for a “low flow” time slot and utilize septage haulers to provide a window for force main maintenance. Based on the relatively low average day flows to the pump station (less than 30,000 GPD), temporary septage hauling from the upstream sewer manhole or from the pump station wet well is an acceptable bypass management approach for force main or pump station maintenance.

#### 4.2.4 Recommendations

Recommendations for the West Road Pump Station have been broken into three categories based on the level of priority. Medium and Low Priority recommendations can be found in the Recommended Facilities Improvement Plan attached as **Appendix B**. The following discussion addresses High Priority and high cost (greater than \$50,000) items identified through this evaluation.

- i. The existing superstructure is approaching the end of its useful life and should be considered for replacement. The City should consider pump station superstructure replacement, or conversion to a submersible pump station within 5-10 years. It should be noted that depending on the City's preference for the future pump station structure upgrade (replacement vs. conversion) and timeline, some of the identified Low and Medium priority recommendations may not apply.
- ii. The existing suction lift pumps are near the end of their expected useful life and should be considered for replacement. The City should consider pump replacement within 3-5 years, or during the next significant pump station upgrade. Alternatively, the City may choose to abandon the suction lift pumps in favor of a submersible pump station.
- iii. Complete comprehensive electrical upgrade concurrently with Item ii including distribution equipment, starters, and standby generator.
- iv. Complete the following modifications to address code-related life safety concerns and to prevent further building deterioration: seal dry well penetrations; install a mechanism to hold the building door open while occupied; install exit and emergency lighting; relocate exterior propane vent; provide arc-flash safety labeling; confirm wet well instrumentation has an intrinsically safe barrier; and install a utility power bypass circuit for the UPS.
- v. Complete a force main pigging and closed-circuit television (CCTV) investigation in 3 to 5 years along the force main to provide visual verification of the interior pipe condition.

## **4.3 WOODLANDS I**

### **4.3.1 Existing Conditions**

The Woodlands I Pump Station was originally constructed in 1985 and underwent a SCADA upgrade in 2005. The pump station consists of a pre-fabricated structure which contains the pumps, electrical equipment, and standby generator, along with a circular pre-cast wet well. The pump station provides service a residential neighborhood located along FW Hartford Drive.

#### ***4.3.1.1 Equipment***

The suction-lift pump station houses two 5 HP Gorman-Rupp T-4 self-priming centrifugal pumps which are original to the pump station (1985). Based on the City's records, each pump was originally rated for 150 GPM. Each pump is driven by constant speed starter with the pump operation controlled by wet well level. The pumps operate in a lead/standby configuration and operate as much as 21 hours a day (combined). The pumps are operated at constant speed from a pump station control panel located within the pump station. Pump station draw-down tests indicated that the pumps are operating at a capacity between 86 and 92 GPM. Observed head conditions were lower than the anticipated design pressures. It should be noted the sheave configuration of the pumps is unknown and may be contributing to the lower observed pump capacity. The reduced pump efficiency may also be due to wear attributed to the age of the pumps (33 years). Based on the age of the pumps and motors, this equipment has surpassed its expected useful design life. While the pumps were noted to run reliably and have relatively low operational hours, the City should begin to plan for replacement of these pumps in the next 3 to 5 years. Based on the low runtimes and pump flowrates, the City may also consider conversion of this pump station to a submersible pump station for a capital cost savings.

The pump station's 8-foot diameter interior wet well structure was observed to be in good condition due to the City's biannual cleaning program. However, the underside surface of the top concrete slab showed extensive spalling and deterioration. The wet well hatch showed some minor signs of corrosion which should be monitored. The wet well hatch was missing a safety net. The

pump suction and discharge piping showed significant signs of corrosion and should be considered for replacement.

#### *4.3.1.1.1 Heating, Ventilation and Air Conditioning*

The pump station building is heated by one wall-mounted electric unit heater which was noted to be in good condition. The building is not actively ventilated which is authorized per the Building Code, but a mechanism must be in place to allow the door to remain open while the pump station is occupied. The City indicated the pump station can get very hot in the summertime due to the lack of ventilation and/or air conditioning. The City should consider installation of a split air conditioning unit or exhaust fan.

During the site visit, the pump and process area showed signs of condensation. To mitigate corrosion of process equipment and piping, a dehumidifier is recommended for this area.

#### *4.3.1.1.2 Electrical*

The existing electrical distribution equipment and pump motor starters date back to the original pump station construction in 1985. This equipment has surpassed its useful design life. Many of the components are obsolete, and considerations should be given to a comprehensive electrical upgrade, including panelboards, emergency power equipment, and other ancillary electrical components. A few minor deficiencies were noted, such as the lack of exit and emergency lighting, as well as missing arc-flash safety labeling.

A 30-kW Cummins Onan standby generator and automatic transfer switch (ATS) are located inside the pump station. The generator was installed in 1985 and operates on one 130-gallon propane storage tank located outside of the building. The ATS was replaced more recently based on discussions with the City. While not required, the generator's exhaust piping should be re-insulated for safety purposes and, installation of a ventilated exhaust wall thimble should be considered to avoid wall damage.

#### *4.3.1.1.3 Instrumentation*

The pump station controls are located in a control panel in the Pump Room. The control panel was upgraded in 2004 to include PLC based controls. The control panel was found to be in good condition, but has an estimated lifespan of approximately 20 years. The City should plan to replace the pump control panel, or the major components, based on this timeframe or during the next major pump station upgrade.

The pump station's PLC (Programmable Logic Controller), which is installed in the control panel, is connected to a pole-mounted microwave radio that communicates with the City's SCADA system for monitoring, control, and alarming. The radio uses an antenna mounted on the side of the building.

The wet well instruments include an ultrasonic transducer, a differential level float, and two backup alarm floats (high-high and low-low). Based on the City's experience with ultrasonic transducers in wet wells, it is recommended that, once it has failed, the instrument be replaced with a submersible transducer. Submersible transducers can alleviate faulty fats, oils and grease (FOG) related readings which sometimes cause issues with ultrasonic transducers. For ease of operator maintenance, it is recommended that seal-offs are installed on the instrument conduits out of the wet well with a junction box on the wet well side of the seal off, but still outside the wet well to allow for instrument replacement without confined space entry.

During the site visit, the wet well level floats were observed to be in the immediate vicinity of the influent sewer. To avoid ragging and hydraulic interference, it is recommended the wet well level floats be moved to the opposite side of the wet well.

Emergency/exit lighting was observed to be missing from pump station.

### **4.3.1.2 Building**

#### *4.3.1.2.1 Exterior*

The existing building consists of a precast concrete structure with a stone aggregate exterior finish. The exterior of the building appears to be in good condition with the exception of a degraded corner of the foundation, which should be monitored/repaired. The pre-cast roof slab seam is showing signs of roof leaking. Installation of a membrane-type should be anticipated within 2 years to prevent water damage. The joint between the foundation and the superstructure is showing signs of interior leaking at the base of the structure. This joint should be pressure washed and the joint sealed.

The existing pre-cast pump station superstructure is 33 years old. While this pre-fabricated structure has served the City well, the overall condition is deteriorating and building maintenance and improvement needs will only increase in the coming years. Based on the increased building maintenance costs, it is recommended that the City evaluate the following options for the Woodlands I pump station in the future (5 to 10 years):

- **Option 1: Building Replacement** – Begin capital planning for replacement of the existing building structure.
- **Option 2: Pump Station Conversion** – Convert the suction lift pump station to a submersible style pump station with a small outbuilding electrical distribution equipment

#### *4.3.1.2.2 Interior*

Several open piping penetrations from the wet well to the interior building were observed. These penetrations should be sealed to mitigate transfer of gases between the wet well and the building, and to maintain the proper NFPA 820 classification for the building space. The pre-cast roof slab seam has been sealed with caulking to mitigate roof leaking.

#### **4.3.1.3 Site**

The pump station is located directly adjacent to FW Hartford Drive in a residential district. The station has its own paved driveway and is abutted by single family homes and undeveloped forest. The pump station is located adjacent to a culvert and stream, but no drainage or runoff issues have been observed.

Based on the City's Climate Change Vulnerability Assessment, the pump station will not be impacted by tidal flood elevations (**Appendix C**).

#### **4.3.1.4 Force main**

Based on a review of the existing plans, the pump station's force main was installed during the original construction of the pump station in 1985. The polyvinyl chloride (PVC) pipe is 4-inches in diameter and discharges to a sewer manhole located approximately 1,900 feet away on FW Hartford Drive.

The average useful lifespan of PVC force main pipe depends on a variety of factors, including: soil conditions, pumping conditions, and installation methods. Under normal conditions and good engineering practice, PVC pipe can have a service life of 50 to 75 years. The force main pipe is currently 34-years old and the City has no records of pipe failure or maintenance issues. PVC is very resistant to corrosion, so the soil conditions should not impact the expected lifespan of the pipe.

#### **4.3.2 Capacity Review**

Based on a review of the pump station runtime data, the pumps are currently operating an average of 3 hours per day (total run time both pumps). This equates to approximately 16,000 gallons per day. Under peak conditions, the pumps may run up to 22 hours per day (total run time for both pumps). Given the minimal average use of both pumps, the station appears to have adequate capacity to handle existing flows.

The pump station appears to have significant peaks in run times during the spring (March - June). This trend suggests the pump station experiences inflow and infiltration (I/I) during the spring

season when groundwater levels and stormwater/meltwater runoff are peaking. The City should investigate the Woodlands I sewershed to identify and mitigate potential sources of I/I.

### **4.3.3 Emergency Bypass Plan**

The Woodlands I Pump Station does not contain a force main or pump station bypass connection. In the event the City needed to isolate the force main for maintenance, the City would coordinate maintenance efforts for a “low flow” time slot and utilize septage haulers to provide a window for force main maintenance. Based on the relatively low average day flows to the pump station (less than 20,000 GPD), temporary septage hauling from the upstream sewer manhole or from the pump station wet well is an acceptable bypass management approach for force main or pump station maintenance.

### **4.3.4 Recommendations**

Recommendations for the Woodlands I Pump Station have been broken into three categories based on the level of priority. Medium and Low Priority recommendations can be found in the Recommended Facilities Improvement Plan attached as **Appendix B**. The following discussion addresses High Priority and high cost (greater than \$50,000) items identified through this evaluation.

- i. The existing superstructure is approaching the end of its useful life and should be considered for replacement. The City should consider pump station superstructure replacement, or conversion to a submersible pump station within 5 to 10 years. It should be noted that depending on the City’s preference for the future pump station structure upgrade (replacement vs. conversion) and timeline, some of the identified Low and Medium priority recommendations may not apply.
- ii. The existing suction lift pumps are near the end of their expected useful life and should be considered for replacement. The City should consider pump replacement within 3 to 5 years, or during the next significant pump station upgrade. Alternatively, the City may choose to abandon the suction lift pumps in favor of a submersible pump station.

- iii. Complete comprehensive electrical upgrade concurrently with Item ii including distribution equipment, starters, and standby generator.
- iv. Complete the following modifications to address code-related life safety concerns and to prevent further building deterioration: replace leaking roof, re-grout and seal exterior building seams, seal dry well penetrations; install a mechanism to hold the building door open while occupied; install exit and emergency lighting; provide arc-flash safety labeling; cap/cover exterior wet well conduit junction boxes.

## **4.4 WOODLANDS II**

### **4.4.1 Existing Conditions**

The Woodlands II Pump Station was originally constructed in 1984 and underwent a SCADA upgrade in 2005. The pump station consists of a pre-fabricated structure which contains the pumps, electrical equipment, and standby generator, along with a circular pre-cast wet well. The pump station provides service to a residential neighborhood located along FW Hartford Drive.

#### ***4.4.1.1 Equipment***

The suction-lift pump station houses two 5 HP Gorman-Rupp T-4 self-priming centrifugal pumps which are original to the pump station (1984). Based on the City's records, each pump was originally rated for 130 GPM. Each pump is driven by constant speed starter with the pump operation controlled by wet well level. The pumps operate in a lead/standby configuration and operate as much as 15 hours a day (combined). The pumps are operated at constant speed from a pump station control panel located within the pump station. Pump station draw-down tests indicated that the pumps are operating at a capacity of 75 GPM. Observed head conditions were lower than the anticipated design pressures. It should be noted the sheave configuration of the pumps is unknown and may be contributing to the lower observed pump capacity. The reduced pump efficiency may also be due to wear attributed to the age of the pumps (33 years). Based on the age of the pumps and motors, this equipment has surpassed its expected useful design life. While the pumps were noted to run reliably and have relatively low operational hours, the City should begin to plan for replacement of these pumps in the next 3 to 5 years. Based on the low

runtimes and pump flowrates, the City may also consider conversion of this pump station to a submersible pump station for a capital cost savings.

The pump station's 8-foot diameter interior wet well structure was observed to be in good condition due to the City's biannual cleaning program. The wet well hatch was missing a safety net. The pump suction piping showed significant signs of corrosion and should be considered for replacement.

#### *4.4.1.1.1 Heating, Ventilation and Air Conditioning*

The pump station building is heated by one wall-mounted electric unit heater which was noted to be in good condition. The building is not actively ventilated which is authorized per the Building Code, but a mechanism must be in place to allow the door to remain open while the pump station is occupied. The City indicated the pump station can get very hot in the summertime due to the lack of ventilation and/or air conditioning. The City should consider installation of a split air conditioning unit or exhaust fan.

During the site visit, the pump and process area showed signs of condensation. To mitigate corrosion of process equipment and piping, a dehumidifier is recommended for this area.

In addition, the existing exterior propane vent should be relocated to be greater than 5 feet from any building air intake or exhaust.

#### *4.4.1.1.2 Electrical*

The existing electrical distribution equipment and pump motor starters date back to the original pump station construction in 1984. This equipment has surpassed its useful design life. Many of the components are obsolete, and considerations should be given to a comprehensive electrical upgrade, including panelboards, emergency power equipment, and other ancillary electrical components. A few minor deficiencies were noted, such as the lack of exit and emergency lighting, as well as missing arc-flash safety labeling.

A 30-kW Kohler standby generator and automatic transfer switch (ATS) are located inside the pump station. The generator was installed in 2018 and operates on two 130-gallon propane storage tanks located outside of the building. The ATS was replaced more recently based on discussions with the City. While not required, the generator's exhaust piping should be re-insulated for safety purposes, and installation of a ventilated exhaust wall thimble should be considered to avoid wall damage.

#### *4.4.1.1.3 Instrumentation*

The pump station controls are located in a control panel in the Pump Room. The control panel was upgraded in 2004 to include PLC (Programmable Logic Controller) based controls. The control panel was found to be in good condition, but has an estimated lifespan of approximately 20 years. The City should plan to replace the pump control panel, or the major components, based on this timeframe or during the next major pump station upgrade.

The pump station's PLC, which is installed in the control panel, is connected to a pole-mounted microwave radio that communicates with the City's SCADA system for monitoring, control, and alarming. The radio uses an antenna mounted on the side of the building.

The wet well instruments include an ultrasonic transducer, a differential level float, and two backup alarm floats (high-high and low-low). Based on the City's experience with ultrasonic transducers in wet wells, it is recommended that, once it has failed, the instrument be replaced with a submersible transducer. Submersible transducers can alleviate faulty "fog" related readings which sometimes cause issues with ultrasonic transducers. For ease of operator maintenance, it is recommended that seal-offs are installed on the instrument conduits out of the wet well with a junction box on the wet well side of the seal off, but still outside the wet well to allow for instrument replacement without confined space entry.

During the site visit, the wet well level floats were observed to be in the immediate vicinity of the influent sewer. To avoid ragging and hydraulic interference, it is recommended the location of the wet well level floats are moved to the opposite side of the wet well.

Emergency/exit lighting was observed to be missing from pump station.

#### **4.4.1.2 Building**

##### *4.4.1.2.1 Exterior*

The existing building consists of a precast concrete structure with a stone aggregate exterior finish. The exterior of the building appears to be in good condition, but minor graffiti was noted on the back side of the building. Although no obvious tears or open joints were observed on the roof membrane, it does appear to be faded and may be thinning and brittle as it is likely nearing the end of its design life. The pre-cast roof slab seam has been sealed by the City to mitigate leaking. Replacement of the membrane should be anticipated within 5 years. When the roof is replaced, a higher sloped roof is recommended to assist drainage.

The existing pre-cast pump station superstructure is 33 years old. While this pre-fabricated structure has served the City well, the overall condition is deteriorating and building maintenance and improvement needs will only increase in the coming years. Based on the increased building maintenance costs, it is recommended that the City evaluate the following options for the Woodlands II pump station in the future (5 to 10 years):

- **Option 1: Building Replacement** – Begin capital planning for replacement of the existing building structure.
- **Option 2: Pump Station Conversion** – Convert the suction lift pump station to a submersible style pump station with a small outbuilding electrical distribution equipment

##### *4.4.1.2.2 Interior*

The interior floors and wall finishes are in good condition. Several open piping penetrations from the wet well to the interior building were observed. These penetrations should be sealed to mitigate transfer of gases between the wet well and the building, and to maintain the proper NFPA 820 classification for the building space.

#### **4.4.1.3 Site**

The pump station is located directly adjacent to FW Hartford Drive in a residential district. The station has its own paved driveway and is abutted by undeveloped forest. Several graffiti tags were noted on the side of the pump station. The City may consider installation of a perimeter fence to avoid future tagging or other forms of vandalism.

Based on the City's Climate Change Vulnerability Assessment, the pump station will not be impacted by tidal flood elevations (**Appendix C**).

#### **4.4.1.4 Force Main**

Based on review of the existing plans, the pump station's force main was installed during original construction of the original pump station in 1984. The polyvinyl chloride (PVC) pipe is 4-inches in diameter and discharges to a sewer manhole located approximately 1,400 feet away at the intersection of Adams Avenue and Harding's Road.

The average useful lifespan of PVC force main pipe depends on a variety of factors, including: soil conditions, pumping conditions, and installation methods. Under normal conditions and good engineering practice, PVC pipe can have a service life of 50 to 75 years. The force main pipe is currently 34-years old and the City has no records of pipe failure or maintenance issues. PVC is very resistant to corrosion, so the soil conditions should not impact the expected lifespan of the pipe.

Based on observed pump flowrates, the velocity of flow through the PVC force main is 1.9 feet per second, which is near the minimum scour velocity. Long-term low-velocity operation increases the risk of solids settling in the force main, and reducing force main capacity. While the City has not reported any issues with force main solids settling, it is recommended the force main is periodically jetted to ensure it remains at full capacity.

#### **4.4.2 Capacity Review**

Based on a review of the pump station runtime data, the pumps are currently operating an average of 2.25 hours per day (combined). This equates to approximately 10,000 gallons per day. Under peak conditions, the pumps may run up to 15 hours per day (total run time for both pumps). Given the minimal average use of both pumps, the station appears to have adequate capacity to handle existing flows.

The pump station appears to have significant peaks in run times during the spring (February - May). This trend suggests the pump station experiences inflow and infiltration (I/I) during the spring season when groundwater levels and stormwater/meltwater runoff are peaking. The City should investigate the Woodlands II sewershed to identify and mitigate potential sources of I/I.

#### **4.4.3 Emergency Bypass Plan**

The Woodlands II Pump Station does not contain a force main or pump station bypass connection. In the event the City needed to isolate the force main for maintenance, the City would coordinate maintenance efforts for a “low flow” time slot and utilize septage haulers to provide a window for force main maintenance. Based on the relatively low average day flows to the pump station (less than 10,000 GPD), temporary septage hauling from the upstream sewer manhole or from the pump station wet well is an acceptable bypass management approach for force main or pump station maintenance.

#### **4.4.4 Recommendations**

Recommendations for the Woodlands II Pump Station have been broken into three categories based on the level of priority. Medium and Low Priority recommendations can be found in the Recommended Facilities Improvement Plan attached as **Appendix B**. The following discussion addresses High Priority and high cost (greater than \$50,000) items identified through this evaluation.

- i. The existing superstructure is approaching the end of its useful life and should be considered for replacement. The City should consider pump station superstructure replacement, or conversion to a submersible pump station within 5 to 10 years. It should be noted that depending on the City's preference for the future pump station structure upgrade (replacement vs. conversion) and timeline, some of the identified Low and Medium priority recommendations may not apply.
- ii. The existing suction lift pumps are near the end of their expected useful life and should be considered for replacement. The City should consider pump replacement within 3 to 5 years, or during the next significant pump station upgrade. Alternatively, the City may choose to abandon the suction lift pumps in favor of a submersible pump station.
- iii. Complete comprehensive electrical upgrade concurrently with Item ii including distribution equipment, starters, and standby generator.
- iv. Complete the following modifications to address several code-related life safety concerns and to prevent further building deterioration: seal dry well penetrations; relocate exterior propane vent; install a mechanism to hold the building door open while occupied; install exit and emergency lighting; provide arc-flash safety labeling; and confirm intrinsically safe installation of wet well instruments.

## **4.5 ATLANTIC HEIGHTS**

### **4.5.1 Existing Conditions**

The Atlantic Heights Pump Station was originally constructed in 1986 and underwent a SCADA upgrade in 2005. The pump station consists of a two-level dry well structure and a separate circular pre-cast wet well. The station provides service to the Atlantic Heights residential neighborhood.

#### ***4.5.1.1 Equipment***

The suction-lift pump station houses two 15 HP Gorman-Rupp T-6 (Super T-series) self-priming centrifugal pumps. One of the pumps (Pump No. 1) is original to the pump station construction, while Pump No. 2 was replaced around 2013. Based on the City's records, both pumps were

originally rated for 385 GPM. Each pump is driven by constant speed starter with the pump operation controlled by wet well level. The pumps operate in a lead/standby configuration and operate as much as 13 hours a day (combined). The pumps are operated at constant speed from a pump station control panel located within the pump station. Pump station draw-down tests indicated that the pumps are operating at a capacity between 285 and 300 GPM. Observed head conditions were lower than the anticipated design pressures. It should be noted the sheave configuration of the pumps is unknown and may be contributing to the lower observed pump capacity. Based on the age of Pump No. 1, this equipment has surpassed its expected useful design life although it was reported to be operating reliably upon site visit. The City should begin to plan for replacement of this Pump No. 1 in the next 3 to 5 years. In addition, the motor for Pump No. 2 was noted to be original to the pump station construction. The City should plan on motor replacement for Pump No. 2 concurrently with Pump No. 1 replacement.

The pump station's 8-foot diameter wet well was observed to be in good condition due to the City's biannual cleaning program. The wet well grating appeared to be dislodged and wedged between the manhole interior. It is recommended the loose grating be removed for safety. The pump suction piping showed evidence of corrosion and should be considered for replacement.

#### *4.5.1.1.1 Heating, Ventilation and Air Conditioning*

The pump station building is heated by two wall-mounted electric unit heaters. One is located in the Pump Room (lower level) and the other is located in the Control Room (upper level); both heating units appear to be in good condition. Ventilation air is circulated by an inline exhaust fan located in the Control Room. The fan and controls date back to the original pump station construction (1986), but they appear to be in fair condition. The exhaust fan must be operated at all times to comply with NFPA 820 requirements. The exhaust register in the Control Room has been removed, which does not allow the exhaust fan to balance airflow to the lower level. The register should be replaced to allow proper airflow balancing throughout the upper and lower levels.

A simplex sump pump with integral float control is located in the Pump Room. The discharge piping is routed to the wet well. The sump pump appears to be in relatively good condition,

however the sump pit is shallow, and the float does not initiate the pump until water has accumulated on the floor well beyond the sump pit. The sump pump float actuator should be adjusted, or the sump pump should be replaced to mitigate water accumulation on the lower level and subsequent equipment rusting and floor finish peeling.

#### *4.5.1.1.2 Electrical*

The existing electrical distribution equipment and pump motor starters date back to the original pump station construction in 1985. This equipment has surpassed its useful design life. Many of the components are obsolete, and considerations should be given to a comprehensive electrical upgrade, including panelboards, emergency power equipment, and other ancillary electrical components. Based on the current standby power setup, only one of the two pumps is connected to standby power at a time. A manual switch on the pump station control panel dictates which pump is available for standby power. The Pump Room's gas detection system is currently not functioning; it is recommended the system be replaced.

Other deficiencies noted at the time of inspection include the need for emergency lighting and arc-flash safety labeling. Also, the belt drive pumps are recommended to have emergency stop switches adjacent to the pumps for operator safety.

A 45-kW Cummins Onan standby generator and automatic transfer switch (ATS) are located inside the pump station. The generator and ATS were installed in 1985 and operates on two 1,000-gallon propane storage tanks located outside of the building. The existing standby generator location does not meet current NEC code for minimum set back requirements from the Motor Control Center. The standby generator and automatic transfer switch (ATS) are both nearing the end of their useful life and should be considered for replacement.

#### *4.5.1.1.3 Instrumentation*

The pump and pump station controls are located in a control panel in the Dry Well. The control panel, installed as part of the 2005 upgrade, was found to be in good condition and has an estimated

lifespan of approximately 15 to 20 years. The City should plan to replace the control panel, or the major components, based on this timeframe or during the next major pump station upgrade.

The pump station's PLC (Programmable Logic Controller), which is installed in the control panel, is connected to a pole-mounted microwave radio that communicates with the City's SCADA system for monitoring, control, and alarming. The radio uses an antenna mounted on the north side of the building. It is recommended the antenna must be grounded.

The wet well instruments include a submersible pressure transducer, differential level floats, and two backup alarm floats (high-high and low-low). It is recommended the submersible level instruments be installed with an intrinsically safe barrier for compliance with the NEC. For ease of operator maintenance, it is recommended that seal-offs are installed on the instrument conduits out of the wet well with a junction box on the wet well side of the seal off, but still outside the wet well to allow for instrument replacement without confined space entry.

Effluent flow is measured through a Foxboro 6-inch electromagnetic meter (with an integral transmitter). The flow meter is original to the pump station and has exceeded its estimated useful life of 20 years. It is recommended the magnetic flow meter be planned for replacement in the near future.

Emergency/exit lighting was observed to be missing from pump station.

#### **4.5.1.2 Building**

##### *4.5.1.2.1 Exterior*

The existing building consists of a brick finish, two-story structure with a metal roof. The exterior building materials appear to be in fair condition, however the brick veneer has some staining and deteriorating of the mortar joints. Deteriorating mortar joints should be spot repaired as needed. The metal roof was in fair condition, with no visible signs of leaking. The roof is original to the pump station and has exceeded its 30-year life expectancy. The exterior door is in good condition but is missing miscellaneous hardware which should be replaced. The steel lintel above the

generator louver is exposed and corroding. It is recommended the lintel be repaired or replaced to avoid building envelope leaks.

#### *4.5.1.2.2 Interior*

The foundation of the building and interior are in good condition. The interior lower level floors and wall finishes should be cleaned and recoated for continued use.

#### *4.5.1.3 Site*

The pump station property is located in a largely residential neighborhood on a parcel that abuts the Piscataqua River. The rear of the building has a fenced-in gated area that contains the standby generator propane tank. There were no deficiencies noted with the site.

Based on the City's Climate Change Vulnerability Assessment, the pump station will not be impacted by tidal flood elevations (**Appendix C**).

#### *4.5.1.4 Force Main*

Based on review of the existing plans, the pump station's force main was installed during original construction of the pump station in 1986. The ductile iron (DI) pipe is 6-inches in diameter and discharges to a sewer manhole located approximately 800 feet away near the intersection of Kearsarge Way and Falkland Place.

The average useful lifespan of DI force main pipe depends on a variety of factors, including: soil conditions, pumping conditions, and installation methods. Under normal conditions and good engineering practice, DI pipe can have a service life of 50 to 100 years. The older portions of the force main pipe are currently 32-years old. The City did not report any maintenance issues with the ductile iron force main; however, the exposed wet well portions of the force main were noted to be in poor condition.

The force main is located in an area of soils that are reported to have a low corrosivity index. Based on this data, soil corrosion is not expected to contribute to accelerated deterioration of the force main pipe. However, based on the age of the force main and the condition of the exposed wet well force main, it is recommended that the City plan to complete a visual investigation (CCTV) of the force main to provide further confirmation of the interior pipe condition.

#### **4.5.2 Capacity Review**

Based on a review of the pump station runtime data, the pumps are currently operating an average of less than 2 hours per day (total run time for both pumps). Based on draw-down test observations, this equates to approximately 37,000 gallons per day. Under peak conditions, the pumps may run up to 13 hours per day (total run time for both pumps). Given the minimal operating times for the both pumps, the station appears to have adequate capacity to handle existing flows.

The pump station appears to have slightly longer average run times from February through June. This trend suggests the pump station experiences inflow and infiltration (I/I) during the spring season when groundwater levels and stormwater/meltwater runoff are peaking. We recommend the City investigate this area as part of a larger I/I study to identify and mitigate potential sources of I/I.

#### **4.5.3 Emergency Bypass Plan**

The Atlantic Heights Pump Station does not contain a force main or pump station bypass connection. In the event the City needed to isolate the force main for maintenance, the City would coordinate maintenance efforts for a “low flow” time slot and utilize septage haulers to provide a window for force main maintenance. Based on the relatively low average day flows to the pump station (less than 30,000 GPD), temporary septage hauling from the upstream sewer manhole or from the pump station wet well is an acceptable bypass management approach for force main or pump station maintenance.

#### **4.5.4 Recommendations**

Recommendations for the Atlantic Avenue Pump Station have been broken into three categories based on the level of priority. Medium and Low Priority recommendations can be found in the Recommended Facilities Improvement Plan attached as **Appendix B**. The following discussion addresses High Priority and high cost (greater than \$50,000) items identified through this evaluation.

- i. Complete comprehensive electrical upgrade concurrently distribution equipment, motor control centers, and control panels.
- ii. Complete a comprehensive standby power upgrade including a new, exterior standby generator and automatic transfer switch (ATS). Relocation of the standby generator outside alleviates current code issues caused by the existing MCC/standby generator clearance.
- iii. Replace existing pump station exhaust fan and exhaust fan controls to provide reliable ventilation and NFPA declassification of the dry well.
- iv. Complete the following modifications to address life safety concerns and to prevent further building deterioration: seal dry well penetrations; provide local pump emergency stops; adjust existing sump pump float; replace gas detection system; install exit and emergency lighting; provide arc-flash safety labeling; and ground the antenna mast.

#### **4.6 LESLIE DRIVE**

##### **4.6.1 Existing Conditions**

The Leslie Drive Pump Station was originally constructed in 1986 and underwent a SCADA upgrade in 2005. The pump station consists of a two-level dry well structure and a separate rectangular concrete wet well. Leslie Drive Pump Station provides service to several residential neighborhoods including Spinnaker Way and the Atlantic Heights area.

#### ***4.6.1.1 Equipment***

The suction-lift pump station houses two 25 HP Gorman-Rupp T-10 (Super T-series) self-priming centrifugal pumps. Both pumps were replaced between 2012 and 2015 with the motors being original to the pump station construction (1986). Based on the City's records, both pumps were originally rated for 1,550 GPM. Each pump is driven by constant speed starter with the pump operation controlled by wet well level. The pumps operate in a lead/standby configuration and operate as much as 17-hours a day (combined). The pumps are operated at constant speed from a pump station control panel located within the pump station. Pump station draw-down tests indicated that the pumps are operating at a capacity of 1,485 GPM which is within the expected range of the duty point. The City should begin to plan for replacement of the pump motors in the next 3-5 years to maintain reliable operation.

The pump station's wet well is 12-foot by 12-foot by 11-foot and was observed to be in good condition due to the City's biannual cleaning program. It was noted the wet well has had issues with significant scum accumulation, and to mitigate the City has recently installed a large bubble wet well mixing system. The grating and pump suction piping was observed to be in fair condition. Minor deficiencies were observed in the wet well, such as missing safety net/guard for one of the wet well hatches, and unsealed penetrations in the wet well slab (for old electrical conduit).

##### ***4.6.1.1.1 Heating, Ventilation, and Air Conditioning***

The pump station building is heated by two wall-mounted electric unit heaters. One is located in the Pump Room (lower level) and the other is located in the Control Room (upper level); both heating units appear to be in good condition. Ventilation air is circulated by an inline exhaust fan located in the Control Room. The exhaust fan intake damper was not operational during the site visit and should be repaired. The fan and controls date back to the original pump station construction (1986), but appear to be in fair condition. The exhaust fan and associated damper system must be operated at all times to comply with NFPA 820 requirements.

A simplex sump pump with integral float control is located in the Pump Room. The discharge piping is routed to the wet well. The sump pump appears to be in relatively good condition,

however the sump pit is shallow, and the float does not initiate the pump until water has accumulated on the floor well beyond the sump pit. The sump pump float actuator should be adjusted, or the sump pump should be replaced to mitigate water accumulation on the lower level and subsequent equipment rusting and floor finish peeling.

#### *4.6.1.1.2 Electrical*

The existing electrical distribution equipment and pump motor starters date back to the original pump station construction in 1985. The City noted the Pump No. 2 motor starter was replaced with a soft starter in 2015. Overall, the pump station electrical equipment has surpassed its useful design life. Many of the components are obsolete, and considerations should be given to a comprehensive electrical upgrade, including panelboards, emergency power equipment, and other ancillary electrical components. Based on the current standby power setup, only one of the two pumps is connected to standby power at a time. A manual switch on the pump station control panel dictates which pump is available for standby power.

The Pump Room's gas detection system is currently not functioning; it is recommended the system be replaced. Other deficiencies noted at the time of inspection include: missing emergency lighting, missing arc-flash safety labeling, and exterior electrical service enclosure corrosion. Also, the belt drive pumps are recommended to have emergency stop switches adjacent to the pumps for operator safety.

A 45-kW Cummins Onan standby generator and automatic transfer switch (ATS) is located inside the pump station. The generator and ATS were installed in 1985 and operates on two 1,000-gallon propane storage tanks located outside of the building. The existing standby generator location does not meet current NEC code for minimum set back requirements from the Motor Control Center. The standby generator and automatic transfer switch (ATS) are both nearing the end of their useful life and should be considered for replacement.

#### *4.6.1.1.3 Instrumentation*

The pump and pump station controls are located in a control panel in the Dry Well. The control panel, installed as part of the 2005 upgrade, was found to be in good condition and has an estimated lifespan of approximately 15 to 20 years. The City should plan to replace the control panel, or the major components, based on this timeframe or during the next major pump station upgrade.

The pump station's PLC (Programmable Logic Controller), which is installed in the control panel, is connected to a pole-mounted microwave radio that communicates with the City's SCADA system for monitoring, control, and alarming. The radio uses an antenna mounted on the side of the building. It is recommended the antenna must be grounded.

The wet well instruments include a submersible pressure transducer, differential level floats, and two backup alarm floats (high-high and low-low). It is recommended the submersible level instruments be installed with an intrinsically safe barrier for compliance with the NEC. For ease of operator maintenance, it is recommended that seal-offs are installed on the instrument conduits out of the wet well with a junction box on the wet well side of the seal off, but still outside the wet well to allow for instrument replacement without confined space entry.

Effluent flow is measured through a Foxboro 10-inch electromagnetic meter (with an integral transmitter). The flow meter is original to the pump station and has exceeded its estimated useful life of 20 years. It is recommended the meter be replaced. The Pump Room's gas detection system is currently not functioning; it is recommended the system be replaced.

Emergency/exit lighting was observed to be missing from the pump station.

#### **4.6.1.2 Building**

##### *4.6.1.2.1 Exterior*

The existing building consists of a brick finish, two-story structure with a metal roof. The exterior building materials appear to be in fair condition, however the brick veneer has some staining and

deteriorating of the mortar joints. Deteriorating mortar joints should be spot repaired as needed. The roof is original to the pump station and has exceeded its 30-year life expectancy and should be scheduled for replacement. The exterior door is in good condition but is missing miscellaneous hardware and should be repainted to preserve longevity. The steel lintel above the generator louver is exposed and corroding. It is recommended the lintel be repaired or replaced to avoid building envelope leaks.

#### *4.6.1.2.2 Interior*

The building foundation and interior dry well were observed to be in good condition. The lower dry well showed signs of significant moisture accumulation and rust on pumps skids and pipe supports. Link seals for the suction piping penetrations showed significant signs of groundwater intrusion. The link seal should be repaired to prevent further water damage. In addition all corroded metal equipment should be stripped and repainted for continued protection. The lower portion of the interior Dry Well should be cleaned and repainted to mitigate moisture damage. The grated aluminum stair is open at both levels with a single-height top mounted guardrail. The stair was observed to be in good condition, but missing a toeplate.

#### *4.6.1.3 Site*

The pump station site is located adjacent to the Route 1 bypass between two tidally influenced drainage areas. The rear of the building has a fenced-in gated area that contains the standby generator propane tank.

The pump station's finished floor elevation is 9.5 feet (NAVD) with the surrounding grade between 7.0 – 8.5 feet (NAVD). These elevations fall within the floodplain of multiple flood scenarios from the City's Climate Change Vulnerability Assessment (**Appendix C**):

- 1) Year 2013 (present day) mean high tide scenario with a 100-year coastal storm surge (Elev. +11.2 feet)
- 2) Year 2100 (high sea level rise scenario) mean high tide (Elev. +10.7 feet)

Based on these current and forecasted flood conditions, the Leslie Drive pump station and electrical transformer may be susceptible to flooding in the future. While historical flooding issues were not noted in the pump station, the City should begin to evaluate potential flooding mitigation measures to take for the next significant pump station upgrade. This mitigation measures may include one or more of the following approaches:

- Raising the finished floor elevation in the dry well;
- Upgrading the pump station to a dry-pit *submersible* type station to allow pumps to operate while submerged;
- Upgrading the pump station with flood prevention measures such as flood panel doors, high capacity sump pumps, gasketed door stop gates, etc.

In addition to the pump station, the exterior propane tank is within the area that is a potential flood risk. The City should confirm that the propane tank is properly secured to a stationary foundation capable of resisting flotation forces of the propane tank.

#### ***4.6.1.4 Force Main***

Based on review of the existing drawings, the force main leaves the pump station as a 12-inch ductile iron (DI) force main and transitions at some point to an asbestos cement (AC) force main based on the City's existing GIS database. Records indicate the pump station's force main was installed in 1986 and connects to a section of force main that pre-dates 1986. Given this information, the age of the AC section of the Leslie Street Pump station is unknown. The force main discharges to a sewer manhole located approximately 850 feet away on the southeast side of the bridge on Market Street.

The average useful lifespan of DI/AC force main pipe depends on a variety of factors, including: soil conditions, pumping conditions, and installation methods. Under normal conditions and good engineering practice, DI/AC pipe can have a service life of 50 to 100 years. The known section of the force main pipe (DI) is currently 32-years old, but the remaining sections of the force main are of unknown age. The City has no records of pipe failure or maintenance issues with this force main.

The force main is located in an area of soils where corrosivity is not an issue for asbestos cement or ductile iron pipes. Based on this data, it is unlikely that soil conditions alone would contribute to accelerated degradation of the force main pipe. However, it should be noted the force main is in a low elevation area in close proximity to the Piscataqua River. It is expected that the water table is high and possibly saline, which can lead to accelerated corrosion of the force mains. Based on the questionable age and material of the entire length of force main, combined with the proximity to a brackish water source, it is recommended the City plan to complete a visual investigation (CCTV) of the force main to provide further confirmation of the interior pipe condition.

#### **4.6.2 Capacity Review**

Based on a review of the pump station runtime data, the pumps are currently operating an average of less than 2.5 hours per day (total run time for both pumps). Based on draw-down test observations, this equates to approximately 220,000 gallons per day. Under peak conditions, the pumps may run up to 18 hours per day (total run time for both pumps). Given the minimal operating times for the both pumps, the station appears to have adequate capacity to handle existing flows.

The pump station appears to have slightly longer average run times from February through June. This trend suggests the pump station experiences inflow and infiltration (I/I) during the spring season when groundwater levels and stormwater/meltwater runoff are peaking. We recommend the City investigate this area as part of a larger I/I study to identify and mitigate potential sources of I/I.

#### **4.6.3 Emergency Bypass Plan**

The Leslie Drive Pump Station is equipped with a 6-inch force main bypass connection which can be accessed from outside of the pump station. This allows the City to bypass the existing force main using the dry well pumps, and connect a temporary force main, if required. If the dry well/pumps needed to be bypassed, which is considered an extreme scenario, the City would need to supply temporary bypass pumps to pump from the wet well via a temporary force main.

#### **4.6.4 Recommendations**

Recommendations for the Leslie Drive Pump Station have been broken into three categories based on the level of priority. Medium and Low Priority recommendations can be found in the Recommended Facilities Improvement Plan attached as **Appendix B**. The following discussion addresses High Priority and high cost (greater than \$50,000) items identified through this evaluation.

- i. Complete comprehensive electrical upgrade concurrently distribution equipment, motor control centers, and control panels.
- ii. Complete a comprehensive standby power upgrade including a new, exterior standby generator and automatic transfer switch (ATS); relocate the standby generator outside to alleviate code issues caused by the existing MCC/standby generator clearance.
- iii. Replace existing pump station exhaust fan and exhaust fan controls/damper to provide reliable ventilation and NFPA declassification of the dry well.
- iv. Confirm exterior propane tank foundation bracing and attachment.
- v. Complete the following modifications to address life safety concerns and to prevent further building deterioration: seal wet well penetrations; install missing toeplates on dry well stair well; provide local pump emergency stops; adjust existing sump pump float; replace gas detection system; install exit and emergency lighting; provide arc-flash safety labeling; and ground the antenna mast.

#### **4.7 MARCY STREET**

The Marcy Street Pump Station was originally constructed in 1986 and underwent a SCADA upgrade in 2005. The pump station consists of a two-level dry well structure and a circular pre-cast concrete wet well. The pump station provides service to a small residential district on the east side of the downtown area.

## **4.7.1 Existing Conditions**

### ***4.7.1.1 Equipment***

The suction-lift pump station houses two 10 HP Gorman-Rupp T-4 (Super T-series) self-priming centrifugal pumps. Both pumps were replaced between 2004 and 2008 with the motors being original to the pump station construction (1986). The City should begin to plan for replacement of the pump motors in the next 3 to 5 years to maintain reliable operation. Based on the City's records, both pumps were originally rated for 210 GPM. Each pump is driven by a constant speed starter with the pump operation controlled by wet well level. The pumps operate in a lead/standby configuration and operate as much as 24 hours a day (combined). The pumps are operated at constant speed from a pump station control panel located within the pump station. Pump station draw-down tests indicated that the pumps are operating at a capacity of 125 GPM which is well below the design capacity. It was also noted that the discharge pressures were more than double the design TDH (44 feet), as reported by the City. Based on the high discharge pressures, the City should consider cleaning and/or assessment of the Marcy Street force main to evaluate the capacity and condition of the force main.

The pump station's 6-foot diameter wet well structure interior was observed to be in overall good condition due to the City's biannual cleaning program. It was noted the concrete top slab was in poor condition, with major degradation and section loss. The reinforcing steel was exposed in many locations. It is recommended the top slab be replaced. In addition, the pump suction piping showed significant signs of corrosion and should be replaced.

#### ***4.7.1.1.1 Heating, Ventilation and Air Conditioning***

The pump station building is heated by a wall-mounted natural gas-fired unit heater, which appears to be in good condition. Ventilation air is circulated by an inline exhaust fan located in the Control Room. The exhaust fan intake damper was not operational during the site visit and should be repaired. The fan and controls date back to the original pump station construction (1986), but appear to be in fair condition. The exhaust fan and associated damper system must be operated at all times to comply with NFPA 820 requirements.

A simplex sump pump with integral float control is located in the Pump Room. The discharge piping is routed to the wet well. The sump pump appears to be in relatively good condition, however the sump pit is shallow, and the float does not initiate the pump until water has accumulated on the floor well beyond the sump pit. The sump pump float actuator should be adjusted, or the sump pump should be replaced to mitigate water accumulation on the lower level and subsequent equipment rusting and floor finish peeling.

#### *4.7.1.1.2 Electrical*

The existing electrical distribution equipment and pump motor starters date back to the original pump station construction in 1986. Overall, the pump station electrical equipment has surpassed its useful design life. Many of the components are obsolete, and considerations should be given to a comprehensive electrical upgrade, including panelboards, emergency power equipment, and other ancillary electrical components. Based on the current standby power setup, only one of the two pumps is connected to standby power at a time. A manual switch on the pump station control panel dictates which pump is available for standby power.

The Pump Room's gas detection system is currently not functioning; it is recommended the system be replaced. Other deficiencies noted at the time of inspection include the need for emergency lighting, arc-flash safety labeling, and exterior electrical service enclosure corrosion. Also, the belt drive pumps are recommended to have emergency stop switches adjacent to the pumps for operator safety.

A 20-kW Cummins Onan standby generator and automatic transfer switch (ATS) are located inside the pump station. The generator and ATS were installed in 1985 and operates on a natural gas service. The existing standby generator location does not meet current NEC code for minimum set back requirements from the Motor Control Center. The standby generator and ATS are both nearing the end of their useful life and should be considered for replacement.

#### 4.7.1.1.3 Instrumentation

The pump station controls are located in a control panel in the Dry Well. The control panel, installed as part of the 2005 upgrade, was found to be in good condition and has an estimated lifespan of approximately 15 to 20 years. The City should plan to replace the control panel, or the major components, based on this timeframe or during the next major pump station upgrade.

The pump station's PLC (Programmable Logic Controller), which is installed in the control panel, is connected to a pole-mounted microwave radio that communicates with the City's SCADA system for monitoring, control, and alarming. The radio uses an antenna mounted on the north side of the building. It is recommended the antenna must be grounded.

The wet well instruments include a submersible pressure transducer, differential level floats, and two backup alarm floats (high-high and low-low). It is recommended the submersible level instruments be installed with an intrinsically safe barrier for compliance with the NEC. For ease of operator maintenance, it is recommended that seal-offs are installed on the instrument conduits out of the wet well with a junction box on the wet well side of the seal off, but still outside the wet well to allow for instrument replacement without confined space entry.

Effluent flow is measured through a Foxboro 4-inch electromagnetic meter (with an integral transmitter). The flow meter is original to the pump station and has exceeded its estimated useful life of 20 years. It is recommended the magnetic flow meter be planned for replacement in the near future.

Emergency/exit lighting was observed to be missing from pump station.

#### 4.7.1.2 *Building*

##### 4.7.1.2.1 *Exterior*

The existing building consists of a wood sided, two story structure with a shingled roof. The exterior building materials appear to be in fair condition, however the pump station is adjacent to

the saltwater portion of the Piscataqua River which is a moist, harsh environment. Based on observations, the City has done a good job keeping up with maintaining the exterior of the pump station. A few areas of trim are in need of repair, replacement, or painting/priming. The City should consider roof gutters for the building to help preserve the trim and siding. The attic louver was noted to be in poor condition and should be replaced.

#### *4.7.1.2.2 Interior*

The building foundation and interior dry well were observed to be in good condition. The lower dry well showed signs of significant moisture accumulation and rust on pumps skids. The lower portion of the interior dry well should be cleaned and repainted to mitigate moisture damage. The grated aluminum stair is open at both levels with a single-height top mounted guardrail. The stair is in good condition but is missing a toeplate.

#### *4.7.1.3 Site*

The pump station site is located within a residential neighborhood between a house and a tidal portion of the Piscataqua River. The pump station has a small parking area street-side for maintenance access. Observations indicate that high tide levels come within several feet of the pump station wet well and finished floor elevation.

The pump station's finished floor elevation is 10.2 feet (NAVD) with the surrounding grade between 8.0 and 9.5 feet (NAVD). These elevations fall within the floodplain of multiple flood scenarios based on the City's Climate Change Vulnerability Assessment (**Appendix C**):

- 3) Year 2013 (present day) mean high tide scenario with a 100-year coastal storm surge (Elev. +11.2 feet)
- 4) Year 2100 (high sea level rise scenario) mean high tide (Elev. +10.7 feet)

Based on these current and forecasted flood conditions, the Marcy Street pump station and electrical transformer may be susceptible to flooding. While historical flooding issues were not noted in the pump station, the City should begin to evaluate potential flooding mitigation measures

to take for the next significant pump station upgrade. These mitigation measures may include one or more of the following approaches:

- Raising the finished floor elevation in the dry well and wet well;
- Upgrading the pump station to a *submersible* type station to allow pumps to operate while submerged;
- Upgrading the pump station with flood prevention measures such as flood panel doors, high capacity sump pumps, gasketed door stop gates, etc.

The wet well top slab was noted to be significantly damaged by plow use and should be replaced. Bollards or markers should be installed to avoid plow damage in the future.

#### ***4.7.1.4 Force Main***

The pump station's force main was installed in 1985. The ductile iron (DI) pipe is 4-inches in diameter and discharges to a sewer manhole located approximately 900 feet away on the northwest side of the Marcy Street Bridge.

The average useful lifespan of DI force main pipe depends on a variety of factors, including soil conditions, pumping conditions, and installation methods. Under normal conditions and good engineering practice, DI pipe can have a service life of 50 to 100 years. The force main pipe is currently 33-years old. The force main is located in an area of soils where corrosivity is not an issue for ductile iron pipes. Based on this data, it is unlikely that soil conditions alone would contribute to accelerated degradation of the force main pipe. However, it should be noted that the force main is in a low elevation area in close proximity to the Piscataqua River. It is expected that the water table is high and possibly saline, which can lead to accelerated corrosion of the pipe.

Based on observations and discussions with the City, the Marcy Street pumps have been operating at higher than expected pressures under low flows. Based on the small diameter of the pipe, it is difficult to complete a visual inspection of the force main. However, the City may contract a subcontractor to "jet" the force main in an attempt to clean out any solids which may have accumulated over the years of use, potentially causing high discharge pressures. The City may

then re-evaluate the capacity of the force main and assess alternative force main investigations, if warranted.

#### **4.7.2 Capacity Review**

Based on a review of the pump station runtime data, the pumps are currently operating an average of 4.25 hours per day (combined). This equates to approximately 32,000 gallons per day of pumped wastewater. Under peak conditions, the pumps may run up to 24 hours per day (total run time for both pumps). Given the minimal average use of both pumps, the station appears to have adequate capacity to handle existing flows.

A comparison of average pump run times during the wet spring months versus the dryer summer months indicate the pump sewer shed experiences infiltration/inflow (I/I). We recommend the City investigate this area as part of a larger I/I study to identify and mitigate potential sources of I/I.

#### **4.7.3 Emergency Bypass Plan**

The Marcy Street Pump Station does not contain a force main or pump station bypass connection. In the event that the City needed to isolate the force main for maintenance, the City would coordinate maintenance efforts for a “low flow” time slot and utilize septage haulers to provide a window for force main maintenance. Based on the relatively low average day flows to the pump station (less than 30,000 GPD), temporary septage hauling from the upstream sewer manhole or from the pump station wet well is an acceptable bypass management approach for force main or pump station maintenance.

#### **4.7.4 Recommendations**

Recommendations for the Marcy Street Pump Station have been broken into three categories based on the level of priority. Medium and Low Priority recommendations can be found in the Recommended Facilities Improvement Plan attached as **Appendix B**. The following discussion addresses High Priority and high cost (greater than \$50,000) items identified through this evaluation.

- i. Complete comprehensive electrical upgrade of distribution equipment, motor control centers, and control panels;
- ii. Complete a comprehensive standby power upgrade including a new, exterior standby generator and automatic transfer switch (ATS). Relocation of the standby generator outside alleviates current code issues caused by the existing MCC/standby generator clearance.
- iii. Replace existing pump station exhaust fan and exhaust fan controls/damper to provide reliable ventilation and NFPA declassification of the dry well.
- iv. Complete the following modifications to address code-related life safety concerns and to prevent further building deterioration: install missing toeplates on dry well stair well; provide local pump emergency stops; adjust existing sump pump float; replace gas detection system; install exit and emergency lighting; provide arc-flash safety labeling; and ground the antenna mast.

## **4.8 CORPORATE DRIVE**

The Corporate Drive Pump Station was originally constructed in 2001. The pump station consists of an at-grade dry well structure and a separate pre-cast concrete circular wet well. The pump station provides service to commercial and industrial properties located along Corporate Drive in the Pease Tradeport Area.

### **4.8.1 Existing Conditions**

#### ***4.8.1.1 Equipment***

The suction lift pump station houses three 30 HP Gorman-Rupp T-6 (Super T-series) self-priming centrifugal pumps designed for 600 GPM. Each pump is driven by a VFD with the pump operation controlled by wet well level. The pumps operate in a lead/lag/standby configuration and operate up to 2.5 hours a day (combined). Pump station drawdown tests indicated that the pumps are operating at a capacity of 940 GPM against a reduced head condition compared to the original design.

The pump station's 8-foot diameter wet well structure was observed to be in overall good condition due to the City's biannual cleaning program. No deficiencies were noted at the time of observation.

#### *4.8.1.1.1 Heating, Ventilation, and Air Conditioning*

The pump station building is heated by a combustion (natural) gas fired unit heater. A propeller sidewall exhaust fan provides ventilation for the space. All units, piping, and ducts appeared to be in good working condition.

#### *4.8.1.1.2 Electrical*

The existing electrical distribution equipment at the pump station were installed as part of the 2001 upgrade and are in good condition. No deficiencies were noted.

A 100-kW Olympian standby generator is located inside the pump station. It was installed in 2001 and runs off of a natural gas service line which provides fuel to the generator and unit heater. The generator and automatic transfer switch (ATS) are both in good condition. The generator's exhaust piping should be insulated for safety purposes, and while not required, installation of a ventilated exhaust wall thimble should be considered to avoid continued wall damage.

#### *4.8.1.1.3 Instrumentation*

The pump and pump station controls are located in a control panel in the pump station. The control panel, installed in 2001 has an anticipated useful design life of 15-20 years. The control panel is controlled by Allen Bradley SLC 50/5 PLC's which are no longer actively supported. These PLC's can be difficult to find replacements for if maintenance is required. It is recommended the existing PLC's in the control panels are upgraded to updated PLC's which are actively supported by the manufacturer.

The wet well instruments include an air bubbler, submersible pressure transducer, differential level floats, and two backup alarm floats (high-high and low-low).

### **4.8.1.2 Building**

#### *4.8.1.2.1 Exterior*

The pump station building was constructed in 2001 and all exterior surfaces were observed to be in fair condition. The masonry appears to be in good condition with no observed deficiencies. It is recommended the gable end of the buildings be reprimed and painted within the next five years. The shingled roof is also in good condition, but replacement or repairs will likely be warranted in 8-10 years.

#### *4.8.1.2.2 Interior*

The interior masonry surfaces were observed to be in good condition with no deficiencies.

### **4.8.1.3 Site**

The station is located in a commercial section of Pease Development with a dedicated access driveway. No site issues were noted.

Based on the City's Climate Change Vulnerability Assessment, the pump station will not be impacted by flood elevations (**Appendix C**).

### **4.8.1.4 Force Main**

The pump station's force main was installed during the original construction of the pump station in 2001. The polyvinyl chloride (PVC) pipe is 8-inches in diameter and discharges to a sewer manhole located approximately 1,400 feet away at the intersection of Corporate Drive and Rye Street. There is a 30-foot section of the force main that is Ductile Iron (DI) where it passes under a 36-inch drain pipe approximately 50 feet before Rye Street.

The average useful lifespan of PVC force main pipe depends on a variety of factors, including soil conditions, pumping conditions, and installation methods. Under normal conditions and good engineering practice, PVC pipe can have a service life of 50 to 75 years. The force main pipe is

currently 17-years old and the City has no records of pipe failure or maintenance issues. PVC is very resistant to corrosion, so the soil conditions should not impact the expected lifespan of the pipe.

#### **4.8.2 Capacity Review**

Based on a review of the pump station runtime data, each pump is currently operating an average of 30 minutes per day. This equates to approximately 36,000 gallons per day of pumped wastewater total. Under peak conditions, the pumps may run up to 2.25 hours per day (total run time for all three pumps). Given the minimal average use of the pumps, the station appears to have adequate capacity to handle existing flows.

#### **4.8.3 Recommendations**

Recommendations for the Corporate Drive Pump Station have been broken into three categories based on the level of priority. Medium and Low Priority recommendations can be found in the Recommended Facilities Improvement Plan attached as **Appendix B**. Given the relatively good condition of the pump station, this evaluation did not identify any High Priority or high cost (greater than \$50,000) recommendations.

### **4.9 GRIFFIN PARK**

The Griffin Park Pump Station was originally constructed in 1990 and underwent a SCADA upgrade in 2005. The pump station consists of a single room above grade structure and a separate pre-cast circular wet well. The pump station provides service to a small number of commercial properties located along Griffin Road, including the Griffin Park Professional Building.

#### **4.9.1 Existing Conditions**

##### ***4.9.1.1 Equipment***

The suction-lift pump station houses two 7.5 HP Gorman-Rupp T-4 self-priming centrifugal pumps. Pump No. 1 is original to the pump station construction (1990) and Pump No. 2 was

installed in 2001. Both motors are original to the pump station construction (1990). Based on the City's records, the pumps were originally rated for 200 GPM. Each pump is driven by a constant speed starter with the pump operation controlled by wet well level. The pumps operate in a lead/standby configuration and operate up to 2 hours a day (combined). The pumps are operated at constant speed from a pump station control panel located within the pump station. Pump station drawdown tests indicated that the pumps are operating at a capacity of approximately 220 to 250 GPM. The pumps appear to be operating against a lower duty discharge pressure, resulting in higher than design flowrates. It is recommended the City begin to plan for replacement of Pump No. 1, in addition to replacement/rehabilitation of both pump motors.

The pump station's 8-foot diameter wet well structure was observed to be in overall good condition due to the City's biannual cleaning program. The interior concrete surfaces were found to be in good condition with no significant observed deficiencies. The top side of the top slab appeared to be in good condition with minimal to no spalling or exposed aggregate. The suction pipes showed signs of limited corrosion, but were still in good operating condition. The discharge pipe which penetrates through the wet well was observed to be severely corroded and the pipe support bracket was broken. It is recommended the discharge pipe be replaced and redirected so the force main does not route under the building foundation.

#### *4.9.1.1.1 Heating, Ventilation, and Air Conditioning*

The pump station building is heated by a combustion (natural) gas fired unit heater. The unit was installed in 2016 and appears to be in very good condition. The building is not actively ventilated which is authorized per the Building Code, but a mechanism should be in place to allow the door to remain open while the pump station occupied.

#### *4.9.1.1.2 Electrical*

The existing electrical distribution equipment and pump motor starters date back to the original pump station construction in 1990. The equipment, while in good condition, is approaching the end of its useful design life. Many of the components are obsolete or will become obsolete within the next 5 to 10 years. Low priority consideration should be given to a comprehensive electrical

upgrade including panelboards, emergency power equipment, and other ancillary electrical components. A few minor deficiencies were noted, such as the lack of exit and emergency lighting, as well as missing arc-flash safety labeling.

A 30-kW Cummins Onan standby generator and automatic transfer switch (ATS) is located inside the pump station. The ATS was replaced in 2009 and may be able to be reused depending on the generator upgrade requirements. The generator operates on a natural gas service. While not required, installation of a ventilated exhaust wall thimble should be considered to avoid continued wall damage.

#### *4.9.1.1.3 Instrumentation*

The pump station controls are located in a control panel in the Pump Room. The control panel was upgraded in 2005 to include PLC (Programmable Logic Controller) based controls. The control panel was found to be in good condition, but has an estimated lifespan of approximately 20 years. The City should plan to replace the pump control panel, or the major components, based on this timeframe or during the next major pump station upgrade. The pump station's PLC, which is installed in the control panel, is connected to a pole-mounted microwave radio that communicates with the City's SCADA system for monitoring, control, and alarming. The radio uses an antenna mounted on the side of the building.

The wet well instruments include a submersible pressure transducer, differential level floats, and two backup alarm floats (high-high and low-low). Submersible level instruments in hazardous locations should be installed with an intrinsically safe barriers. For ease of operator maintenance, it is recommended that conduit seal-offs are installed on the instrument conduits outside of the wet well with a junction box on the wet well side of the seal off, but still outside the wet well to allow for instrument replacement without confined space entry.

Effluent flow is measured through a Fischer Porter 4-inch electromagnetic meter (with an integral transmitter). The flow meter is original to the pump station and has exceeded its estimated useful life of 20 years. It is recommended the magnetic flow meter be planned for replacement in the near future.

Emergency/exit lighting was observed to be missing from pump station.

#### **4.9.1.2 Building**

##### *4.9.1.2.1 Exterior*

The existing pump station building was constructed in 1990 and consists of a slab on-grade with split rib masonry exterior. The exterior surfaces appear to be in fair condition, with some staining of the masonry in the bottom several feet. The concrete foundation is cracked near the entrance pad, which should be repaired. The exterior wood trim surfaces appear dried, faded, and have peeling paint. It is recommended the trim be re-primed and repainted. The wood soffit was observed to be coming apart on one side of the building and should be repaired.

The shingle roof is original to the construction of the pump station. While it was observed to be in good condition, the roof is approaching the end of its useful life. It is recommended the City begin to plan for roof replacement and consider adding roof gutters to prolong the life of the eaves/trim.

##### *4.9.1.2.2 Interior*

The interior masonry surfaces appear to be in good condition with no observed deficiencies.

#### **4.9.1.3 Site**

The station is located in a commercial district adjacent to Griffin Road. The station has its own dedicated access driveway. No site issues were noted.

Based on the City's Climate Change Vulnerability Assessment, the pump station will not be impacted by tidal flood elevations (**Appendix C**).

#### **4.9.1.4 Force Main**

The pump station's force main was installed in 1990. The ductile iron (DI) pipe is 6-inches in diameter and discharges to a sewer manhole located approximately 1,200 feet away at the intersection of Oxford Avenue and Greenland Road.

The average useful lifespan of DI force main pipe depends on a variety of factors, including soil conditions, pumping conditions, and installation methods. Under normal conditions and good engineering practice, DI pipe can have a service life of 50 to 100 years. The older portions of the force main pipe are currently 28 years old. The City did not report any maintenance issues with the ductile iron force main; however, the exposed wet well portions of the force main were noted to be in poor condition.

The force main is located in an area of soils where corrosivity is not an issue for ductile iron pipes. Based on this data, it is unlikely that soil conditions alone would contribute to accelerated degradation of the force main pipe. However, based on the age of the force main and the condition of the exposed wet well force main, it is recommended the City plan to complete a visual investigation (CCTV) of the force main to provide further verification of the interior pipe condition.

#### **4.9.2 Capacity Review**

Based on a review of the pump station runtime data, the pumps are currently operating an average of less than 0.5 hours per day (total run time for both pumps). Based on drawdown test observations, this equates to approximately 4,000 gallons per day. Under peak conditions, the pumps may run up to 2 hours per day (total run time for both pumps). Given the minimal operating times for the both pumps, the station appears to have adequate capacity to handle existing flows.

Evaluation of average and maximum pump runtimes indicate that I/I is not a problem in the pump station's sewershed.

### **4.9.3 Emergency Bypass Plan**

The Griffin Park Pump Station does not contain a force main or pump station bypass connection. In the event that the City needed to isolate the force main for maintenance, the City would coordinate maintenance efforts for a “low flow” time slot and utilize septage haulers to provide a window for force main maintenance. Based on the relatively low average day flows to the pump station (less than 5,000 GPD), temporary septage hauling from the upstream sewer manhole or from the pump station wet well is an acceptable bypass management approach for force main or pump station maintenance.

### **4.9.4 Recommendations**

Recommendations for the Griffin Park Pump Station have been broken into three categories based on the level of priority. Medium and Low Priority recommendations can be found in the Recommended Facilities Improvement Plan attached as **Appendix B**. The following discussion addresses High Priority and high cost (greater than \$50,000) items identified through this evaluation.

- i. Replace the corroded wet well discharge piping.
- ii. Complete the follow recommendations to address code-related life safety concerns and to prevent further building deterioration: install exit and emergency lighting and provide arc-flash safety labeling.

## **4.10 TUCKERS COVE**

### **4.10.1 Existing Conditions**

The Tuckers Cover Pump Station was originally constructed in 1998 and underwent a SCADA upgrade in 2004. The pump station consists of a two-level dry well structure and a circular pre-cast concrete wet well. The pump station provides service to a residential development adjacent to Sagamore Creek, in addition to business and residences along the southern portions of Sagamore Road.

#### ***4.10.1.1 Equipment***

The suction lift pump station houses two 15 HP Gorman-Rupp T-4 self-priming centrifugal pumps installed in 1998. Based on the City's records, the pumps were originally rated for 280 GPM. Each pump is driven by a constant speed starter with the pump operation controlled by wet well level. The pumps operate in a lead/standby configuration and operate up to 1 hour per day (combined). The pumps are operated at constant speed from a pump station control panel located within the pump station. Pump station drawdown tests indicated that the pumps are operating at a capacity of 240 GPM at a reduced head condition.

The pump station's 8-foot diameter wet well structure interior was observed to be in overall good condition due to the City's biannual cleaning program. The steel hatch closure arm was observed to be corroded and detached from the hatch. The arm should be removed for safety during confined space entry. Interior concrete surfaces were in good condition with no observed deficiencies.

##### ***4.10.1.1.1 Heating, Ventilation, and Air Conditioning***

The pump station building is heated by a wall-mounted gas-fired unit heater. The heater appears to be in good condition, but has exceeded its expected useful life. A sidewall mounted exhaust fan and motorized damper provides ventilation air for the space when the area is occupied. This equipment was also found to be in good condition.

##### ***4.10.1.1.2 Electrical***

The existing electrical distribution equipment and pump motor starters date back to the original pump station construction in 1998. The existing electrical distribution equipment is approaching the end of its useful design life. Many of the components will become obsolete within the next 10-15 years and consideration should be given to a comprehensive electrical upgrade, including panelboards, emergency power equipment, and other ancillary electrical components. A few minor deficiencies were noted, such as lack of emergency lighting, as well as missing arc-flash safety labeling.

A 45-kW Cummins Onan standby generator and automatic transfer switch (ATS) are located inside the pump station. The generator operates on a natural gas service. While not required, installation of a ventilated exhaust wall thimble should be considered to avoid continued wall damage.

#### *4.10.1.1.3 Instrumentation*

The pump station controls are located in a control panel in the Pump Room. The control panel was upgraded in 2004 to include PLC (Programmable Logic Controller) based controls. The control panel was found to be in good condition, but has an estimated lifespan of approximately 20 years. The City should plan to replace the pump control panel, or the major components, based on this timeframe or during the next major pump station upgrade. The pump station's PLC, which is installed in the control panel, is connected to a pole-mounted microwave radio that communicates with the City's SCADA system for monitoring, control, and alarming. The radio uses an antenna mounted on the side of the building.

The wet well instruments include an ultrasonic pressure transducer, differential level floats, and two backup alarm floats (high-high and low-low). For ease of operator maintenance, it is recommended that conduit seal-offs are installed on the instrument conduits outside of the wet well with a junction box on the wet well side of the seal off, but still outside the wet well to allow for instrument replacement without confined space entry.

Effluent flow is measured through a 4-inch electromagnetic meter (with an integral transmitter). The flow meter is original to the pump station and has exceeded its estimated useful life of 20 years. It is recommended the magnetic flow meter be planned for replacement in the near future.

Emergency/exit lighting was observed to be missing from pump station.

### **4.10.1.2 Building**

#### *4.10.1.2.1 Exterior*

The pump station building was constructed in 1998. The exterior surfaces were found to be in fair to good structural condition. The bottom two courses of masonry were stained, potentially due to moisture from the ground. The exterior wood trim surfaces were faded with peeling paint. It is recommended they are reprimed and painted.

The shingle roof is original to the construction of the pump station. The roof's asphalt shingles are near the end of their useful life as they appeared to be curled and weathered. It is recommended the City begin to plan for roof replacement, and consider adding roof gutters to prolong the life of the eaves/trim.

#### *4.10.1.2.2 Interior*

The interior masonry appeared to be in good structural condition, but it is recommended the surfaces be pressure-washed and sealed or painted for aesthetic purposes. There was evidence of efflorescence on the inside face of masonry in the vicinity of the generator intake louver. It appears that a sealant was not installed, or has failed, allowing water to migrate into the building.

### **4.10.1.3 Site**

The pump station site is located in a residential neighborhood. It is accessed via a dedicated paved driveway. No issues were noted with the exterior site.

Based on the City's Climate Change Vulnerability Assessment, the pump station will not be impacted by tidal flood elevations (**Appendix C**).

#### **4.10.1.4 Force Main**

Based on a review of the existing plan, the Tucker Cove pump station's force main was installed in 1998. The ductile iron (DI) pipe is 6-inches in diameter and travels cross country before discharging into a sewer manhole located approximately 1,450 feet away by Elwyn Road.

The average useful lifespan of DI force main pipe depends on a variety of factors, including soil conditions, pumping conditions, and installation methods. Under normal conditions and good engineering practice, DI pipe can have a service life of 50 to 100 years. The force main pipe is currently 20-years old and the City has no records of pipe failure or maintenance issues. The force main is located in an area of soils that have a low to moderate soil corrosivity index. However, the force main is relatively new and will likely not yet have been adversely affected by the soil conditions.

#### **4.10.2 Capacity Review**

Based on a review of the pump station runtime data, the pumps are currently operating an average of less than 0.5 hours per day (total run time for both pumps). Based on drawdown testing, this equates to approximately 10,000 gallons per day. Under peak conditions, the pumps may run up to 1.5 hours per day (total run time for both pumps). Given the minimal operating times for the both pumps, the station appears to have adequate capacity to handle existing flows.

Evaluation of average and maximum pump runtimes indicate that I/I is not a problem in the pump station' sewershed.

#### **4.10.3 Emergency Bypass Plan**

The Tucker Cove Pump Station does not contain a force main or pump station bypass connection. In the event that the City needed to isolate the force main for maintenance, the City would coordinate maintenance efforts for a "low flow" time slot and utilize septage haulers to provide a window for force main maintenance. Based on the relatively low average day flows to the pump station (< 10,000 GPD), temporary septage hauling from the upstream sewer manhole or from the

pump station wet well is an acceptable bypass management approach for force main or pump station maintenance.

#### **4.10.4 Recommendations**

Recommendations for the Tucker Cove Pump Station have been broken into three categories based on the level of priority. Medium and Low Priority recommendations can be found in the Recommended Facilities Improvement Plan attached as **Appendix B**. The following discussion addresses High Priority and high cost (greater than \$50,000) items identified through this evaluation.

- i. Replace roof and add roof gutters.
- ii. Provide arc-flash safety labeling.

#### **4.11 COMBINED PROJECT RECOMMENDATIONS**

As described in the previous Sections, facilities improvement recommendations for each pump station were made based on their current conditions. A full list of all recommended improvements can be found in the Recommended Facilities Improvement Plan (RFIP) attached under **Appendix B**. In addition to the individual recommendations for each suction lift pump station, several combined sample Improvement Projects have also been developed which group together improvements based on similar scope of work and prioritization.

##### **4.11.1 Combined Electrical, Standby Generator, and HVAC Upgrades**

General Scope: Comprehensive electrical distribution equipment upgrade including distribution panels, motor control centers, automatic transfer switches, and standby generators. The combined upgrade should also include upgrade of the existing HVAC systems in the buildings to provide reliable heating, cooling, and ventilation.

##### Proposed Suction Lift Pump Stations for Combined Project:

- Leslie Drive

- Atlantic Heights
- Marcy Street

The costs for the proposed combined pump station upgrade project are included under each individual Pump Station in **Appendix B**. If the City elects to move forward with the proposed combined project, the total project cost (all three pump stations combined) should be evaluated further based on City input on proposed project scope, approach, construction specifications, etc.

#### **4.11.2 Combined Pump Station Conversion or Building Replacement**

General Scope: Comprehensive pump station upgrade including building replacement, pump station conversion (optional), electrical upgrades, standby generator upgrades, etc.;

- Constitution Avenue
- West Road
- Woodlands I
- Woodlands II

The costs for the proposed combined pump station upgrade project are included under each individual Pump Station in **Appendix B**. If the City elects to move forward with the proposed combined project, the total project cost (all four pump stations combined) should be evaluated further based on City input on proposed project scope, approach (suction lift vs. submersible), construction specifications, etc.

5

## SECTION 5

### PUMP STATION EVALUATIONS SUBMERSIBLE PUMP STATIONS

#### 5.1 CLOUGH DRIVE

##### 5.1.1 Existing Conditions

The Clough Drive Pump Station was originally constructed in 2005 and provides service to a small residential area, including the Little Harbour School.

##### *5.1.1.1 Equipment*

The pump station houses two ITT-Flygt Submersible grinder pumps with double-sealed vortexing semi-recessed impellers. Each pump is rated for 55 GPM at 40 feet of total dynamic head. The 2.3 HP pumps are constant speed and are powered from a pad-mounted electrical cabinet. A wet well draw-down test was conducted to verify the pumping capacity of the station. Pump 1 was found to have a capacity of 31 GPM, and Pump 2 was found to have a capacity of 41 GPM. The pumps are configured to operate as lead/standby based on wet well setpoints. The City has indicated that these pumps are removed and rehabilitated every 1 to 2 years.

The pumps are located in the station's 8-foot diameter pre-cast concrete wet well and are accessible via a pump lifting rail. The wet well is cleaned three times a year and appears to be in good condition. The wet well hatch is also in good condition, although it should be equipped with a safety net/hatch grating for operational protection. The wet well has a 4-inch PVC vent that vents immediately adjacent to the electrical cabinet. The clearance from the vent to the cabinet does not meet current NFPA 820 standards and it is recommended it be relocated to provide a minimum of 3-foot clearance.

A pre-cast concrete valve pit with 30-inch access hatch is located adjacent to the wet well (outside of the fenced area). The vault houses 2-inch check valves and a resilient gate valve. During the site inspection, the vault was observed to be flooded with water. The valve vault does not include a

means to drain back to the wet well. It is recommended a passive valve vault drain be installed to prevent the vault from future flooding.

A pad-mounted electrical cabinet is located adjacent to the pump station wet well. The weatherproof cabinet is rated NEMA 4X and contains the motor starter panels, electrical distribution equipment, and pump control panels. Currently, pump station alarms are transferred to the City's WWTF SCADA system through radio transmission. The pump is equipped with a microwave remote terminal unit (RTU) for future transition to microwave transmission.

The pump station does not have a dedicated standby generator, so in the event of a power failure, a temporary gas-powered generator is transported to the site and used on an as-needed basis. Alternatively, the City may use their vacor truck to empty the wet well as needed. The pump station has sufficient capacity to accommodate short-term power outages.

#### **5.1.1.2 Site**

The pump station is located adjacent to the Little Harbour School. The electrical (service) cabinet is within a fenced area, but the wet well and valve vault are located outside of the fence, adjacent to Clough Drive. The un-enclosed area is not protected from traffic (bollards, etc.), and the valve vault and wet well hatch show signs of plow damage. It is recommended vehicle protection be installed to prevent the site from being used as snow storage by vehicles plowing the road.

The fenced area containing the electrical cabinet is commonly locked. During the site visit, the wet and valve vault were not locked. It is recommended the City install locks to prevent unauthorized access of these facilities.

The pump station's wet well hatch is at an of elevation 14 feet (NAVD). This elevation falls within the floodplain for projected tidal flooding scenarios in the year 2100. However, based on the City's Climate Change Vulnerability Assessment (**Appendix C**), the pump station is not likely to be impacted by tidal flooding within the next 30 years.

### **5.1.1.3 Force Main**

The pump station's force main was installed during original construction of the pump station in 2005. The polyvinyl chloride (PVC) pipe is 2-inches in diameter and discharges to a sewer manhole located 500-feet away on Clough Drive.

The average useful lifespan of PVC force main pipe depends on a variety of factors, including: soil conditions, pumping conditions, and installation methods. Under normal conditions and good engineering practice, PVC pipe can have a service life of 50 to 75 years. The force main pipe is currently 13-years old and the City has no records of pipe failure or maintenance issues. PVC is very resistant to corrosion, so the soil conditions should not impact the expected lifespan of the pipe.

### **5.1.2 Capacity Review**

Based on a review of the pump station runtime data, the pumps are currently operating an average of 1.5 to 2 hours per day. This equates to approximately 3,000 to 4,300 gallons per day of pumped wastewater. Under peak conditions, the pumps may run up to 22 hours per day (total run time for both pumps). Given the minimal average use of both pumps, the station appears to have adequate capacity to handle existing flows.

### **5.1.3 Recommendations**

Recommendations for the Clough Drive Pump Station have been broken into three categories based on the level of priority. Medium and Low Priority recommendations can be found in the Recommended Facilities Improvement Plan attached as **Appendix B**.

#### **5.1.3.1 High Priority**

- Install wet well and valve pit hatch security lock;
- Install industrial bollards to protect the un-fenced area (wet well and valve vault);
- Install valve vault drain to wet well;
- Relocate the wet well vent to be more than 3-feet from the electrical panel (as per current NFPA 820 requirements);

- Install utility power bypass circuit for UPS.

### ***5.1.3.2 Medium Priority***

- Install safety net/fall protection on the wet well hatch;
- Replace grinder pumps (planning level).

### ***5.1.3.3 Low Priority***

- Expand the fence limits to include the valve vault and wet well access hatches;
- Upgrade the control panel/pump starters;
- Replace submersible transducer/wet well float (planning).

## **5.2 MARSH LANE**

### **5.2.1 Existing Conditions**

The Marsh Lane Pump Station was originally constructed in 1985 and underwent a pump and control panel upgrade in 2004. It provides service to a small residential area on the north side of North Mill Pond.

#### ***5.2.1.1 Equipment***

The pump station houses two ITT-Flygt Submersible grinder pumps. Each pump is rated for 55 GPM at 40 feet of total dynamic head. The 2.3 HP pumps are constant speed and are run from a pad-mounted electrical cabinet. A draw-down test was conducted to verify the pumping capacity of the station. Pump 1 was found to have a capacity of 32 GPM, and Pump 2 was found to have a capacity of 37 GPM. The pumps are configured to operate as lead/standby based on wetwell setpoints.

The pumps are located in the station's 6-foot diameter wet well and are accessible via a pump lifting rail. The wet well is cleaned three times a year and appears to be in good condition. Minor cracks were observed at the electrical conduit penetration and upper hatch foundation, which are recommended for repair. The wet well has experienced flooding and the City has plans to raise

the wet well hatch. It is recommended the hatch be replaced with a gasketed, watertight hatch (with safety net) to help mitigate flooding concerns.

As part of the 2004 upgrade, the original 3-inch ductile iron discharge pipe was replaced with a 2-inch PVC pipe, including isolation valves located within the wet well. The original isolation valves outside of the wet well have been abandoned in place.

A pad-mounted electrical cabinet is located adjacent to the pump station wet well. The cabinet door latch was broken at the time of the site visit.

A separate enclosure houses the electrical distribution equipment. The enclosure is showing signs of aging and there are several unsealed penetrations. The electrical distribution equipment, including the enclosure, are original to the pump station and are recommended for replacement.

The pump station does not have a dedicated generator, so in the event of a power failure, a temporary gas-powered generator (10 kW) can be used, or the City's vector truck can empty the wet well as-needed. The pump station has sufficient capacity to accommodate short-term power outages.

#### **5.2.1.2 Site**

The pump station is located at the end of Marsh Lane less than 50 feet from a tidal inlet to North Mill Pond. The pump station is close to being submerged during high tide events. The City has had minimal success mitigating flood impacts by placing sandbags around the wet well hatch. At the time of the site visit, the wet well hatch elevation was 5.9 feet (NAVD). However, since the site visit, the City has replaced the top slab wet well sections and increased the rim elevation by 18 inches (approximately). Based on the new assumed rim elevation of 7.5 feet, the pump station falls within the floodplain of multiple flood scenarios from the City's Climate Change Vulnerability Assessment (**Appendix C**):

- 1) Year 2013 (present day) mean high tide scenario with a 100-year coastal storm surge (Elev. +11.2 feet)
- 2) Year 2100 (high sea level rise scenario) mean high tide (Elev. +10.7 feet)

Based on these forecasted flood conditions, the Marsh Lane pump station and its electrical equipment may be susceptible to flooding in the future. The City should continue to monitor flood events in the area and consider these minimum flood elevations for all future pump station upgrades.

The pump station is not fenced, but the electrical panels and wet well utilize standard door padlocks. The above-grade wet well hatch is marked by industrial bollards.

### **5.2.1.3 Force Main**

The pump station's force main was installed during original construction of the pump station in 1985. The polyvinyl chloride (PVC) pipe is 2-inches in diameter and discharges to a sewer manhole located 460-feet away on Maplewood Avenue.

The average useful lifespan of PVC force main pipe depends on a variety of factors, including: soil conditions, pumping conditions, and installation methods. Under normal conditions and good engineering practice, PVC pipe can have a service life of 50 to 75 years. The force main pipe is currently 33-years old and the City has no records of pipe failure or maintenance issues. PVC is very resistant to corrosion, so the soil conditions should not impact the expected lifespan of the pipe.

### **5.2.2 Capacity Review**

Based on a review of the pump station runtime data, the pumps are currently operating an average of 1.5 hours per day (combined). This equates to approximately 3,000 gallons per day of pumped wastewater. Under peak conditions, the pumps may run up to 18 hours per day (total run time for both pumps). Given the minimal average use of both pumps and the small sewershed that the pump station serves, the station appears to have adequate capacity to handle existing flows and is not considered a significant I/I concern.

### **5.2.3 Recommendations**

Recommendations for the Marsh Lane Pump Station have been broken into three categories based on the level of priority. Medium and Low Priority recommendations can be found in the Recommended Facilities Improvement Plan attached as **Appendix B**.

### **5.2.3.1 High Priority**

- Install utility power bypass circuit for UPS.

### **5.2.3.2 Medium Priority**

- Install safety net/fall protection on the wet well hatch;
- Replace grinder pumps (planning);
- Install intrinsically safe barrier for wet well instruments.

### **5.2.3.3 Low Priority**

- Upgrade electrical distribution enclosure and equipment;
- Upgrade the control panel/pump starters.

## **5.3 MILL POND WAY**

### **5.3.1 Existing Conditions**

The Mill Pond Way Pump Station was originally constructed in 1985 and underwent a pump and control panel upgrade in 2009. It provides service to a small residential area on the east side of North Mill Pond.

#### **5.3.1.1 Equipment**

The pump station houses two ITT-Flygt Submersible grinder pumps. Each pump is rated for 55 GPM at 40 feet of total dynamic head. The 2.3 HP pumps are constant speed and are run from a pad-mounted electrical cabinet. A draw-down test was conducted to verify the pumping capacity of the station. Pump 1 was found to have a capacity of 24 GPM, and Pump 2 was found to have a capacity of 25 GPM. The pumps are configured to operate as lead/standby based on wetwell setpoints.

The pumps are located in the station's 6-foot diameter wet well and are accessible via a pump lifting rail. The wet well is cleaned three times a year and appears to be in good condition. The wet well hatch is also in good condition, but does not meet current safety standards as it is missing

a safety net/hatch grating. The wet well has a 3-inch galvanized vent that vents immediately adjacent to the wet well. The wet well hatch is equipped with a padlock.

Based on the site visit observations, the original discharge piping and isolation valves were replaced with PVC valves located inside the wet well. The PVC piping and valves were observed to be in good condition. The original isolation valve boxes were observed, but their operability was not verified.

A pad-mounted electrical cabinet is located adjacent to the pump station wet well. The weatherproof cabinet houses the motor starter panel (Flygt), a pump control panel, and electrical disconnects. The cabinet is equipped with a standard door padlock. Currently, pump station alarms are transferred to the City's WWTF SCADA System through radio transmission. The pump is equipped with a microwave remote terminal unit (RTU) for future transition to microwave transmission. City staff have installed a small battery-powered exhaust fan to mitigate heat issues.

The pump station does not have a dedicated standby generator, so in the event of a power failure, a temporary gas-powered generator is transported to the site and used on an as-needed basis. Alternatively, the City may use their vacor truck to empty the wet well as needed. The pump station has sufficient capacity to accommodate short-term power outages.

### **5.3.1.2 Site**

The pump station is located in a grass lot within a residential area. The wet-well is marked by two light-duty bollards and the site showed no signs of damage or flooding.

The wet well hatch elevation is 11.8 feet (NAVD) which is close to the range of possible floodplain scenarios based on the City's Climate Change Vulnerability Assessment (**Appendix C**):

- 1) Year 2013 (present day) mean high tide scenario with a 100-year coastal storm surge (Elev. +11.2 feet)
- 2) Year 2100 (high sea level rise scenario) mean high tide (Elev. +10.7 feet)

Based on these forecasted flood conditions, the Mill Pond pump station and electrical equipment may be susceptible to flooding in the future. The City should continue to monitor flood events in the area and consider these minimum flood elevations for all future pump station upgrades.

### **5.3.1.3 Force Main**

The pump station's force main was installed during original construction of the pump station in 1985. The 3-inch diameter pipe discharges to a sewer manhole located 580 feet away on Mill Pond Way.

The average useful lifespan of PVC force main pipe depends on a variety of factors, including: soil conditions, pumping conditions, and installation methods. Under normal conditions and good engineering practice, PVC pipe can have a service life of 50 to 75 years. The force main pipe is currently 33-years old and the City has no records of pipe failure or maintenance issues. PVC is very resistant to corrosion, so the soil conditions should not impact the expected lifespan of the pipe.

### **5.3.2 Capacity Review**

Based on a review of the pump station runtime data, the pumps are currently operating an average of 1.5 hours per day (combined). This equates to approximately 2,800 gallons per day of pumped wastewater. Under peak conditions, the pumps may run up to 20 hours per day (total run time for both pumps). Given the minimal average use of both pumps, the station appears to have adequate capacity to handle existing flows. Given the minimal average use of both pumps and the small sewershed that the pump station serves, the station appears to have adequate capacity to handle existing flows and is not considered a significant I/I concern.

### **5.3.3 Recommendations**

Recommendations for the Mill Pond Way Pump Station have been broken into three categories based on the level of priority. Medium and Low Priority recommendations can be found in the Recommended Facilities Improvement Plan attached as **Appendix B**.

### **5.3.3.1 High Priority**

- Install utility power bypass circuit for UPS.

### **5.3.3.2 Medium Priority**

- Install safety net/fall protection on the wet well hatch;
- Replace grinder pumps (planning);
- Replace buried valve operator boxes/valves.

### **5.3.3.3 Low Priority**

- Upgrade electrical distribution enclosure and equipment;
- Upgrade the control panel/pump starters.

## **5.4 NORTHWEST STREET**

### **5.4.1 Existing Conditions**

The Northwest Street Pump Station was originally constructed in 1985 and underwent a pump and control panel upgrade in 2004. It provides service to a small residential area on the north end of North Mill Pond.

#### **5.4.1.1 Equipment**

The pump station houses two ITT-Flygt Submersible grinder pumps. Each pump is rated for 55 GPM at 40 feet of total dynamic head. The 2.3 HP pumps are constant speed and are run from a pad-mounted electrical cabinet. A draw-down test was conducted to verify the pumping capacity of the station. Pump 1 was found to have a capacity of 55 GPM, and Pump 2 was found to have a capacity of 43 GPM. The pumps are configured to operate as lead/lag based on wet well setpoints.

The pumps are located in the station's 6-foot diameter wet well and are accessible via a pump lifting rail. The wet well is cleaned three times a year and appears to be in good condition. The wet well hatch is also in good condition, but does not meet current safety standards as it is missing a safety net/hatch grating. The wet well hatch is equipped with a padlock.

As part of the 2004 upgrade, the original discharge piping and isolation valves were replaced with PVC valves located inside the wet well. The PVC piping and valves were observed to be in good condition. The original isolation valve boxes were observed, but their operability was not verified.

A pad-mounted electrical cabinet is located adjacent to the pump station wet well. The weatherproof cabinet houses the motor starter panel (Flygt), a pump control panel, and electrical disconnects. The cabinet is equipped with a standard door padlock. Currently, pump station alarms are transferred to the City's WWTF SCADA System through radio transmission. The pump is equipped with a microwave remote terminal unit (RTU) for future transition to microwave transmission. City staff indicated concerns with the combined panel overheating in the summer and have installed a small battery-powered exhaust fan to mitigate heat issues.

The pump station does not have a dedicated generator, so in the event of a power failure, a temporary gas-powered generator (10 kW) can be used, or the City's vactor truck can empty the wet well as-needed. The pump station has sufficient capacity to accommodate short-term power outages.

#### ***5.4.1.2 Site***

The pump station is located within a fenced-in area directly adjacent to Northwest Street. The site shows no signs of damage or flooding.

Based on the City's Climate Change Vulnerability Assessment, the pump station will not be impacted by flood elevations (**Appendix C**).

#### ***5.4.1.3 Force Main***

The pump station's force main was installed during original construction of the pump station in 1985. The 2.5-inch diameter PVC pipe discharges to a sewer manhole located 710 feet away on Northwest Street.

The average useful lifespan of PVC force main pipe depends on a variety of factors, including: soil conditions, pumping conditions, and installation methods. Under normal conditions and good engineering practice, PVC pipe can have a service life of 50 to 75 years. The force main pipe is

currently 33-years old and the City has no records of pipe failure or maintenance issues. PVC is very resistant to corrosion, so the soil conditions should not impact the expected lifespan of the pipe.

#### **5.4.2 Capacity Review**

Based on a review of the pump station runtime data, the pumps are currently operating an average of 30 minutes per day. This equates to approximately 1,500 gallons per day of pumped wastewater. Under peak conditions, the pumps may run up to 3 hours per day (total run time for both pumps). Given the minimal average use of both pumps, the station appears to have more than adequate capacity to handle existing flows. Given the minimal average use of both pumps and the small sewershed that the pump station serves, the station appears to have adequate capacity to handle existing flows and is not considered a significant I/I concern.

#### **5.4.3 Recommendations**

Recommendations for the Northwest Street Pump Station have been broken into three categories based on the level of priority. Medium and Low Priority recommendations can be found in the Recommended Facilities Improvement Plan attached as **Appendix B**.

##### ***5.4.3.1 High Priority***

- Install utility power bypass circuit for UPS.

##### ***5.4.3.2 Medium Priority***

- Install intrinsically safe barrier for wet well instruments;
- Install safety net/fall protection on the wet well hatch;
- Replace grinder pumps.

##### ***5.4.3.3 Low Priority***

- Upgrade electrical enclosure exhaust fan;
- Install pump discharge isolation valves;
- Upgrade electrical distribution enclosure and equipment;

- Upgrade the control panel/pump starters.

## **5.5 COMBINED PROJECT RECOMMENDATIONS**

As described in the previous Sections, recommended facility improvements for each pump station were made based on their current condition. A full list of all recommended improvements can be found in the Recommended Facilities Improvement Plan (RFIP) attached under **Appendix B**. In addition to the individual recommendations for each submersible pump station, several combined sample Facilities Improvement Projects have also been developed which group together recommended improvements based on similar scope of work and prioritization.


### **5.5.1 Combined Electrical Upgrade**

General Scope: Comprehensive electrical distribution equipment upgrade including distribution panels, motor control centers, automatic transfer switches, and electrical enclosures.

Pump Stations:

- Marsh Lane
- Northwest Road
- Mill Pond Way

The costs for the proposed combined pump station upgrade project are included under each individual Pump Station in **Appendix B**. If the City elects to move forward with the proposed combined project, the total project cost (all three pump stations combined) should be evaluated further based on City input on proposed project scope, approach, construction specifications, etc.




## **WET PIT/DRY PIT EVALUATION FORMS**

**City of Portsmouth, New Hampshire  
WET PIT DRY PIT Pump Station Evaluation  
Mechanic St.**

*Last Update:* MAC      *By:* 11/7/2018  
*This Update:*              *By:*

| General Pump Station Information  |   |
|---|---|
| Location:   | 113 Mechanic Street   |
| Pump Station Finished Floor Elevation, ft.:                                       | 8.5   |
| Coastal Resiliency Flood Elevation (2050 High Emissions), ft.:                    | 13.5  |
| Distance from WWTF (straightline), miles:   | 0.5   |
| Year Constructed/Upgraded:  | 1976/1990/2000/2007   |
| Station Type:   | Dry Pit submersible   |
| Wet Well Size, L x W x H, ft.:  | 22 x 10 x 11  |
| Wet Well Volume (1+2), gallons  | 14,481  |
| No. of Pumps:   | Raw Influent Pumps (Dry Pit Submersible)<br>Bypass Pump (Submersible) |
| Main Pump Installation Date:  | 1991  |
| Bypass Pump Installation Date:  | 2000  |
| Main Pump Design Operating Point, 1 Pump  |   |
| Flow, MGD:  | 22.05   |
| Total Dynamic head, ft.:  | 95  |
| Bypass Pump Design Operating Point, 1 Pump  |   |
| Flow, MGD:  | 11.53   |
| Total Dynamic head, ft.:  | 59  |
| Main Pump Make/Model:   | Davis EMU, Submersible, FA 50.97-690                                  |
| Motor Size, HP:   | 450   |
| Motor/Pump Speed, rpm:  | 880   |
| Bypass Pump Make/Model:   | Flygt Model CP 3356-610, 735 drive unit                               |
| Bypass Motor Size, HP:  | 143   |
| Bypass Motor/Pump Speed, rpm:   | 1160  |
| Electrical Service, V/Ph/Hz:  | 480/3/60  |
| Drive Type:   | VFD   |
| Seal Make & Type:   | Upper and Lower mechanical shaft seal                                 |
| Force Main Diam., in.:  | 30, 24, 18, 16  |
| Force Main Velocity (1 pump, average day flow), feet per sec (varying diameters): | 2.3 - 2.9   |
| Force Main Velocity (typical low flow), feet per sec. (varying diameters):        | 1.3 - 1.7   |
| Force Main Type:  | Ductile Iron & Cast Iron  |
| Force Main Age:   | 1973-1998   |
| Force Main Length, ft.:   | 3100  |



| Pump Flow and Run Time Information  |            |            |            |
|---|------------|------------|------------|
|   | P1         | P2         | P3(Bypass) |
| Pump Flow Data (Magnetic Flow Meter)  |            |            |            |
| Data Start Date   |            | 1/1/2016   |            |
| Data End Date   |            | 10/31/2017 |            |
| Observed Instantaneous Flowrate*, GPM   | 10,688     | 10,688     | Not tested |
| Observed Instantaneous Flowrate*, MGD   | 15.4       | 15.4       | -          |
| *Maximum pump capacity may be greater than observed flowrates when high flow elevate the wet well water surface level.<br>Historical magnetic flow meter data indicates that a single raw pump has conveyed 20-22 MGD reliably in the past. |            |            |            |
| Pump Totalized Data   |            |            |            |
| Data Start Date   | 1/1/2014   | 1/1/2014   | 1/1/2014   |
| Data End Date   | 10/31/2017 | 10/31/2017 | 10/31/2017 |
| Annual Average Flow, GPM (Magnetic Flow Meter)  | 5,025      |            | 465        |
| Annual Average Flow, MGD (Magnetic Flow Meter)  | 7.24       |            | 0.67       |

| Generator Information  |  |
|------------------------|--|
| Make/Model:            | DMT, Cummins KTA-38G1, 940 HP  |
| Interior/Exterior:     | Exterior within enclosure  |
| Gen. Installation Date | 1990   |
| Size, KW:              | 750  |
| Fuel Type:             | Oil, aboveground double walled storage tank, Unknown volume (< 1000 gallon estimate) |

| Controls Information                  |  |
|---------------------------------------|--|
| Pump Control Sequence:                | Controls start and stop the pumps in an alternating Lead/Standby sequence based on wet well level setpoints. If lead pump fails to start, Lag pump starts. The pumps use wet well level and a proportional control logic to vary the speed of the pumps based on wet well level. Alternatively, the City can divert influent flow from the main wet well to a separate submersible wet well via an electrically actuated bypass gate if pump station bypass is required. |
| Pump Control Panel:                   | Dedicated Main Pump Control Panel and Separate Bypass Pump Control Panel   |
| Installation Date:                    | Main Pump Control Panel (2007), Bypass Pump Control Panel (1990s)  |
| Control Type:                         | PLC based (SLC 5/05)   |
| Location:                             | In pump station Control Room   |
| SCADA Connectivity:                   | Radio, future microwave system transition in progress  |
| Level & Alarm Controls (Main Pumps):  | Division 13 Control Panels   |
| Type:                                 | Two submersible pressure transducers (primary)   |
| Backup Alarm                          | High level float switches in wet well  |
| Flow Meter Make/Model:                | Magnetic Flow Meter, 20-inch   |
| Level & Alarm Controls (Bypass Pump): | Division 13 Control Panels   |
| Type:                                 | Ultrasonic Level Element, Siemens Miniranger   |
| Backup Alarm                          | Low and High Level Float Switches  |
| Flow Meter Make/Model:                | Magnetic Flow Meter, 16-inch   |
| Alarm Transmission:                   | All pump station alarms transferred via radio (existing) to WWTF SCADA, equipment in place to transition to microwave  |
| Pump Motor Starters (Main) :          | Allen-Bradley Powerflex 18 Pulse Custom VFD Drives (500 HP)  |
| Pump Motor Starters (Bypass) :        | Allen-Bradley Powerflex  |

**City of Portsmouth, New Hampshire  
WET PIT DRY PIT Pump Station Evaluation**

**Mechanic St.**  
Last Update: MAC By: 11/7/2018  
This Update: By:

| Mechanical                      |   |              |                                       |
|---------------------------------|---|--------------|---------------------------------------|
| Heating & Cooling (Dry well):   |   | Ventilation: | Building (Dry Well)                   |
| Type:                           | Gas Fired Rooftop unit                  | Exhaust Fan: | Roof Mounted                          |
| Furnace Size(MBH) and Fan (CFM) | 158 MBH, 4500 CFM                       | Size (CFM)   | 1200/600                              |
| Furnace Make/Model:             | -                                       |              |                                       |
| Supplemental Cooling            | Ductless Split AC unit, Carrier         | Ventilation: | Wet Well                              |
| City Water Supply:              | 1" with RPZ BFP                         | System       | Qty: 1-supply 1-exhaust               |
|                                 |   | Size:        | 1200 CFM (supply), 2450 CFM (exhaust) |
|                                 |   | L&D          | -                                     |
| Heating (Wet Well):             |   |              |                                       |
| Type:                           | Electric Unit Heater                    |              |                                       |
| Size (kW)                       | 15 (estimated)                          | Quantity:    | 1                                     |
| Make/Model                      | -                                       |              |                                       |
| Odor Control :                  | Granular Activated Carbon, 1500 CFM fan | Quantity:    | 1                                     |
| Make/Model                      | Siemens RJMC-0550                       |              |                                       |

**Energy Efficiency Information**

The maximum observed pump capacity during the site visit (15.4 MGD) is lower than totalized pump station flows observed over the past several years of data. This may be due in part to elevated wet well water surface levels. Historical magnetic flow meter data indicates that a single raw pump has conveyed 20-22 MGD reliably since 2014. At this flowrate, both main pumps are operating between 80-82% optimization rating. While the existing pumps remain efficient, they are quickly approaching the end of their useful life and replacement/upgrade of pumps should be considered in the near future. Further discussion regarding replacement/repair of the existing main pumps can be found in the Pump Station Master Plan Report.

The pump station is serviced by two separate force mains with varying diameters between 12 and 20-inch. Flow is divided between the two force mains. Based on an approximation of the flow split between the two force mains, the approximate velocity at low flow (1 pump, ~30 Hz) is < 1 fps. Velocities below 2 fps can lead to solids settling within the force main. The City reported that they have not experienced issues with the force mains with this type of pump control. While short duration operation at low velocities is acceptable, it is recommended that the City ensure that the pump station flowrate is increased to at least 6,000 gpm periodically to properly scour/flush solids which may have accumulated in the force main at lower flows.

The City could see a heating savings benefit with a new dry well heating system which would allow for interior air recirculation (75%) depending on occupancy and outside temperature.

**Condition of Equipment/Identified Issues**

**Capacity:**  
Recent capacity assessment testing on 5/1/18 indicated the pumps have the following capacities: P1 - 10,700 gpm (92 ft TDH) and P2 - 10,700 gpm (102 ft TDH). Historical magnetic flow meter data indicate that the P1 and P2 have the capability to convey between 20-22 MGD (15,300 gpm) during peak flow events. These results compare favorably with the pump curves, indicating the pumps at full speed are operating as designed. Each pump runs for as much as 24 hours per day. The existing pump station cannot convey peak combined (sanitary & stormwater) flows to the pump station and during high flow events, the existing sewer system has relief in one of two CSO structure in Mill Pond. The City has indicated the pumps cavitate at low and high flows.

The City indicated that over the past several years, Pump No. 1 had developed a hole in the side of the pump volute. This required the pump be removed. A third party installed a wear ring within the volute to patch the hole. In addition, Pump No. 1 motor was re-wound for future reliability. The pump was then re-installed for continued use. The condition of the volute for Pump No. 2 is unknown.

**Exterior Site:**  
The pump station is located in a residential neighborhood at the entrance of the bridge to Peirce Island. The exterior of the pump station site includes the standby generator, standby generator diesel storage tank, odor control system (structural frame lofted), and submersible bypass wet well. The fuel tank was not protected by bollards, which are recommended with a parking area nearby. The top slab of the bypass wet well is degrading and should be repaired/replaced to prolong the life of the structure. The City has indicated they have received neighbor noise complaints when the pump station rooftop air handling unit is operated, and as such, the rooftop air unit is operated sparingly. The pump station is approximately 30 feet from a main tidal channel. The finished grade on the tidal channel side of the pump station site is approximately 7.4-ft +/-, with the finished floor of the pump station located at 8.6-ft +/- . Based on historical observations, the tidal channel has flooded to < 6" below the finished floor of the pump station. All future pump station upgrades should consider future flood elevations in this area.

The City indicated that the adjacent lot to the north, currently an apartment complex, is owned by the City and is a potential site for the future pump station.

**Building Structures (if applicable):**  
The exterior brick veneer appeared to be in good condition, with the exception of some mold growth and minor mortar deterioration. Building trim and fascia showed signs of minor deterioration to the finish. The City indicated that both skylights in the roof leak. Roof leaks should be remedied immediately to avoid future damage. The roof is equipped with much of the mechanical HVAC equipment for the pump station, but was not accessed as part of the building evaluation. The existing outdoor electrical transformers are located close to the roof, making it a hazard to access the HVAC equipment on the roof without shutting off power to the pump station. It should also be noted that all equipment located within 10 feet of the roof edge should be provided with a 42" high fall protection on the edges, or be accessed using the requisite fall protection.

**Wet Well:**  
The upper level concrete floor surfaces and walls showed significant staining and a few areas of degradation, likely due to the age and environment associated with the wet well area. The floor should be repaired by the City as needed. The stair concrete was in poor condition with several steps missing imbedded stair nosings. The stair deficiencies present a tripping hazard and should be repaired to reduce tripping hazards. The wet well contains a climber screen, screenings wash press, and influent sewer sluice gate for wet well bypass. The wet well divider gate was severely corroded and no longer in use. This equipment is approaching the end of its useful life and should be replaced or upgraded. Concrete beams in the wet well area showed signs of spalling and cracking and should be repaired as soon as possible to prevent further damage. Steel columns in the wet well area showed signs of moderate corrosion and should be sandblasted/repainted to extend their useful life.

**Dry Well:**  
**Control Room (upper level):** Interior masonry surfaces on the upper level appeared to be mostly in good condition. The concrete floor near the entrance door has delaminated and should be repaired for safety. The City should replace the missing toe plates on the guard around the stair openings for safety. Corrosion was noted on the mezzanine steel beams, handrails, grating, and welds. The City should monitor this corrosion for integrity and replace if the lifespan for the existing pump station exceeds 3 years. The overhead concrete slab from the mezzanine is degraded and should be resurfaced. The dry well contains two main influent pumps which were installed in 1990 and have reached the end of their useful life. Pump 1 recently was rehabilitated to fix a hole in the volute and re-wind the motor. The condition and reliability of Pump 2 is unknown. However, based on the age, criticality, and continuous operation of these pumps, replacement is recommended within 0-3 years to sustain reliable operation.

**Pump Area (lower level):** Interior masonry surfaces are in poor condition. Pump 1 pipe penetrations have loose and degraded concrete and should be sandblasted, repainted, and repaired to prevent further corrosion. Pump 2 suction piping was recently replaced after a leak developed. The City reported the pumps experience cavitation at low and high speeds. This could potentially be due to inadequate net positive suction head due to the small wet well volume, volute recirculation, or pump size limitations at lower flows. Similar to the pumps, the suction and discharge piping has reached the end of its useful life. One of the pump discharge check valves was noted as being faulty and should be replaced for continued operation. A comprehensive pump station replacement is recommended to upgrade all of the dry well equipment including pumps, piping, valves, etc;



**City of Portsmouth, New Hampshire  
WET PIT DRY PIT Pump Station Evaluation**

**Deer St.**

Last Update:           MAC           By: 10/31/2018  
This Update:           By:


| General Pump Station Information  |                                      |
|---|--------------------------------------|
| Location:   | 2 Deer Street                        |
| Pump Station Finished Floor Elevation, ft.:                                 | 13                                   |
| Coastal Resiliency Flood Elevation (2050 High Emissions), ft.:              | 13.5                                 |
| Distance from WWTF (straightline), miles:                                   | 1                                    |
| Year Constructed/Upgraded:  | 1976/2008                            |
| Station Type:   | Wet Well Dry Well                    |
| Wet Well Size, L x W x H, ft.:  | 22 x 10 x 7.5                        |
| Wet Well Volume, gallons  | 15,140                               |
| No. of Pumps:   | 3                                    |
| Pump Installation Date:   | 2008                                 |
| Design Operating Point, 1 Pump  |                                      |
| Flow, gpm:  | 4300                                 |
| Total Dynamic head, ft.:  | 116                                  |
| Two Pump Capacity (max)   | 12.7                                 |
| Two Pump Capacity (PLC limited)   | 10.4                                 |
| Pump Make/Model:  | Morris, Series 7100, NC 12X14-25 3V3 |
| Motor Size, HP:   | 200                                  |
| Motor/Pump Speed, rpm:  | 890 (max)                            |
| Electrical Service, V/Ph/Hz:  | 460/3/60                             |
| Drive Type:   | Digital AC Pulse, VFD                |
| Seal Make & Type:   | Mechanical flushing seal water       |
| Force Main Diam., in. (varies)  | 12, 14, 16, 20                       |
| Force Main Velocity (1 pump, full speed), feet per sec (varying diameters): | 3.0 - 6.9                            |
| Force Main Velocity (typical low flow), feet per sec. (varying diameters):  | 0.8 - 1.9                            |
| Force Main Type:  | Ductile Iron                         |
| Force Main Age:   | 1981-1990                            |
| Force Main Length, ft.:   | 2200                                 |



| Pump Flow and Run Time Information             |            |            |            |
|--|------------|------------|------------|
|  | P1         | P2         | P3         |
| Pump Flow Data (Magnetic Flow Meter)           |            |            |            |
| Observed Instantaneous Flowrate, GPM           | 6080       | 5970       | 5800       |
| MGD  | 8.8        | 8.6        | 8.4        |
| Pump Totalized Data                            |            |            |            |
| Data Start Date                                | 1/1/2014   | 1/1/2014   | 1/1/2014   |
| Data End Date                                  | 10/31/2017 | 10/31/2017 | 10/31/2017 |
| Annual Average Flow, MGD (Magnetic Flow Meter) | 1.21       |            |            |

| Pump Performance Testing Results  |  |
|-----------------------------------|--|
| Date of Test:                     | 1-May-18   |
| Min./Max. VFD Setpoints (Hz)      | 32, 60 (SCADA limits total flow to 10.4 MGD total) |
| VFD Speed (Hz)                    | 60   |
| Pump RPM                          | 890  |
| Pump Test Flow, gpm:              | P1 - 6080, P2 - 5970, P3 - 5800                    |
| Pump Test TDH, ft.:               | P1 - 97, P2 - 92, P3 - 95                          |
| Influent Pump Station Flow @ Test | N/A  |
| Note for Pump Start Type          | VFD, soft start                                    |

| Generator Information  |   |
|------------------------|---|
| Make/Model:            | Caterpillar/3456                              |
| Interior/Exterior:     | Interior                                      |
| Gen. Installation Date | 2008  |
| Size, kW:              | 500   |
| Fuel Type:             | Diesel Storage Sub Base Fuel Tank 650 Gallons |



| Controls Information    |  |
|-------------------------|--|
| Pump Control Sequence:  | Controls start and stop the pumps in an alternating Lead/Lag/Standby sequence based on wet well level setpoints. If Lead pump fails to start, Lag pump starts. Pumps operate in Lead/Lag arrangement based on wetwell set points until the Lead reaches a certain speed and the Lag turns on. The pumps are limited by the Control Panel to discharge a maximum of 10.4 MGD to control CSO discharges. |
| Pump Control Panel:     | Division 13 Control Panel  |
| Installation Date:      | 2008   |
| Control Type:           | PLC Based  |
| Location:               | Control Room in Pump Station   |
| SCADA Connectivity:     | Radio, future microwave system   |
| Level & Alarm Controls: | Division 13 Control Panel  |
| Type:                   | Submersible pressure transducer (primary), differential level floats (secondary)   |
| Backup Alarm            | High-high, low-low back up floats  |
| Flow Meter Make/Model:  | 16" Siemens Magnetic Flowmeter Mag5100   |
| Alarm Transmission:     | All pump station alarms transferred via radio (existing) to WWTF SCADA, equipment in place to transition to microwave.   |
| Pump Motor Starters :   | Allen Bradley Standard 1336 PLUS II AC pulse with VFDs. VFDs No. 1 and VFD No. 3 are equipped with bypass contactors.  |



**City of Portsmouth, New Hampshire  
WET PIT DRY PIT Pump Station Evaluation**

**Deer St.**

Last Update:           MAC           By: 10/31/2018  
This Update:           By:

HVAC:  
The ventilation and heating equipment were upgraded in 2008 and appeared to be in good condition overall. However, much of this equipment has a lifespan of 15-20 years depending on the severity of use.

DRY WELL: An air handling unit and duct furnace in the upper mezzanine area supplies heating and cooling to the dry well and generator room. These units appeared to be in good condition, but the City should plan for replacement over the next 7-10 years. The exterior condensing unit for the air handling unit showed exterior signs of corrosion, but was fully functional. It should be noted that no air is positively exhausted from the dry well, which is required by NFPA 820 to unclassified the dry well. It is recommended the City add an exhaust fan, louver, and associated ductwork to provide positive exhaust from the dry well. The utility sink potable water line is not backflow prevented from other process water connections, this sink should be labeled as non-potable water source. In addition, the utility sink drain line is unvented and should have an air admittance valve installed to mitigate trap priming issues. The supply fan which provides air to the wet well has damaged ductwork insulation. This insulation should be repaired.

WET WELL: No issues noted.

GENERATOR ROOM: Per NFPA 37 requirements, the generator room should be fire separated from all other areas of the building, including connecting ductwork. All existing ductwork penetrating into the generator room should be equipped with fire dampers.

Security Measures:  
The station is equipped with a security system, but it is not actively used. The pump station is equipped with a fire alarm system for both the wet well and dry well. The pump station is equipped with gas detection systems (recently replaced) in both the wet well and dry well.

Summary of Previous Reports  
The pump station has undergone a complete renovation since the 201 Facilities Plan Update (Underwood Engineers, 1999).

Other:

| Miscellaneous Issues: |    |           |  |
|-----------------------|----|-----------|--|
| Grease Accumulation?  | No | Source:   |  |
| Clogging Issues?      | No | Describe: |  |
| Nuisance Odors?       | No | Cause:    |  |
| Concrete Corrosion?   | No | Location: |  |

**City of Portsmouth, New Hampshire  
WET PIT DRY PIT Pump Station Evaluation**

**Gosling Rd.**

Last Update: MAC By: 10/29/2018  
This Update: By:

| Mechanical         |                            |             |   |
|--------------------|----------------------------|-------------|---|
| Heating:           |                            |             | Ventilation: Dry Well                                 |
| Type:              | Gas Combustion unit heater |             | System Exhaust Fan, Louver Damper                     |
| Size, kW:          | 24600 BTU/hr, 400 CFM      | Quantity: 1 | Size: 1/3 HP 400 CFM, Exhaust 12"x36", Intake 16"x48" |
| Make/Model:        | Reznor UDBS30              |             | Make & Model: Cook                                    |
| Odor Control :     | None                       |             | Ventilation: Dry Well                                 |
| City Water Supply: | 1.5", BFP                  |             | Exhaust Fan: Smartwout, 12SA2, 800 CFM 1/8 HP Qty: 1  |
|                    |                            |             | L&D: Yes  |

**Energy Efficiency Information**

The pumps are operating between 65-70% of their efficiency based on the provided pump curves. However, based on the low operating point (<30 Hz) the pumps are likely operating outside of their best efficiency point. Pump efficiency curves for the variable speeds were not available for review. It is recommended the City adjust the minimum operating pump speed to be higher to allow not only proper flushing of the force main, but also be closer to the pump's intended operational efficiency point. The dry well ventilation system is not currently set up to recirculate building air, or reduce ventilation rates when the outside air temperature is < 50 degrees F. The City may realize a heating cost savings if the HVAC system is upgraded to include this control.

**Condition of Equipment/Identified Issues**

**Capacity:**  
Recent capacity assessment via drawdown testing on 4/3/18 indicated that the pumps have the following capacities: P1 - 800 gpm (99 ft TDH) and P2 - 807 gpm (88 ft TDH). Both of these pump conditions are less than the original estimated operating point of 900 gpm (105 ft TDH). The reduced capacity could be due to general impeller/clearance wear, but is not considered to be outside the acceptable operating range. The City indicated the typical operation of these pumps is to operate at very low flowrates (~150 gpm) continuously for long portions of the day (8-12 hours). Based on this "low speed" operation, the pump station is within its current design capacity. However, at these low flowrates, the force main velocity is < 1 fps which could lead to settling issues in the force main. The City should consider increasing the minimum speed of the pumps to provide 300 gpm to provide the minimum flushing velocity (2 fps) for the force main and also increase the efficiency of the pump. Based on the magnetic flow meter maximum totalized daily readings over a 3 year span, the pump station is operating within its current capacity.

**Exterior Site:**  
The pump station is located in a commercial district in the back corner of a Ryder rental truck establishment. The pump station consists of a wet well and dry well, along with a fenced in area containing a standby generator and electrical ATS equipment. The City indicated that years ago a Ryder truck hit the side of the pump station wet well, requiring brick repair. The building structure has been protected via concrete bollards around the periphery. No issues were noted on-site.

**Building Structures (if applicable):**  
The pump station dry well and wet well exterior buildings were upgraded in 2005 and the surfaces were found to be in good condition. The top sides of each painted monorails exhibited failed paint, corroding steel, and were missing a load capacity label. The age of the membrane roof could not be verified. However, based on observations, the membrane may be nearing the end of its design life and need replacement.

**Wet Well:**  
The interior surfaces of the wet well were observed to be in fair condition. The City should install toeplates on all the guards in the wet well, and replace wet well channel grating where missing on the influent channels. The wet well contains an influent grinder that is in good condition. The City should plan on replacing the cutter stacks and possibly the grinder body, depending on its condition, every 4-8 years. Considering the age of the grinder, it is recommended that the City begin to plan for grinder and/or grinder stack replacement.

**Dry Well:** The interior masonry surfaces were mostly in good condition. The monorails were missing load capacity labels; these labels should be added for operator information. Painted concrete wall, top slab, and steel framing surfaces were in good condition with minimal to no peeling paint. The City should replace the missing toe plate on the guard around the spiral stair opening for safety. The dry well contains an influent grinder hydraulic power pack that is in good condition. The City has indicated the current pumps have been discontinued and that replacement parts are no longer available. While the City has stocked spare parts to the best extent possible, it is recommended that pump replacement be planned for within 5-7 years.

**Electrical/Instrumentation:**  
The existing electrical distribution equipment at the pump station was installed in 2005 and appeared to be in good condition. The City should begin to plan on replacement of the Control Panel and magnetic flow meter within the next 5 years or so, based on typical equipment life. The existing hazardous gas system should be repaired/replaced.

**HVAC:**  
DRY WELL: Ventilation and heating equipment were operational and in good condition. Dry well ventilation should operate at all times to maintain proper NFPA 820 classifications. The City reported the pump station dry well gets hot during the summer and is difficult to keep cool. It is recommended a split AC unit be installed to help maintain reasonable temperatures in the dry well.

WET WELL: Ventilation and heating equipment were operational and in good condition. No operational or mechanical deficiencies were noted.

**Security Measures:**  
There is no active security system in the building.

**Summary of Previous Reports**  
The 201 Facilities Plan Update (Underwood Engineers, 1999) indicated the pump station needed to be upgraded for capacity reasons. The 2005 upgrade appears to have addressed this issue.

**Other:**

**Miscellaneous Issues:**

| Issue                | Yes (minor) | Source:   | Describe:                     |
|----------------------|-------------|-----------|-------------------------------|
| Grease Accumulation? | Yes (minor) | Source:   | Restaurants in the sewer shed |
| Clogging Issues?     | No          | Describe: |                               |
| Nuisance Odors?      | No          | Cause:    |                               |
| Concrete Corrosion?  | No          | Location: |                               |

**City of Portsmouth, New Hampshire  
WET PIT DRY PIT Pump Station Evaluation**

**Gosling Rd.**

Last Update: MAC By: 10/29/2018  
This Update: By:

| General Pump Station Information                             |                                |
|--|--------------------------------|
| Location:  | 120 Gosling Road               |
| Pump Station Finished Floor Elevation, ft.                   | 31.3                           |
| Coastal Resiliency Flood Elevation (2050 High Emissions), ft | 13.5                           |
| Distance from WWTF (straight line), miles                    | 2.9                            |
| Year Constructed/Upgraded:                                   | 1970/2005                      |
| Station Type:  | Wet Well Dry Well              |
| Wet well Shape   | Rectangular                    |
| Wet Well Size, L x W x H, ft:                                | 9 x 5.5 x 8                    |
| Wet Well Volume (1+2), gallons                               | 4300                           |
| No. of Pumps:  | 2                              |
| Pump Installation Date:                                      | 2005                           |
| Design Operating Point, 1 Pump                               |                                |
| Flow, gpm:   | 900                            |
| Total Dynamic head, ft.:                                     | 105                            |
| Pump Make/Model:   | Paco Model 52-401221           |
| Motor Size, HP:  | 40                             |
| Motor/Pump Speed, rpm:                                       | 1800                           |
| Electrical Service, V/Ph/Hz:                                 | 480/3/60                       |
| Drive Type:  | VFD                            |
| Seal Make & Type:  | Mechanical flushing seal water |
| Force Main Diam., in.:                                       | 8                              |
| Force Main Velocity (observed full speed), feet per sec.:    | 5.12                           |
| Force Main Type:   | AC                             |
| Force Main Age (estimate):                                   | 1969                           |
| Force Main Length, ft.:                                      | 2847                           |



| Pump Flow and Run Time Information                |            |            |
|---|------------|------------|
|   | <i>P1</i>  | <i>P2</i>  |
| Pump Flow Data (Magnetic Flow Meter)              |            |            |
| Observed Instantaneous Flowrate, GPM              | 800        | 806        |
| Pump Totalized Data                               |            |            |
| Data Start Date                                   | 12/1/2014  | 12/1/2014  |
| Data End Date                                     | 10/31/2017 | 10/31/2017 |
| Annual Average Flow, GPM (Magnetic Flow Observed) | 80         |            |



| Pump Performance Testing Results  |                    |
|-----------------------------------|--------------------|
| Date of Test:                     | 3-Apr-18           |
| Min./Max. VFD Setpoints (Hz)      | -                  |
| VFD Speed (Hz)                    | 60                 |
| Pump RPM                          | 1800               |
| Pump Test Flow, gpm:              | P1 - 800, P2 - 806 |
| Pump Test TDH, ft:                | P1 - 99, P2 - 88   |
| Influent Pump Station Flow @ Tes: | N/A                |
| Note for Pump Start Type          | Slow start, VFD    |

| Generator Information  |  |
|------------------------|--|
| Make/Model:            | Onan/Model DGDK5700184/B                 |
| Interior/Exterior:     | Exterior                                 |
| Gen. Installation Date | 2005                                     |
| Size, KW:              | 125                                      |
| Fuel Type:             | Diesel underbelly dual wall storage tank |


| Controls Information    |   |
|-------------------------|---|
| Pump Control Sequence:  | Controls start and stop the pumps in an alternating Lead/ Lag sequence based on wet well level setpoints. If Lead pump fails to start, Lag pump starts. If level rises above Lag start both will run. |
| Pump Control Panel:     | Division 13 Control Panel   |
| Installation Date:      | 2004  |
| Control Type:           | PLC based   |
| Location:               | Dry well upper level  |
| SCADA Connectivity:     | Radio, future microwave system  |
| Level & Alarm Controls: | Division 13 Control Panel   |
| Type:                   | Submersible level transducers (primary) with differential floats (secondary)  |
| Backup Alarm            | High-high, low-low back up floats   |
| Flow Meter Make/Model:  | Krohne Aquaflux F with IFC 010 K signal converter. 8-inch diameter  |
| Alarm Transmission:     | All pump station alarms transferred via radio (existing) to WWTF SCADA, equipment in place to transition to microwave   |
| Pump Motor Starters :   | Allen Bradley Powerflex 700 Series 40 HP VFD  |

**City of Portsmouth, New Hampshire  
WET PIT DRY PIT Pump Station Evaluation**

**Ryeline**

Last Update:           MAC           By: 10/29/2018  
This Update:           By:

| General Pump Station Information                              |  |
|---|--|
| Location:   | 3618 Lafayette Road                        |
| Pump Station Finished Floor Elevation, ft.:                   | 44.3                                       |
| Coastal Resiliency Flood Elevation (2050 High Emissions), ft: | 13.5                                       |
| Distance from WWTF (straightline), miles:                     | 4.8  |
| Year Constructed/Upgraded:                                    | 1964/2009                                  |
| Station Type:   | Wet Well Dry Well                          |
| Wet Well Size, L x W x H, ft:                                 | 14.67 x 5.5 x 8                            |
| Wet Well Volume (1 & 2), gallons                              | 4300                                       |
| No. of Pumps:   | 2 (space for future 3rd)                   |
| Pump Installation Date:                                       | 2009                                       |
| Design Operating Point, 1 Pump                                |  |
| Flow, gpm:  | 600  |
| Total Dynamic head, ft.:                                      | 85   |
| Pump Make/Model:  | Smith & Loveless/4C2, 9.875" imp.          |
| Motor Size, HP:   | 20   |
| Motor/Pump Speed, rpm:  | 1800                                       |
| Electrical Service, V/Ph/Hz:                                  | 460/3/60                                   |
| Drive Type:   | VFD  |
| Seal Make & Type:   | Mechanical flushing seal water (potable)   |
| Force Main Diam., in.:  | 8  |
| Force Main Velocity (observed full speed), feet per sec.:     | 3.22                                       |
| Force Main Type:  | Asbestos cement                            |
| Force Main Age:   | 1970                                       |
| Force Main Length, ft.:                                       | 4083                                       |
| Pump Flow and Run Time Information                            |  |
|   | <i>P1</i> <i>P2</i>                        |
| Pump Flow Data (Magnetic Flow Meter)                          |  |
| Observed Instantaneous Flowrate, GPM                          | 507                      500               |
| Pump Totalized Data   | Yes                      Yes               |
| Data Start Date   | 12/1/2014                      12/1/2014   |
| Data End Date   | 10/31/2017                      10/31/2017 |
| Annual Average Flow, GPM (Observed)                           | 125  |



| Pump Performance Testing Results  |                    |
|-----------------------------------|--------------------|
| Date of Test:                     | 2-May-18           |
| Min./Max. VFD Setpoints (Hz)      | 30, 60             |
| VFD Speed (Hz)                    | 60                 |
| Pump RPM                          | 1765               |
| Pump Test Flow, gpm:              | P1 - 507, P2 - 500 |
| Pump Test TDH, ft:                | P1 - 78, P2 - 78   |
| Influent Pump Station Flow @ Test | N/A                |
| Note for Pump Start Type          | Slow start, VFD    |

| Generator Information  |                                       |
|------------------------|---------------------------------------|
| Make/Model:            | Caterpillar/Olympian Model AVR14-AREP |
| Interior/Exterior:     | Interior                              |
| Gen. Installation Date | 2009                                  |
| Size, KW:              | 80                                    |
| Fuel Type:             | Natural Gas fired                     |

| Controls Information    |   |
|-------------------------|---|
| Pump Control Sequence:  | Controls start and stop the pumps in an alternating Lead/ Lag sequence based on wet well level setpoints. If Lead pump fails to start, Lag pump starts. If level rises above Lag start both will run. |
| Pump Control Panel:     | Division 13 Control Panel   |
| Installation Date:      | 2009  |
| Control Type:           | PLC based   |
| Location:               | In the dry well on the upper level  |
| SCADA Connectivity:     | Radio, future microwave system  |
| Level & Alarm Controls: | Division 13 Control Panel   |
| Type:                   | Radar level sensor (primary) with differential floats (secondary)   |
| Backup Alarm            | High-high, low-low back up floats   |
| Flow Meter Make/Model:  | 10" Siemens Sitrans F Magflow MAG 5100  |
| Alarm Transmission:     | All pump station alarms transferred via radio (existing) to WWTF SCADA, equipment in place to transition to microwave.  |
| Pump Motor Starters :   | Allen Bradley Powerflex (standalone)  |

**City of Portsmouth, New Hampshire  
WET PIT DRY PIT Pump Station Evaluation**

**Ryeline**

*Last Update:*                   MAC                   *By:*   10/29/2018  
*This Update:*                   By:

| Mechanical         |  |               |                                  |
|--------------------|--|---------------|----------------------------------|
| Heating:           |  | Ventilation:  | Standby Generator                |
| Type:              | Gas Combustion unit heater                           | System        | Louvers and Damper               |
| Size:              | 60,000 BTU/hr, 700 CFM                   Quantity: 1 | Size:         | 60"x72" Qty: 1 intake, 1 exhaust |
| Make/Model:        | Reznor SDH-75  | Make & Model: | Unknown                          |
| Odor Control :     | None   | Ventilation:  | Building                         |
| City Water Supply: | 1.5", BFP  | Exhaust Fan:  | None                             |
|                    |  | L&D:          | None                             |

**Energy Efficiency Information**

Ryeline Pump Curves were not readily available for review. It is recommended the City adjust the minimum operating pump speed to be higher to allow not only proper flushing of the force main, but also be closer to the pump's intended operational efficiency point.

**Condition of Equipment/Identified Issues**

Capacity:  
Recent capacity assessment via drawdown testing on 5/2/18 indicated the pumps have the following capacities: P1 - 507 gpm (78 ft TDH) and P2 - 500 gpm (78 ft TDH). Both of these pump conditions are less than the original estimated operating point of 600 gpm (85 ft TDH). The reduced capacity could be due to general impeller/clearance wear, but is not considered to be outside an acceptable operating range for the pump. The City indicated the pumps typically operate at very low flowrates (~150 gpm) continuously for long portions of the day (8-12 hours). Based on this "low speed" operation, the pump station is within its current design capacity. However, at these low flowrates, the force main velocity is < 1 fps which could lead to settling issues in the force main. The City should consider increasing the minimum speed of the pumps to provide 300 gpm to provide the minimum flushing velocity (2 fps) for the force main and also increase the efficiency of the pump. It must be noted that no specific pump curve information was available for review. Based on the magnetic flow meter maximum totalized daily readings over a 2 year span, the pump station is operating within its current capacity.

Exterior Site:  
The station is located on a parcel of low lying land surrounded by jurisdictional wetlands associated with Berry's Brook. The existing pump station facility was upgraded in 2009 to include a dry well area that is elevated from the original 1970s pump station. This was done in an effort to minimize the risk of flooding from the adjacent wetlands. No issues were noted on-site.

Building Structures (if applicable):  
The pump station dry well and wet well exterior buildings were upgraded in 2009 and their surfaces appeared to be in good condition overall. A few spots on the steel framing were exhibiting peeling paint and corroding steel that should be sandblasted and repainted. Interior surfaces were in good condition with minimal corrosion. Hand rail toeplates should be installed on each guard.

Wet Well:  
Interior surfaces of the wet well were in fair condition. The epoxy wet well coating which was applied as part of the 2009 upgrade was peeling in localized concrete and masonry areas in the wet well entrance area. While the failing coating is undesirable, it is not recommended the City repair the existing coating system based on cost considerations. The City should install toeplates on all the guards in the wet well in addition to installing a rigid guard (in lieu of a chain guard) on the wet well elevated platform to conform with OSHA regulations. The wet well divider sluice gate was broken and should be replaced to allow for wet well isolation/combining and wet well cleaning. The wet well contains an influent grinder that is in good condition. The City should plan on replacing the cutter stacks on this type of grinder every 4-8 years depending on the pump station use.

Dry Well (if applicable): The dry well contains an upper and lower level of continuous space and contains all of the HVAC, process, electrical, and standby power equipment for the pump station. The dry well contains two vertical centrifugal pumps (Smith & Loveless) in the lower level, a magnetic flow meter and grinder hydraulic power pack in an intermediate level, and the standby generator and electrical equipment on the first level. In general, the dry well equipment is all new (< 10 years old) and in good condition.

The existing standby generator is common to the entire dry well space and is not provided with a 1-hour space separation as required by NFPA 37. Additional discussion regarding standby generator location and code is included in the Pump Station Master Plan Report.

Electrical/Instrumentation:  
The existing electrical distribution equipment at the pump station was installed in 2009 and found to be in good condition. The City should begin to plan on replacement of this equipment beginning in 2029 based on typical equipment life. The magnetic flow meter is located in an area that should be considered a confined space entry area and should be labeled appropriately.

HVAC:  
DRY WELL: The existing ventilation and heating equipment appeared to be in good condition. The inline supply fan and damper provides air to the dry well. During the site visit, the AUTO setting of the fan was not operational when the station was occupied. Based on NFPA 820 requirements, the dry well should be ventilated at 6 ACH (air changes per hour) continuously to declassify the space for electrical equipment. The existing supply fan does not have the capacity to provide this air quantity. It is recommended the ventilation system (supply and exhaust) is upgraded (controls and equipment) to comply with NFPA 820 requirements. Heat is provided by a gas fired unit heater. The standby generator intake louver/dampers is designed to operate when the emergency generator is operating or when the room temperature exceeds an operator adjustable setpoint. City staff indicated the pump station is extremely hot in the summer time. The dry well contains a simplex sump pump which appears to be in good condition. The standby generator exhaust piping needs to be insulated for safety. While not required, a ventilated exhaust wall thimble should be considered to avoid continued wall damage.

WET WELL: The wet well contains an FRP explosion proof exhaust fan that operates continuously. No dedicated intake is provided in the wet well, meaning that much of the supply air is likely being pulled from the influent sewer. The wet well should have a dedicated supply louver/damper assembly.

Security Measures:  
There is no active security system in the building.

Summary of Previous Reports  
The 201 Facilities Plan Update (Underwood Engineers, 1999) identified numerous pump station issues which were addressed as part of the 2009 upgrade.

Other:

| Miscellaneous Issues: |    |           |  |
|-----------------------|----|-----------|--|
| Grease Accumulation?  | No | Source:   |  |
| Clogging Issues?      | No | Describe: |  |
| Nuisance Odors?       | No | Cause:    |  |
| Concrete Corrosion?   | No | Location: |  |

## SUCTION LIFT EVALUATION FORMS

**City of Portsmouth, New Hampshire  
SUCTION LIFT Pump Station Evaluation**

**Constitution Ave.**

Last Update: 10/19/2018 By: MAC  
This Update: By: W-P

| General Pump Station Information                               |                               |
|--|-------------------------------|
| Location:  | 278 Constitution Ave.         |
| Pump Station Finished Floor Elevation, ft.:                    | 49                            |
| Coastal Resiliency Flood Elevation (2050 High Emissions), ft.: | 13.5                          |
| Distance from WWTF (straightline), miles:                      | 3.1                           |
| Year Constructed/Upgraded:                                     | 1985                          |
| Station Type:  | Gorman-Rupp suction-lift      |
| Wet Well Diameter, ft.:  | 8                             |
| Wet Well Volume, gal/ft  | 376                           |
| No. of Pumps:  | 2                             |
| Pump Installation Date:  |                               |
| Pump No. 1   | 2017                          |
| Pump No. 2   | 2016                          |
| Design Operating Point, 1 Pump                                 |                               |
| Flow, gpm:   | 320                           |
| Total Dynamic head, ft.:                                       | 67                            |
| Pump Make/Model:   | G-R T-Series, T4A3-B STD      |
| Self-Priming Method  | Air Purge                     |
| Motor Size, HP:  | 15                            |
| Motor/Pump Speed, rpm:   | 1558                          |
| Electrical Service, V/Ph/Hz:                                   | 208/3/60                      |
| Drive Type:  | Belt & Sheave, Constant Speed |
| Belt and Sheave Speed:   | Unknown                       |
| Seal Make & Type:  | G-R, Double Mech Oil Bath     |
| Force Main Diam., in.:   | 6                             |
| Force Main Velocity, feet per sec.:                            | 1.9                           |
| Force Main Type:   | Ductile iron                  |
| Force Main Age:  | 1985                          |
| Force Main Length, ft.:  | 2624                          |



| Pump Flow and Run Time Information    |            |            |
|---------------------------------------|------------|------------|
|                                       | P1         | P2         |
| Pump Runtime Data                     |            |            |
| Data Start Date                       | 12/1/2014  | 12/1/2014  |
| Data End Date                         | 10/31/2017 | 10/31/2017 |
| Annual Average Flow, GPM (Calculated) | 10         | 10         |



| Pump Performance Testing Results  |                                  |
|-----------------------------------|----------------------------------|
| Date of Test:                     | 29-Mar-18                        |
| Min./Max. VFD Setpoints (Hz)      | 60                               |
| VFD Speed (Hz)                    | N/A                              |
| Pump RPM                          | 1280                             |
| Drawdown Flow, gpm:               | P1 - 177, P2 - 177               |
| Drawdown TDH, ft.:                | P1 - 53 ft, P2 - 28 ft           |
| Influent Pump Station Flow @ Test | Estimate during visit, 5 gpm     |
| Note for Pump Start Type          | Slow start, constant speed, etc; |



| Generator Information  |  |
|------------------------|--|
| Make/Model:            | Cummins Onan                             |
| Interior/Exterior:     | Interior                                 |
| Gen. Installation Date | 1985                                     |
| Size, KW:              | 45                                       |
| Fuel Type:             | Propane Storage Two Vertical Tanks 150 g |

| Controls Information    |   |
|-------------------------|---|
| Pump Control Sequence:  | Controls start and stop the pumps in an alternating Lead/ Lag sequence based on wet well level setpoints. If lead pump fails to start, Lag pump starts. If level rises above Lag start both will run. |
| Pump Control Panel:     | Motor Starter Panel with original G-R starters (controls bypassed), PLC based Control Panel Upgrade   |
| Installation Date:      | Motor Starter Panel (Updated starters), PLC Control Panel (2005)  |
| Control Type:           | PLC-based   |
| Location:               | In station at pump level  |
| SCADA Connectivity:     | Yes, microwave RTU installed  |
| Level & Alarm Controls: | PLC Based Control Panel   |
| Type:                   | Submersible pressure transducer (primary), differential level floats (secondary)  |
| Backup Alarm            | High-high, low-low level floats   |
| Flow Meter Make/Model:  | Not installed   |
| Alarm Transmission:     | All pump station alarms transferred via radio (existing) to WWTF SCADA, equipment in place to transition to microwave   |
| Pump Motor Starters :   | Motor starters updated and installed through original combined G-R panel  |

**City of Portsmouth, New Hampshire  
SUCTION LIFT Pump Station Evaluation**

**Constitution Ave.**

*Last Update:* 10/19/2018 *By:* MAC

*This Update:* *By:* W-P

| Mechanical         |                                    |               |  |
|--------------------|------------------------------------|---------------|--|
| Heating:           |                                    | Ventilation:  | Generator  |
| Type:              | Electric Unit heater Wall mount    | System        | Louvers and Damper   |
| Size, kW:          | 5                                  | Quantity: 2   | Size:  |
|                    |                                    |               | Qty: 1-motorized fresh air intake louver, 1-exhaust louver |
| Make/Model:        | Dayton 3UG73                       | Make & Model: | -  |
| Odor Control :     | None                               | Ventilation:  | Building   |
| City Water Supply: | 3/4" Potable Water Supply with BFP | Exhaust Fan:  | None   |
|                    |                                    | L&D:          | -  |

**Energy Efficiency Information**

Based on pump information gathered from the pump manufacturer's website, both pumps are operating at < 45% efficiency which is not atypical for suction lift style pumps. It must be noted that the pump belt/sheave configuration was unknown, which may change the operating efficiency conclusion. Regardless, it is recommended that the City staff investigate the difference in discharge pressure conditions between the two pumps.

**Condition of Equipment/Identified Issues**

Capacity:  
Recent capacity assessment via drawdown testing on 3/29/18 indicated that the pumps have the following capacities: P1 - 177 gpm (53 ft TDH) and P2 - 177 gpm (28 ft TDH). Both of these pump conditions are less than the original estimated operating point of 320 gpm (67 ft TDH). However, it must be noted that no information was available regarding the belt and sheave setup, which may be the cause for the reduced pump capacity. The station appears to have adequate capacity to handle existing flows as, each pump runs for about 1.5 hours per day on average, but under peak conditions, both pumps may run as much as 8 hours per day.

Exterior Site:  
The station is located off the side of the road in a largely commercial district. The station has its own driveway and is surrounded by forested area on the remaining three sides. The station grade was raised by 3-5 ft from the surrounding area for construction to avoid stormwater issues associated with nearby drainage. While current surrounding site drainage does not appear to be an issue as of the date of the site visit, City staff should periodically check to ensure that stormwater/erosion issues do not develop.

Building Structures (if applicable):  
The existing building consists of a precast concrete structure with a stone aggregate exterior finish. The exterior aggregate is missing aggregate in locations that require cosmetic repair. The pre-cast concrete slab is in good condition with the exception of a corner which needs to be rebuilt. The joint between the foundation and the superstructure should be pressure washed and the joint sealed. The interior floors and wall finishes need to be recoated for continued use. Several old piping penetrations from the wet well to the interior were observed. These penetrations should be sealed. The back wall of the interior structure contains a visible crack where the standby generator exhaust penetrates the wall. This crack is likely due to excessive heat from the exhaust pipe, and a lack of a ventilated wall thimble and should be sealed to prevent air and water leakage. The membrane roof appears to be in good condition, but has a relatively low slope which allows water to pool. If the roof is replaced, a higher sloped roof is recommended to assist drainage. The double access door is missing misc. hardware and should be painted to preserve longevity.

Wet Well:  
The pump suction piping was replaced in the wet well 3 years ago due to corrosion. The pump discharge pipe is showing significant signs of corrosion, and should also be replaced. In general, the wet well structure is in good condition due to bi yearly cleaning. Hatch should have safety net

Dry Well (if applicable): See Building Structure section. Pump Station consists of a single, abovegrade room.

Electrical/Instrumentation:  
The existing electrical distribution equipment at the pump station is approaching the end of its useful design life. Many of the components are obsolete. Consideration should be given to a comprehensive electrical upgrade including panelboards, emergency power equipment, and other ancillary electrical components. The emergency generator and automatic transfer switch should be considered for replacement based on their age (33-years).

Submersible level instruments are recommended to be installed with an intrinsically safe barrier for compliance with the NEC. For ease of operator maintenance, it is recommended that seal-offs are installed on the instrument conduits out of the wet well with a junction box on the wet well side of the seal off, but still outside the wet well to allow for instrument replacement without confined space entry. The Control Panel (2005) is in good condition and has an estimated lifespan of approximately 20-years. The City should plan to replace the control panel or the major components based on this timeframe or during the next major pump station upgrade.

HVAC:  
The electric unit heaters are in good condition. No ventilation is provided for the space. In order to adhere to HVAC code requirements the Town should installed a mechanism to hold the door open when the pump station is occupied. The standby generator exhaust piping needs to be insulated for safety. While not required, a ventilated exhaust wall thimble should be considered to avoid continued wall damage. The dry well was noted to have condensation around some of the process equipment. A small local dehumidifier is recommended.

Security Measures:  
There is no active security system in the building. A smoke detector appears to be wired to the Control Panel for alarming. There is no gas detection system in this station, as it is not required.

Summary of Previous Reports  
The 201 Facilities Plan Update (Underwood Engineers, 1999) did not note any significant pump station issues.

Other:

| Miscellaneous Issues: |         |           |  |
|-----------------------|---------|-----------|--|
| Grease Accumulation?  | Minor   | Source:   |  |
| Clogging Issues?      | No      | Describe: |  |
| Nuisance Odors?       | No      | Cause:    |  |
| Concrete Corrosion?   | Minimal | Location: |  |

**City of Portsmouth, New Hampshire**  
**SUCTION LIFT Pump Station Evaluation**  
**West Rd.**

Last Update: 10/19/2018 By: MAC  
 This Update: By:

| General Pump Station Information                              |                               |
|---|-------------------------------|
| Location:   | 280 West Rd.                  |
| Pump Station Finished Floor Elevation, ft.:                   | 43.8                          |
| Coastal Resiliency Flood Elevation (2050 High Emissions), ft: | 13.5                          |
| Distance from WWTF (straightline), miles:                     | 3.1                           |
| Year Constructed/Upgraded:                                    | 1984                          |
| Station Type:   | Gorman-Rupp suction-lift      |
| Wet Well Diameter, ft:  | 8                             |
| Wet Well Volume, gal/ft                                       | 377                           |
| No. of Pumps:   | 2                             |
| Pump Installation Date:                                       | 1984                          |
| Design Operating Point, 1 Pump                                |                               |
| Flow, gpm:  | 400                           |
| Total Dynamic head, ft.:                                      | 40                            |
| Pump Make/Model:  | T4A3-B (Classic Series)       |
| Self-Priming Method   | Manual Air Purge              |
| Motor Size, HP:   | 10                            |
| Motor/Pump Speed, rpm:  | 1745/1280                     |
| Electrical Service, V/Ph/Hz:                                  | 208/3/60                      |
| Drive Type:   | Belt & Sheave, Constant Speed |
| Belt and Sheave Speed:  | Unknown                       |
| Seal Make & Type:   | G-R , Double Mech Oil Bath    |
| Force Main Diam., in.:  | 6                             |
| Force Main Velocity, feet per sec.:                           | 2.9                           |
| Force Main Type:  | Ductile Iron                  |
| Force Main Age:   | 1984                          |
| Force Main Length, ft.:                                       | 1281                          |



| Pump Flow and Run Time Information    |                                  |            |
|---------------------------------------|----------------------------------|------------|
|                                       | P1                               | P2         |
| Pump Runtime Data                     |                                  |            |
| Data Start Date                       | 12/1/2014                        | 12/1/2014  |
| Data End Date                         | 10/31/2017                       | 10/31/2017 |
| Annual Average Flow, GPM (Calculated) | 12                               | 12         |
| Pump Performance Testing Results      |                                  |            |
| Date of Test:                         | 29-Mar-18                        |            |
| Min./Max. VFD Setpoints (Hz)          | 60                               |            |
| VFD Speed (Hz)                        | N/A                              |            |
| Pump RPM                              | 1280                             |            |
| Drawdown Flow, gpm:                   | P1 - 300, P2 - 278               |            |
| Drawdown TDH, ft:                     | P1 - 28 ft, P2 - 28 ft           |            |
| Influent Pump Station Flow @ Test     | Estimate during visit, 15 gpm    |            |
| Note for Pump Start Type              | Slow start, constant speed, etc; |            |

| Generator Information  |  |
|------------------------|--|
| Make/Model:            | Cummins Onan                             |
| Interior/Exterior:     | Interior                                 |
| Gen. Installation Date | 1984, (ATS replaced within past 5 years) |
| Size, KW:              | 30                                       |
| Fuel Type:             | Propane Storage Two Vertical Tanks 100 g |

| Controls Information    |   |
|-------------------------|---|
| Pump Control Sequence:  | Controls start and stop the pumps in an alternating Lead/ Lag sequence based on wet well level setpoints. If lead pump fails to start, Lag pump starts. If level rises above Lag start both will run. |
| Pump Control Panel:     | Motor Starter Panel with original G-R starters (controls bypassed), PLC based Control Panel Upgrade   |
| Installation Date:      | Motor Starter Panel (1984), PLC Control Panel (2005)  |
| Control Type:           | PLC-based   |
| Location:               | In station at pump level  |
| SCADA Connectivity:     | Yes, microwave RTU installed  |
| Level & Alarm Controls: | PLC Based Control Panel   |
| Type:                   | Submersible pressure transducer (primary), differential level floats (secondary)  |
| Backup Alarm            | High-high, low-low level floats   |
| Flow Meter Make/Model:  | Not installed   |
| Alarm Transmission:     | All pump station alarms transferred via radio (existing) to WWTF SCADA, equipment in place to transition to r   |
| Pump Motor Starters :   | Motor starters in original combined G-R panel   |

**City of Portsmouth, New Hampshire  
SUCTION LIFT Pump Station Evaluation**

**West Rd.**

*Last Update:* 10/19/2018 *By:* MAC

*This Update:* *By:*

| Mechanical         |                                    |               |  |
|--------------------|------------------------------------|---------------|--|
| Heating:           |                                    | Ventilation:  | Generator  |
| Type:              | Electric Unit heater Wall mount    | System:       | Louvers and Damper   |
| Size, kW:          | 5                                  | Quantity: 1   | Size:  |
|                    |                                    |               | Qty: 1-motorized fresh air intake louver, 1-exhaust louver |
| Make/Model:        | Dayton 3UG73                       | Make & Model: | -  |
| Odor Control :     | None                               | Ventilation:  | Building   |
| City Water Supply: | 3/4" Potable Water Supply with BFP | Exhaust Fan:  | None   |
|                    |                                    | L&D:          | -  |

**Energy Efficiency Information**

Based on pump information gathered from the pump manufacturer's website, both pumps are operating between 40-50% depending on the sheave configuration. It must be noted that the pump belt/sheave configuration was unknown, which may change the operating efficiency conclusion. Based on the low pump runtime operation at the station, this pump station may benefit from smaller, submersible style pumps which would increase overall efficiency.

**Condition of Equipment/Identified Issues**

**Capacity:**  
Recent capacity assessment via drawdown testing on 3/29/18 indicated that the pumps have the following capacities: P1 - 300 gpm (28 ft TDH) and P2 - 278 gpm (28 ft TDH). Both of these pump conditions are less than the original estimated operating point of 400 gpm (40 ft TDH). However, it must be noted that no information was available regarding the belt and sheave setup, which may be the cause for the reduced pump capacity. The station appears to have adequate capacity to handle existing flows as, each pump runs for less than 1 hour per day on average. Under peak conditions, both pumps may run close to 3 hours per day.

**Exterior Site:**  
The station is located in a largely commercial area with a dedicated access driveway. No issues were noted with the exterior site.

**Building Structures (if applicable):**  
The existing building consists of a precast concrete structure with a stone aggregate exterior finish. The exterior of the building appears to be in good condition with the exception of degraded sealant between precast sections, which should be replaced. Interior wall surfaces appear to be in good condition with no observed deficiencies. The interior floors and wall finishes appear to have recently been redone and are in good condition. The pre-cast roof slab seam has been sealed with caulking to mitigate roof leaking. The precast concrete top slab has many pop-outs and a large crack that should be repaired. Several old piping penetrations from the wet well to the interior were observed. These penetrations should be sealed. The membrane roof shows evidence of minor leaks and has a relatively low slope which allows water to pool. Although no obvious tears or open joints were observed on the roof membrane, it does appear to be faded and may be thinning and brittle as it is likely nearing the end of its design life. Replacement of the membrane should be anticipated within 5 years. When the roof is replaced, a higher sloped roof is recommended to assist drainage. The double access door is missing misc. hardware and should be painted to preserve longevity.

**Wet Well:**  
The pump suction and pump discharge pipe showing significant signs of corrosion, and should also be replaced. In general, the wet well structure is in good condition due to bi yearly cleaning. Wet well hatch should be equipped with a safety net.

**Dry Well (if applicable):** See Building Structure section. Pump Station consists of a single, abovegrade room.

**Electrical/Instrumentation:**  
The existing electrical distribution equipment at the pump station is approaching the end of its useful design life. Many of the components are obsolete. Consideration should be given to a comprehensive electrical upgrade including panelboards, emergency power equipment, and other ancillary electrical components. The emergency generator should be considered for replacement based on age (33-years). The ATS has been recently replaced and may be able to be re-used depending on the generator upgrade requirements.

Submersible level instruments are recommended to be installed with an intrinsically safe barrier for compliance with the NEC. For ease of operator maintenance, it is recommended that seal-offs are installed on the instrument conduits out of the wet well with a junction box on the wet well side of the seal off, but still outside the wet well to allow for instrument replacement without confined space entry. The Control Panel (2005) is in good condition and has an estimated lifespan of approximately 20 years. The City should plan to replace the control panel or the major components based on this timeframe or during the next major pump station upgrade.

**HVAC:**  
The electric unit heater is in good condition. No ventilation is provided for the space. In order to adhere to HVAC code requirements the Town should installed a mechanism to hold the door open when the pump station is occupied. While not required, a ventilated exhaust wall thimble should be considered to avoid wall damage. The dry well was noted to have condensation around some of the process equipment. A small local dehumidifier is recommended.

**Security Measures:**  
There is no active security system in the building. A smoke detector appears to be wired to the Control Panel for alarming. There is no gas detection system in this station, as it is not required.

**Summary of Previous Reports**  
The 201 Facilities Plan Update (Underwood Engineers, 1999) indicated that the pump stations was operating at 1/2 of the design capacity. Based on the 2018 tests, the pumps are operating below the proposed design point, but are able to handle the current pump station flows.

**Other:**

**Miscellaneous Issues:**

|                      |       |           |  |
|----------------------|-------|-----------|--|
| Grease Accumulation? | Minor | Source:   |  |
| Clogging Issues?     | No    | Describe: |  |
| Nuisance Odors?      | No    | Cause:    |  |
| Concrete Corrosion?  | No    | Location: |  |


**City of Portsmouth, New Hampshire  
SUCTION LIFT Pump Station Evaluation**

**Woodlands I**

Last Update: 10/22/2018 By: MAC

This Update: By: W-P

| General Pump Station Information                               |                               |
|--|-------------------------------|
| Location:  | 307 F.W. Hartford             |
| Pump Station Finished Floor Elevation, ft.:                    | 31                            |
| Coastal Resiliency Flood Elevation (2050 High Emissions), ft.: | 13.5                          |
| Distance from WWTF (straightline), miles:                      | 3.4                           |
| Year Constructed/Upgraded:                                     | 1985                          |
| Station Type:  | Gorman-Rupp suction-lift      |
| Wet Well Diameter, ft.:  | 8                             |
| Wet Well Volume, gal/ft  | 376                           |
| No. of Pumps:  | 2                             |
| Pump Installation Date:  | 1985                          |
| Design Operating Point, 1 Pump                                 |                               |
| Flow, gpm:   | 150                           |
| Total Dynamic head, ft.:                                       | 38.5                          |
| Pump Make/Model:   | T4A3-B                        |
| Self-Priming Method  | Air Purge                     |
| Motor Size, HP:  | 5                             |
| Motor/Pump Speed, rpm:   | 1740                          |
| Electrical Service, V/Ph/Hz:                                   | 230/1/60                      |
| Drive Type:  | Belt & Sheave, Constant Speed |
| Belt and Sheave Speed:   | Unknown                       |
| Seal Make & Type:  | G-R , Double Mech Oil Bath    |
| Force Main Diam., in.:   | 4                             |
| Force Main Velocity, feet per sec.:                            | 2.3                           |
| Force Main Type:   | PVC                           |
| Force Main Age:  | 1985                          |
| Force Main Length, ft.:  | 1902                          |



| Pump Flow and Run Time Information    |            |            |
|---------------------------------------|------------|------------|
|                                       | P1         | P2         |
| Pump Runtime Data                     |            |            |
| Data Start Date                       | 12/1/2014  | 12/1/2014  |
| Data End Date                         | 10/31/2017 | 10/31/2017 |
| Annual Average Flow, GPM (Calculated) | 5.7        | 5.5        |



| Pump Performance Testing Results  |                                    |
|-----------------------------------|------------------------------------|
| Date of Test:                     | 29-Mar-18                          |
| Min./Max. VFD Setpoints (Hz)      | 60                                 |
| VFD Speed (Hz)                    | N/A                                |
| Pump RPM                          | 1280 (assumed)                     |
| Drawdown Flow, gpm:               | P1 - 92, P2 - 86                   |
| Drawdown TDH, ft.:                | P1 - 30 ft, P2 - 28 ft             |
| Influent Pump Station Flow @ Test | Estimate during visit, 10 - 20 gpm |
| Note for Pump Start Type          | Slow start, constant speed, etc;   |



| Generator Information  |                                     |
|------------------------|-------------------------------------|
| Make/Model:            | Onan                                |
| Interior/Exterior:     | Interior                            |
| Gen. Installation Date | 1985                                |
| Size, KW:              | 30                                  |
| Fuel Type:             | Propane Storage Vertical Tank 130 g |

| Controls Information    |   |
|-------------------------|---|
| Pump Control Sequence:  | Controls start and stop the pumps in an alternating Lead/ Lag sequence based on wet well level setpoints. If lead pump fails to start, Lag pump starts. If level rises above Lag start both will run. |
| Pump Control Panel:     | Motor Starter Panel with original G-R starters (controls bypassed), PLC based Control Panel Upgrade   |
| Installation Date:      | Motor Starter Panel (1985), PLC Control Panel (2004)  |
| Control Type:           | PLC-based   |
| Location:               | In station at pump level  |
| SCADA Connectivity:     | Yes, microwave RTU installed  |
| Level & Alarm Controls: | PLC Based Control Panel   |
| Type:                   | Ultrasonic transducer (primary), differential level floats (secondary)  |
| Backup Alarm            | High-high, low-low level floats   |
| Flow Meter Make/Model:  | Not installed   |
| Alarm Transmission:     | All pump station alarms transferred via radio (existing) to WWTF SCADA, equipment in place to transition t  |
| Pump Motor Starters :   | Motor starters in original combined G-R panel   |

**City of Portsmouth, New Hampshire  
SUCTION LIFT Pump Station Evaluation**

**Woodlands I**

Last Update: 10/22/2018 By: MAC

This Update: By: W-P

| Mechanical         |                                    |               |                                   |
|--------------------|------------------------------------|---------------|-----------------------------------|
| Heating:           |                                    | Ventilation:  | Generator                         |
| Type:              | Electric Unit heater Wall mount    | System        | Louvers and Damper                |
| Size, kW:          | 5                                  | Quantity:     | 2                                 |
| Make/Model:        | Dayton 3UG73                       | Size:         | Qty: 1-motorized fresh air intake |
| Odor Control :     | None                               | Make & Model: | -                                 |
| City Water Supply: | 3/4" Potable Water Supply with BFP | Ventilation:  | Building                          |
|                    |                                    | Exhaust Fan:  | None                              |
|                    |                                    | L&D:          | -                                 |

**Energy Efficiency Information**

Based on pump information gathered from the pump manufacturer's website, both pumps are operating between 40-50% depending on the sheave configuration. It must be noted that the pump belt/sheave configuration was unknown, which may change the operating efficiency conclusion. Based on the low pump runtime operation at the station, this pump station may benefit from smaller, submersible style pumps which would increase overall efficiency from the suction lift style pump.

**Condition of Equipment/Identified Issues**

Capacity:  
Recent capacity assessment via drawdown testing on 3/29/18 indicated that the pumps have the following capacities: P1 - 92 gpm (30 ft TDH) and P2 - 86 gpm (28 ft TDH). Both of these pump conditions are less than the original estimated operating point of 150 gpm (39 ft TDH). However, it must be noted that no information was available regarding the belt and sheave setup, which may be the cause for the reduced pump capacity. The station appears to have adequate capacity to handle existing flows as, each pump runs for 1.5 hours per day on average. Under peak conditions, both pumps may run close to 20 hours per day. Seasonal high runtimes between March-May of each year indicate that this pump station may experience I/I from the sewershed. Sources of I/I should be

Exterior Site:  
The station is located off the side of the road in a residential district. The station has its own driveway and is surrounded by forested areas. The pump station is located adjacent to a culvert and stream.

Building Structures (if applicable):  
The existing building consists of a precast concrete structure with a stone aggregate exterior finish. The exterior of the building appears to be in good condition. The pre-cast concrete slab is in good condition with the exception of a corner which needs to be rebuilt. The joint between the foundation and the superstructure is showing signs of interior leaking. This joint should be pressure washed and the joint sealed. The pre-cast roof slab seam is showing signs of roof leaking. The pre-cast roof slab should be covered with an EPDM membrane roof to prevent further water damage on the interior of the structure. Several old piping penetrations from the wet well to the interior were observed. These penetrations should be permanently sealed. The double access door has been recently replaced and should be properly sealed between the interior door frame and the existing superstructure.

Wet Well:  
The underside surface of concrete top slab is in poor condition with extensive spalling and deterioration. In addition, the steel hatch frame is corroding. The pump suction and pump discharge pipe showing significant signs of corrosion, and should also be replaced. In general, the wet well structure is in good condition due to bi yearly cleaning. Wet well hatch should be equipped with a safety net.

Dry Well (if applicable): See Building Structure section. Pump Station consists of a single, abovegrade room.

Electrical/Instrumentation:  
The existing electrical distribution equipment at the pump station is approaching the end of its useful design life. Many of the components are obsolete. Consideration should be given to a comprehensive electrical upgrade including panelboards, emergency power equipment, and other ancillary electrical components. The emergency generator should be considered for replacement based on age (33-years). The ATS has been recently replaced and may be able to be re-used depending on the generator upgrade requirements.

Level instruments are recommended to be installed with an intrinsically safe barrier for compliance with the NEC. For ease of operator maintenance, it is recommended that seal-offs are installed on the instrument conduits out of the wet well with a junction box on the wet well side of the seal off, but still outside the wet well to allow for instrument replacement without confined space entry. The Control Panel (2004) is in good condition and has an estimated lifespan of approximately 20-years. The City should plan to replace the control panel or the major components based on this timeframe or during the next major pump station upgrade. In the interim, it is recommended that the City modify the location of the wet well level float away from the influent sewer pipe to avoid hydraulic interference and mitigate ragging.

HVAC:  
The electric unit heater is in good condition. No ventilation is provided for the space. In order to adhere to HVAC code requirements the Town should installed a mechanism to hold the door open when the pump station is occupied. While not required, a ventilated exhaust wall thimble should be considered to avoid wall damage. The dry well was noted to have condensation around some of the process equipment. A small local dehumidifier is recommended to mitigate humidity and condensation in the building.

Security Measures:  
There is no active security system in the building. A smoke detector appears to be wired to the Control Panel for alarming. There is no gas detection system in this station, as it is not required.

Summary of Previous Reports  
The 201 Facilities Plan Update (Underwood Engineers, 1999) indicated that the pump station had no significant issues and was operating within adequate capacity.

Other:

Miscellaneous Issues:

|                      |             |           |          |
|----------------------|-------------|-----------|----------|
| Grease Accumulation? | No          | Source:   |          |
| Clogging Issues?     | No          | Describe: |          |
| Nuisance Odors?      | No          | Cause:    |          |
| Concrete Corrosion?  | Yes (minor) | Location: | Wet well |

**City of Portsmouth, New Hampshire  
SUCTION LIFT Pump Station Evaluation**

**Woodlands II**

Last Update: 10/23/2018 By: MAC

This Update: By:

| General Pump Station Information                              |                               |
|---|-------------------------------|
| Location:   | 516 F.W. Hartford             |
| Pump Station Finished Floor Elevation, ft.:                   | 35.8                          |
| Coastal Resiliency Flood Elevation (2050 High Emissions), ft: | 13.5                          |
| Distance from WWTF (straightline), miles:                     | 3                             |
| Year Constructed/Upgraded:                                    | 1984                          |
| Station Type:   | Gorman-Rupp suction-lift      |
| Wet Well Diameter, ft:  | 8                             |
| Wet Well Volume, gal/ft                                       | 376                           |
| No. of Pumps:   | 2                             |
| Pump Installation Date:                                       | 1984                          |
| Design Operating Point, 1 Pump                                |                               |
| Flow, gpm:  | 130                           |
| Total Dynamic head, ft.:                                      | 31                            |
| Pump Make/Model:  | T4A3-B                        |
| Self-Priming Method   | Air Purge                     |
| Motor Size, HP:   | 5                             |
| Motor/Pump Speed, rpm:  | 1750 (assumed)                |
| Electrical Service, V/Ph/Hz:                                  | 240/1/60                      |
| Drive Type:   | Belt & Sheave, Constant Speed |
| Belt and Sheave Speed:  | Unknown                       |
| Seal Make & Type:   | G-R , Double Mech Oil Bath    |
| Force Main Diam., in.:  | 4                             |
| Force Main Velocity, feet per sec.:                           | 1.9                           |
| Force Main Type:  | PVC                           |
| Force Main Age:   | 1984                          |
| Force Main Length, ft.:                                       | 1369                          |



| Pump Flow and Run Time Information    |           |           |
|---------------------------------------|-----------|-----------|
|                                       | P1        | P2        |
| Pump Runtime Data                     |           |           |
| Data Start Date                       | 10/1/2015 | 10/1/2015 |
| Data End Date                         | 7/24/2017 | 7/24/2017 |
| Annual Average Flow, GPM (Calculated) | 3.3       | 3.6       |



| Pump Performance Testing Results  |                                  |
|-----------------------------------|----------------------------------|
| Date of Test:                     | 29-Mar-18                        |
| Min./Max. VFD Setpoints (Hz)      | 60                               |
| VFD Speed (Hz)                    | N/A                              |
| Pump RPM                          | 1280                             |
| Drawdown Flow, gpm:               | P1 - 75, P2 - 76                 |
| Drawdown TDH, ft:                 | P1 - 12 ft, P2 - 11 ft           |
| Influent Pump Station Flow @ Test | Estimate during visit, 10 gpm    |
| Note for Pump Start Type          | Slow start, constant speed, etc; |



| Generator Information  |                          |
|------------------------|--------------------------|
| Make/Model:            | Kohler                   |
| Interior/Exterior:     | Interior                 |
| Gen. Installation Date | 2018                     |
| Size, KW:              | 30                       |
| Fuel Type:             | Propane, two 130 g tanks |

| Controls Information    |   |
|-------------------------|---|
| Pump Control Sequence:  | Controls start and stop the pumps in an alternating Lead/ Lag sequence based on wet well level setpoints. If lead pump fails to start, Lag pump starts. If level rises above Lag start both will run. |
| Pump Control Panel:     | Motor Starter Panel with original G-R starters (controls bypassed), PLC based Control Panel Upgrade   |
| Installation Date:      | Motor Starter Panel (1984), PLC Control Panel (2004)  |
| Control Type:           | PLC-based   |
| Location:               | In station at pump level  |
| SCADA Connectivity:     | Yes, microwave RTU installed  |
| Level & Alarm Controls: | PLC Based Control Panel   |
| Type:                   | Ultrasonic transducer (primary), differential level floats (secondary)  |
| Backup Alarm            | High-high, low-low level floats   |
| Flow Meter Make/Model:  | Not installed   |
| Alarm Transmission:     | All pump station alarms transferred via radio (existing) to WWTF SCADA, equipment in place to transition to micro   |
| Pump Motor Starters :   | Motor starters in original combined G-R panel   |

**City of Portsmouth, New Hampshire  
SUCTION LIFT Pump Station Evaluation**

**Woodlands II**

*Last Update:* 10/23/2018 *By:* MAC

*This Update:* *By:*

| Mechanical         |                                    |               |  |
|--------------------|------------------------------------|---------------|--|
| Heating:           |                                    | Ventilation:  | Generator                                    |
| Type:              | Electric Unit heater Wall mount    | System        | Louvers and Damper                           |
| Size, kW:          | 5                                  | Quantity:     | 1  |
| Make/Model:        | Dayton 3UG73                       | Size:         | Qty: 1-motorized fresh air intake louver, 1- |
| Odor Control :     | None                               | Make & Model: | -  |
| City Water Supply: | 3/4" Potable Water Supply with BFP | Ventilation:  | Building                                     |
|                    |                                    | Exhaust Fan:  | None   |
|                    |                                    | L&D:          | -  |

| Energy Efficiency Information  |
|--|
| Based on pump information gathered from the pump manufacturer's website, both pumps are operating between 40-50% depending on the sheave configuration. It must be noted that the pump belt/sheave configuration was unknown, which may change the operating efficiency conclusion. Based on the low pump runtime operation at the station, this pump station may benefit from smaller, submersible style pumps which would increase overall efficiency. |

| Condition of Equipment/Identified Issues  |                      |           |         |  |                  |    |           |  |                 |    |        |  |                     |    |           |  |
|---|----------------------|-----------|---------|--|------------------|----|-----------|--|-----------------|----|--------|--|---------------------|----|-----------|--|
| <p><b>Capacity:</b><br/>Recent capacity assessment via drawdown testing on 3/29/18 indicated that the pumps have the following capacities: P1 - 75 gpm (12 ft TDH) and P2 - 76 gpm (11 ft TDH). Both of these pump conditions are less than the original estimated operating point of 130 gpm (31 ft TDH). However, it must be noted that no information was available regarding the belt and sheave setup, which may be the cause for the reduced pump capacity. The station appears to have adequate capacity to handle existing flows as, each pump runs for approximately 1 hour per day on average. Under peak conditions, both pumps may run close to combined 15 hours per day. Seasonal high runtimes between March-May of each year indicate that this pump station may experience I/I from the sewershed. Sources of I/I should be investigated.</p>  |                      |           |         |  |                  |    |           |  |                 |    |        |  |                     |    |           |  |
| <p><b>Exterior Site:</b><br/>The station is located off the side of the road in a residential district. The station has its own driveway and is surrounded by forested areas. The backside of the pump station has some graffiti, but nothing of significant damage.</p>  |                      |           |         |  |                  |    |           |  |                 |    |        |  |                     |    |           |  |
| <p><b>Building Structures (if applicable):</b><br/>The existing building consists of a precast concrete structure with a stone aggregate exterior finish. The exterior of the building appears to be in good condition. Interior wall surfaces appear to be in good condition with no observed deficiencies. The wall finishes are in good condition, but the floor finish needs to be re-coated. The pre-cast roof slab seam has been sealed with caulking to mitigate roof leaking. The precast concrete top slab has many pop-outs and a large crack that should be repaired. Several old piping penetrations from the wet well to the interior were observed. These penetrations should be sealed. Although no obvious tears or open joints were observed on the roof membrane, it does appear to be faded and may be thinning and brittle as it is likely nearing the end of its design life. Replacement of the membrane should be anticipated within 7 years. When the roof is replaced, a higher sloped roof is recommended to assist drainage. The double access door is missing misc. hardware and should be painted to preserve longevity.</p> |                      |           |         |  |                  |    |           |  |                 |    |        |  |                     |    |           |  |
| <p><b>Wet Well:</b><br/>The pump suction pipe is showing significant signs of corrosion and should be replaced. In general, the wet well structure is in good condition due to bi yearly cleaning. Wet well hatch should be equipped with a safety net.</p>   |                      |           |         |  |                  |    |           |  |                 |    |        |  |                     |    |           |  |
| <p><b>Dry Well (if applicable):</b> See Building Structure section. Pump Station consists of a single, abovegrade room.</p>   |                      |           |         |  |                  |    |           |  |                 |    |        |  |                     |    |           |  |
| <p><b>Electrical/Instrumentation:</b><br/>The existing electrical distribution equipment at the pump station is approaching the end of its useful design life. Many of the components are obsolete. Consideration should be given to a comprehensive electrical upgrade including panelboards, emergency power equipment, and other ancillary electrical components. The emergency generator was replaced recently and could be re-used.</p> <p>Level instruments are recommended to be installed with an intrinsically safe barrier for compliance with the NEC. For ease of operator maintenance, it is recommended that seal-offs are installed on the instrument conduits out of the wet well with a junction box on the wet well side of the seal off, but still outside the wet well to allow for instrument replacement without confined space entry. The Control Panel (2004) is in good condition and has an estimated lifespan of approximately 20-years. The City should plan to replace the control panel or the major components based on this timeframe or during the next major pump station upgrade.</p>                                  |                      |           |         |  |                  |    |           |  |                 |    |        |  |                     |    |           |  |
| <p><b>HVAC:</b><br/>The electric unit heater is in good condition. No ventilation is provided for the space. In order to adhere to HVAC code requirements the Town should installed a mechanism to hold the door open when the pump station is occupied. While not required, a ventilated exhaust wall thimble should be considered to avoid wall damage. The dry well was noted to have condensation around some of the process equipment. A small local dehumidifier is recommended to mitigate humidity and condensation in the building.</p>  |                      |           |         |  |                  |    |           |  |                 |    |        |  |                     |    |           |  |
| <p><b>Security Measures:</b><br/>There is no active security system in the building. A smoke detector appears to be wired to the Control Panel for alarming. There is no gas detection system in this station, as it is not required.</p>   |                      |           |         |  |                  |    |           |  |                 |    |        |  |                     |    |           |  |
| <p><b>Summary of Previous Reports</b><br/>The 201 Facilities Plan Update (Underwood Engineers, 1999) indicated that the pump station has high run times but still has adequate capacity.</p>  |                      |           |         |  |                  |    |           |  |                 |    |        |  |                     |    |           |  |
| <p><b>Other:</b></p>  |                      |           |         |  |                  |    |           |  |                 |    |        |  |                     |    |           |  |
| <p><b>Miscellaneous Issues:</b></p> <table border="1"> <tbody> <tr> <td>Grease Accumulation?</td> <td>No</td> <td>Source:</td> <td></td> </tr> <tr> <td>Clogging Issues?</td> <td>No</td> <td>Describe:</td> <td></td> </tr> <tr> <td>Nuisance Odors?</td> <td>No</td> <td>Cause:</td> <td></td> </tr> <tr> <td>Concrete Corrosion?</td> <td>No</td> <td>Location:</td> <td></td> </tr> </tbody> </table>   | Grease Accumulation? | No        | Source: |  | Clogging Issues? | No | Describe: |  | Nuisance Odors? | No | Cause: |  | Concrete Corrosion? | No | Location: |  |
| Grease Accumulation?  | No                   | Source:   |         |  |                  |    |           |  |                 |    |        |  |                     |    |           |  |
| Clogging Issues?  | No                   | Describe: |         |  |                  |    |           |  |                 |    |        |  |                     |    |           |  |
| Nuisance Odors?   | No                   | Cause:    |         |  |                  |    |           |  |                 |    |        |  |                     |    |           |  |
| Concrete Corrosion?   | No                   | Location: |         |  |                  |    |           |  |                 |    |        |  |                     |    |           |  |


**City of Portsmouth, New Hampshire  
SUCTION LIFT Pump Station Evaluation**

**Atlantic Heights**

Last Update: 10/23/2018 By: MAC

This Update: By: W-P


| General Pump Station Information                               |                                      |
|--|--------------------------------------|
| Location:  | 134 Preble Way                       |
| Pump Station Finished Floor Elevation, ft.:                    | 49                                   |
| Coastal Resiliency Flood Elevation (2050 High Emissions), ft.: | 13.5                                 |
| Distance from WWTF (straightline), miles:                      | 2                                    |
| Year Constructed/Upgraded:                                     | 1986                                 |
| Station Type:  | Gorman-Rupp suction-lift             |
| Wet Well Diameter, ft.:  | 8                                    |
| Wet Well Volume, gal/ft  | 376                                  |
| No. of Pumps:  | 2                                    |
| Pump Installation Date:  |                                      |
| Pump 1   | 2013 +/-                             |
| Pump 2   | 1985                                 |
| Design Operating Point, 1 Pump                                 |                                      |
| Flow, gpm:   | 385                                  |
| Total Dynamic head, ft.:                                       | 43                                   |
| Pump Make/Model:   | Pump 1 - T6A3S-B, Pump 2 - Classic T |
| Self-Priming Method  | Air Purge                            |
| Motor Size, HP:  | 15                                   |
| Motor/Pump Speed, rpm:   | 1750                                 |
| Electrical Service, V/Ph/Hz:                                   | 460/3/60                             |
| Drive Type:  | Belt & Sheave, Constant Speed        |
| Belt and Sheave Speed:   | Unknown                              |
| Seal Make & Type:  | G-R , Double Mech Oil Bath           |
| Force Main Diam., in.:   | 6                                    |
| Force Main Velocity, feet per sec.:                            | 3.3                                  |
| Force Main Type:   | Ductile Iron                         |
| Force Main Age:  | 1986                                 |
| Force Main Length, ft.:  | 802                                  |



| Pump Flow and Run Time Information    |            |            |
|---------------------------------------|------------|------------|
|                                       | P1         | P2         |
| Pump Flow Data (Magnetic Flow Meter)  |            |            |
| Observed Instantaneous Flowrate, GPM  | 300        | 285        |
| Pump Runtime Data                     | Yes        | Yes        |
| Data Start Date                       | 12/1/2014  | 12/1/2014  |
| Data End Date                         | 10/31/2017 | 10/31/2017 |
| Annual Average Flow, GPM (Calculated) | 12.819     | 12.753     |



| Pump Performance Testing Results  |                                  |
|-----------------------------------|----------------------------------|
| Date of Test:                     | 3-Apr-18                         |
| Min./Max. VFD Setpoints (Hz)      | 60, Constant speed               |
| VFD Speed (Hz)                    | 1875                             |
| Pump RPM                          | 1875 (assumed)                   |
| Flow Meter Flow, gpm:             | P1 - 300, P2 - 285               |
| Flowmeter test TDH, ft.:          | P1 - 33, P2 - 33                 |
| Influent Pump Station Flow @ Test | N/A                              |
| Note for Pump Start Type          | Slow start, constant speed, etc; |



| Generator Information  |   |
|------------------------|---|
| Make/Model:            | Onan                                    |
| Interior/Exterior:     | Interior                                |
| Gen. Installation Date | 1985                                    |
| Size, KW:              | 30                                      |
| Fuel Type:             | 1,000 gal exterior Propane Storage Tank |

| Controls Information    |   |
|-------------------------|---|
| Pump Control Sequence:  | Controls start and stop the pumps in an alternating Lead/ Lag sequence based on wet well level setpoints. If lead pump fails to start, Lag pump starts. If level rises above Lag start both will run. |
| Pump Control Panel:     | MCC for starters, separate Control Panel (Electrical Installations, Inc.) for Alarm and Level Control Panel   |
| Installation Date:      | 1986 (Motor Control Center), 2005 (Control Panel)   |
| Control Type:           | PLC-based   |
| Location:               | Within main pump station, dry well  |
| SCADA Connectivity:     | Yes, microwave RTU  |
| Level & Alarm Controls: | PLC Based Control Panel (2005)  |
| Type:                   | Submersible transducer (primary), differential level floats (secondary)   |
| Backup Alarm            | High-high, low-low level floats   |
| Flow Meter Make/Model:  | Foxboro 6" Mag. Flow Meter on Discharge Header  |
| Alarm Transmission:     | All pump station alarms transferred via radio (existing) to WWTF SCADA, equipment in place to transition to micro   |
| Pump Motor Starters :   | Motor starters in original MCC  |

**City of Portsmouth, New Hampshire  
SUCTION LIFT Pump Station Evaluation**

**Atlantic Heights**

*Last Update:* 10/23/2018      *By:* MAC  
*This Update:*                                      *By:* W-P

| Mechanical         |                                  |             |  |
|--------------------|----------------------------------|-------------|--|
| Heating:           |                                  |             | Ventilation: Generator & Building      |
| Type:              | Electric Unit heater, Wall mount | System:     | Louvers and Damper                     |
| Size, kW:          | 5                                | Quantity: 2 | Size: 66"x 72" , two separate sections |
| Make/Model:        | Dayton, 3UF80, 480 V 3 ph        |             | Make & Model: -                        |
| Odor Control :     | None                             |             | Ventilation: Building                  |
| City Water Supply: | 1" City water with BFP           |             | Exhaust Fan: Inline, 1/3 HP Qty: 1     |
|                    |                                  | L&D:        | Yes                                    |

| Energy Efficiency Information                 |
|---|
| Pump curves not readily available for review. |

| Condition of Equipment/Identified Issues   |                      |           |         |  |                  |    |           |  |                 |    |        |  |                     |    |           |  |
|--|----------------------|-----------|---------|--|------------------|----|-----------|--|-----------------|----|--------|--|---------------------|----|-----------|--|
| <p><u>Capacity:</u><br/>Recent capacity assessment via flow meter observation on 4/3/18 indicated that the pumps have the following capacities: P1 - 300 gpm (33 ft TDH) and P2 - 285 gpm (33 ft TDH). Both of these pump conditions are below the reported rated capacity of 385 gpm (43 ft TDH). However, it must be noted that no information was available regarding the belt and sheave setup, which may be the cause for the reduced pump capacity. The station appears to have adequate capacity to handle existing flows as, each pump runs for approximately 1 hours per day on average. Under peak conditions, both pumps may run close to combined 13 hours per day. Seasonal high runtimes between Jan-May of each year indicate that this pump station may experience I/I from the sewershed. Sources of I/I should be investigated. The existing MCC/instrumentation scheme requires the City to manually select which pump is on standby power. This operation should be addressed with subsequent MCC/control panel upgrades.</p>  |                      |           |         |  |                  |    |           |  |                 |    |        |  |                     |    |           |  |
| <p><u>Exterior Site:</u><br/>The pump station is located in a largely residential neighborhood on a parcel which backs up to the Piscataqua River. The rear of the building has a fenced in gate area containing a propane tank. No issues were noted with the site.</p>   |                      |           |         |  |                  |    |           |  |                 |    |        |  |                     |    |           |  |
| <p><u>Building Structures (if applicable):</u><br/>The exterior of the building, including the brick and metal roof appeared to be in fair condition. The exterior brick is original to the construction of the building and should be cleaned and repointed in areas where mortar has degraded. The access door sill in particular needs to be repaired with mortarted to prevent further damage. The roof appears to be in fair condition but has reached the end of its useful life and should be scheduled for replacement. The exterior door is in good condition, but missing hardware should be replaced. The foundation and the interior of the building appeared to be in good condition. The lower portion of the interior dry well should be cleaned and repainted based on moisture damage. In addition, the City should consider moisture mitigation as described in the HVAC section. The corroded lintel steel above the generator louver should be replaced/repainted to prevent building envelope leaks.</p>  |                      |           |         |  |                  |    |           |  |                 |    |        |  |                     |    |           |  |
| <p><u>Wet Well:</u><br/>Wet Well Good condition due to bi-yearly cleaning. Grating for the wet well appears to have been dislodged and wedged between manhole interior. It is recommende that loose grating sections be removed for safety. Pump suction piping shows signs of corrosion and should be considered for replacement evaluation.</p>  |                      |           |         |  |                  |    |           |  |                 |    |        |  |                     |    |           |  |
| <p><u>Dry Well (if applicable):</u> See Building Structure section.</p>  |                      |           |         |  |                  |    |           |  |                 |    |        |  |                     |    |           |  |
| <p><u>Electrical/Instrumentation:</u><br/>The existing electrical distribution equipment at the pump station is approaching the end of its useful design life. Many of the components are obsolete. Consideration should be given to a comprehensive electrical upgrade including panelboards, emergency power equipment, and other ancillary electrical components. It is recommended that the City install emergency lighting, arch-flash safety labeling, and hazardous gas detection system in the dry well side of the pump station. In addition, the belt drive pumps are recommended to have emergency stop switches adjacent to the pumps for operator safety.</p> <p>Level instruments are recommended to be installed with an intrinsically safe barrier for compliance with the NEC. For ease of operator maintenance, it is recommended that seal-offs are installed on the instrument conduits out of the wet well with a junction box on the wet well side of the seal off, but still outside the wet well to allow for instrument replacement without confined space entry. The Control Panel (2005) is in good condition and has an estimated lifespan of approximately 20-years. The City should plan to replace the control panel or the major components based on this timeframe or during the next major pump station upgrade.</p> |                      |           |         |  |                  |    |           |  |                 |    |        |  |                     |    |           |  |
| <p><u>HVAC:</u><br/>The existing ventilation equipment is operational and in fair condition considering it's age. The ventilation equipment should planned to be replaced within the next several years. Consideration should be given to equipment that reduces ventilation rates based on space occupancy and outside air temperature. Proof of air flow switches are recommended if a new ventilation system is installed. The exhaust fan should be operated continuously to satisfy NFPA 820 requirements for declassification. The associated intake damper for the exhaust fan does not open and should be repaired/replaced. The lower level sump pump float should be adjusted to avoid water from overtopping the sump pit.</p>  |                      |           |         |  |                  |    |           |  |                 |    |        |  |                     |    |           |  |
| <p><u>Security Measures:</u><br/>There is no active security system in the building. A smoke detector appears to be wired to the Control Panel for alarming. There is no gas detection system in this station, as it is not required.</p>  |                      |           |         |  |                  |    |           |  |                 |    |        |  |                     |    |           |  |
| <p><u>Summary of Previous Reports</u><br/>The 201 Facilities Plan Update (Underwood Engineers, 1999)indicated that the sewershed was a combined sewer system. The pump station was reported to have adequate capacity, but the pumps were discahrging at of the design capacity.</p>   |                      |           |         |  |                  |    |           |  |                 |    |        |  |                     |    |           |  |
| <p><u>Other:</u></p>   |                      |           |         |  |                  |    |           |  |                 |    |        |  |                     |    |           |  |
| <p><u>Miscellaneous Issues:</u></p> <table border="1"> <tbody> <tr> <td>Grease Accumulation?</td> <td>No</td> <td>Source:</td> <td></td> </tr> <tr> <td>Clogging Issues?</td> <td>No</td> <td>Describe:</td> <td></td> </tr> <tr> <td>Nuisance Odors?</td> <td>No</td> <td>Cause:</td> <td></td> </tr> <tr> <td>Concrete Corrosion?</td> <td>No</td> <td>Location:</td> <td></td> </tr> </tbody> </table>  | Grease Accumulation? | No        | Source: |  | Clogging Issues? | No | Describe: |  | Nuisance Odors? | No | Cause: |  | Concrete Corrosion? | No | Location: |  |
| Grease Accumulation?   | No                   | Source:   |         |  |                  |    |           |  |                 |    |        |  |                     |    |           |  |
| Clogging Issues?   | No                   | Describe: |         |  |                  |    |           |  |                 |    |        |  |                     |    |           |  |
| Nuisance Odors?  | No                   | Cause:    |         |  |                  |    |           |  |                 |    |        |  |                     |    |           |  |
| Concrete Corrosion?  | No                   | Location: |         |  |                  |    |           |  |                 |    |        |  |                     |    |           |  |

**City of Portsmouth, New Hampshire  
SUCTION LIFT Pump Station Evaluation  
Leslie Dr.**

Last Update: 10/23/2018 By: MAC  
This Update: By:


| General Pump Station Information                              |                               |
|---|-------------------------------|
| Location:   | 590 Market Street             |
| Pump Station Finished Floor Elevation, ft.:                   | 9.5                           |
| Coastal Resiliency Flood Elevation (2050 High Emissions), ft: | 13.5                          |
| Distance from WWTF (straightline), miles:                     | 1.4                           |
| Year Constructed/Upgraded:                                    | Constructed: 1986             |
| Station Type:   | Gorman-Rupp suction-lift      |
| Wet Well Dimensions, L x W x D:                               | 12 x 12 x 11                  |
| Wet Well Volume, gal/ft                                       | 1,077                         |
| No. of Pumps:   | 2                             |
| Pump Installation Date:                                       | 1986                          |
| Design Operating Point, 1 Pump                                |                               |
| Flow, gpm:  | 1550                          |
| Total Dynamic head, ft.:                                      | 34                            |
| Pump Make/Model:  | T10A3S-B                      |
| Self-Priming Method   | Air Purge                     |
| Motor Size, HP:   | 25                            |
| Motor/Pump Speed, rpm:  | 1760                          |
| Electrical Service, V/Ph/Hz:                                  | 480/3/60                      |
| Drive Type:   | Belt & Sheave, Constant Speed |
| Belt and Sheave Speed:  | Unknown                       |
| Seal Make & Type:   | G-R , Double Mech Oil Bath    |
| Force Main Diam., in.:  | 12                            |
| Force Main Velocity, feet per sec.:                           | 2.1                           |
| Force Main Length, ft.:                                       | 846                           |
| Force Main Type:  | Ductile iron                  |
| Force Main Age:   | 1986                          |



| Pump Flow and Run Time Information    |            |            |
|---------------------------------------|------------|------------|
|                                       | P1         | P2         |
| Pump Flow Data (Magnetic Flow Meter)  |            |            |
| Observed Instantaneous Flowrate, GPM  | 1487       | 1485       |
| Pump Runtime Data                     |            |            |
| Data Start Date                       | 12/1/2014  | 12/1/2014  |
| Data End Date                         | 10/31/2017 | 10/31/2017 |
| Annual Average Flow, MGD (Calculated) | 0.11       | 0.11       |

| Pump Performance Testing Results  |  |
|-----------------------------------|--|
| Date of Test:                     | 3-Apr-18   |
| Min./Max. VFD Setpoints (Hz)      | 60, Constant speed                                       |
| VFD Speed (Hz)                    | 1760   |
| Pump RPM                          | 1760   |
| Flow Meter, gpm:                  | P1 - 1487, P2 - 1485                                     |
| Flowmeter test TDH, ft:           | P1 - 28, P2 - 18.5                                       |
| Influent Pump Station Flow @ Test | N/A  |
| Note for Pump Start Type          | P1 constant speed starter (1986), P2 soft starter (2015) |

| Generator Information  |   |
|------------------------|---|
| Make/Model:            | Onan                                    |
| Interior/Exterior:     | Interior                                |
| Gen. Installation Date | 1986                                    |
| Size, KW:              | 45                                      |
| Fuel Type:             | 1,000 gal exterior Propane Storage Tank |



| Controls Information    |   |
|-------------------------|---|
| Pump Control Sequence:  | Controls start and stop the pumps in an alternating Lead/ Lag sequence based on wet well level setpoints. If lead pump fails to start, Lag pump starts. If level rises above Lag start both will run. |
| Pump Control Panel:     | MCC for starters, separate Control Panel (Electrical Installations, Inc.) for Alarm and Level Control Panel   |
| Installation Date:      | 1986 (Motor Control Center), 2005 (Control Panel)   |
| Control Type:           | PLC-based   |
| Location:               | Within main pump station, dry well  |
| SCADA Connectivity:     | Yes, microwave RTU  |
| Level & Alarm Controls: | PLC Based Control Panel (2005)  |
| Type:                   | Submersible transducer (primary), differential level floats (secondary)   |
| Backup Alarm            | High-high, low-low level floats   |
| Flow Meter Make/Model:  | Foxboro 10" Mag. Flow Meter on Discharge Header   |
| Alarm Transmission:     | All pump station alarms transferred via radio (existing) to WWTF SCADA, equipment in place to transition to microwave   |
| Pump Motor Starters :   | P1: 1986 MCC starter, P2: 2015 soft starter in MCC.   |

**City of Portsmouth, New Hampshire  
SUCTION LIFT Pump Station Evaluation**

**Leslie Dr.**

Last Update: 10/23/2018 By: MAC  
This Update: By:

| Mechanical         |                                  |             |   |
|--------------------|----------------------------------|-------------|---|
| Heating:           |                                  |             | Ventilation: Generator & Building       |
| Type:              | Electric Unit heater, Wall mount |             | System Louvers and Damper               |
| Size, kW:          | 5                                | Quantity: 2 | Size: 66" x 72" , two separate sections |
| Make/Model:        | Dayton, 3UF80, 480 V 3 ph        |             | Make & Model: -                         |
| Odor Control :     | None                             |             | Ventilation: Building                   |
| City Water Supply: | 1" City water with BFP           |             | Exhaust Fan: Inline, 1/3 HP Qty: 1      |
|                    |                                  |             | L&D: Yes                                |

**Energy Efficiency Information**

Based on pump information gathered from the pump manufacturer's website, both pumps are operating between 60-70% depending on the sheave configuration. It must be noted that the pump belt/sheave configuration was unknown, which may change the operating efficiency conclusion.

**Condition of Equipment/Identified Issues**

Capacity:  
Recent capacity assessment via flow meter observation on 4/3/18 indicated that the pumps have the following capacities: P1 - 1487 gpm (28 ft TDH) and P2 - 1485 gpm (18.5 ft TDH). Both of these pump conditions considered to be within the reported rated capacity of 1550 gpm (34 ft TDH). The station appears to have adequate capacity to handle existing flows as, each pump runs for approximately 1.25 hours per day on average. Under peak conditions, both pumps may run close to combined 16 hours per day. Seasonal high runtimes between Jan-May of each year indicate that this pump station may experience I/I from the sewershed. Sources of I/I should be investigated.

Exterior Site:  
The station is located on a parcel adjacent to the Route 1 bypass and between two tidally influenced drainage areas. No significant issues were noted with the site.

Building Structures (if applicable):  
The exterior of the building, including the brick and metal roof appeared to be in fair condition, with the exception of some graffiti. The exterior brick is original to the construction of the building and should be cleaned and repointed in areas where mortar has degraded. The pump piping penetration link seals in the lower level show significant signs of leakage. It is recommended that this penetration is repaired/replaced to prevent further moisture from entering the drywell. The roof appears to be in fair condition but has reached the end of its useful life and should be scheduled for replacement. The exterior door is in good condition, but should be repainted and missing hardware should be replaced. The foundation and the interior of the building appeared to be in good condition. The lower Dry Well shows signs of significant moisture accumulation and rust. All corroded metal equipment (i.e., pipe supports, pump skids) should be stripped and repainted for continued protection. The lower portion of the interior dry well should be cleaned and repainted based on moisture damage. In addition, the City should consider moisture mitigation as described in the HVAC section.

Wet Well:  
Wet Well Good condition due to bi-yearly cleaning. The City noted that the wet well has issues with significant scum accumulation. The City has recently installed a large bubble wet well mixing system (Medora) to try and mitigate scum accumulation, results have not yet been confirmed. Grating and pump suction piping are in fair condition. Each wet well access hatch should have a safety net/guard installed. The old electrical penetrations into the wet well slab should be patched/sealed.

Electrical/Instrumentation:  
The existing electrical distribution equipment at the pump station is approaching the end of its useful design life. Many of the components are obsolete. Consideration should be given to a comprehensive electrical upgrade including panelboards, emergency power equipment, and other ancillary electrical components. It is recommended that the City install emergency lighting, arch-flash safety labeling, and hazardous gas detection system in the dry well side of the pump station. In addition, the belt drive pumps are recommended to have emergency stop switches adjacent to the pumps for operator safety. The existing MCC/instrumentation scheme requires the City to manually select which pump is on standby power. This operation should be addressed with subsequent MCC/control panel upgrades.

Level instruments are recommended to be installed with an intrinsically safe barrier for compliance with the NEC. For ease of operator maintenance, it is recommended that seal-offs are installed on the instrument conduits out of the wet well with a junction box on the wet well side of the seal off, but still outside the wet well to allow for instrument replacement without confined space entry. The Control Panel (2005) is in good condition and has an estimated lifespan of approximately 20-years. The City should plan to replace the control panel or the

HVAC:  
The existing ventilation equipment is operational and in fair condition considering it's age. The ventilation equipment should be replaced within the next several years. Consideration should be given to equipment that reduces ventilation rates based on space occupancy and outside air temperature. Proof of air flow switches are recommended if a new ventilation system is installed. The exhaust fan should be operated continuously to satisfy NFPA 820 requirements for declassification. The associated intake damper for the exhaust fan does not open and should be repaired/replaced. The lower level sump pump float should be adjusted to avoid water from overtopping the sump pit.

Security Measures:  
There is no active security system in the building. A smoke detector appears to be wired to the Control Panel for alarming. There is no gas detection system in this station, as it is not required.

Summary of Previous Reports  
The 201 Facilities Plan Update (Underwood Engineers, 1999) indicated that Leslie Drive has adequate capacity for next 20 years.

Other:

Miscellaneous Issues:

|                      |     |           |  |
|----------------------|-----|-----------|--|
| Grease Accumulation? | Yes | Source:   |  |
| Clogging Issues?     | No  | Describe: |  |
| Nuisance Odors?      | No  | Cause:    |  |
| Concrete Corrosion?  | No  | Location: |  |


**City of Portsmouth, New Hampshire  
SUCTION LIFT Pump Station Evaluation**

**Marcy St.**

Last Update: 10/23/2018 By: MAC

This Update: By:

| General Pump Station Information                               |                               |
|--|-------------------------------|
| Location:  | 535 Marcy St                  |
| Pump Station Finished Floor Elevation, ft.:                    | 10.2                          |
| Coastal Resiliency Flood Elevation (2050 High Emissions), ft.: | 13.5                          |
| Distance from WWTF (straightline), miles:                      | 0.5                           |
| Year Constructed/Upgraded:                                     | 1986                          |
| Station Type:  | Gorman-Rupp suction-lift      |
| Wet Well Diameter, ft:   | 6                             |
| Wet Well Volume, gal/ft  | 211                           |
| No. of Pumps:  | 2                             |
| Pump Installation Date:  | P1 - 2008, P2 - 2004          |
| Design Operating Point, 1 Pump                                 |                               |
| Flow, gpm:   | 210                           |
| Total Dynamic head, ft.:                                       | 44                            |
| Pump Make/Model:   | T-4A3S-B                      |
| Self-Priming Method  | Air Purge                     |
| Motor Size, HP:  | 10                            |
| Motor/Pump Speed, rpm:   | 1755                          |
| Electrical Service, V/Ph/Hz:                                   | 480/3/60                      |
| Drive Type:  | Belt & Sheave, Constant Speed |
| Belt and Sheave Speed:   | Unknown                       |
| Seal Make & Type:  | G-R , Double Mech Oil Bath    |
| Force Main Diam., in.:   | 4                             |
| Force Main Velocity, feet per sec.:                            | 3.2                           |
| Force Main Type:   | Ductile iron                  |
| Force Main Age:  | 1985                          |
| Force Main Length, ft.:  | 878                           |



| Pump Flow and Run Time Information    |            |            |
|---------------------------------------|------------|------------|
|                                       | P1         | P2         |
| Pump Flow Data (Magnetic Flow Meter)  |            |            |
| Observed Instantaneous Flowrate, GPM  | 125        | 125        |
| Pump Runtime Data                     |            |            |
| Data Start Date                       | 12/1/2014  | 12/1/2014  |
| Data End Date                         | 10/31/2017 | 10/31/2017 |
| Annual Average Flow, GPM (Calculated) | 10.7       | 11.3       |



| Pump Performance Testing Results  |                                  |
|-----------------------------------|----------------------------------|
| Date of Test:                     | 3-Apr-18                         |
| Min./Max. VFD Setpoints (Hz)      | Constant speed, 60               |
| VFD Speed (Hz)                    | 1875                             |
| Pump RPM                          | 1875 (assumed)                   |
| Drawdown Flow, gpm:               | P1 - 125, P2 - 125               |
| Drawdown TDH, ft:                 | P1 - 94, P2 - 92                 |
| Influent Pump Station Flow @ Test | Estimate during visit            |
| Note for Pump Start Type          | Slow start, constant speed, etc; |



| Generator Information  |             |
|------------------------|-------------|
| Make/Model:            | Onan        |
| Interior/Exterior:     | Interior    |
| Gen. Installation Date | 1986        |
| Size, KW:              | 20          |
| Fuel Type:             | Natural Gas |

| Controls Information    |   |
|-------------------------|---|
| Pump Control Sequence:  | Controls start and stop the pumps in an alternating Lead/ Lag sequence based on wet well level setpoints. If lead pump fails to start, Lag pump starts. If level rises above Lag start both will run. |
| Pump Control Panel:     | MCC for starters, separate Control Panel (Electrical Installations, Inc.) for Alarm and Level Control Panel   |
| Installation Date:      | 1986 (Motor Control Center), 2005 (Control Panel)   |
| Control Type:           | PLC-based   |
| Location:               | Within main pump station, dry well  |
| SCADA Connectivity:     | Yes, microwave RTU  |
| Level & Alarm Controls: | PLC Based Control Panel (2005)  |
| Type:                   | Submersible transducer (primary), differential level floats (secondary)   |
| Backup Alarm            | High-high, low-low level floats   |
| Flow Meter Make/Model:  | Foxboro 4" Mag. Flow Meter on Discharge Header  |
| Alarm Transmission:     | All pump station alarms transferred via radio (existing) to WWTF SCADA, equipment in place to transition to   |
| Pump Motor Starters :   | Motor starters in original MCC  |

**City of Portsmouth, New Hampshire  
SUCTION LIFT Pump Station Evaluation**

**Marcy St.**

Last Update: 10/23/2018 By: MAC

This Update: By:

| Mechanical         |                                     |               |                                  |
|--------------------|-------------------------------------|---------------|----------------------------------|
| Heating:           |                                     | Ventilation:  | Generator & Building             |
| Type:              | Natural Gas Unit heater, Wall mount | System:       | Louvers and Damper               |
| Size, MBH:         | 50                                  | Quantity:     | 2                                |
| Make/Model:        | Modine                              | Size:         | 66"x 72" , two separate sections |
| Odor Control :     | None                                | Make & Model: | -                                |
| City Water Supply: | 1" City water with BFP              | Ventilation:  | Building                         |
|                    |                                     | Exhaust Fan:  | Inline, 1/3 HP Qty: 1            |
|                    |                                     | L&D:          | Yes                              |

| Energy Efficiency Information   |
|---|
| Based on pump information gathered from the pump manufacturer's website, both pumps are operating at less than 40% efficiency depending on the sheave configuration. It must be noted that the pump belt/sheave configuration was unknown, which may change the operating efficiency conclusion. The low efficiency is due at least in part to the high head conditions the pumps are experiencing. Based on the low pump runtime operation at the station, this pump station may benefit from submersible style pumps which would increase overall efficiency. |

| Condition of Equipment/Identified Issues   |                      |           |         |  |                  |    |           |  |                 |    |        |  |                     |    |           |  |
|--|----------------------|-----------|---------|--|------------------|----|-----------|--|-----------------|----|--------|--|---------------------|----|-----------|--|
| <p><b>Capacity:</b><br/>Recent capacity assessment via flow meter observation on 4/3/18 indicated that the pumps have the following capacities: P1 - 125 gpm (94 ft TDH) and P2 - 125 gpm (92 ft TDH). Both of these pump conditions are below the reported rated capacity of 210 gpm (44 ft TDH). However, it must be noted that no information was available regarding the belt and sheave setup, which may be the cause for the reduced pump capacity. Based on the high TDH conditions observed during pump testing, the forcemain should be evaluated for possible flow impediments or deterioration. Regardless of the observed flowrates, the station appears to have adequate capacity to handle existing flows as, each pump runs for approximately 2 hours per day on average. Under peak conditions, both pumps may run close to combined 24 hours per day. Seasonal high runtimes between April-May of each year indicate that this pump station may experience I/I from the sewershed. Sources of I/I (i.e., direct roof drain and sump pump influence) should be investigated.</p>   |                      |           |         |  |                  |    |           |  |                 |    |        |  |                     |    |           |  |
| <p><b>Exterior Site:</b><br/>The station is located in a residential neighborhood between a house and a tidal portion of the river. Observations indicated that high tide levels come within several feet of the pump station finished floor elevation. The pump station has a small access driveway where the front door and wet well access hatch can be accessed. The wet well top slab has been significantly damaged by plow use and should be replaced. Bollards or markers should be installed to avoid plow damage in the future. Based on the small parcel footprint, the City should consider an alternative pump station approach (i.e., submersible) for future upgrades.</p>  |                      |           |         |  |                  |    |           |  |                 |    |        |  |                     |    |           |  |
| <p><b>Building Structures (if applicable):</b><br/>The exterior of the building, including the wood siding and shingled roof appeared to be in fair condition. A few areas of trim are in need of repair/painting/replacement. It is recommended that the City install roof gutters to preserve siding/trim. The roof appears to be in fair condition. The lower portion of the interior dry well shows significant signs of moisture accumulation and resulting corrosion. The floors and equipment should be cleaned and repainted. In addition, the City should consider moisture mitigation as described in the HVAC section.</p>  |                      |           |         |  |                  |    |           |  |                 |    |        |  |                     |    |           |  |
| <p><b>Wet Well:</b><br/>The concrete top slab is in poor condition with major degradation and section loss. Reinforcing steel is exposed in many locations. This top slab should be replaced. Wet Well Good condition due to bi-yearly cleaning. Pump suction piping shows signs of corrosion and should be considered for replacement evaluation</p>  |                      |           |         |  |                  |    |           |  |                 |    |        |  |                     |    |           |  |
| <p><b>Dry Well (if applicable):</b> See Building Structure section.</p>  |                      |           |         |  |                  |    |           |  |                 |    |        |  |                     |    |           |  |
| <p><b>Electrical/Instrumentation:</b><br/>The existing electrical distribution equipment at the pump station is approaching the end of its useful design life. Many of the components are obsolete. Consideration should be given to a comprehensive electrical upgrade including panelboards, emergency power equipment, and other ancillary electrical components. It is recommended that the City install emergency lighting, arch-flash safety labeling, and hazardous gas detection system in the dry well side of the pump station. In addition, the belt drive pumps are recommended to have emergency stop switches adjacent to the pumps for operator safety.</p> <p>Level instruments are recommended to be installed with an intrinsically safe barrier for compliance with the NEC. For ease of operator maintenance, it is recommended that seal-offs are installed on the instrument conduits out of the wet well with a junction box on the wet well side of the seal off, but still outside the wet well to allow for instrument replacement without confined space entry. The Control Panel (2005) is in good condition and has an estimated lifespan of approximately 20-years. The City should plan to replace the control panel or the major components based on this timeframe or during the next major pump station upgrade.</p> |                      |           |         |  |                  |    |           |  |                 |    |        |  |                     |    |           |  |
| <p><b>HVAC:</b><br/>The existing ventilation equipment is operational and in fair condition considering it's age. The ventilation equipment should be planned to be replaced within the next several years. Consideration should be given to equipment that reduces ventilation rates based on space occupancy and outside air temperature. Proof of air flow switches are recommended if a new ventilation system is installed. The exhaust fan should be operated continuously to satisfy NFPA 820 requirements for declassification. The associated intake damper for the exhaust fan linkage for ventilation and standby generator need to be repaired/replaced. The lower level sump pump float should be adjusted to avoid water from overtopping the sump pit. Based on the proximity of tidal water and the depth of the dry well, a dehumidifier is recommended for installation on the lower level.</p>  |                      |           |         |  |                  |    |           |  |                 |    |        |  |                     |    |           |  |
| <p><b>Security Measures:</b><br/>There is no active security system in the building. A smoke detector appears to be wired to the Control Panel for alarming. There is no gas detection system in this station, as it is not required.</p>  |                      |           |         |  |                  |    |           |  |                 |    |        |  |                     |    |           |  |
| <p><b>Summary of Previous Reports</b><br/>The 201 Facilities Plan Update (Underwood Engineers, 1999) indicated that the pump station had high operational run times and required electrical</p>  |                      |           |         |  |                  |    |           |  |                 |    |        |  |                     |    |           |  |
| <p><b>Other:</b></p>   |                      |           |         |  |                  |    |           |  |                 |    |        |  |                     |    |           |  |
| <p><b>Miscellaneous Issues:</b></p> <table border="1"> <tbody> <tr> <td>Grease Accumulation?</td> <td>No</td> <td>Source:</td> <td></td> </tr> <tr> <td>Clogging Issues?</td> <td>No</td> <td>Describe:</td> <td></td> </tr> <tr> <td>Nuisance Odors?</td> <td>No</td> <td>Cause:</td> <td></td> </tr> <tr> <td>Concrete Corrosion?</td> <td>No</td> <td>Location:</td> <td></td> </tr> </tbody> </table>  | Grease Accumulation? | No        | Source: |  | Clogging Issues? | No | Describe: |  | Nuisance Odors? | No | Cause: |  | Concrete Corrosion? | No | Location: |  |
| Grease Accumulation?   | No                   | Source:   |         |  |                  |    |           |  |                 |    |        |  |                     |    |           |  |
| Clogging Issues?   | No                   | Describe: |         |  |                  |    |           |  |                 |    |        |  |                     |    |           |  |
| Nuisance Odors?  | No                   | Cause:    |         |  |                  |    |           |  |                 |    |        |  |                     |    |           |  |
| Concrete Corrosion?  | No                   | Location: |         |  |                  |    |           |  |                 |    |        |  |                     |    |           |  |

**City of Portsmouth, New Hampshire  
SUCTION LIFT Pump Station Evaluation  
Corporate Drive**

Last Update: 10/26/2018

By: MAC

This Update:

By: W-P

| General Pump Station Information                              |                            |
|---|----------------------------|
| Location:   | 215 Corporate Dr.          |
| Pump Station Finished Floor Elevation, ft.:                   | 30                         |
| Coastal Resiliency Flood Elevation (2050 High Emissions), ft: | 13.5                       |
| Distance from WWTF (straightline), miles:                     | 2.7                        |
| Year Constructed/Upgraded:                                    | 2001                       |
| Station Type:   | Gorman-Rupp suction-lift   |
| Wet Well Diameter, ft:  | 8                          |
| Wet Well Volume, gal/ft                                       | 376                        |
| No. of Pumps:   | 3                          |
| Pump Installation Date:                                       | 2001                       |
| Design Operating Point, 1 Pump                                |                            |
| Flow, gpm:  | 600                        |
| Total Dynamic head, ft.:                                      | 83.5                       |
| Pump Make/Model:  | T6A3-B/F                   |
| Self-Priming Method   | Air Purge                  |
| Motor Size, HP:   | 30                         |
| Motor/Pump Speed, rpm:  | 1765/1875                  |
| Electrical Service, V/Ph/Hz:                                  | 480/3/60                   |
| Drive Type:   | Belt & Sheave, VFD         |
| Belt and Sheave Speed:  | Unknown                    |
| Seal Make & Type:   | G-R , Double Mech Oil Bath |
| Force Main Diam., in.:  | 8                          |
| Force Main Velocity, feet per sec. (full speed):              | 5.9                        |
| Force Main Type:  | PVC                        |
| Force Main Age:   | 2001                       |
| Force Main Length, ft.:                                       | 2286                       |



| Pump Flow and Run Time Information           |            |            |            |
|--|------------|------------|------------|
|  | P1         | P2         | P3         |
| Pump Flow Data (Magnetic Flow Meter)         |            |            |            |
| Observed Instantaneous Flowrate (60 Hz), GPM | 930        | 940        | 930        |
| Pump Runtime Data                            |            |            |            |
|  | Yes        | Yes        | Yes        |
| Data Start Date                              | 12/1/2014  | 12/1/2014  | 12/1/2014  |
| Data End Date                                | 10/31/2017 | 10/31/2017 | 10/31/2017 |
| Annual Average Flow, GPM (Calculated)        | 9.8        | 10.0       | 5.4        |

| Pump Performance Testing Results  |                              |
|-----------------------------------|------------------------------|
| Date of Test:                     | 3-Apr-18                     |
| Min./Max. VFD Setpoints (Hz)      | 10, 60                       |
| VFD Speed (Hz)                    | 1875                         |
| Pump RPM                          | 1770                         |
| Observed Flow, gpm:               | P1 - 940, P2 - 940, P3 - 930 |
| Observed TDH, ft:                 | P1 - 58, P2 - 58, P3 - 58    |
| Influent Pump Station Flow @ Test | Estimate during visit        |
| Note for Pump Start Type          | Slow start, variable speed   |

| Generator Information  |                        |
|------------------------|------------------------|
| Make/Model:            | Olympian (Caterpillar) |
| Interior/Exterior:     | Interior               |
| Gen. Installation Date | 2001                   |
| Size, KW:              | 100                    |
| Fuel Type:             | Natural Gas            |



| Controls Information    |  |
|-------------------------|--|
| Pump Control Sequence:  | Controls start and stop the pumps in an alternating Lead/Lag/Standby sequence based on wet well level setpoints. If lead pump fails to start, Lag pump starts. If level rises above Lag start both will run. |
| Pump Control Panel:     | Combination Control and Power Panel by Gorman Rupp, separate MCC panels for VFDs   |
| Installation Date:      | 2001   |
| Control Type:           | PLC based  |
| Location:               | Within pump station building   |
| SCADA Connectivity:     | Radio, RTU to master MTU connection to SCADA. City will be connecting this pump station to microwave in the near future.   |
| Level & Alarm Controls: | Gorman-Rupp Pump Control Panel   |
| Type:                   | Air bubbler (Gorman Rupp original - primary), submersible pressure transducer (secondary), differential level floats (backup)  |
| Backup Alarm            | High-high, low-low level floats  |
| Flow Meter Make/Model:  | 6" Krohne Magnetic Flow Meter  |
| Alarm Transmission:     | All pump station alarms transferred via radio (existing) to WWTF SCADA, nearterm transition to microwave   |
| Pump Motor Starters :   | Allen Bradley 30 hp VFD  |

**City of Portsmouth, New Hampshire  
SUCTION LIFT Pump Station Evaluation  
Corporate Drive**

*Last Update:* 10/26/2018

*By:* MAC

*This Update:*

*By:* W-P

| Mechanical         |                                    |               |                                    |
|--------------------|------------------------------------|---------------|------------------------------------|
| Heating:           |                                    | Ventilation:  | Generator                          |
| Type:              | Gas Unit heater, Wall mount (2018) | System        | Louvers and Damper                 |
| Size, kW:          | Unk. Quantity: 1                   | Size:         | 54"x54" (exhaust) 72"x66" (intake) |
| Make/Model:        | Modine Hot Dawg                    | Make & Model: | -                                  |
| Odor Control :     | None                               | Ventilation:  | Building                           |
| City Water Supply: | 3/4" water supply with RPZ BFP     | Exhaust Fan:  | Penn Model 40340, 1 PH, 1/2 HP     |
|                    |                                    | L&D:          | Yes                                |

| Energy Efficiency Information   |
|---|
| Based on pump information gathered from the pump manufacturer's website, pumps are operating at full speed between 55-60% efficiency depending on the sheave configuration. It must be noted that the pump belt/sheave configuration was unknown, which may change the operating efficiency conclusion. |

| Condition of Equipment/Identified Issues   |                      |           |         |  |                  |    |           |  |                 |    |        |  |                     |    |           |  |
|--|----------------------|-----------|---------|--|------------------|----|-----------|--|-----------------|----|--------|--|---------------------|----|-----------|--|
| <p><u>Capacity:</u><br/>Recent capacity assessment via flow meter observation on 4/3/18 indicated that all three pumps are operating at relatively the same capacity 930 gpm (58 ft TDH). The reported duty point of these pumps was reported as 600 gpm (84 ft TDH). Based on this evaluation the pumps are operating against a lower pressure and as a result, producing higher flowrates. It must be noted that no information was available regarding the belt and sheave setup, which could lead to a different duty point pump capacity. The station appears to have adequate capacity to handle existing flows as, each pump runs for less than 20 minutes per day on average. Under peak conditions, each pump can operate for as much as an hour per day indicating that the pump station is operating well under the total capacity.</p> |                      |           |         |  |                  |    |           |  |                 |    |        |  |                     |    |           |  |
| <p><u>Exterior Site:</u><br/>The station is located in a commercial section of Pease Development with a dedicated access driveway. No site issues were noted.</p>  |                      |           |         |  |                  |    |           |  |                 |    |        |  |                     |    |           |  |
| <p><u>Building Structures (if applicable):</u><br/>The pump station Building was constructed in (2001). All exterior surfaces were observed to be in fair condition. Masonry appears to be in good condition with no observed deficiencies. The gable end of the buildings should be planned to be reprimed/painted within the next 5 years. The shingled roof is in good condition but the City should plan on replacement/repair in 8-10 years. Interior masonry surfaces are in good condition with no observed deficiencies.</p>   |                      |           |         |  |                  |    |           |  |                 |    |        |  |                     |    |           |  |
| <p><u>Wet Well:</u><br/>Top surface of the concrete top slab appears to be in fair to good condition with no observed structural deficiencies.</p>   |                      |           |         |  |                  |    |           |  |                 |    |        |  |                     |    |           |  |
| <p><u>Electrical/Instrumentation:</u><br/>The existing electrical distribution equipment at the pump station is new and in good condition. While the existing bubbler level instrument remains in-use, the City should consider replacement with a submersible pressure transducer once the instrument needs to be replaced. The Control Panel is controlled by Allen Bradley PLC's which are no longer actively supported (SLC 5/05) and can be difficult to find replacements for. It is recommended that the City replace the existing SLC 5/05 components with more updated PLC products (i.e., Micrologix 1200) which are actively supported by the manufacturer.</p>   |                      |           |         |  |                  |    |           |  |                 |    |        |  |                     |    |           |  |
| <p><u>HVAC:</u><br/>Ventilation and heating equipment are operational and in good condition. The emergency generator exhaust piping should be insulated for safety. The building wall sleeve for the generator exhaust penetration should be equipped with a ventilated wall thimble to prevent wall damage.</p>   |                      |           |         |  |                  |    |           |  |                 |    |        |  |                     |    |           |  |
| <p><u>Security Measures:</u><br/>There is no fire alarm or security system in the building. There is no gas detection system in this station, as it is not required.</p>   |                      |           |         |  |                  |    |           |  |                 |    |        |  |                     |    |           |  |
| <p><u>Summary of Previous Reports</u><br/>Not applicable.</p>  |                      |           |         |  |                  |    |           |  |                 |    |        |  |                     |    |           |  |
| <p><u>Other:</u></p>   |                      |           |         |  |                  |    |           |  |                 |    |        |  |                     |    |           |  |
| <p><u>Miscellaneous Issues:</u></p> <table border="1"> <tbody> <tr> <td>Grease Accumulation?</td> <td>No</td> <td>Source:</td> <td></td> </tr> <tr> <td>Clogging Issues?</td> <td>No</td> <td>Describe:</td> <td></td> </tr> <tr> <td>Nuisance Odors?</td> <td>No</td> <td>Cause:</td> <td></td> </tr> <tr> <td>Concrete Corrosion?</td> <td>No</td> <td>Location:</td> <td></td> </tr> </tbody> </table>  | Grease Accumulation? | No        | Source: |  | Clogging Issues? | No | Describe: |  | Nuisance Odors? | No | Cause: |  | Concrete Corrosion? | No | Location: |  |
| Grease Accumulation?   | No                   | Source:   |         |  |                  |    |           |  |                 |    |        |  |                     |    |           |  |
| Clogging Issues?   | No                   | Describe: |         |  |                  |    |           |  |                 |    |        |  |                     |    |           |  |
| Nuisance Odors?  | No                   | Cause:    |         |  |                  |    |           |  |                 |    |        |  |                     |    |           |  |
| Concrete Corrosion?  | No                   | Location: |         |  |                  |    |           |  |                 |    |        |  |                     |    |           |  |

**City of Portsmouth, New Hampshire  
SUCTION LIFT Pump Station Evaluation**

**Griffin Park**

Last Update: 10/26/2018 By: MAC

This Update: By: W-P

| General Pump Station Information                               |                               |
|--|-------------------------------|
| Location:  | 205 Griffin Park              |
| Pump Station Finished Floor Elevation, ft.:                    | 37.75                         |
| Coastal Resiliency Flood Elevation (2050 High Emissions), ft.: | 13.5                          |
| Distance from WWTF (straightline), miles:                      | 3                             |
| Year Constructed/Upgraded:                                     | 1990                          |
| Station Type:  | Gorman-Rupp suction-lift      |
| Wet Well Diameter, ft.:  | 8                             |
| Wet Well Volume, gal/ft  | 376                           |
| No. of Pumps:  | 2                             |
| Pump Installation Date:  | 1990                          |
| Design Operating Point, 1 Pump                                 |                               |
| Flow, gpm:   | 200                           |
| Total Dynamic head, ft.:                                       | 40                            |
| Pump Make/Model:   | T4A3/S-B (Classic & Super T)  |
| Self-Priming Method  | Air Purge                     |
| Motor Size, HP:  | 7.5                           |
| Motor/Pump Speed, rpm:   | 1745                          |
| Electrical Service, V/Ph/Hz:                                   | 460/3/60                      |
| Drive Type:  | Belt & Sheave, Constant Speed |
| Belt and Sheave Speed:   | Unknown                       |
| Seal Make & Type:  | G-R , Double Mech Oil Bath    |
| Force Main Diam., in.:   | 6                             |
| Force Main Velocity, feet per sec.:                            | 2.7                           |
| Force Main Type:   | Ductile Iron                  |
| Force Main Age:  | 1990                          |
| Force Main Length, ft.:  | 1200                          |



| Pump Flow and Run Time Information    |            |            |
|---------------------------------------|------------|------------|
|                                       | P1 (1990)  | P2 (2001)  |
| Pump Flow Data (Magnetic Flow Meter)  |            |            |
| Observed Instantaneous Flow, MGD      | 0.35       | 0.32       |
| Pump Runtime Data                     |            |            |
|                                       | Yes        | Yes        |
| Data Start Date                       | 12/1/2014  | 12/1/2014  |
| Data End Date                         | 10/31/2017 | 10/31/2017 |
| Annual Average Flow, GPD (Calculated) | 1807       | 1602       |

| Pump Performance Testing Results  |                            |
|-----------------------------------|----------------------------|
| Date of Test:                     | 2-Apr-18                   |
| Min./Max. VFD Setpoints (Hz)      | N/A                        |
| VFD Speed (Hz)                    | 60 Hz, Constant            |
| Pump RPM                          | 1875                       |
| Drawdown Flow, gpm:               | P1 - 246, P2 - 222         |
| Drawdown TDH, ft.:                | P1 - 21, P2 - 20           |
| Influent Pump Station Flow @ Test | Estimate during visit      |
| Note for Pump Start Type          | Slow start, constant speed |

| Generator Information  |                    |
|------------------------|--------------------|
| Make/Model:            | Cummins Onan       |
| Interior/Exterior:     | Interior           |
| Gen. Installation Date | 1990 (ATS is 2009) |
| Size, KW:              | 30                 |
| Fuel Type:             | Natural Gas        |



| Controls Information    |   |
|-------------------------|---|
| Pump Control Sequence:  | Controls start and stop the pumps in an alternating Lead/ Lag sequence based on wet well level setpoints. If lead pump fails to start, Lag pump starts. If level rises above Lag start both will run. |
| Pump Control Panel:     | MCC for starters, separate Control Panel (Electrical Installations, Inc.) for Alarm and Level Control Panel   |
| Installation Date:      | 1990 (Motor Control Center), 2005 (Control Panel)   |
| Control Type:           | PLC-based   |
| Location:               | Within main pump station, dry well  |
| SCADA Connectivity:     | Yes, microwave RTU  |
| Level & Alarm Controls: | PLC Based Control Panel (2005)  |
| Type:                   | Submersible transducer (primary), differential level floats (secondary)   |
| Backup Alarm            | High-high, low-low level floats   |
| Flow Meter Make/Model:  | Fischer Porter 4" Mag. Flow Meter on Discharge Header   |
| Alarm Transmission:     | All pump station alarms transferred via radio (existing) to WWTF SCADA, equipment in place to transition to microwave   |
| Pump Motor Starters :   | Motor starters in original GR Control Panel (1990)  |

**City of Portsmouth, New Hampshire  
SUCTION LIFT Pump Station Evaluation**

**Griffin Park**

*Last Update:* 10/26/2018 *By:* MAC

*This Update:* *By:* W-P

| Mechanical         |                                    |               |                         |
|--------------------|------------------------------------|---------------|-------------------------|
| Heating:           |                                    | Ventilation:  | Generator               |
| Type:              | Gas Unit heater, Wall mount (2016) | System:       | Louvers and Damper      |
| Size, kW:          | Unk. Quantity: 1                   | Size:         | Qty: 1-intake 1-exhaust |
| Make/Model:        | Modine Hot Dawg                    | Make & Model: | Unk.                    |
| Odor Control :     | None                               | Ventilation:  | Building                |
| City Water Supply: | 3/4" water supply with RPZ BFP     | Exhaust Fan:  | None                    |
|                    |                                    | L&D:          | -                       |

**Energy Efficiency Information**

Based on pump information gathered from the pump manufacturer's website, both pumps are operating at less than 40% efficiency depending on the sheave configuration. It must be noted that the pump belt/sheave configuration was unknown, which may change the operating efficiency conclusion. The low efficiency is typical for this type of pump.

| Condition of Equipment/Identified Issues  |    |           |  |
|---|----|-----------|--|
| <u>Capacity:</u><br>Recent capacity assessment via flow meter observation on 4/2/18 indicated that all three pumps are operating between 220-250 gpm (20 ft TDH). The reported duty point of these pumps was reported as 200 gpm (40 ft TDH). Based on this evaluation the pumps are operating against a lower pressure and as a result, producing higher flowrates. It must be noted that no information was available regarding the belt and sheave setup, which could lead to a different duty point pump capacity. The station appears to have adequate capacity to handle existing flows as, each pump runs for less than 10 minutes per day on average. Under peak conditions, each pump can operate for as much as 1.5 hours per day indicating that the pump station is operating well under the total capacity.  |    |           |  |
| <u>Exterior Site:</u><br>The pump station is located in a commercial district. No site issues were noted.   |    |           |  |
| <u>Building Structures (if applicable):</u><br>The pump station was constructed in 1990. The Exterior building split rib masonry surfaces appear to be in fair condition with some staining of the masonry in the bottom several feet. The concrete foundation is cracked near the entrance pad. Exterior wood trim surfaces exhibit dried, faded, and peeling paint and should be reprimed/repainted. The roof is in good condition but is approaching the end of its useful life. The wood soffit is coming apart on one side of the building. Interior masonry surfaces appear to be in good condition with no observed deficiencies.  |    |           |  |
| <u>Wetwell:</u><br>The interior concrete surfaces are in good condition with no significant observed deficiencies. Some leakage is evident at isolated locations in a few joints. The top side of the top slab appears to be in good condition with minimal to no spalling or exposed aggregate. The suction pipes show signs of limited corrosion, but are still in good operating condition. The discharge pipe which penetrates through the wet well is severely corroded and the pipe support bracket has been broken. It is recommended that this discharge pipe is replaced and redirected so that the force main does not route under the building foundation.   |    |           |  |
| <u>Dry Well (if applicable):</u> See Building Structure section.  |    |           |  |
| <u>Electrical/Instrumentation:</u><br>The existing electrical distribution equipment at the pump station was installed in 1990 is approaching the end of its useful design life. Many of the components are obsolete, or will become obsolete within the next 5-10 years. Low priority consideration should be given to a comprehensive electrical upgrade including panelboards, emergency power equipment, and other ancillary electrical components. It is recommended that the City install emergency lighting and provide arch-flash safety labeling.<br><br>The Control Panel (2005) is in good condition and has an estimated lifespan of approximately 20-years. The City should plan to replace the control panel or the major components based on this timeframe or during the next major pump station upgrade. |    |           |  |
| <u>HVAC:</u><br>The electric unit heater and are in good condition. No ventilation is provided for the space. In order to adhere to HVAC code requirements the Town should installed a mechanism to hold the door open when the pump station is occupied. While not required, a ventilated exhaust wall thimble should be considered to avoid continued wall damage.  |    |           |  |
| <u>Security Measures:</u><br>There is no active security system in the building. A smoke detector appears to be wired to the Control Panel for alarming. There is no gas detection system in this station, as it is not required.   |    |           |  |
| <u>Summary of Previous Reports</u><br>The 201 Facilities Plan Update (Underwood Engineers, 1999) indicated that the pump station was in good condition and had adequate capacity.   |    |           |  |
| <u>Other:</u>   |    |           |  |
| <u>Miscellaneous Issues:</u>  |    |           |  |
| Grease Accumulation?  | No | Source:   |  |
| Clogging Issues?  | No | Describe: |  |
| Nuisance Odors?   | No | Cause:    |  |
| Concrete Corrosion?   | No | Location: |  |

**City of Portsmouth, New Hampshire  
SUCTION LIFT Pump Station Evaluation**

**Tuckers Cove**

Last Update: 10/29/2018 By: MAC

This Update: By:

| General Pump Station Information                              |                               |
|---|-------------------------------|
| Location:   | 91 Gosport Rd.                |
| Pump Station Finished Floor Elevation, ft.:                   | 19.5                          |
| Coastal Resiliency Flood Elevation (2050 High Emissions), ft: | 13.5                          |
| Distance from WWTF (straightline), miles:                     | 2                             |
| Year Constructed/Upgraded:                                    | 1998                          |
| Station Type:   | Gorman-Rupp suction-lift      |
| Wet Well Diameter, ft:  | 8                             |
| Wet Well Volume, gal/ft                                       | 376                           |
| No. of Pumps:   | 2                             |
| Pump Installation Date:                                       | 1998                          |
| Design Operating Point, 1 Pump                                |                               |
| Flow, gpm:  | 280                           |
| Total Dynamic head, ft.:                                      | 33                            |
| Pump Make/Model:  | T4A3-B                        |
| Self-Priming Method   | Air Purge                     |
| Motor Size, HP:   | 15                            |
| Motor/Pump Speed, rpm:  | 1780/1125                     |
| Electrical Service, V/Ph/Hz:                                  | 460/3/60                      |
| Drive Type:   | Belt & Sheave, Constant Speed |
| Belt and Sheave Speed:  | Unknown                       |
| Seal Make & Type:   | GR Double Mechanical Oil      |
| Force Main Diam., in.:  | 6                             |
| Force Main Velocity, feet per sec.:                           | 2.7                           |
| Force Main Type:  | Ductile Iron                  |
| Force Main Age:   | 1998 (est.)                   |
| Force Main Length, ft.:                                       | 1450                          |



| Pump Flow and Run Time Information    |            |            |
|---------------------------------------|------------|------------|
|                                       | P1         | P2         |
| Pump Flow Data (Magnetic Flow Meter)  |            |            |
| Observed Instantaneous Flow, MGD      | 0.35       | 0.34       |
| Pump Runtime Data                     |            |            |
| Data Start Date                       | 12/1/2014  | 12/1/2014  |
| Data End Date                         | 10/31/2017 | 10/31/2017 |
| Annual Average Flow, GPD (Calculated) | 4766       | 4860       |



| Pump Performance Testing Results  |                            |
|-----------------------------------|----------------------------|
| Date of Test:                     | 2-May-18                   |
| Min./Max. VFD Setpoints (Hz)      | N/A                        |
| VFD Speed (Hz)                    | 60 Hz, Constant            |
| Pump RPM                          | 1765                       |
| Drawdown Flow, gpm:               | P1 - 243, P2 - 233         |
| Drawdown TDH, ft:                 | P1 - 18.5, P2 - 24         |
| Influent Pump Station Flow @ Test | Estimate during visit      |
| Note for Pump Start Type          | Slow start, constant speed |



| Generator Information  |                 |
|------------------------|-----------------|
| Make/Model:            | Cummins Onan    |
| Interior/Exterior:     | Interior        |
| Gen. Installation Date | 1998 (ATS 2015) |
| Size, KW:              | 45              |
| Fuel Type:             | Propane         |

| Controls Information    |   |
|-------------------------|---|
| Pump Control Sequence:  | Controls start and stop the pumps in an alternating Lead/ Lag sequence based on wet well level setpoints. If lead pump fails to start, Lag pump starts. If level rises above Lag start both will run. |
| Pump Control Panel:     | MCC for starters, separate Control Panel (Electrical Installations, Inc.) for Alarm and Level Control Panel   |
| Installation Date:      | 1998 (Motor Control Center), 2004 (Control Panel)   |
| Control Type:           | PLC-based   |
| Location:               | Within main pump station, dry well  |
| SCADA Connectivity:     | Yes, microwave RTU  |
| Level & Alarm Controls: | PLC Based Control Panel (2004)  |
| Type:                   | Ultrasonic transducer (primary), differential level floats (secondary)  |
| Backup Alarm            | High-high, low-low level floats   |
| Flow Meter Make/Model:  | Fischer Porter 4" Mag. Flow Meter on Discharge Header   |
| Alarm Transmission:     | All pump station alarms transferred via radio (existing) to WWTF SCADA, equipment in place to transition to   |
| Pump Motor Starters :   | Motor starters in original GR Control Panel (1990)  |

**City of Portsmouth, New Hampshire  
SUCTION LIFT Pump Station Evaluation**

**Tuckers Cove**

Last Update: 10/29/2018 By: MAC

This Update: By:

| Mechanical         |                                |               |                                |
|--------------------|--------------------------------|---------------|--------------------------------|
| Heating:           |                                | Ventilation:  | Generator                      |
| Type:              | Gas Unit heater, Wall mount    | System:       | Louvers and Damper             |
| Size, kW:          | Unk. Quantity: 1               | Size:         | Qty: 1-exhaust                 |
| Make/Model:        | Modine                         | Make & Model: | Unk.                           |
| Odor Control :     | None                           | Ventilation:  | Building                       |
| City Water Supply: | 3/4" water supply with RPZ BFP | Exhaust Fan:  | FRP Prop Fan, occupancy linked |
|                    |                                | L&D:          | Yes, automatic                 |

| Energy Efficiency Information   |
|---|
| Based on pump information gathered from the pump manufacturer's website, both pumps are operating at less than 40% efficiency depending on the sheave configuration. It must be noted that the pump belt/sheave configuration was unknown, which may change the operating efficiency conclusion. The low efficiency is typical for this type of pump. |

| Condition of Equipment/Identified Issues   |                      |           |  |  |                  |    |           |  |                 |    |        |  |                     |    |           |  |
|--|----------------------|-----------|--|--|------------------|----|-----------|--|-----------------|----|--------|--|---------------------|----|-----------|--|
| <p><b>Capacity:</b><br/>Recent capacity assessment via flow meter observation on 4/2/18 indicated that all three pumps are operating between 230-240 gpm (18-24 ft TDH). The reported duty point of these pumps was reported as 280 gpm (33 ft TDH). It must be noted that no information was available regarding the belt and sheave setup, which could lead to a different duty point pump capacity. The station appears to have adequate capacity to handle existing flows as, each pump runs for approximately 20 minutes per day on average. Under peak conditions, each pump can operate for as much as 1 hour per day indicating that the pump station is operating well under the total capacity.</p>  |                      |           |  |  |                  |    |           |  |                 |    |        |  |                     |    |           |  |
| <p><b>Exterior Site:</b><br/>The station pump station is located in a residential neighborhood and can be accessed via a long dedicated paved driveway. No issues were noted for the exterior site.</p>  |                      |           |  |  |                  |    |           |  |                 |    |        |  |                     |    |           |  |
| <p><b>Building Structures (if applicable):</b><br/>The pump station was constructed in 1998. Exterior surfaces are in fair to good condition structurally. The bottom 2 courses of masonry are stained, potentially due to moisture/mold working up from the ground. Exterior wood trim surfaces exhibit dried, faded, and peeling paint and should be reprimed/repainted. Asphalt shingles are near the end of their useful life, are curled and weathered, and in need of replacement. Efflorescence can be seen on the inside face of masonry in the vicinity of the generator intake louver. It appears that a sealant was not installed or has failed and is allowing water to migrate into the building. Aesthetically, the interior surfaces of masonry should be pressurewashed and sealed or painted.</p> |                      |           |  |  |                  |    |           |  |                 |    |        |  |                     |    |           |  |
| <p><b>Wet Well:</b><br/>The top surface of the top slab appears to be in good condition with no observed deficiencies. The steel closure arm is corroded and detached from the hatch. This should be completely removed for safety during confined space entry. Interior concrete surfaces are in good condition with no observed deficiencies.</p>  |                      |           |  |  |                  |    |           |  |                 |    |        |  |                     |    |           |  |
| <p><b>Dry Well (if applicable):</b> See Building Structure section.</p>  |                      |           |  |  |                  |    |           |  |                 |    |        |  |                     |    |           |  |
| <p><b>Electrical/Instrumentation:</b><br/>The existing electrical distribution equipment at the pump station was installed in 1998. Many of the components will become obsolete within the next 10-15 years. Low priority consideration should be given to a comprehensive electrical upgrade including panelboards, emergency power equipment, and other ancillary electrical components. It is recommended that the City install emergency lighting and provide arc-flash safety labeling.<br/><br/>The Control Panel (2004) is in good condition and has an estimated lifespan of approximately 20-years. The City should plan to replace the control panel or the major components based on this timeframe or during the next major pump station upgrade.</p>  |                      |           |  |  |                  |    |           |  |                 |    |        |  |                     |    |           |  |
| <p><b>HVAC:</b><br/>The propane unit heater and exhaust fan/damper assemblies are in good condition. The pump station exhaust fan and associated dampers operates when the station is occupied. This existing control arrangement is not required by code, but is considered good practice. The emergency generator exhaust pipe was observed to not be insulated through the wall. While not required, a ventilated exhaust wall thimble should be considered to avoid continued wall damage.</p>   |                      |           |  |  |                  |    |           |  |                 |    |        |  |                     |    |           |  |
| <p><b>Security Measures:</b><br/>There is no active security system in the building. There is no gas detection system in this station, as it is not required.</p>  |                      |           |  |  |                  |    |           |  |                 |    |        |  |                     |    |           |  |
| <p><b>Summary of Previous Reports</b><br/>The 201 Facilities Plan Update (Underwood Engineers, 1999) indicated that pump station was relatively newer PS and does not receive elevated flows.</p>  |                      |           |  |  |                  |    |           |  |                 |    |        |  |                     |    |           |  |
| <p><b>Other:</b></p>   |                      |           |  |  |                  |    |           |  |                 |    |        |  |                     |    |           |  |
| <p><b>Miscellaneous Issues:</b></p> <table border="1"> <tbody> <tr> <td>Grease Accumulation?</td> <td>Yes</td> <td>Source:</td> <td>Possible restaurant sources (Atlantic Grill)</td> </tr> <tr> <td>Clogging Issues?</td> <td>No</td> <td>Describe:</td> <td></td> </tr> <tr> <td>Nuisance Odors?</td> <td>No</td> <td>Cause:</td> <td></td> </tr> <tr> <td>Concrete Corrosion?</td> <td>No</td> <td>Location:</td> <td></td> </tr> </tbody> </table>   | Grease Accumulation? | Yes       | Source:                                      | Possible restaurant sources (Atlantic Grill) | Clogging Issues? | No | Describe: |  | Nuisance Odors? | No | Cause: |  | Concrete Corrosion? | No | Location: |  |
| Grease Accumulation?   | Yes                  | Source:   | Possible restaurant sources (Atlantic Grill) |  |                  |    |           |  |                 |    |        |  |                     |    |           |  |
| Clogging Issues?   | No                   | Describe: |  |  |                  |    |           |  |                 |    |        |  |                     |    |           |  |
| Nuisance Odors?  | No                   | Cause:    |  |  |                  |    |           |  |                 |    |        |  |                     |    |           |  |
| Concrete Corrosion?  | No                   | Location: |  |  |                  |    |           |  |                 |    |        |  |                     |    |           |  |

## **SUBMERSIBLE EVALUATION FORMS**

**City of Portsmouth, New Hampshire  
SUBMERSIBLE Pump Station Evaluation**

**Clough Drive**

*Last Update:* 7/17/2018

*By:* MAC

*This Update:*

*By:*

| General Pump Station Information                               |                                 |
|--|---------------------------------|
| Location:  | 210 Clough Drive                |
| Pump Station Finished Floor Elevation, ft.:                    | 14                              |
| Coastal Resiliency Flood Elevation (2050 High Emissions), ft.: | 13.5                            |
| Distance from WWTF (straightline), miles:                      | 0.7                             |
| Year Constructed/Upgraded:                                     | Constructed: 2002               |
| Station Type:  | Flygt Submersible grinder pumps |
| Wet Well Diameter, ft.:  | 8                               |
| Wet Well Volume, gal/ vertical ft                              | 376                             |
| No. of Pumps:  | 2                               |
| Pump Installation Date:  | 2002                            |
| Design Operating Point, 1 Pump                                 |                                 |
| Flow, gpm:   | 55                              |
| Total Dynamic head, ft.:                                       | 45                              |
| Pump Make/Model:   | ITT-FLYGT M3068-1770            |
| Motor Size, HP:  | 2.3                             |
| Motor/Pump Speed, rpm:   | Motor: 3,325                    |
| Electrical Service, V/Ph/Hz:                                   | 230/1/60                        |
| Drive Type:  | Direct Drive, Constant Speed    |
| Seal Make & Type:  | Double mechanical               |
| Force Main Diam., in.:   | 2                               |
| Force Main Velocity, feet per sec.:                            | 3.7                             |
| Force Main Type:   | PVC, SDR 21                     |
| Force Main Age:  | 2002                            |
| Force Main Length, ft.:  | 504                             |



| Pump Flow and Run Time Information    |            |            |
|---------------------------------------|------------|------------|
|                                       | P1         | P2         |
| Pump Runtime Data                     | Yes        | Yes        |
| Assumed Pump Flowrate, GPM            | 55         | 55         |
| Data Start Date                       | 12/1/2014  | 1/1/2014   |
| Data End Date                         | 10/31/2017 | 10/31/2017 |
| Annual Average Flow, GPD (Calculated) | 1042       | 2107       |



| Pump Performance Testing Results  |                                |
|-----------------------------------|--------------------------------|
| Date of Test:                     | 29-Apr-18                      |
| Min./Max. VFD Setpoints (Hz)      | N/A - Full Speed               |
| VFD Speed (Hz)                    | N/A - Constant Speed           |
| Pump RPM                          |                                |
| Drawdown Flow, gpm:               | P1 - 31, P2 - 41               |
| Drawdown TDH, ft.:                | N/A                            |
| Influent Pump Station Flow @ Test | Estimate during visit, < 5 gpm |
| Note for Pump Start Type          | Constant speed                 |



| Generator Information  |                               |
|------------------------|-------------------------------|
| Make/Model:            | N/A                           |
| Interior/Exterior:     | N/A                           |
| Gen. Installation Date | N/A                           |
| Size, KW:              | N/A                           |
| Fuel Type:             | Portable generator connection |

| Controls Information    |   |
|-------------------------|---|
| Pump Control Sequence:  | Controls start and stop the pumps in an alternating Lead/ Lag sequence based on wet well level setpoints. If Lead pump fails to start, Lag pump starts. If level rises above Lag start both will run. |
| Pump Control Panel:     | Motor Starter Panel (Flygt), separate adjacent PLC Control Panel  |
| Installation Date:      | 2003  |
| Control Type:           | PLC Based   |
| Location:               | Inside a NEMA 4X weatherproof cabinet   |
| SCADA Connectivity:     | Yes, microwave RTU  |
| Level & Alarm Controls: | PLC Based Control Panel   |
| Type:                   | Submersible transducer (primary)  |
| Backup Alarm            | High float level switch   |
| Flow Meter Make/Model:  | Not installed   |
| Alarm Transmission:     | All pump station alarms transferred via radio (existing) to WWTF SCADA, equipment in place to transition to microwave   |
| Pump Motor Starters :   | Square D motor starters in Flygt Control Panel (2002)   |

**City of Portsmouth, New Hampshire  
SUBMERSIBLE Pump Station Evaluation**

**Clough Drive**

*Last Update:* 7/17/2018      *By:* MAC  
*This Update:*                                      *By:*

| Mechanical         |   |               |      |
|--------------------|---|---------------|------|
| Heating:           |   | Ventilation:  | None |
| Type:              | Electrical cabinet unit heater                            | System        | -    |
| Size:              | 200 watt                                      Quantity: 1 | Size:         | -    |
| Make/Model:        | Unk.  | Make & Model: | -    |
| Odor Control :     | None  | Ventilation:  | -    |
| City Water Supply: | None  | Exhaust Fan:  | -    |
|                    |   | L&D:          | -    |

**Energy Efficiency Information**

Based on an assumed pump model, the submersible grinder pumps operate at < 25% efficiency due to the small pump size and the type of grinder impeller utilized. Due to the low HP requirements of this station, this pump efficiency is considered to be typical for this type of pump and is not considered detrimental to pump station operation.

| Condition of Equipment/Identified Issues   |     |           |   |
|--|-----|-----------|---|
| <u>Capacity:</u><br>Capacity assessment via drawdown testing on 4/29/18 indicated the pumps have the following capacities: P1 - 31 gpm and P2 - 41 gpm. The current pumping rate of P1 and P2 is less than the original pump design operating point (55 gpm @ 45-ft TDH). Based on pump runtime data, the station appears to have adequate capacity to handle existing flows. Each pump runs for about 50 minutes per day on average, but under peak conditions, both pumps may run a combined total of as much as 21 hours per day.   |     |           |   |
| <u>Exterior Site:</u><br>The pump station is located adjacent to a school with the Control/Power enclosure located within a fenced in area. The wet well and valve vault are located outside of the fence adjacent to a roadway. The valve vault and wet well access hatch are located in a grassed area exposed to the roadway without bollard protection and show signs of plow damage. The City indicated that during the winter, the area of the valve vault and wet well hatch are used to pile snow from the adjacent roadway, causing flooding issues at the valve vault. The City should consider plow/vehicle protection of the wet well/valve vault (i.e., bollards) or further measures to expand the fenced area to include the valve vault/wet well to mitigate snow accumulation on the hatches. |     |           |   |
| <u>Building Structures (if applicable):</u><br>Not applicable  |     |           |   |
| <u>Wet Well:</u><br>The wet well was observed to be in good condition due to tri- yearly cleaning. The wet well hatch was observed to be in good condition but does not have a safety net/hatch grating. The PVC piping was in good condition. The wet well has mild grease accumulation on the wet well walls and power cables. The wet well is vented with a 4-inch PVC vent routed to vent immediately adjacent to the Control/Power panel.   |     |           |   |
| <u>Dry Well (if applicable):</u> Not applicable.   |     |           |   |
| <u>Valve Pit (if applicable):</u> The concrete valve vault consists of a 30-inch square access hatch, 2-inch check valves and resilient gate valves. During the site visit, the valve pit was completely flooded with water. The City indicated the valve vault floods in the winter when snow from the adjacent school parking lots are piled up in the area of the pump station wet well and valve pit. The valve pit does not contain a valve vault drain back to the wet well.   |     |           |   |
| <u>Electrical/Instrumentation:</u><br>The pad mounted electrical cabinet houses the pump station's motor starter panel, control panel, electrical disconnects, alarm bell and light. The wet well level instruments are operational, but the City should plan to replace them within the next 5 years to maintain reliability.   |     |           |   |
| <u>HVAC:</u><br>Not applicable.  |     |           |   |
| <u>Security Measures:</u><br>The pump station is situated adjacent to a school. The electrical and control panels are situated in a locked fenced area. The valve vault and wet well hatches are out in the open and were not locked upon site inspection. It is recommended that these hatches remain locked at all times.  |     |           |   |
| <u>Portsmouth Coastal Resilience Initiative Report:</u>  |     |           |   |
| <u>Emergency Procedures:</u><br>Pump Station : If main power is lost, the City can either 1) connect a gas powered mobile emergency generator to power the pump station, or 2) use the City's vac truck to empty the pump station wet well daily or as-needed. The pump station has substantial wet well capacity to accommodate short term power outages. Per NHDES regulations, the City is allowed to utilize wet well storage with an emergency generator receptacle for sewage pumping stations with a capacity of 100-GPM or less.   |     |           |   |
| <u>Force Main Bypass:</u> The City would rely on a vacuum truck if the force main required bypassing.  |     |           |   |
| <u>Summary of Previous Reports</u><br>Clough Drive was not evaluated as part of the 201 Facilities Plan Update (Underwood Engineers, 1999).  |     |           |   |
| <u>Other:</u>  |     |           |   |
| <u>Miscellaneous Issues:</u>   |     |           |   |
| Grease Accumulation?   | Yes | Source:   | Residential grease from Clough Dr and Bracket Rd houses |
| Clogging Issues?   | No  | Describe: |   |
| Nuisance Odors?  | No  | Cause:    |   |
| Concrete Corrosion?  | No  | Location: |   |

**City of Portsmouth, New Hampshire  
SUBMERSIBLE Pump Station Evaluation  
Marsh Ln. (Dearborn Place)**

Last Update: 8/26/2018  
This Update:

By: MAC  
By:

| General Pump Station Information                               |   |
|--|---|
| Location:  | 4 Marsh Lane  |
| Pump Station Finished Floor Elevation, ft.:                    | 5.9   |
| Coastal Resiliency Flood Elevation (2050 High Emissions), ft.: | 13.5  |
| Distance from WWTF (straightline), miles:                      | 1.4   |
| Year Constructed/Upgraded:                                     | Constructed: 1985<br>Pump and Control Panel Upgrade: 2004 |
| Station Type:  | Flygt Submersible grinder pumps                           |
| Wet Well Diameter, ft.:  | 6   |
| Wet Well Volume, gal/ft  | 211   |
| No. of Pumps:  | 2   |
| Pump Installation Date:  | 2004  |
| Design Operating Point, 1 Pump                                 |   |
| Flow, gpm:   | 55  |
| Total Dynamic head, ft.:                                       | 40  |
| Pump Make/Model:   | ITT-FLYGT M3068   |
| Motor Size, HP:  | 2.3   |
| Motor/Pump Speed, rpm:   | Motor: 3,325  |
| Electrical Service, V/Ph/Hz:                                   | 230/1/60  |
| Drive Type:  | Direct Drive, Constant Speed                              |
| Seal Make & Type:  | Double mechanical   |
| Force Main Diam., in.:   | 2   |
| Force Main Velocity (observed), feet per sec.:                 | 3.5   |
| Force Main Type:   | PVC   |
| Force Main Age:  | 1985  |
| Force Main Length, ft.:  | 463   |

| Pump Flow and Run Time Information    |            |            |
|---------------------------------------|------------|------------|
|                                       | P1         | P2         |
| Pump Runtime Data                     | Yes        | Yes        |
| Data Start Date                       | 12/1/2014  | 12/1/2014  |
| Data End Date                         | 10/31/2017 | 10/31/2017 |
| Annual Average Flow, GPD (Calculated) | 1495       | 1777       |

| Pump Performance Testing Results  |                                |
|-----------------------------------|--------------------------------|
| Date of Test:                     | 29-Mar-18                      |
| Min./Max. VFD Setpoints (Hz)      | N/A - Full Speed               |
| VFD Speed (Hz)                    | N/A - Constant Speed           |
| Pump RPM                          |                                |
| Drawdown Flow, gpm:               | P1 - 32, P2 - 37               |
| Drawdown TDH, ft.:                | N/A                            |
| Influent Pump Station Flow @ Test | Estimate during visit, < 5 gpm |
| Note for Pump Start Type          | Constant speed                 |

| Generator Information  |   |
|------------------------|---|
| Make/Model:            | N/A   |
| Interior/Exterior:     | N/A   |
| Gen. Installation Date | N/A   |
| Size, KW:              | N/A   |
| Fuel Type:             | Portable generator connection within electrical enclosure |

| Controls Information    |   |
|-------------------------|---|
| Pump Control Sequence:  | Controls start and stop the pumps in an alternating Lead/ Lag sequence based on wet well level setpoints. If Lead pump fails to start, Lag pump starts. If level rises above Lag start both will run. |
| Pump Control Panel:     | Motor Starter Panel (Flygt), separate adjacent Control Panel (Electrical Installation, Inc)   |
| Installation Date:      | 2004 (Flygt), 2011 (Control Panel)  |
| Control Type:           | PLC Based   |
| Location:               | Exterior enclosure adjacent to wet well   |
| SCADA Connectivity:     | Yes, microwave RTU  |
| Level & Alarm Controls: | PLC Based Control Panel (2011) City reported the UPS for the PLC has been discontinued from service because it caused false SCADA alarms.   |
| Type:                   | Submersible transducer (primary), differential level floats (secondary)   |
| Backup Alarm            | High-high, low-low level floats   |
| Flow Meter Make/Model:  | Not installed   |
| Alarm Transmission:     | All pump station alarms transferred via radio (existing) to WWTF SCADA, equipment in place to transition to microwave   |
| Pump Motor Starters :   | Square D motor starters in Flygt Control Panel (2004)   |



**City of Portsmouth, New Hampshire  
SUBMERSIBLE Pump Station Evaluation  
Marsh Ln. (Dearborn Place)**

*Last Update:* 8/26/2018 *By:* MAC  
*This Update:* *By:*

| Mechanical         |   |               |     |
|--------------------|---|---------------|-----|
| Heating:           |   | Ventilation:  | N/A |
| Type:              | Small portable unit heater in Panel enclosure | System:       | -   |
| Size, kW:          | -   | Quantity:     | 1   |
| Make/Model:        | -   | Make & Model: | -   |
| Odor Control :     | None  | Ventilation:  | N/A |
| City Water Supply: | Hydrant access adjacent to the Pump Station   | Exhaust Fan:  | -   |
|                    |   | L&D:          | -   |

**Energy Efficiency Information**

Based on assumed pump model, the submersible grinder pumps operate at < 25% efficient due to the small pump size and the type of grinder impeller utilized. Due to the low HP requirements of this station, this pump efficiency is considered to be typical for this type of pump and is not considered detrimental to overall pump station operation.

**Condition of Equipment/Identified Issues**

Capacity:  
Capacity assessment via drawdown testing on 3/29/18 indicated the pumps have the following capacities: P1 - 32 gpm and P2 - 37 gpm. These pump are operating below the intended operating point of 55 gpm. The reduced flowrate is potentially due to the 2-inch PVC discharge piping installed on each pump. The station appears to have adequate capacity to handle existing flows, even at reduced pumping capacity, as each pump runs for about 0.75 hours per day on average. Under peak conditions, both pumps may run as much as 10 hours per day.

Exterior Site:  
The pump station wet well and associated hatch are located at a low elevation, less than 50 feet from a tidal inlet to North Mill Pond. During extreme high tidal events, the pump station is close to being submerged and experiences significant infiltration. The City uses sand bags to combat tidal effects with limited success. It is recommended the wet well access hatch and upper concrete section be raised and patched to mitigate flooding concerns. The buoyancy of the structure will need to be analyzed based on the new top of structure elevation. The above-grade wet well should have heavy duty steel bollards installed on the roadside to ensure snow plows do not damage the structure.

Building Structures (if applicable):  
Not applicable.

Wet Well:  
The wet well was observed to be in relatively good condition due to tri- yearly cleaning. The electrical conduit penetrations and upper hatch foundation showed minor cracks with masonry and concrete sections recommended for repair. The wet well hatch was observed to be in good condition. However, if the wet well access level is raised, the City should consider a gasketed watertight hatch with a safety net as a replacement. The City has indicated they plan to raise the elevation of the hatch in the near future to mitigate flooding concerns. The original ductile iron discharge piping was abandoned in place in lieu of the new 2-inch PVC discharge piping with isolation valves within the wet well.

Dry Well (if applicable): Not applicable.

Valve Pit (if applicable): The submersible station does not currently have a valve pit. The submersible pumps have PVC isolation/check valves installed within the wet well. Record drawings from the original pump station design indicate the pump station was formerly equipped with buried isolation valves and a force main bypass located adjacent to the wet well. These features appear to have since been abandoned.

Electrical/Instrumentation:  
The main electrical enclosure and internal equipment (breaker box, manual transfer switch, disconnects, etc.) date back to the original pump station construction and are showing signs of age. The enclosure door latch/handle was broken at the time of the site visit and the enclosure was showing minor signs of ageing (i.e., rusting). In addition, the enclosure has several penetrations which have not been sealed on the cabinet. It is recommended the main electrical distribution enclosure and all associated components be scheduled for replacement within the next 5-7 years. In addition, since the Flygt Control Panel has been discontinued (2004) the float switches and submersible transducers do not have an intrinsically safe barrier as required by the NEC. It is recommended that an intrinsically safe barrier is installed for all wet well instruments.

HVAC:  
Not applicable.

Security Measures:  
The electrical panels and wet well are situated in a residential area with standard door padlock. No security issues were noted.

Emergency Procedures:  
Pump Station : If main power is lost, the City can either 1) connect a gas powered mobile emergency generator to power the pump station, or 2) use the City's vac truck to empty the pump station wet well daily or as-needed. The pump station serves fewer than 5 houses on Marsh Lane and has substantial wet well capacity to accommodate short term power outages. Per NHDES regulations, the City is allowed to utilize wet well storage with an emergency generator receptacle for sewage pumping stations with a capacity of 100-GPM or less.

Force Main Bypass: The City would rely on a vacuum truck if the force main required bypassing.

Summary of Previous Reports  
The 201 Facilities Plan Update (Underwood Engineers, 1999) identified several issues which were addressed with the pump station upgrade in 2004.

Other:

| Miscellaneous Issues: |    |           |   |
|-----------------------|----|-----------|---|
| Grease Accumulation?  | No | Source:   | Grease mitigated significantly by tri-annual cleaning |
| Clogging Issues?      | No | Describe: |   |
| Nuisance Odors?       | No | Cause:    |   |
| Concrete Corrosion?   | No | Location: |   |

**City of Portsmouth, New Hampshire  
SUBMERSIBLE Pump Station Evaluation  
Mill Pond Way (Dearborn Extension)**

Last Update: 7/17/2018  
This Update:

By: MAC  
By:

| General Pump Station Information                               |  |
|--|--|
| Location:  | 131 Mill Pond                                      |
| Pump Station Finished Floor Elevation, ft.:                    | 11.8   |
| Coastal Resiliency Flood Elevation (2050 High Emissions), ft.: | 13.5   |
| Distance from WWTF (straightline), miles:                      | 1.4  |
| Year Constructed/Upgraded:                                     | Constructed: 1985<br>Pumps and Control Panel: 2011 |
| Station Type:  | Flygt Submersible grinder pumps                    |
| Wet Well Diameter, ft.:  | 6  |
| Wet Well Volume, gal/ft  | 211  |
| No. of Pumps:  | 2  |
| Pump Installation Date:  | Installed 2009, rebuilt 2017                       |
| Design Operating Point, 1 Pump                                 |  |
| Flow, gpm:   | 55   |
| Total Dynamic head, ft.:                                       | 40   |
| Pump Make/Model:   | ITT-FLYGT M3068                                    |
| Motor Size, HP:  | 2.3  |
| Motor/Pump Speed, rpm:   | Motor: 3,325                                       |
| Electrical Service, V/Ph/Hz:                                   | 230/1/60   |
| Drive Type:  | Direct Drive, Constant Speed                       |
| Seal Make & Type:  | Double mechanical                                  |
| Force Main Diam., in.:   | 2  |
| Force Main Velocity, feet per sec.:                            | 2.5  |
| Force Main Type:   | PVC  |
| Force Main Age:  | 1985   |
| Force Main Length, ft.:  | 581  |

| Pump Flow and Run Time Information |            |            |
|------------------------------------|------------|------------|
|                                    | P1         | P2         |
| Pump Runtime Data                  | Yes        | Yes        |
| Data Start Date                    | 12/1/2014  | 12/1/2014  |
| Data End Date                      | 10/31/2017 | 10/31/2017 |
| Annual Average Flow, GPD           | 1423.0     | 1459.0     |

| Pump Performance Testing Results  |                                |
|-----------------------------------|--------------------------------|
| Date of Test:                     | 29-Apr-18                      |
| Min./Max. VFD Setpoints (Hz)      | N/A - Full Speed               |
| VFD Speed (Hz)                    | N/A - Constant Speed           |
| Pump RPM                          |                                |
| Drawdown Flow, gpm:               | P1 = 24, P2 = 25               |
| Drawdown TDH, ft.:                | N/A                            |
| Influent Pump Station Flow @ Test | Estimate during visit, < 5 gpm |
| Note for Pump Start Type          | Constant speed                 |

| Generator Information  |                               |
|------------------------|-------------------------------|
| Make/Model:            | N/A                           |
| Interior/Exterior:     | N/A                           |
| Gen. Installation Date | N/A                           |
| Size, KW:              | N/A                           |
| Fuel Type:             | Portable generator connection |



**City of Portsmouth, New Hampshire  
SUBMERSIBLE Pump Station Evaluation  
Mill Pond Way (Dearborn Extension)**

Last Update: 7/17/2018 By: MAC  
This Update: By:

| Controls Information    |   |
|-------------------------|---|
| Pump Control Sequence:  | Controls start and stop the pumps in an alternating Lead/ Lag sequence based on wet well level setpoints. If Lead pump fails to start, Lag pump starts. If level rises above Lag start both will run. |
| Pump Control Panel:     | Combined motor starter and control panel  |
| Installation Date:      | 2009  |
| Control Type:           | PLC Based   |
| Location:               | Inside a common electrical cabinet  |
| SCADA Connectivity:     | Yes, microwave RTU  |
| Level & Alarm Controls: | PLC Based Control Panel   |
| Type:                   | Submersible transducer (primary), differential level floats (secondary)   |
| Backup Alarm            | High-high, low-low level floats   |
| Flow Meter Make/Model:  | Not installed   |
| Alarm Transmission:     | All pump station alarms transferred via radio (existing) to WWTF SCADA, equipment in place to transition to microwave   |
| Pump Motor Starters :   | Motor starters in combined panel  |

| Mechanical         |                               |               |                      |
|--------------------|-------------------------------|---------------|----------------------|
| Heating:           | Enclosure                     | Ventilation:  | Enclosure            |
| Type:              | Small electric cabinet heater | System:       | Electric exhaust fan |
| Size, kW:          | Unk. Quantity: -              | Size:         | Unk.                 |
| Make/Model:        | Unk.                          | Make & Model: | Unk.                 |
| Odor Control :     | None                          | Ventilation:  | -                    |
| City Water Supply: | None                          | Exhaust Fan:  | -                    |
|                    |                               | L&D:          | -                    |

| Energy Efficiency Information  |
|--|
| Based on an assumed pump model, the submersible grinder pumps operate at < 25% efficient due to the small pump size and the type of grinder impeller utilized. Due to the low HP requirements of this station, this pump efficiency is considered to be typical for this type of pump and is not considered detrimental to pump station operation. |

| Condition of Equipment/Identified Issues  |
|---|
| <p><u>Capacity:</u><br/>Capacity assessment via drawdown testing on 3/29/18 indicated the pumps have the following capacities: P1 - 24 gpm and P2 - 25 gpm. These pump are operating below their design operating point of 55 gpm. With both pumps operating at a similar reduced capacity, it is possible that the forcemain may be restricted,. The station appears to have adequate capacity to handle existing flows even with a reduced pumping capacity, as each pump only runs for about 1 hour per day on average. Under peak conditions, both pumps may run as much as 11 hours per day.</p> |
| <p><u>Exterior Site:</u><br/>The station is situated in a grassed lot within a residential neighborhood. The pump station lot is adjacent to North Mill Pond, a tributary pond. The wet well hatch is protected by two light-duty bollards. No issues were noted at the pump station exterior site.</p>   |
| <p><u>Building Structures (if applicable):</u><br/>Not applicable.</p>  |
| <p><u>Wet Well:</u><br/>The wet well was observed to be in good condition due to tri- yearly cleaning. The wet well hatch was observed to be in good condition, but did not have a safety net/hatch grating. The PVC piping and pump check valves were in good condition. There was mild grease accumulation on the wet well. The wet well is vented with a 3-inch galvanized vent routed adjacent to wet well.</p>   |
| <p><u>Dry Well (if applicable):</u> Not applicable.</p>   |
| <p><u>Valve Pit (if applicable):</u> The submersible station does not currently have a valve pit. The submersible pumps have PVC check valves installed within the wet well. The original pump station design included buried isolation valves for each pump, in addition to a force main bypass/flushing connection with buried isolation valves. The valve boxes were observed during the site visit, but the City could not confirm the condition/operability of the buried valves.</p>  |
| <p><u>Electrical/Instrumentation:</u><br/>The electrical service to the service panel is an underground conduit from a nearby utility pole. The main electrical enclosure and equipment (breaker box, manual transfer switch, disconnects, etc.) date back to the original pump station construction and are showing signs of age. It is recommended the main electrical distribution enclosure and all associated components be scheduled for replacement within the next 5-7 years to remain reliable.</p>  |
| <p><u>HVAC:</u><br/>Not applicable.</p>   |
| <p><u>Security Measures:</u><br/>The panel and wet well are situated in a gated area with standard door padlocks. No security issues were noted.</p>  |

**City of Portsmouth, New Hampshire  
SUBMERSIBLE Pump Station Evaluation  
Mill Pond Way (Dearborn Extension)**

*Last Update:* 7/17/2018 *By:* MAC  
*This Update:* *By:*

|  |     |           |                                     |
|--|-----|-----------|-------------------------------------|
| <u>Portsmouth Coastal Resilience Initiative Report:</u>  |     |           |                                     |
| <u>Emergency Procedures:</u>   |     |           |                                     |
| Pump Station : If main power is lost, the City can either 1) connect a gas powered mobile emergency generator to power the pump station, or 2) use the City's vac truck to empty the pump station wet well daily or as-needed. The pump station has substantial wet well capacity to accommodate short term power outages. Per NHDES regulations, the City is allowed to utilize wet well storage with an emergency generator receptacle for sewage pumping stations with a capacity of 100-GPM or less. |     |           |                                     |
| Force Main Bypass: The City would rely on a vacuum truck if the force main required bypassing.   |     |           |                                     |
| <u>Summary of Previous Reports</u>   |     |           |                                     |
| The 201 Facilities Plan Update (Underwood Engineers, 1999) identified potential long pump run times due to I/I experienced by the sewershed.   |     |           |                                     |
| <u>Other:</u>  |     |           |                                     |
| <u>Miscellaneous Issues:</u>   |     |           |                                     |
| Grease Accumulation?   | Yes | Source:   | Minor residential grease            |
| Clogging Issues?   | Yes | Describe: | Minor, hair and dental floss issues |
| Nuisance Odors?  | No  | Cause:    |                                     |
| Concrete Corrosion?  | No  | Location: |                                     |

**City of Portsmouth, New Hampshire  
SUBMERSIBLE Pump Station Evaluation  
Northwest Street**

Last Update: 7/17/2018  
This Update:

By: MAC  
By:

| General Pump Station Information                               |   |
|--|---|
| Location:  | 221 Northwest Street                                      |
| Pump Station Finished Floor Elevation, ft.:                    | 11  |
| Coastal Resiliency Flood Elevation (2050 High Emissions), ft.: | 13.5  |
| Distance from WWTF (straightline), miles:                      | 1.4   |
| Year Constructed/Upgraded:                                     | Constructed: 1985<br>Pump and Control Panel Upgrade: 2012 |
| Station Type:  | Flygt Submersible grinder pumps                           |
| Wet Well Diameter, ft.:  | 6   |
| Wet Well Volume, gal/ft  | 211   |
| No. of Pumps:  | 2   |
| Pump Installation Date:  | 2012  |
| Design Operating Point, 1 Pump                                 |   |
| Flow, gpm:   | 55  |
| Total Dynamic head, ft.:                                       | 40  |
| Pump Make/Model:   | ITT-FLYGT M3068   |
| Motor Size, HP:  | 2.3   |
| Motor/Pump Speed, rpm:   | Motor: 3,325  |
| Electrical Service, V/Ph/Hz:                                   | 230/1/60  |
| Drive Type:  | Direct drive, constant speed                              |
| Seal Make & Type:  | Double mechanical   |
| Force Main Diam., in.:   | 2.5   |
| Force Main Velocity, feet per sec.:                            | 3.2   |
| Force Main Type:   | PVC   |
| Force Main Age:  | 1985  |
| Force Main Length, ft.:  | 711   |



| Pump Flow and Run Time Information    |            |            |
|---------------------------------------|------------|------------|
|                                       | P1         | P2         |
| Pump Runtime Data                     | Yes        | Yes        |
| Data Start Date                       | 12/1/2014  | 12/1/2014  |
| Data End Date                         | 10/31/2017 | 10/31/2017 |
| Annual Average Flow, GPD (Calculated) | 912        | 575        |

| Pump Performance Testing Results  |                                |
|-----------------------------------|--------------------------------|
| Date of Test:                     | 29-Mar-18                      |
| Min./Max. VFD Setpoints (Hz)      | N/A - Full Speed               |
| VFD Speed (Hz)                    | N/A - Constant Speed           |
| Pump RPM                          |                                |
| Drawdown Flow, gpm:               | P1 - 55, P2 - 43               |
| Drawdown TDH, ft.:                | N/A                            |
| Influent Pump Station Flow @ Test | Estimate during visit, < 5 gpm |
| Note for Pump Start Type          | Constant speed                 |

| Generator Information  |   |
|------------------------|---|
| Make/Model:            | N/A   |
| Interior/Exterior:     | N/A   |
| Gen. Installation Date | N/A   |
| Size, KW:              | N/A   |
| Fuel Type:             | Portable generator connection within electrical enclosure |



| Controls Information    |   |
|-------------------------|---|
| Pump Control Sequence:  | Controls start and stop the pumps in an alternating Lead/ Lag sequence based on wet well level setpoints. If lead pump fails to start, Lag pump starts. If level rises above Lag start both will run. |
| Pump Control Panel:     | Combined Control and Power Panel (Electrical Installation, Inc)   |
| Installation Date:      | 2011  |
| Control Type:           | PLC Based   |
| Location:               | Exterior enclosure adjacent to wet well   |
| SCADA Connectivity:     | Yes, microwave RTU  |
| Level & Alarm Controls: | PLC Based Control Panel (2011)  |
| Type:                   | Submersible transducer (primary), differential level floats (secondary)   |
| Backup Alarm            | High-high, low-low level floats   |
| Flow Meter Make/Model:  | Not installed   |
| Alarm Transmission:     | All pump station alarms transferred via radio (existing) to WWTF SCADA, equipment in place to transition to microwave   |
| Pump Motor Starters :   | Square D motor starters within the Control Panel (2011)   |

**City of Portsmouth, New Hampshire**  
**SUBMERSIBLE Pump Station Evaluation**  
**Northwest Street**

Last Update: 7/17/2018 By: MAC  
 This Update: By:

| Mechanical         |   |             |               |                       |
|--------------------|---|-------------|---------------|-----------------------|
| Heating:           |   |             | Ventilation:  | Control Panel exhaust |
| Type:              | Small portable unit heater in Panel enclosure |             | System:       | Electric exhaust fan  |
| Size, kW:          | Unk.  | Quantity: 1 | Size:         | Unk.                  |
| Make/Model:        | Unk.  |             | Make & Model: | Unk.                  |
| Odor Control :     | None  |             | Ventilation:  | -                     |
| City Water Supply: | None  |             | Exhaust Fan:  | -                     |
|                    |   |             | L&D:          | -                     |

**Energy Efficiency Information**

Based on assumed pump model, the submersible grinder pumps operate at < 25% efficiency due to the small pump size and the type of grinder impeller utilized. Due to the low HP requirements of this station, this pump efficiency is considered to be typical for this type of pump and is not considered detrimental to pump station operation.

| Condition of Equipment/Identified Issues  |    |           |  |
|---|----|-----------|--|
| <b>Capacity:</b><br>Capacity assessment via drawdown testing on 3/29/18 indicated that the pumps have the following capacities: P1 - 55 gpm and P2 - 42 gpm. These pump are operating near the design operating point of 55 gpm. The station appears to have adequate capacity to handle existing flows with each pump only operating for about 0.25 hours per day on average. Under peak conditions, both pumps may run as much as 2 hours per day.  |    |           |  |
| <b>Exterior Site:</b><br>The pump station is located in a gated area at the end of a dead end street. The City has gated in the pump station to combat dog waste.   |    |           |  |
| <b>Building Structures (if applicable):</b><br>Not applicable   |    |           |  |
| <b>Wet Well:</b><br>The wet well appears to be in good condition due to tri- yearly cleaning. The wet well hatch was observed to be in good condition but does not have a safety net/hatch grating. The original ductile iron pump discharge piping has been replaced with flanged PVC piping, including check valves located within the wet well. No isolation valves were observed.   |    |           |  |
| <b>Dry Well (if applicable):</b> Not applicable.  |    |           |  |
| <b>Valve Pit (if applicable):</b> The submersible station does not currently have a valve pit. The submersible pumps have PVC check valves installed within the wet well. Record drawings from the original pump station design indicate the pump station was formerly equipped with buried isolation valves and a force main bypass located adjacent to the wet well. These features appear to have since been abandoned. Isolation valves are recommended to be installed with in a new valve pit, buried valves, or within the wet well itself.  |    |           |  |
| <b>Electrical/Instrumentation:</b><br>The electrical service to the pump station was recently replaced after breaking. The new service is an underground conduit from a nearby utility pole. Overhead electrical lines will be removed once this upgrade is complete. The main electrical enclosure and equipment (breaker box, manual transfer switch, disconnects, etc.) date back to the original pump station construction and are showing signs of age. It is recommended the main electrical distribution enclosure and all associated components be scheduled for replacement within the next 5-7 years to remain reliable.  |    |           |  |
| <b>HVAC:</b><br>The combined control and power panel was reported to get hot in the summertime. The City has installed a small, battery powered exhaust fan in an effort to mitigate heat issues within the panel.  |    |           |  |
| <b>Security Measures:</b><br>The panels and wet well are situated in a gated area with standard door padlocks. No security issues were noted.   |    |           |  |
| <b>Emergency Procedures:</b><br>Pump Station : If main power is lost, the City can either 1) connect a gas powered mobile emergency generator to power the pump station, or 2) use the City's vac truck to empty the pump station wet well daily or as-needed. The pump station serves fewer than 5 houses on Northwest Street and has substantial wet well capacity to accommodate short term power outages. Per NHDES regulations, the City is allowed to utilize wet well storage with an emergency generator receptacle for sewage pumping stations with a capacity of 100-GPM or less.<br><br>Force Main Bypass: The City would rely on a vacuum truck if the force main required bypassing. |    |           |  |
| <b>Summary of Previous Reports</b><br>The 201 Facilities Plan Update (Underwood Engineers, 1999) identified no issues with the pump station.  |    |           |  |
| <b>Other:</b>   |    |           |  |
| <b>Miscellaneous Issues:</b>  |    |           |  |
| Grease Accumulation?  | No | Source:   |  |
| Clogging Issues?  | No | Describe: |  |
| Nuisance Odors?   | No | Cause:    |  |
| Concrete Corrosion?   | No | Location: |  |

B

**RECOMMENDED FACILITIES IMPROVEMENT PLAN COSTS - BY YEAR (20% CONTINGENCY, 20% DESIGN)**

|              |                            | <b>Year 0</b>    | <b>Year 1</b>    | <b>Year 2</b>    | <b>Year 3</b>       | <b>Year 4</b>    | <b>Year 5</b>      | <b>Year 6</b>    | <b>Year 7</b>    | <b>Year 8</b>   | <b>Year 9</b>    | <b>Year 10</b>   | <b>TOTAL</b>        |
|--------------|----------------------------|------------------|------------------|------------------|---------------------|------------------|--------------------|------------------|------------------|-----------------|------------------|------------------|---------------------|
|              |                            | <b>2019</b>      | <b>2020</b>      | <b>2021</b>      | <b>2022</b>         | <b>2023</b>      | <b>2024</b>        | <b>2025</b>      | <b>2026</b>      | <b>2027</b>     | <b>2028</b>      | <b>2029</b>      |                     |
| <b>1</b>     | <b>Mechanic St PS</b>      | \$484,600        | \$8,600          | \$0              | \$14,400,000        | \$0              | \$0                | \$0              | \$0              | \$0             | \$0              | \$0              | \$14,893,200        |
| <b>2</b>     | <b>Deer Street PS</b>      | \$98,600         | \$385,200        | \$23,000         | \$53,300            | \$0              | \$0                | \$32,400         | \$100,800        | \$25,900        | \$1,400          | \$496,800        | \$1,217,400         |
| <b>3</b>     | <b>Lafayette Street PS</b> | -                | -                | -                | -                   | -                | -                  | -                | -                | -               | -                | -                | -                   |
| <b>4</b>     | <b>Heritage Street PS</b>  | -                | -                | -                | -                   | -                | -                  | -                | -                | -               | -                | -                | -                   |
| <b>5</b>     | <b>Gosling Road PS</b>     | \$14,400         | \$3,600          | \$0              | \$41,000            | \$0              | \$118,800          | \$0              | \$50,400         | \$0             | \$0              | \$21,600         |                     |
| <b>6</b>     | <b>Ryeline PS</b>          | \$16,600         | \$0              | \$5,000          | \$28,800            | \$14,400         | \$85,700           | \$0              | \$0              | \$0             | \$115,200        | \$223,200        | \$488,900           |
| <b>7</b>     | <b>Constitution Ave PS</b> | \$15,100         | \$21,600         | \$28,800         | \$115,900           | \$0              | \$144,000          | \$37,400         | \$0              | \$0             | \$0              | \$0              | \$362,800           |
| <b>8</b>     | <b>West Road PS</b>        | \$19,400         | \$2,900          | \$7,200          | \$112,300           | \$136,100        | \$149,800          | \$37,400         | \$0              | \$0             | \$0              | \$0              | \$465,100           |
| <b>9</b>     | <b>Woodlands I PS</b>      | \$28,100         | \$25,200         | \$0              | \$127,400           | \$86,400         | \$144,000          | \$28,800         | \$0              | \$0             | \$0              | \$0              | \$439,900           |
| <b>10</b>    | <b>Woodlands II PS</b>     | \$19,400         | \$2,900          | \$0              | \$28,100            | \$17,300         | \$144,000          | \$36,000         | \$0              | \$0             | \$0              | \$0              | \$247,700           |
| <b>11</b>    | <b>Atlantic Heights PS</b> | \$49,700         | \$2,900          | \$28,800         | \$257,800           | \$0              | \$86,400           | \$1,400          | \$0              | \$0             | \$0              | \$0              | \$427,000           |
| <b>12</b>    | <b>Marcy Street PS</b>     | \$67,100         | \$8,600          | \$14,400         | \$213,800           | \$0              | \$70,600           | \$0              | \$0              | \$0             | \$0              | \$14,400         | \$388,900           |
| <b>13</b>    | <b>Corporate Drive PS</b>  | \$0              | \$2,900          | \$0              | \$3,600             | \$1,400          | \$21,600           | \$0              | \$14,400         | \$0             | \$0              | \$0              | \$43,900            |
| <b>14</b>    | <b>Griffin Park PS</b>     | \$20,200         | \$23,800         | \$0              | \$17,300            | \$28,800         | \$0                | \$169,900        | \$0              | \$0             | \$108,000        | \$0              | \$368,000           |
| <b>15</b>    | <b>Tuckers Cove PS</b>     | \$21,600         | \$14,400         | \$0              | \$0                 | \$10,800         | \$0                | \$15,800         | \$21,600         | \$0             | \$0              | \$0              | \$84,200            |
| <b>16</b>    | <b>Leslie Drive PS</b>     | \$53,300         | \$20,600         | \$64,800         | \$265,700           | \$0              | \$28,800           | \$23,000         | \$0              | \$0             | \$0              | \$0              | \$456,200           |
| <b>17</b>    | <b>Clough Drive PS</b>     | \$9,800          | \$1,400          | \$7,200          | \$11,500            | \$26,600         | \$0                | \$0              | \$0              | \$0             | \$0              | \$0              | \$56,500            |
| <b>18</b>    | <b>Marsh Lane PS</b>       | \$3,600          | \$4,300          | \$0              | \$69,100            | \$0              | \$0                | \$0              | \$21,600         | \$0             | \$0              | \$0              | \$98,600            |
| <b>19</b>    | <b>Mill Pond Way PS</b>    | \$3,600          | \$7,200          | \$0              | \$11,500            | \$0              | \$64,800           | \$0              | \$0              | \$0             | \$0              | \$0              | \$87,100            |
| <b>20</b>    | <b>North West Road PS</b>  | \$3,600          | \$8,600          | \$0              | \$69,100            | \$0              | \$0                | \$0              | \$21,600         | \$0             | \$0              | \$0              | \$102,900           |
| <b>TOTAL</b> |                            | <b>\$928,700</b> | <b>\$544,700</b> | <b>\$179,200</b> | <b>\$15,826,200</b> | <b>\$321,800</b> | <b>\$1,058,500</b> | <b>\$382,100</b> | <b>\$230,400</b> | <b>\$25,900</b> | <b>\$224,600</b> | <b>\$756,000</b> | <b>\$20,478,100</b> |



CITY OF PORTSMOUTH, NEW HAMPSHIRE  
Pump Station Recommended Facilities Improvement Plan

**Deer Street Pump Station**  
Updated

10/10/2018

|  |   |                    |           |                    |                |                    |        |      | 0               | 1                | 2               | 3               | 4          | 5          | 6               | 7                | 8               | 9              | 10               |
|--|---|--------------------|-----------|--------------------|----------------|--------------------|--------|------|-----------------|------------------|-----------------|-----------------|------------|------------|-----------------|------------------|-----------------|----------------|------------------|
| Item   | Location  | Unit Cost          | Unit      | Estimated Quantity | Estimated Cost | Priority           | Year   |      | 2019            | 2020             | 2021            | 2022            | 2023       | 2024       | 2025            | 2026             | 2027            | 2028           | 2029             |
| <b>General Improvements</b>                    |   |                    |           |                    |                |                    |        |      |                 |                  |                 |                 |            |            |                 |                  |                 |                |                  |
| 1  | N/A   |                    |           |                    |                |                    |        |      |                 |                  |                 |                 |            |            |                 |                  |                 |                |                  |
| <b>Civil Improvements</b>                      |   |                    |           |                    |                |                    |        |      |                 |                  |                 |                 |            |            |                 |                  |                 |                |                  |
| 1  | N/A   |                    |           |                    |                |                    |        |      |                 |                  |                 |                 |            |            |                 |                  |                 |                |                  |
| <b>Architectural / Structural Improvements</b> |   |                    |           |                    |                |                    |        |      |                 |                  |                 |                 |            |            |                 |                  |                 |                |                  |
| 1  | Modify Generator Room Egress Door Louvers to allow for adequate egress clearance      | Generator Room     | \$20,000  | LS                 | 1              | \$20,000           | High   | 2020 |                 | \$20,000         |                 |                 |            |            |                 |                  |                 |                |                  |
| 2  | Provide 1-hour fire rating for Emergency Generator room per NFPA 37                   | Generator Room     | \$40,000  | LS                 | 1              | \$40,000           | High   | 2020 |                 | \$40,000         |                 |                 |            |            |                 |                  |                 |                |                  |
| 3  | Install missing toeplate on stairwell guard   | Dry Well           | \$500     | LS                 | 1              | \$500              | Low    | 2022 |                 |                  |                 | \$500           |            |            |                 |                  |                 |                |                  |
| 4  | Repair stair nosing and concrete in dry well  | Dry Well           | \$1,500   | LS                 | 1              | \$1,500            | Low    | 2022 |                 |                  |                 | \$1,500         |            |            |                 |                  |                 |                |                  |
| 5  | Repair foundation crack in Generator room slab  | Generator Room     | \$1,000   | LS                 | 1              | \$1,000            | Medium | 2021 |                 |                  | \$1,000         |                 |            |            |                 |                  |                 |                |                  |
| 6  | Evaluate repair/reinforcement of Odor Control Unit structural supports                | Wet Well           | \$10,000  | LS                 | 1              | \$10,000           | High   | 2019 | \$10,000        |                  |                 |                 |            |            |                 |                  |                 |                |                  |
| 7  | Resurface the ground floor slab in wet well   | Wet Well           | \$5,000   | LS                 | 1              | \$5,000            | Low    | 2020 |                 | \$5,000          |                 |                 |            |            |                 |                  |                 |                |                  |
| 8  | Replace the aluminum stair in wet well  | Wet Well           | \$15,000  | LS                 | 1              | \$15,000           | Medium | 2025 |                 |                  |                 |                 |            |            | \$15,000        |                  |                 |                |                  |
| <b>Mechanical Improvements</b>                 |   |                    |           |                    |                |                    |        |      |                 |                  |                 |                 |            |            |                 |                  |                 |                |                  |
| 1  | Install exhaust fan and louver for space to meet NFPA 820 classification requirements | Electric/Pump Room | \$35,000  | LS                 | 1              | \$35,000           | High   | 2019 | \$35,000        |                  |                 |                 |            |            |                 |                  |                 |                |                  |
| 2  | Add Fire Dampers to all ductwork that penetrates Emergency Generator Room             | Generator Room     | \$10,000  | LS                 | 1              | \$10,000           | High   | 2019 | \$10,000        |                  |                 |                 |            |            |                 |                  |                 |                |                  |
| 3  | Replace exterior refrigerant piping insulation  | Exterior           | \$1,500   | LS                 | 1              | \$1,500            | Low    | 2020 |                 | \$1,500          |                 |                 |            |            |                 |                  |                 |                |                  |
| 5  | Install replacement Emergency Generator louvers (See Arch Line item in addition)      | Generator Room     | \$10,000  | LS                 | 1              | \$10,000           | High   | 2019 | \$10,000        |                  |                 |                 |            |            |                 |                  |                 |                |                  |
| 6  | Replace supply fan insulation   | Wet well           | \$500     | LS                 | 1              | \$500              | Medium | 2020 |                 | \$500            |                 |                 |            |            |                 |                  |                 |                |                  |
| 7  | Add air admittance valve to utility sink  | Dry well           | \$500     | LS                 | 1              | \$500              | Medium | 2020 |                 | \$500            |                 |                 |            |            |                 |                  |                 |                |                  |
| 9  | Replace water heater  | Dry well           | \$1,000   | LS                 | 1              | \$1,000            | Low    | 2028 |                 |                  |                 |                 |            |            |                 |                  |                 | \$1,000        |                  |
| 10   | Replace condensing unit   | Exterior           | \$15,000  | LS                 | 1              | \$15,000           | Low    | 2022 |                 |                  |                 | \$15,000        |            |            |                 |                  |                 |                |                  |
| 11   | Replace gas fired duct furnace  | Attic space        | \$7,500   | LS                 | 1              | \$7,500            | Low    | 2025 |                 |                  |                 |                 |            |            | \$7,500         |                  |                 |                |                  |
| 12   | Replace air handling unit   | Attic space        | \$18,000  | LS                 | 1              | \$18,000           | Low    | 2027 |                 |                  |                 |                 |            |            |                 |                  |                 | \$18,000       |                  |
| <b>Process Improvements</b>                    |   |                    |           |                    |                |                    |        |      |                 |                  |                 |                 |            |            |                 |                  |                 |                |                  |
| 1  | Replace grinder cutter stack  | Wet Well           | \$15,000  | LS                 | 1              | \$15,000           | Medium | 2021 |                 |                  | \$15,000        |                 |            |            |                 |                  |                 |                |                  |
| 2  | Replace grinder   | Wet Well           | \$70,000  | LS                 | 1              | \$70,000           | Low    | 2026 |                 |                  |                 |                 |            |            |                 | \$70,000         |                 |                |                  |
| 3  | Pump Rehabilitation/Replacement (planning)  | Wet Well           | \$115,000 | EA                 | 3              | \$345,000          | Low    | 2029 |                 |                  |                 |                 |            |            |                 |                  |                 |                | \$345,000        |
| 4  | Replace force main isolation valves (two buried gate valves)                          | Exterior           | \$200,000 | LS                 | 1              | \$200,000          | High   | 2020 |                 | \$200,000        |                 |                 |            |            |                 |                  |                 |                |                  |
| <b>Electrical/Instrumentation Improvements</b> |   |                    |           |                    |                |                    |        |      |                 |                  |                 |                 |            |            |                 |                  |                 |                |                  |
| 1  | Upgrade Control Panel PLC components (SLC 505)  | Control Room       | \$20,000  | LS                 | 1              | \$20,000           | Low    | 2022 |                 |                  |                 | \$20,000        |            |            |                 |                  |                 |                |                  |
| 2  | Install a horn within the pump station to alert occupants of unsafe atmosphere        | Interior           | \$2,500   | LS                 | 1              | \$2,500            | Medium | 2019 | \$2,500         |                  |                 |                 |            |            |                 |                  |                 |                |                  |
| 3  | Provide arc-flash safety labeling   | Interior           | \$1,000   | LS                 | 1              | \$1,000            | High   | 2019 | \$1,000         |                  |                 |                 |            |            |                 |                  |                 |                |                  |
| 4  | Monitor transformer corrosion   | Exterior           | -         | -                  | -              | -                  | Medium | 2020 |                 |                  |                 |                 |            |            |                 |                  |                 |                |                  |
| <b>High Priority Projects</b>                  |   |                    |           |                    |                | \$326,000          |        |      |                 |                  |                 |                 |            |            |                 |                  |                 |                |                  |
| <b>Medium Priority Projects</b>                |   |                    |           |                    |                | \$34,500           |        |      |                 |                  |                 |                 |            |            |                 |                  |                 |                |                  |
| <b>Low Priority Projects</b>                   |   |                    |           |                    |                | \$485,000          |        |      |                 |                  |                 |                 |            |            |                 |                  |                 |                |                  |
| Subtotal                                       |   |                    |           |                    |                | \$845,500          |        |      | \$68,500        | \$267,500        | \$16,000        | \$37,000        | \$0        | \$0        | \$22,500        | \$70,000         | \$18,000        | \$1,000        | \$345,000        |
| Contingencies                                  |   |                    |           |                    | 20%            | \$169,100          |        |      | \$13,700        | \$53,500         | \$3,200         | \$7,400         | \$0        | \$0        | \$4,500         | \$14,000         | \$3,600         | \$200          | \$69,000         |
| Estimated Construction Cost                    |   |                    |           |                    |                | \$1,014,600        |        |      | \$82,200        | \$321,000        | \$19,200        | \$44,400        | \$0        | \$0        | \$27,000        | \$84,000         | \$21,600        | \$1,200        | \$414,000        |
| Engineering and Administrative Allowance       |   |                    |           |                    |                | \$202,900          |        |      | \$16,400        | \$64,200         | \$3,800         | \$8,900         | \$0        | \$0        | \$5,400         | \$16,800         | \$4,300         | \$200          | \$82,800         |
| <b>Estimated Total Project Cost</b>            |   |                    |           |                    |                | <b>\$1,217,500</b> |        |      | <b>\$98,600</b> | <b>\$385,200</b> | <b>\$23,000</b> | <b>\$53,300</b> | <b>\$0</b> | <b>\$0</b> | <b>\$32,400</b> | <b>\$100,800</b> | <b>\$25,900</b> | <b>\$1,400</b> | <b>\$496,800</b> |

**CITY OF PORTSMOUTH, NEW HAMPSHIRE**  
**Pump Station Recommended Facilities Improvement Plan**

**Gosling Road**  
 Updated 10/10/2018

|  |      |   |           |          |                    |                |          |        | 0    | 1       | 2       | 3        | 4    | 5        | 6    | 7        | 8    | 9    | 10       |
|--|------|---|-----------|----------|--------------------|----------------|----------|--------|------|---------|---------|----------|------|----------|------|----------|------|------|----------|
|  | Item | Location  | Unit Cost | Unit     | Estimated Quantity | Estimated Cost | Priority | Year   | 2019 | 2020    | 2021    | 2022     | 2023 | 2024     | 2025 | 2026     | 2027 | 2028 | 2029     |
| <b>General Improvements</b>                    |      |   |           |          |                    |                |          |        |      |         |         |          |      |          |      |          |      |      |          |
|  | 1    | N/A   |           |          |                    |                |          |        |      |         |         |          |      |          |      |          |      |      |          |
| <b>Civil Improvements</b>                      |      |   |           |          |                    |                |          |        |      |         |         |          |      |          |      |          |      |      |          |
|  | 1    | N/A   |           |          |                    |                |          |        |      |         |         |          |      |          |      |          |      |      |          |
| <b>Architectural / Structural Improvements</b> |      |   |           |          |                    |                |          |        |      |         |         |          |      |          |      |          |      |      |          |
|  | 1    | Sandblast/paint exterior monorail                 | Exterior  | \$2,500  | EA                 | 1              | \$2,500  | Medium | 2020 |         | \$2,500 |          |      |          |      |          |      |      |          |
|  | 2    | Roof replacement                                  | Exterior  | \$15,000 | EA                 | 1              | \$15,000 | Low    | 2029 |         |         |          |      |          |      |          |      |      | \$15,000 |
|  | 3    | Install wet well channel grating where missing    | Interior  | \$3,500  | EA                 | 1              | \$3,500  | High   | 2022 |         |         | \$3,500  |      |          |      |          |      |      |          |
| <b>Mechanical Improvements</b>                 |      |   |           |          |                    |                |          |        |      |         |         |          |      |          |      |          |      |      |          |
|  | 1    | Install split-duct AC unit for dry well           | Dry Well  | \$15,000 | EA                 | 1              | \$15,000 | Low    | 2022 |         |         | \$15,000 |      |          |      |          |      |      |          |
| <b>Process Improvements</b>                    |      |   |           |          |                    |                |          |        |      |         |         |          |      |          |      |          |      |      |          |
|  | 1    | Replace cutter stack in influent grinder          | Wet Well  | \$10,000 | EA                 | 1              | \$10,000 | Medium | 2022 |         |         | \$10,000 |      |          |      |          |      |      |          |
|  | 2    | Replace influent grinder                          | Wet Well  | \$35,000 | EA                 | 1              | \$35,000 | Low    | 2026 |         |         |          |      |          |      | \$35,000 |      |      |          |
|  | 3    | Pump rehabilitation/replacement (planning)        | Dry Well  | \$30,000 | EA                 | 2              | \$60,000 | Medium | 2024 |         |         |          |      | \$60,000 |      |          |      |      |          |
| <b>Electrical/instrumentation Improvements</b> |      |   |           |          |                    |                |          |        |      |         |         |          |      |          |      |          |      |      |          |
|  | 1    | Install Exit/Emergency lighting                   | Dry Well  | \$5,000  | LS                 | 1              | \$5,000  | High   | 2019 | \$5,000 |         |          |      |          |      |          |      |      |          |
|  | 2    | Repair hazardous gas detection system in dry well | Dry Well  | \$2,500  | LS                 | 1              | \$2,500  | High   | 2019 | \$2,500 |         |          |      |          |      |          |      |      |          |
|  | 3    | Control Panel Upgrade                             | Dry Well  | \$15,000 | LS                 | 1              | \$15,000 | Medium | 2024 |         |         |          |      | \$15,000 |      |          |      |      |          |
|  | 4    | Magnetic Flow Meter Replacement                   | Dry Well  | \$7,500  | LS                 | 1              | \$7,500  | Medium | 2024 |         |         |          |      | \$7,500  |      |          |      |      |          |
|  | 5    | Install utility power bypass circuit for UPS      | Controls  | \$2,500  | EA                 | 1              | \$2,500  | High   | 2019 | \$2,500 |         |          |      |          |      |          |      |      |          |

|                          |          |
|--------------------------|----------|
| High Priority Projects   | \$13,500 |
| Medium Priority Projects | \$95,000 |
| Low Priority Projects    | \$65,000 |

|  |                  |                 |                |            |                 |            |                  |            |                 |            |            |                 |
|--|------------------|-----------------|----------------|------------|-----------------|------------|------------------|------------|-----------------|------------|------------|-----------------|
| Subtotal                                 | \$173,500        | \$10,000        | \$2,500        | \$0        | \$28,500        | \$0        | \$82,500         | \$0        | \$35,000        | \$0        | \$0        | \$15,000        |
| Contingencies (20%)                      | \$34,700         | \$2,000         | \$500          | \$0        | \$5,700         | \$0        | \$16,500         | \$0        | \$7,000         | \$0        | \$0        | \$3,000         |
| Estimated Construction Cost              | \$208,200        | \$12,000        | \$3,000        | \$0        | \$34,200        | \$0        | \$99,000         | \$0        | \$42,000        | \$0        | \$0        | \$18,000        |
| Engineering and Administrative Allowance | \$41,600         | \$2,400         | \$600          | \$0        | \$6,800         | \$0        | \$19,800         | \$0        | \$8,400         | \$0        | \$0        | \$3,600         |
| <b>Estimated Total Project Cost</b>      | <b>\$249,800</b> | <b>\$14,400</b> | <b>\$3,600</b> | <b>\$0</b> | <b>\$41,000</b> | <b>\$0</b> | <b>\$118,800</b> | <b>\$0</b> | <b>\$50,400</b> | <b>\$0</b> | <b>\$0</b> | <b>\$21,600</b> |

CITY OF PORTSMOUTH, NEW HAMPSHIRE  
Pump Station Recommended Facilities Improvement Plan

Ryeline Updated 10/29/2018

| Item  | Location            | Unit Cost | Unit | Estimated Quantity | Estimated Cost | Priority | Year | 2019    | 2020 | 2021    | 2022     | 2023     | 2024     | 2025 | 2026 | 2027 | 2028     | 2029     |
|---|---------------------|-----------|------|--------------------|----------------|----------|------|---------|------|---------|----------|----------|----------|------|------|------|----------|----------|
| <b>General Improvements</b>   |                     |           |      |                    |                |          |      |         |      |         |          |          |          |      |      |      |          |          |
| 1 N/A   |                     |           |      |                    |                |          |      |         |      |         |          |          |          |      |      |      |          |          |
| <b>Civil Improvements</b>   |                     |           |      |                    |                |          |      |         |      |         |          |          |          |      |      |      |          |          |
| 1 N/A   |                     |           |      |                    |                |          |      |         |      |         |          |          |          |      |      |      |          |          |
| <b>Architectural / Structural Improvements</b>  |                     |           |      |                    |                |          |      |         |      |         |          |          |          |      |      |      |          |          |
| 1 disconnected for entrance into this vault.  | Dry Well            | -         | -    | -                  | -              | High     | 2019 | -       |      |         |          |          |          |      |      |      |          |          |
| 2 Evaluate relocation of the emergency generator to an exterior location for next significant upgrade | Dry Well            | \$80,000  | EA   | 1                  | \$ 80,000      | Low      | 2028 |         |      |         |          |          |          |      |      |      | \$80,000 |          |
| 3 Spot repair tneec coating failed areas in wet well (optional)                                       | Wet Well            | \$5,000   | EA   | 1                  | \$5,000        | Low      | 2022 |         |      |         | \$5,000  |          |          |      |      |      |          |          |
| 4 Add toe plates to aluminum stair handrails.   | Dry Well & Wet Well | \$1,000   | EA   | 1                  | \$1,000        | Medium   | 2021 |         |      | \$1,000 |          |          |          |      |      |      |          |          |
| 5 Install rigid handrail guard on elevated wet well platform to replace safety chain                  | Wet Well            | \$2,000   | EA   | 1                  | \$2,500        | Medium   | 2021 |         |      | \$2,500 |          |          |          |      |      |      |          |          |
| <b>Mechanical Improvements</b>  |                     |           |      |                    |                |          |      |         |      |         |          |          |          |      |      |      |          |          |
| 1 Repair existing AUTO ventilation controls for SF-1  | Dry Well            | \$1,500   | EA   | 1                  | \$1,500        | High     | 2019 | \$1,500 |      |         |          |          |          |      |      |      |          |          |
| 2 Install dedicated air intake in wet well  | Wet Well            | \$7,500   | EA   | 1                  | \$7,500        | Medium   | 2019 | \$7,500 |      |         |          |          |          |      |      |      |          |          |
| 3 HVAC Upgrade to address lack of ventilation and NFPA Code compliance                                | Dry Well            | \$35,000  | EA   | 1                  | \$35,000       | Medium   | 2024 |         |      |         |          |          | \$35,000 |      |      |      |          |          |
| 4 Provide ventilated thimble penetration for emergency generator exhaust                              | Dry Well            | \$3,000   | EA   | 1                  | \$3,000        | Medium   | 2024 |         |      |         |          |          | \$3,000  |      |      |      |          |          |
| 5 Insulate emergency generator exhaust piping   | Dry Well            | \$1,500   | EA   | 1                  | \$1,500        | Medium   | 2024 |         |      |         |          |          | \$1,500  |      |      |      |          |          |
| 6 Install split AC unit for dry well side cooling   | Dry Well            | \$20,000  | EA   | 1                  | \$20,000       | Low      | 2024 |         |      |         |          |          | \$20,000 |      |      |      |          |          |
| <b>Process Improvements</b>   |                     |           |      |                    |                |          |      |         |      |         |          |          |          |      |      |      |          |          |
| 1 Replace wet well divider sluice gate  | Wet Well            | \$10,000  | EA   | 1                  | \$10,000       | Medium   | 2022 |         |      |         | \$10,000 |          |          |      |      |      |          |          |
| 2 Replace cutter stack in influent grinder  | Wet Well            | \$5,000   | EA   | 1                  | \$5,000        | Medium   | 2022 |         |      |         | \$5,000  |          |          |      |      |      |          |          |
| 3 Replace influent grinder  | Wet Well            | \$30,000  | EA   | 1                  | \$30,000       | Low      | 2029 |         |      |         |          |          |          |      |      |      |          | \$30,000 |
| 4 Pump Impeller Replacement   | Dry Well            | \$5,000   | EA   | 2                  | \$10,000       | Low      | 2023 |         |      |         |          | \$10,000 |          |      |      |      |          |          |
| 5 Pump rehabilitation/replacement (planning)  | Dry Well            | \$25,000  | EA   | 2                  | \$50,000       | Low      | 2029 |         |      |         |          |          |          |      |      |      |          | \$50,000 |
| <b>Electrical Improvements</b>  |                     |           |      |                    |                |          |      |         |      |         |          |          |          |      |      |      |          |          |
| 1 Install utility power bypass circuit for UPS  | Controls            | \$2,500   | EA   | 1                  | \$2,500        | High     | 2019 | \$2,500 |      |         |          |          |          |      |      |      |          |          |
| 2 Electrical Equipment Upgrade - Planning (MCC, VFDs, Control Panel)                                  | Dry Well            | \$75,000  | EA   | 1                  | \$75,000       | Low      | 2029 |         |      |         |          |          |          |      |      |      |          | \$75,000 |

|                          |           |
|--------------------------|-----------|
| High Priority Projects   | \$4,000   |
| Medium Priority Projects | \$65,500  |
| Low Priority Projects    | \$270,000 |

|  |                  |                 |            |                |                 |                 |                 |            |            |            |                  |                  |
|--|------------------|-----------------|------------|----------------|-----------------|-----------------|-----------------|------------|------------|------------|------------------|------------------|
| Subtotal                                 | \$339,500        | \$11,500        | \$0        | \$3,500        | \$20,000        | \$10,000        | \$59,500        | \$0        | \$0        | \$0        | \$80,000         | \$155,000        |
| Contingencies (20%)                      | \$67,900         | \$2,300         | \$0        | \$700          | \$4,000         | \$2,000         | \$11,900        | \$0        | \$0        | \$0        | \$16,000         | \$31,000         |
| Estimated Construction Cost              | \$407,400        | \$13,800        | \$0        | \$4,200        | \$24,000        | \$12,000        | \$71,400        | \$0        | \$0        | \$0        | \$96,000         | \$186,000        |
| Engineering and Administrative Allowance | \$81,500         | \$2,800         | \$0        | \$800          | \$4,800         | \$2,400         | \$14,300        | \$0        | \$0        | \$0        | \$19,200         | \$37,200         |
| <b>Estimated Total Project Cost</b>      | <b>\$488,900</b> | <b>\$16,600</b> | <b>\$0</b> | <b>\$5,000</b> | <b>\$28,800</b> | <b>\$14,400</b> | <b>\$85,700</b> | <b>\$0</b> | <b>\$0</b> | <b>\$0</b> | <b>\$115,200</b> | <b>\$223,200</b> |

**CITY OF PORTSMOUTH, NEW HAMPSHIRE**  
**Pump Station Recommended Facilities Improvements Plan**  
**Constitution Avenue**  
**Updated**

11/14/2018

|  |   |           |           |      |                    |                |          |      |         | 0       | 1        | 2        | 3    | 4         | 5        | 6    | 7    | 8    | 9    | 10 |
|--|---|-----------|-----------|------|--------------------|----------------|----------|------|---------|---------|----------|----------|------|-----------|----------|------|------|------|------|----|
| Item   |   | Location  | Unit Cost | Unit | Estimated Quantity | Estimated Cost | Priority | Year | 2019    | 2020    | 2021     | 2022     | 2023 | 2024      | 2025     | 2026 | 2027 | 2028 | 2029 |    |
| <b>General Improvements</b>                    |   |           |           |      |                    |                |          |      |         |         |          |          |      |           |          |      |      |      |      |    |
| 1  | Investigate inflow and infiltration sources in the sewershed                    | -         | -         | -    | -                  | -              | Low      |      |         |         |          |          |      |           |          |      |      |      |      |    |
| 2  | Conduct CCTV survey of force main to confirm condition                          | Pump Room | \$5,000   | LS   | 1                  | \$5,000        | Medium   | 2021 |         |         | \$5,000  |          |      |           |          |      |      |      |      |    |
| <b>Civil Improvements</b>                      |   |           |           |      |                    |                |          |      |         |         |          |          |      |           |          |      |      |      |      |    |
| 1  | N/A   |           |           |      |                    |                |          |      |         |         |          |          |      |           |          |      |      |      |      |    |
| <b>Architectural / Structural Improvements</b> |   |           |           |      |                    |                |          |      |         |         |          |          |      |           |          |      |      |      |      |    |
| 1  | EVALUATE BUILDING REPLACEMENT OR CONVERSION TO SUBMERSIBLE STATION (7-10 years) | -         | -         | -    | -                  | -              | Medium   | 2025 |         |         |          |          |      |           |          |      |      |      |      |    |
| 2  | Pressure inject emergency generator exhaust crack                               | Pump Room | \$1,000   | LS   | 1                  | \$1,000        | Medium   | 2020 |         | \$1,000 |          |          |      |           |          |      |      |      |      |    |
| 3  | Seal conduit penetrations to wet well   | Wet Well  | \$1,000   | LS   | 1                  | \$1,000        | Medium   | 2020 |         | \$1,000 |          |          |      |           |          |      |      |      |      |    |
| 4  | Seal pump station dry well penetrations permanently                             | Pump Room | \$500     | LS   | 1                  | \$500          | High     | 2019 | \$500   |         |          |          |      |           |          |      |      |      |      |    |
| 5  | Replace roof with higher slope and adequate roof drainage                       | Wet Well  | \$10,000  | LS   | 1                  | \$10,000       | Low      | 2025 |         |         |          |          |      |           | \$10,000 |      |      |      |      |    |
| 6  | Door Hardware Replacement   | Pump Room | \$1,000   | LS   | 1                  | \$1,000        | Medium   | 2020 |         | \$1,000 |          |          |      |           |          |      |      |      |      |    |
| 7  | Interior surface refinishing  | Pump Room | \$5,000   | LS   | 1                  | \$5,000        | Medium   | 2020 |         | \$5,000 |          |          |      |           |          |      |      |      |      |    |
| <b>Mechanical Improvements</b>                 |   |           |           |      |                    |                |          |      |         |         |          |          |      |           |          |      |      |      |      |    |
| 1  | Install mechanism to hold door open while pump station is occupied.             | Pump Room | \$1,000   | LS   | 1                  | \$1,000        | High     | 2019 | \$1,000 |         |          |          |      |           |          |      |      |      |      |    |
| 2  | Insulate emergency generator exhaust piping                                     | Pump Room | \$1,000   | LS   | 1                  | \$1,000        | Medium   | 2020 |         | \$1,000 |          |          |      |           |          |      |      |      |      |    |
| 3  | Replace emergency generator exhaust through the wall with a ventilated thimble  | Pump Room | \$1,000   | LS   | 1                  | \$1,000        | Medium   | 2020 |         | \$1,000 |          |          |      |           |          |      |      |      |      |    |
| 4  | Replace the water service entrance piping insulation                            | Pump Room | \$1,000   | LS   | 1                  | \$1,000        | Low      | 2022 |         |         |          | \$1,000  |      |           |          |      |      |      |      |    |
| 5  | Add a small dehumidifier to remove excess humidity                              | Pump Room | \$1,500   | LS   | 1                  | \$1,500        | Low      | 2022 |         |         |          | \$1,500  |      |           |          |      |      |      |      |    |
| 6  | Add a split AC unit for summertime interior heat                                | Pump Room | \$5,000   | LS   | 1                  | \$5,000        | Medium   | 2020 |         | \$5,000 |          |          |      |           |          |      |      |      |      |    |
| <b>Process Improvements</b>                    |   |           |           |      |                    |                |          |      |         |         |          |          |      |           |          |      |      |      |      |    |
| 1  | Replace wet well discharge piping   | Wet Well  | \$5,000   | LS   | 1                  | \$5,000        | Medium   | 2021 |         |         | \$5,000  |          |      |           |          |      |      |      |      |    |
| 2  | Pump Motor Replacement (planning)   | Pump Room | \$5,000   | LS   | 2                  | \$10,000       | Medium   | 2021 |         |         | \$10,000 |          |      |           |          |      |      |      |      |    |
| <b>Electrical/Instrumentation Improvements</b> |   |           |           |      |                    |                |          |      |         |         |          |          |      |           |          |      |      |      |      |    |
| 1  | Install Exit/Emergency lighting   | Mult.     | \$5,000   | LS   | 1                  | \$5,000        | High     | 2019 | \$5,000 |         |          |          |      |           |          |      |      |      |      |    |
| 2  | Provide arc-flash safety labeling   | Mult.     | \$500     | LS   | 1                  | \$500          | High     | 2019 | \$500   |         |          |          |      |           |          |      |      |      |      |    |
| 3  | Comprehensive Electrical Upgrade  | Pump Room | \$100,000 | LS   | 1                  | \$100,000      | Medium   | 2024 |         |         |          |          |      | \$100,000 |          |      |      |      |      |    |
| 4  | Emergency Generator and ATS Upgrade   | Pump Room | \$75,000  | LS   | 1                  | \$75,000       | Medium   | 2022 |         |         |          | \$75,000 |      |           |          |      |      |      |      |    |
| 8  | Install an intrinsically safe barrier for submersible transducer                | Exterior  | \$3,000   | LS   | 1                  | \$3,000        | Medium   | 2022 |         |         |          | \$3,000  |      |           |          |      |      |      |      |    |
| 7  | Ground the antennae mast  | Exterior  | \$500     | LS   | 2                  | \$1,000        | High     | 2019 | \$1,000 |         |          |          |      |           |          |      |      |      |      |    |
| 8  | Install wet well seal instrument bypass seal-offs                               | Exterior  | \$1,000   | LS   | 1                  | \$1,000        | Low      | 2025 |         |         |          |          |      |           | \$1,000  |      |      |      |      |    |
| 8  | Control Panel/Pump Starter Replacement  | Exterior  | \$15,000  | LS   | 1                  | \$15,000       | Low      | 2025 |         |         |          |          |      |           | \$15,000 |      |      |      |      |    |
| 11   | Install utility power bypass circuit for UPS                                    | Controls  | \$2,500   | EA   | 1                  | \$2,500        | High     | 2019 | \$2,500 |         |          |          |      |           |          |      |      |      |      |    |

|                          |           |
|--------------------------|-----------|
| High Priority Projects   | \$10,500  |
| Medium Priority Projects | \$213,000 |
| Low Priority Projects    | \$28,500  |

|  |                  |                 |                 |                 |                  |            |                  |                 |            |            |            |            |
|--|------------------|-----------------|-----------------|-----------------|------------------|------------|------------------|-----------------|------------|------------|------------|------------|
| Subtotal                                 | \$252,000        | \$10,500        | \$15,000        | \$20,000        | \$80,500         | \$0        | \$100,000        | \$26,000        | \$0        | \$0        | \$0        | \$0        |
| Contingencies (20%)                      | \$50,400         | \$2,100         | \$3,000         | \$4,000         | \$16,100         | \$0        | \$20,000         | \$5,200         | \$0        | \$0        | \$0        | \$0        |
| Estimated Construction Cost              | \$302,400        | \$12,600        | \$18,000        | \$24,000        | \$96,600         | \$0        | \$120,000        | \$31,200        | \$0        | \$0        | \$0        | \$0        |
| Engineering and Administrative Allowance | \$60,500         | \$2,500         | \$3,600         | \$4,800         | \$19,300         | \$0        | \$24,000         | \$6,200         | \$0        | \$0        | \$0        | \$0        |
| <b>Estimated Total Project Cost</b>      | <b>\$362,900</b> | <b>\$15,100</b> | <b>\$21,600</b> | <b>\$28,800</b> | <b>\$115,900</b> | <b>\$0</b> | <b>\$144,000</b> | <b>\$37,400</b> | <b>\$0</b> | <b>\$0</b> | <b>\$0</b> | <b>\$0</b> |

CITY OF PORTSMOUTH, NEW HAMPSHIRE  
Pump Station Recommended Facilities Improvement Plan

West Road  
Updated 11/14/2018

| Item   | Location  | Unit Cost | Unit      | Estimated Quantity | Estimated Cost | Priority  | Year   | 0    | 1       | 2       | 3        | 4         | 5    | 6        | 7    | 8    | 9    | 10   |
|--|---|-----------|-----------|--------------------|----------------|-----------|--------|------|---------|---------|----------|-----------|------|----------|------|------|------|------|
|  |   |           |           |                    |                |           |        | 2019 | 2020    | 2021    | 2022     | 2023      | 2024 | 2025     | 2026 | 2027 | 2028 | 2029 |
| <b>General Improvements</b>                    |   |           |           |                    |                |           |        |      |         |         |          |           |      |          |      |      |      |      |
| 1  | Conduct CCTV survey of force main to confirm condition                          | Pump Room | \$5,000   | LS                 | 1              | \$5,000   | Medium | 2021 |         |         | \$5,000  |           |      |          |      |      |      |      |
| <b>Civil Improvements</b>                      |   |           |           |                    |                |           |        |      |         |         |          |           |      |          |      |      |      |      |
| 1  | N/A   |           |           |                    |                |           |        |      |         |         |          |           |      |          |      |      |      |      |
| <b>Architectural / Structural Improvements</b> |   |           |           |                    |                |           |        |      |         |         |          |           |      |          |      |      |      |      |
| 1  | EVALUATE BUILDING REPLACEMENT OR CONVERSION TO SUBMERSIBLE STATION (5-10 years) | -         | -         | -                  | -              | -         | Medium | 2025 |         |         |          |           |      |          |      |      |      |      |
| 2  | Replace entrance door/frame   | Exterior  | \$3,000   | LS                 | 1              | \$3,000   | Low    | 2023 |         |         |          | \$3,000   |      |          |      |      |      |      |
| 3  | Re-grout pump station exterior seams  | Exterior  | \$1,500   | LS                 | 1              | \$1,500   | Low    | 2023 |         |         |          | \$1,500   |      |          |      |      |      |      |
| 4  | Seal pump station dry well penetrations permanently                             | Pump Room | \$500     | LS                 | 1              | \$500     | High   | 2019 | \$500   |         |          |           |      |          |      |      |      |      |
| 5  | Replace roof with higher slope and adequate roof drainage                       | Wet Well  | \$10,000  | LS                 | 1              | \$10,000  | Medium | 2023 |         |         |          | \$10,000  |      |          |      |      |      |      |
| 6  | Refinish interior floor   | Pump Room | \$5,000   | LS                 | 1              | \$5,000   | Low    | 2025 |         |         |          |           |      | \$5,000  |      |      |      |      |
| <b>Mechanical Improvements</b>                 |   |           |           |                    |                |           |        |      |         |         |          |           |      |          |      |      |      |      |
| 1  | > 5 ft from any louver or air intake  | Pump Room | \$1,000   | LS                 | 1              | \$1,000   | High   | 2019 | \$1,000 |         |          |           |      |          |      |      |      |      |
| 2  | Replace/repair exterior emergency generator intake/exhaust louvers              | Pump Room | \$4,000   | LS                 | 1              | \$4,000   | Medium | 2024 |         |         |          | \$4,000   |      |          |      |      |      |      |
| 3  | Install mechanism to hold door open while pump station is occupied              | Exterior  | \$1,000   | LS                 | 1              | \$1,000   | High   | 2019 | \$1,000 |         |          |           |      |          |      |      |      |      |
| 4  | Replace insulation for emergency generator exhaust piping                       | Pump Room | \$1,000   | LS                 | 1              | \$1,000   | Medium | 2020 |         | \$1,000 |          |           |      |          |      |      |      |      |
| 5  | Replace emergency generator exhaust through the wall with a ventilated thimble  | Pump Room | \$1,000   | LS                 | 1              | \$1,000   | Medium | 2020 |         | \$1,000 |          |           |      |          |      |      |      |      |
| 6  | Insulate water service lines  | Exterior  | \$1,500   | LS                 | 1              | \$1,500   | Low    | 2022 |         |         | \$1,500  |           |      |          |      |      |      |      |
| 7  | Add a small dehumidifier to remove excess humidity                              | Pump Room | \$1,500   | LS                 | 1              | \$1,500   | Low    | 2022 |         |         | \$1,500  |           |      |          |      |      |      |      |
| 8  | Add a split AC unit for summertime interior heat                                | Pump Room | \$5,000   | LS                 | 1              | \$5,000   | Low    | 2025 |         |         |          |           |      | \$5,000  |      |      |      |      |
| <b>Process Improvements</b>                    |   |           |           |                    |                |           |        |      |         |         |          |           |      |          |      |      |      |      |
| 1  | Pump Replacement (including motors)   | Pump Room | \$30,000  | EA                 | 2              | \$60,000  | Medium | 2023 |         |         |          | \$60,000  |      |          |      |      |      |      |
| 2  | Replace wet well suction/discharge piping                                       | Wet Well  | \$10,000  | LS                 | 1              | \$10,000  | Medium | 2023 |         |         |          | \$10,000  |      |          |      |      |      |      |
| 3  | Replace pump motors   | Pump Room | \$5,000   | LS                 | 2              | \$10,000  | Medium | 2023 |         |         |          | \$10,000  |      |          |      |      |      |      |
| <b>Electrical/Instrumentation Improvements</b> |   |           |           |                    |                |           |        |      |         |         |          |           |      |          |      |      |      |      |
| 1  | Install Exit/Emergency lighting   | Mult.     | \$5,000   | LS                 | 1              | \$5,000   | High   | 2019 | \$5,000 |         |          |           |      |          |      |      |      |      |
| 2  | Provide arc-flash safety labeling   | Mult.     | \$500     | LS                 | 1              | \$500     | High   | 2019 | \$500   |         |          |           |      |          |      |      |      |      |
| 3  | Comprehensive Electrical Upgrade  | Pump Room | \$100,000 | LS                 | 1              | \$100,000 | Medium | 2024 |         |         |          | \$100,000 |      |          |      |      |      |      |
| 4  | Emergency Generator Upgrade   | Pump Room | \$75,000  | LS                 | 1              | \$75,000  | Medium | 2022 |         |         | \$75,000 |           |      |          |      |      |      |      |
| 5  | Confirm intrinsically safe barrier for submersible transducer                   | Exterior  | \$3,000   | LS                 | 1              | \$3,000   | High   | 2019 | \$3,000 |         |          |           |      |          |      |      |      |      |
| 6  | Install wet well seal instrument bypass seal-offs                               | Exterior  | \$1,000   | LS                 | 1              | \$1,000   | Low    | 2025 |         |         |          |           |      | \$1,000  |      |      |      |      |
| 7  | Control Panel/Pump Starter Replacement  | Exterior  | \$15,000  | LS                 | 1              | \$15,000  | Low    | 2025 |         |         |          |           |      | \$15,000 |      |      |      |      |
| 8  | Install utility power bypass circuit for UPS                                    | Controls  | \$2,500   | EA                 | 1              | \$2,500   | High   | 2019 | \$2,500 |         |          |           |      |          |      |      |      |      |

|  |                  |                 |                |                |                  |                  |                  |                 |            |            |            |            |  |  |  |  |  |  |
|--|------------------|-----------------|----------------|----------------|------------------|------------------|------------------|-----------------|------------|------------|------------|------------|--|--|--|--|--|--|
| High Priority Projects                   | \$13,500         |                 |                |                |                  |                  |                  |                 |            |            |            |            |  |  |  |  |  |  |
| Medium Priority Projects                 | \$276,000        |                 |                |                |                  |                  |                  |                 |            |            |            |            |  |  |  |  |  |  |
| Low Priority Projects                    | \$33,500         |                 |                |                |                  |                  |                  |                 |            |            |            |            |  |  |  |  |  |  |
| Subtotal                                 | \$323,000        | \$13,500        | \$2,000        | \$5,000        | \$78,000         | \$94,500         | \$104,000        | \$26,000        | \$0        | \$0        | \$0        | \$0        |  |  |  |  |  |  |
| Contingencies (20%)                      | \$64,600         | \$2,700         | \$400          | \$1,000        | \$15,600         | \$18,900         | \$20,800         | \$5,200         | \$0        | \$0        | \$0        | \$0        |  |  |  |  |  |  |
| Estimated Construction Cost              | \$387,600        | \$16,200        | \$2,400        | \$6,000        | \$93,600         | \$113,400        | \$124,800        | \$31,200        | \$0        | \$0        | \$0        | \$0        |  |  |  |  |  |  |
| Engineering and Administrative Allowance | \$77,500         | \$3,200         | \$500          | \$1,200        | \$18,700         | \$22,700         | \$25,000         | \$6,200         | \$0        | \$0        | \$0        | \$0        |  |  |  |  |  |  |
| <b>Estimated Total Project Cost</b>      | <b>\$465,100</b> | <b>\$19,400</b> | <b>\$2,900</b> | <b>\$7,200</b> | <b>\$112,300</b> | <b>\$136,100</b> | <b>\$149,800</b> | <b>\$37,400</b> | <b>\$0</b> | <b>\$0</b> | <b>\$0</b> | <b>\$0</b> |  |  |  |  |  |  |





CITY OF PORTSMOUTH, NEW HAMPSHIRE  
Pump Station Recommended Facilities Improvement Plan  
Atlantic Heights  
Updated

10/10/2018

| Item                                    | Location   | Unit Cost                   | Unit     | Estimated Quantity | Estimated Cost | Priority | Year   | 0    | 1        | 2       | 3        | 4        | 5        | 6    | 7    | 8       | 9        | 10   |
|---|--|-----------------------------|----------|--------------------|----------------|----------|--------|------|----------|---------|----------|----------|----------|------|------|---------|----------|------|
|   |  |                             |          |                    |                |          |        | 2019 | 2020     | 2021    | 2022     | 2023     | 2024     | 2025 | 2026 | 2027    | 2028     | 2029 |
| General Improvements                    |  |                             |          |                    |                |          |        |      |          |         |          |          |          |      |      |         |          |      |
| 1                                       | N/A  |                             |          |                    |                |          |        |      |          |         |          |          |          |      |      |         |          |      |
| Civil Improvements                      |  |                             |          |                    |                |          |        |      |          |         |          |          |          |      |      |         |          |      |
| 1                                       | N/A  |                             |          |                    |                |          |        |      |          |         |          |          |          |      |      |         |          |      |
| Architectural / Structural Improvements |  |                             |          |                    |                |          |        |      |          |         |          |          |          |      |      |         |          |      |
| 1                                       | Clean exterior brick face, localized repointing as required                    | Exterior                    | \$10,000 | LS                 | 1              | \$10,000 | Medium | 2021 |          |         | \$10,000 |          |          |      |      |         |          |      |
| 2                                       | Replace corroded lintel steel above generator louver                           | Exterior                    | \$1,000  | LS                 | 1              | \$1,000  | Medium | 2020 |          | \$1,000 |          |          |          |      |      |         |          |      |
| 3                                       | Replace door hardware  | Interior                    | \$1,000  | LS                 | 1              | \$1,000  | Medium | 2020 |          | \$1,000 |          |          |          |      |      |         |          |      |
| 4                                       | Replace roof with single point drainage  | Exterior                    | \$10,000 | LS                 | 1              | \$10,000 | Medium | 2022 |          |         |          | \$10,000 |          |      |      |         |          |      |
| 5                                       | Refinish walls/floors through lower level of structure                         | Interior                    | \$5,000  | LS                 | 1              | \$5,000  | Low    | 2024 |          |         |          |          | \$5,000  |      |      |         |          |      |
| Mechanical Improvements                 |  |                             |          |                    |                |          |        |      |          |         |          |          |          |      |      |         |          |      |
| 1                                       | Replace Exhaust Fan and Controls   | First floor, Generator Area | \$5,000  | LS                 | 1              | \$5,000  | High   | 2019 | \$5,000  |         |          |          |          |      |      |         |          |      |
| 2                                       | Seal propane tank exterior/interior building penetrations                      | Exterior                    | \$1,000  | LS                 | 1              | \$1,000  | Low    | 2019 | \$1,000  |         |          |          |          |      |      |         |          |      |
| 3                                       | Adjust sump pump float/replace sump pump                                       | Dry Well                    | \$500    | LS                 | 1              | \$500    | High   | 2019 | \$500    |         |          |          |          |      |      |         |          |      |
| 4                                       | Replace Unit Heaters   | Generator Room/Pump Room    | \$3,000  | EA                 | 2              | \$6,000  | Low    | 2022 |          |         |          | \$6,000  |          |      |      |         |          |      |
| 5                                       | Repair emergency generator exhaust piping insulation                           | Generator Room/Pump Room    | \$500    | LS                 | 1              | \$500    | Low    | 2019 | \$500    |         |          |          |          |      |      |         |          |      |
| Process Improvements                    |  |                             |          |                    |                |          |        |      |          |         |          |          |          |      |      |         |          |      |
| 1                                       | Pump/motor rehabilitation/replacement (planning)                               | Dry Well                    | \$20,000 | EA                 | 2              | \$40,000 | Medium | 2024 |          |         |          |          |          |      |      |         | \$40,000 |      |
| 2                                       | Replace wet well piping  | Wet Well                    | \$10,000 | LS                 | 1              | \$10,000 | Medium | 2022 |          |         | \$10,000 |          |          |      |      |         |          |      |
| Electrical/Instrumentation Improvements |  |                             |          |                    |                |          |        |      |          |         |          |          |          |      |      |         |          |      |
| 1                                       | Install Exit/Emergency lighting  | Mult.                       | \$5,000  | LS                 | 1              | \$5,000  | High   | 2019 | \$5,000  |         |          |          |          |      |      |         |          |      |
| 2                                       | Provide arc-flash safety labeling  | Mult.                       | \$500    | LS                 | 1              | \$500    | High   | 2019 | \$500    |         |          |          |          |      |      |         |          |      |
| 3                                       | Comprehensive MCC/Electrical Upgrade   | Mult.                       | \$75,000 | LS                 | 1              | \$75,000 | Medium | 2022 |          |         | \$75,000 |          |          |      |      |         |          |      |
| 4                                       | Emergency Generator and ATS Upgrade  | Mult.                       | \$75,000 | LS                 | 1              | \$75,000 | Medium | 2022 |          |         | \$75,000 |          |          |      |      |         |          |      |
| 5                                       | Install pump E-Stops   | Pump Room                   | \$4,000  | LS                 | 1              | \$4,000  | High   | 2019 | \$4,000  |         |          |          |          |      |      |         |          |      |
| 6                                       | Replace gas detection system (O2, H2S) recommended                             | Interior                    | \$5,000  | EA                 | 2              | \$10,000 | High   | 2019 | \$10,000 |         |          |          |          |      |      |         |          |      |
| 7                                       | Ground the antennae mast   | Exterior                    | \$500    | LS                 | 2              | \$1,000  | High   | 2019 | \$1,000  |         |          |          |          |      |      |         |          |      |
| 8                                       | Install wet well seal instrument bypass seal-offs                              | Exterior                    | \$1,000  | LS                 | 1              | \$1,000  | Low    | 2025 |          |         |          |          |          |      |      | \$1,000 |          |      |
| 9                                       | Install an intrinsically safe barrier for submersible transducer               | Exterior                    | \$3,000  | LS                 | 1              | \$3,000  | Medium | 2022 |          |         | \$3,000  |          |          |      |      |         |          |      |
| 10                                      | Install proof of airflow switches for ventilation confirmation                 | Exterior                    | \$2,000  | LS                 | 1              | \$2,000  | Medium | 2019 | \$2,000  |         |          |          |          |      |      |         |          |      |
| 11                                      | Control Panel Upgrade  | Dry Well                    | \$15,000 | LS                 | 1              | \$15,000 | Medium | 2024 |          |         |          |          | \$15,000 |      |      |         |          |      |
| 12                                      | Install utility power bypass circuit for UPS                                   | Controls                    | \$2,500  | EA                 | 1              | \$2,500  | Medium | 2019 | \$2,500  |         |          |          |          |      |      |         |          |      |
| 13                                      | Replace magnetic flow meter  | Dry Well                    | \$10,000 | EA                 | 1              | \$10,000 | Medium | 2021 |          |         | \$10,000 |          |          |      |      |         |          |      |
| 14                                      | Install a horn within the pump station to alert occupants of unsafe atmosphere | Interior                    | \$2,500  | LS                 | 1              | \$2,500  | Medium | 2019 | \$2,500  |         |          |          |          |      |      |         |          |      |

|                          |           |
|--------------------------|-----------|
| High Priority Projects   | \$26,000  |
| Medium Priority Projects | \$257,000 |
| Low Priority Projects    | \$13,500  |

|  |                  |                 |                |                 |                  |            |                 |                |            |            |            |            |
|--|------------------|-----------------|----------------|-----------------|------------------|------------|-----------------|----------------|------------|------------|------------|------------|
| Subtotal                                 | \$296,500        | \$34,500        | \$2,000        | \$20,000        | \$179,000        | \$0        | \$60,000        | \$1,000        | \$0        | \$0        | \$0        | \$0        |
| Contingencies (20%)                      | \$59,300         | \$6,900         | \$400          | \$4,000         | \$35,800         | \$0        | \$12,000        | \$200          | \$0        | \$0        | \$0        | \$0        |
| Estimated Construction Cost              | \$355,800        | \$41,400        | \$2,400        | \$24,000        | \$214,800        | \$0        | \$72,000        | \$1,200        | \$0        | \$0        | \$0        | \$0        |
| Engineering and Administrative Allowance | \$71,200         | \$8,300         | \$500          | \$4,800         | \$43,000         | \$0        | \$14,400        | \$200          | \$0        | \$0        | \$0        | \$0        |
| <b>Estimated Total Project Cost</b>      | <b>\$427,000</b> | <b>\$49,700</b> | <b>\$2,900</b> | <b>\$28,800</b> | <b>\$257,800</b> | <b>\$0</b> | <b>\$86,400</b> | <b>\$1,400</b> | <b>\$0</b> | <b>\$0</b> | <b>\$0</b> | <b>\$0</b> |



**CITY OF PORTSMOUTH, NEW HAMPSHIRE**  
**Pump Station Recommended Facilities Improvement Plan**  
**Leslie Drive**  
**Updated 10/10/2018**

|  |   |                             |          |                    |                |          |        |      | 0        | 1       | 2        | 3        | 4    | 5        | 6        | 7    | 8    | 9    | 10   |
|--|---|-----------------------------|----------|--------------------|----------------|----------|--------|------|----------|---------|----------|----------|------|----------|----------|------|------|------|------|
| Item   | Location  | Unit Cost                   | Unit     | Estimated Quantity | Estimated Cost | Priority | Year   |      | 2019     | 2020    | 2021     | 2022     | 2023 | 2024     | 2025     | 2026 | 2027 | 2028 | 2029 |
| <b>General Improvements</b>                    |   |                             |          |                    |                |          |        |      |          |         |          |          |      |          |          |      |      |      |      |
| 1  | Conduct CCTV survey of force main to confirm condition                          | Pump Room                   | \$5,000  | LS                 | 1              | \$5,000  | Medium | 2021 |          |         | \$5,000  |          |      |          |          |      |      |      |      |
| <b>Civil Improvements</b>                      |   |                             |          |                    |                |          |        |      |          |         |          |          |      |          |          |      |      |      |      |
| 1  | Confirm propane tank is fastened to foundation supports                         | Exterior                    | \$500    | LS                 | 1              | \$500    | High   | 2019 | \$500    |         |          |          |      |          |          |      |      |      |      |
| <b>Architectural / Structural Improvements</b> |   |                             |          |                    |                |          |        |      |          |         |          |          |      |          |          |      |      |      |      |
| 1  | Clean exterior brick face, repaint  | Exterior                    | \$15,000 | LS                 | 1              | \$15,000 | Low    | 2025 |          |         |          |          |      |          | \$15,000 |      |      |      |      |
| 2  | Repair/replace link seal from piping penetration in dry well                    | Dry Well                    | \$7,500  | LS                 | 1              | \$7,500  | Medium | 2020 |          | \$7,500 |          |          |      |          |          |      |      |      |      |
| 3  | Sandblast/repaint/reseal exposed lintel steel over louver                       | Exterior                    | \$1,000  | LS                 | 1              | \$1,000  | Medium | 2020 |          | \$1,000 |          |          |      |          |          |      |      |      |      |
| 4  | Replace pipe supports with new supports set atop grout pads                     | Dry Well                    | \$2,500  | LS                 | 1              | \$2,500  | Medium | 2022 |          |         |          | \$2,500  |      |          |          |      |      |      |      |
| 5  | Replace door hardware   | Interior                    | \$750    | LS                 | 1              | \$800    | Low    | 2020 |          | \$800   |          |          |      |          |          |      |      |      |      |
| 6  | Replace roof  | Exterior                    | \$10,000 | LS                 | 1              | \$10,000 | Medium | 2022 |          |         |          | \$10,000 |      |          |          |      |      |      |      |
| 7  | Refinish walls/floors through structure   | Interior                    | \$5,000  | LS                 | 1              | \$5,000  | Low    | 2024 |          |         |          |          |      | \$5,000  |          |      |      |      |      |
| 8  | Strip/repaint corroding pump skids  | Interior                    | \$2,500  | LS                 | 1              | \$2,500  | Medium | 2022 |          |         |          | \$2,500  |      |          |          |      |      |      |      |
| 9  | Install missing toeplate on the guard at the stairwell                          | Interior                    | \$500    | LS                 | 1              | \$500    | High   | 2019 | \$500    |         |          |          |      |          |          |      |      |      |      |
| 10   | Seal old conduit penetrations into existing wet well top slab                   | Wet well exterior           | \$500    | LS                 | 1              | \$500    | Low    | 2022 |          |         |          | \$500    |      |          |          |      |      |      |      |
| <b>Mechanical Improvements</b>                 |   |                             |          |                    |                |          |        |      |          |         |          |          |      |          |          |      |      |      |      |
| 1  | Replace Exhaust Fan and Controls  | First floor, Generator Area | \$5,000  | LS                 | 1              | \$5,000  | High   | 2019 | \$5,000  |         |          |          |      |          |          |      |      |      |      |
| 2  | Seal propane tank exterior/interior building penetrations                       | Exterior                    | \$1,000  | LS                 | 1              | \$1,000  | Low    | 2019 | \$1,000  |         |          |          |      |          |          |      |      |      |      |
| 3  | Adjust sump pump float/replace sump pump  | Dry Well                    | \$500    | LS                 | 1              | \$500    | High   | 2019 | \$500    |         |          |          |      |          |          |      |      |      |      |
| 4  | Replace intake damper associated with exhaust fan (linkage removed)             | Dry Well                    | \$1,000  | LS                 | 1              | \$1,000  | High   | 2019 | \$1,000  |         |          |          |      |          |          |      |      |      |      |
| 5  | Replace Unit Heaters  | Generator Room/Pump Room    | \$3,000  | EA                 | 2              | \$6,000  | Low    | 2022 |          |         |          | \$6,000  |      |          |          |      |      |      |      |
| <b>Process Improvements</b>                    |   |                             |          |                    |                |          |        |      |          |         |          |          |      |          |          |      |      |      |      |
| 1  | Pump motor rehabilitation/replacement (planning)                                | Dry Well                    | \$15,000 | EA                 | 2              | \$30,000 | Medium | 2021 |          |         | \$30,000 |          |      |          |          |      |      |      |      |
| <b>Electrical/Instrumentation Improvements</b> |   |                             |          |                    |                |          |        |      |          |         |          |          |      |          |          |      |      |      |      |
| 1  | Install Exit/Emergency lighting   | Mult.                       | \$5,000  | LS                 | 1              | \$5,000  | High   | 2019 | \$5,000  |         |          |          |      |          |          |      |      |      |      |
| 2  | Provide arc-flash safety labeling   | Mult.                       | \$500    | LS                 | 1              | \$500    | High   | 2019 | \$500    |         |          |          |      |          |          |      |      |      |      |
| 3  | Comprehensive MCC/Electrical Upgrade  | Mult.                       | \$80,000 | LS                 | 1              | \$80,000 | Medium | 2022 |          |         |          | \$80,000 |      |          |          |      |      |      |      |
| 4  | Emergency Generator and ATS Upgrade   | Mult.                       | \$80,000 | LS                 | 1              | \$80,000 | Medium | 2022 |          |         |          | \$80,000 |      |          |          |      |      |      |      |
| 5  | Install pump E-Stops  | Pump Room                   | \$4,000  | LS                 | 1              | \$4,000  | High   | 2019 | \$4,000  |         |          |          |      |          |          |      |      |      |      |
| 6  | Ground the antennae mast  | Exterior                    | \$500    | LS                 | 2              | \$1,000  | High   | 2019 | \$1,000  |         |          |          |      |          |          |      |      |      |      |
| 7  | Replace exterior electrical service entrance enclosure                          | Exterior                    | \$5,000  | LS                 | 1              | \$5,000  | Medium | 2020 |          | \$5,000 |          |          |      |          |          |      |      |      |      |
| 8  | Replace gas detection system (O2, H2S) recommended                              | Interior                    | \$5,000  | EA                 | 2              | \$10,000 | High   | 2019 | \$10,000 |         |          |          |      |          |          |      |      |      |      |
| 9  | Ground the antennae mast  | Exterior                    | \$500    | LS                 | 2              | \$1,000  | High   | 2019 | \$1,000  |         |          |          |      |          |          |      |      |      |      |
| 10   | Install wet well seal instrument bypass seal-offs                               | Exterior                    | \$1,000  | LS                 | 1              | \$1,000  | Low    | 2025 |          |         |          |          |      |          | \$1,000  |      |      |      |      |
| 11   | Install an intrinsically safe barrier for submersible transducer                | Exterior                    | \$3,000  | LS                 | 1              | \$3,000  | Medium | 2022 |          |         |          | \$3,000  |      |          |          |      |      |      |      |
| 12   | Install proof of airflow switches for ventilation confirmation                  | Exterior                    | \$2,000  | LS                 | 1              | \$2,000  | Medium | 2019 | \$2,000  |         |          |          |      |          |          |      |      |      |      |
| 13   | Control Panel Upgrade   | Dry Well                    | \$15,000 | LS                 | 1              | \$15,000 | Medium | 2024 |          |         |          |          |      | \$15,000 |          |      |      |      |      |
| 14   | Install utility power bypass circuit for UPS                                    | Controls                    | \$2,500  | EA                 | 1              | \$2,500  | Medium | 2019 | \$2,500  |         |          |          |      |          |          |      |      |      |      |
| 15   | Replace magnetic flow meter   | Dry Well                    | \$10,000 | EA                 | 1              | \$10,000 | Medium | 2021 |          |         | \$10,000 |          |      |          |          |      |      |      |      |
| 16   | Install a horn within the pump station to alert occupants of unsafe atmosphere. | Interior                    | \$2,500  | LS                 | 1              | \$2,500  | Medium | 2019 | \$2,500  |         |          |          |      |          |          |      |      |      |      |

|                          |           |
|--------------------------|-----------|
| High Priority Projects   | \$29,000  |
| Medium Priority Projects | \$258,500 |
| Low Priority Projects    | \$29,300  |

|  |  |                  |                 |                 |                 |                  |            |                 |                 |            |            |            |            |
|--|--|------------------|-----------------|-----------------|-----------------|------------------|------------|-----------------|-----------------|------------|------------|------------|------------|
| Subtotal                                 |  | \$316,800        | \$37,000        | \$14,300        | \$45,000        | \$184,500        | \$0        | \$20,000        | \$16,000        | \$0        | \$0        | \$0        | \$0        |
| Contingencies (20%)                      |  | \$63,400         | \$7,400         | \$2,860         | \$9,000         | \$36,900         | \$0        | \$4,000         | \$3,200         | \$0        | \$0        | \$0        | \$0        |
| Estimated Construction Cost              |  | \$380,200        | \$44,400        | \$17,200        | \$54,000        | \$221,400        | \$0        | \$24,000        | \$19,200        | \$0        | \$0        | \$0        | \$0        |
| Engineering and Administrative Allowance |  | \$76,000         | \$8,900         | \$3,400         | \$10,800        | \$44,300         | \$0        | \$4,800         | \$3,800         | \$0        | \$0        | \$0        | \$0        |
| <b>Estimated Total Project Cost</b>      |  | <b>\$456,200</b> | <b>\$53,300</b> | <b>\$20,600</b> | <b>\$64,800</b> | <b>\$265,700</b> | <b>\$0</b> | <b>\$28,800</b> | <b>\$23,000</b> | <b>\$0</b> | <b>\$0</b> | <b>\$0</b> | <b>\$0</b> |

CITY OF PORTSMOUTH, NEW HAMPSHIRE  
 Pump Station Recommended Facilities Improvement Plan  
 Corporate Drive  
 Updated 10/10/2018

|   |   |           |          |                    |                |          |        |      |      | 0       | 1    | 2       | 3    | 4    | 5        | 6    | 7    | 8        | 9 | 10 |
|---|---|-----------|----------|--------------------|----------------|----------|--------|------|------|---------|------|---------|------|------|----------|------|------|----------|---|----|
| Item                                    | Location  | Unit Cost | Unit     | Estimated Quantity | Estimated Cost | Priority | Year   | 2019 | 2020 | 2021    | 2022 | 2023    | 2024 | 2025 | 2026     | 2027 | 2028 | 2029     |   |    |
| General Improvements                    |   |           |          |                    |                |          |        |      |      |         |      |         |      |      |          |      |      |          |   |    |
| 1                                       | N/A   |           |          |                    |                |          |        |      |      |         |      |         |      |      |          |      |      |          |   |    |
| Civil Improvements                      |   |           |          |                    |                |          |        |      |      |         |      |         |      |      |          |      |      |          |   |    |
| 1                                       | N/A   |           |          |                    |                |          |        |      |      |         |      |         |      |      |          |      |      |          |   |    |
| Architectural / Structural Improvements |   |           |          |                    |                |          |        |      |      |         |      |         |      |      |          |      |      |          |   |    |
| 1                                       | Prime/paint gable end   | Exterior  | \$1,000  | LS                 | 1              | \$1,000  | Low    | 2023 |      |         |      | \$1,000 |      |      |          |      |      |          |   |    |
| 2                                       | Install new shingled roof   | Exterior  | \$10,000 | LS                 | 1              | \$10,000 | Low    | 2026 |      |         |      |         |      |      |          |      |      | \$10,000 |   |    |
| Mechanical Improvements                 |   |           |          |                    |                |          |        |      |      |         |      |         |      |      |          |      |      |          |   |    |
| 1                                       | Replace emergency generator exhaust piping through wall with a new ventilated thimble | Pump Room | \$1,000  | LS                 | 1              | \$1,000  | Medium | 2020 |      | \$1,000 |      |         |      |      |          |      |      |          |   |    |
| 2                                       | Insulate emergency generator exhaust piping   | Pump Room | \$1,000  | LS                 | 1              | \$1,000  | Medium | 2020 |      | \$1,000 |      |         |      |      |          |      |      |          |   |    |
| Process Improvements                    |   |           |          |                    |                |          |        |      |      |         |      |         |      |      |          |      |      |          |   |    |
| 1                                       | N/A   |           |          |                    |                |          |        | \$0  |      |         |      |         |      |      |          |      |      |          |   |    |
| Electrical/Instrumentation Improvements |   |           |          |                    |                |          |        |      |      |         |      |         |      |      |          |      |      |          |   |    |
| 1                                       | Replace bubbler with submersible transducer   | Wet Well  | \$2,500  | LS                 | 1              | \$2,500  | Low    | 2022 |      |         |      | \$2,500 |      |      |          |      |      |          |   |    |
| 2                                       | Control Panel PLC upgrade (SLC 5/05 obsolete)   | Exterior  | \$15,000 | LS                 | 1              | \$15,000 | Medium | 2024 |      |         |      |         |      |      | \$15,000 |      |      |          |   |    |

|                          |          |
|--------------------------|----------|
| High Priority Projects   | \$0      |
| Medium Priority Projects | \$17,000 |
| Low Priority Projects    | \$13,500 |

|  |                 |            |                |            |                |                |                 |            |                 |            |            |            |
|--|-----------------|------------|----------------|------------|----------------|----------------|-----------------|------------|-----------------|------------|------------|------------|
| Subtotal                                 | \$30,500        | \$0        | \$2,000        | \$0        | \$2,500        | \$1,000        | \$15,000        | \$0        | \$10,000        | \$0        | \$0        | \$0        |
| Contingencies (20%)                      | \$6,100         | \$0        | \$400          | \$0        | \$500          | \$200          | \$3,000         | \$0        | \$2,000         | \$0        | \$0        | \$0        |
| Estimated Construction Cost              | \$36,600        | \$0        | \$2,400        | \$0        | \$3,000        | \$1,200        | \$18,000        | \$0        | \$12,000        | \$0        | \$0        | \$0        |
| Engineering and Administrative Allowance | \$7,300         | \$0        | \$500          | \$0        | \$600          | \$200          | \$3,600         | \$0        | \$2,400         | \$0        | \$0        | \$0        |
| <b>Estimated Total Project Cost</b>      | <b>\$43,900</b> | <b>\$0</b> | <b>\$2,900</b> | <b>\$0</b> | <b>\$3,600</b> | <b>\$1,400</b> | <b>\$21,600</b> | <b>\$0</b> | <b>\$14,400</b> | <b>\$0</b> | <b>\$0</b> | <b>\$0</b> |

CITY OF PORTSMOUTH, NEW HAMPSHIRE  
Pump Station Recommended Facilities Improvement Plan

Griffin Park  
Updated 10/10/2018

| Item                                    | Location  | Unit Cost | Unit      | Estimated Quantity | Estimated Cost | Priority  | Year   | 0    | 1       | 2       | 3       | 4        | 5        | 6         | 7    | 8    | 9        | 10   |
|---|---|-----------|-----------|--------------------|----------------|-----------|--------|------|---------|---------|---------|----------|----------|-----------|------|------|----------|------|
|   |   |           |           |                    |                |           |        | 2019 | 2020    | 2021    | 2022    | 2023     | 2024     | 2025      | 2026 | 2027 | 2028     | 2029 |
| General Improvements                    |   |           |           |                    |                |           |        |      |         |         |         |          |          |           |      |      |          |      |
| 1                                       | N/A   |           |           |                    |                |           |        |      |         |         |         |          |          |           |      |      |          |      |
| Civil Improvements                      |   |           |           |                    |                |           |        |      |         |         |         |          |          |           |      |      |          |      |
| 1                                       | N/A   |           |           |                    |                |           |        |      |         |         |         |          |          |           |      |      |          |      |
| Architectural / Structural Improvements |   |           |           |                    |                |           |        |      |         |         |         |          |          |           |      |      |          |      |
| 1                                       | Repair structure eaves/trim   | Exterior  | \$6,000   | LS                 | 1              | \$6,000   | Medium | 2019 | \$6,000 |         |         |          |          |           |      |      |          |      |
| 2                                       | Replace roof, add roof drains   | Exterior  | \$12,000  | LS                 | 1              | \$12,000  | Medium | 2025 |         |         |         |          |          | \$12,000  |      |      |          |      |
| 3                                       | Repair foundation chipping near the entrance door                                     | Exterior  | \$2,000   | LS                 | 1              | \$2,000   | Medium | 2022 |         |         | \$2,000 |          |          |           |      |      |          |      |
| Mechanical Improvements                 |   |           |           |                    |                |           |        |      |         |         |         |          |          |           |      |      |          |      |
| 1                                       | Replace emergency generator exhaust piping through wall with a new ventilated thimble | Pump Room | \$1,000   | LS                 | 1              | \$1,000   | Medium | 2020 |         | \$1,000 |         |          |          |           |      |      |          |      |
| Process Improvements                    |   |           |           |                    |                |           |        |      |         |         |         |          |          |           |      |      |          |      |
| 1                                       | Replace Pump No. 1 (1990)   | Pump Room | \$10,000  | LS                 | 1              | \$10,000  | Medium | 2022 |         |         |         | \$10,000 |          |           |      |      |          |      |
| 2                                       | Pump motor replacement/rehabilitation   | Pump Room | \$10,000  | LS                 | 2              | \$20,000  | Medium | 2023 |         |         |         |          | \$20,000 |           |      |      |          |      |
| 3                                       | Replace magnetic flow meter   | Pump Room | \$6,000   | LS                 | 1              | \$6,000   | Low    | 2025 |         |         |         |          |          | \$6,000   |      |      |          |      |
| 4                                       | Replace corroded wet well discharge piping and pipe support                           | Wet Well  | \$7,500   | LS                 | 1              | \$7,500   | High   | 2020 |         | \$7,500 |         |          |          |           |      |      |          |      |
| 5                                       | Re-route force main out from under the building structure (optional)                  | Exterior  | \$8,000   | LS                 | 1              | \$8,000   | Low    | 2020 |         | \$8,000 |         |          |          |           |      |      |          |      |
| Electrical/Instrumentation Improvements |   |           |           |                    |                |           |        |      |         |         |         |          |          |           |      |      |          |      |
| 1                                       | Install Exit/Emergency lighting   | Mult.     | \$5,000   | LS                 | 1              | \$5,000   | High   | 2019 | \$5,000 |         |         |          |          |           |      |      |          |      |
| 2                                       | Provide arc-flash safety labeling   | Mult.     | \$500     | LS                 | 1              | \$500     | High   | 2019 | \$500   |         |         |          |          |           |      |      |          |      |
| 3                                       | Comprehensive Control Panel/Electrical Upgrade  | Pump Room | \$100,000 | LS                 | 1              | \$100,000 | Low    | 2025 |         |         |         |          |          | \$100,000 |      |      |          |      |
| 4                                       | Emergency Generator Upgrade   | Pump Room | \$75,000  | LS                 | 1              | \$75,000  | Low    | 2028 |         |         |         |          |          |           |      |      | \$75,000 |      |
| 5                                       | Install utility power bypass circuit for UPS  | Controls  | \$2,500   | EA                 | 1              | \$2,500   | High   | 2019 | \$2,500 |         |         |          |          |           |      |      |          |      |

|                          |           |
|--------------------------|-----------|
| High Priority Projects   | \$15,500  |
| Medium Priority Projects | \$51,000  |
| Low Priority Projects    | \$189,000 |

|  |                  |                 |                 |            |                 |                 |            |                  |            |            |                  |            |
|--|------------------|-----------------|-----------------|------------|-----------------|-----------------|------------|------------------|------------|------------|------------------|------------|
| Subtotal                                 | \$255,500        | \$14,000        | \$16,500        | \$0        | \$12,000        | \$20,000        | \$0        | \$118,000        | \$0        | \$0        | \$75,000         | \$0        |
| Contingencies (20%)                      | \$51,100         | \$2,800         | \$3,300         | \$0        | \$2,400         | \$4,000         | \$0        | \$23,600         | \$0        | \$0        | \$15,000         | \$0        |
| Estimated Construction Cost              | \$306,600        | \$16,800        | \$19,800        | \$0        | \$14,400        | \$24,000        | \$0        | \$141,600        | \$0        | \$0        | \$90,000         | \$0        |
| Engineering and Administrative Allowance | \$61,300         | \$3,400         | \$4,000         | \$0        | \$2,900         | \$4,800         | \$0        | \$28,300         | \$0        | \$0        | \$18,000         | \$0        |
| <b>Estimated Total Project Cost</b>      | <b>\$367,900</b> | <b>\$20,200</b> | <b>\$23,800</b> | <b>\$0</b> | <b>\$17,300</b> | <b>\$28,800</b> | <b>\$0</b> | <b>\$169,900</b> | <b>\$0</b> | <b>\$0</b> | <b>\$108,000</b> | <b>\$0</b> |

**Tuckers Cove**  
**Updated** **10/10/2018**

| Item   | Location  | Unit Cost | Unit     | Estimated Quantity | Estimated Cost | Priority | Year   | 0    | 1        | 2       | 3    | 4       | 5    | 6       | 7    | 8    | 9        | 10   |
|--|---|-----------|----------|--------------------|----------------|----------|--------|------|----------|---------|------|---------|------|---------|------|------|----------|------|
|  |   |           |          |                    |                |          |        | 2019 | 2020     | 2021    | 2022 | 2023    | 2024 | 2025    | 2026 | 2027 | 2028     | 2029 |
| <b>General Improvements</b>                    |   |           |          |                    |                |          |        |      |          |         |      |         |      |         |      |      |          |      |
| 1  | N/A   |           |          |                    |                |          |        |      |          |         |      |         |      |         |      |      |          |      |
| <b>Civil Improvements</b>                      |   |           |          |                    |                |          |        |      |          |         |      |         |      |         |      |      |          |      |
| 1  | N/A   |           |          |                    |                |          |        |      |          |         |      |         |      |         |      |      |          |      |
| <b>Architectural / Structural Improvements</b> |   |           |          |                    |                |          |        |      |          |         |      |         |      |         |      |      |          |      |
| 1  | Repair structure eaves/trim   | Exterior  | \$6,000  | LS                 | 1              | \$6,000  | Medium | 2020 |          | \$6,000 |      |         |      |         |      |      |          |      |
| 2  | Replace roof and add roof gutters   | Exterior  | \$12,000 | LS                 | 1              | \$12,000 | High   | 2019 | \$12,000 |         |      |         |      |         |      |      |          |      |
| 3  | Pressure wash and seal interior masonry CMU   | Interior  | \$5,000  | LS                 | 1              | \$5,000  | Low    | 2023 |          |         |      | \$5,000 |      |         |      |      |          |      |
| 4  | Replace wet well hatch hinge  | Wet Well  | \$5,000  | LS                 | 1              | \$5,000  | Low    | 2025 |          |         |      |         |      | \$5,000 |      |      |          |      |
| <b>Mechanical Improvements</b>                 |   |           |          |                    |                |          |        |      |          |         |      |         |      |         |      |      |          |      |
| 1  | Replace emergency generator exhaust piping through wall with a new ventilated thimble | Pump Room | \$1,000  | LS                 | 1              | \$1,000  | Medium | 2020 |          | \$1,000 |      |         |      |         |      |      |          |      |
| 2  | Replace gas fired unit heater   | Pump Room | \$3,000  | LS                 | 1              | \$3,000  | Medium | 2020 |          | \$3,000 |      |         |      |         |      |      |          |      |
| <b>Process Improvements</b>                    |   |           |          |                    |                |          |        |      |          |         |      |         |      |         |      |      |          |      |
| 1  | Replace magnetic flow meter   | Pump Room | \$6,000  | LS                 | 1              | \$6,000  | Low    | 2025 |          |         |      |         |      | \$6,000 |      |      |          |      |
| <b>Electrical/Instrumentation Improvements</b> |   |           |          |                    |                |          |        |      |          |         |      |         |      |         |      |      |          |      |
| 1  | Comprehensive Control Panel/Starter Upgrade   | Exterior  | \$15,000 | LS                 | 1              | \$15,000 | Low    | 2026 |          |         |      |         |      |         |      |      | \$15,000 |      |
| 2  | Install utility power bypass circuit for UPS  | Controls  | \$2,500  | LS                 | 1              | \$2,500  | High   | 2019 | \$2,500  |         |      |         |      |         |      |      |          |      |
| 3  | Provide arc-flash safety labeling   | Mult.     | \$500    | LS                 | 1              | \$500    | High   | 2019 | \$500    |         |      |         |      |         |      |      |          |      |
| 4  | Replace ultrasonic transducer with submersible transducer                             | Wet Well  | \$2,500  | LS                 | 1              | \$2,500  | Low    | 2023 |          |         |      | \$2,500 |      |         |      |      |          |      |

|                          |          |
|--------------------------|----------|
| High Priority Projects   | \$15,000 |
| Medium Priority Projects | \$10,000 |
| Low Priority Projects    | \$33,500 |

|  |                 |                 |                 |            |            |                 |            |                 |                 |            |            |            |
|--|-----------------|-----------------|-----------------|------------|------------|-----------------|------------|-----------------|-----------------|------------|------------|------------|
| Subtotal                                 | \$58,500        | \$15,000        | \$10,000        | \$0        | \$0        | \$7,500         | \$0        | \$11,000        | \$15,000        | \$0        | \$0        | \$0        |
| Contingencies (20%)                      | \$11,700        | \$3,000         | \$2,000         | \$0        | \$0        | \$1,500         | \$0        | \$2,200         | \$3,000         | \$0        | \$0        | \$0        |
| Estimated Construction Cost              | \$70,200        | \$18,000        | \$12,000        | \$0        | \$0        | \$9,000         | \$0        | \$13,200        | \$18,000        | \$0        | \$0        | \$0        |
| Engineering and Administrative Allowance | \$14,000        | \$3,600         | \$2,400         | \$0        | \$0        | \$1,800         | \$0        | \$2,600         | \$3,600         | \$0        | \$0        | \$0        |
| <b>Estimated Total Project Cost</b>      | <b>\$84,200</b> | <b>\$21,600</b> | <b>\$14,400</b> | <b>\$0</b> | <b>\$0</b> | <b>\$10,800</b> | <b>\$0</b> | <b>\$15,800</b> | <b>\$21,600</b> | <b>\$0</b> | <b>\$0</b> | <b>\$0</b> |



CITY OF PORTSMOUTH, NEW HAMPSHIRE

Pump Station Recommended Facilities Improvement Plan

Marsh Lane

Updated 10/10/2018

|   |   |   |          |           |      |                    |                |          |      | 0       | 1       | 2    | 3        | 4    | 5    | 6    | 7        | 8    | 9    | 10   |
|---|---|---|----------|-----------|------|--------------------|----------------|----------|------|---------|---------|------|----------|------|------|------|----------|------|------|------|
|   |   | Item  | Location | Unit Cost | Unit | Estimated Quantity | Estimated Cost | Priority | Year | 2019    | 2020    | 2021 | 2022     | 2023 | 2024 | 2025 | 2026     | 2027 | 2028 | 2029 |
| General Improvements                    |   |   |          |           |      |                    |                |          |      |         |         |      |          |      |      |      |          |      |      |      |
|   | 1 | -   |          |           |      |                    |                |          |      |         |         |      |          |      |      |      |          |      |      |      |
| Civil Improvements                      |   |   |          |           |      |                    |                |          |      |         |         |      |          |      |      |      |          |      |      |      |
|   | 1 | -   |          |           |      |                    |                |          |      |         |         |      |          |      |      |      |          |      |      |      |
| Architectural / Structural Improvements |   |   |          |           |      |                    |                |          |      |         |         |      |          |      |      |      |          |      |      |      |
|   | 1 | Add safety net/fall protection for wet well hatch           | Wet Well | \$1,000   | LS   | 1                  | \$1,000        | Medium   | 2020 |         | \$1,000 |      |          |      |      |      |          |      |      |      |
| Mechanical Improvements                 |   |   |          |           |      |                    |                |          |      |         |         |      |          |      |      |      |          |      |      |      |
|   | 1 | -   |          |           |      |                    |                |          |      |         |         |      |          |      |      |      |          |      |      |      |
| Process Improvements                    |   |   |          |           |      |                    |                |          |      |         |         |      |          |      |      |      |          |      |      |      |
|   | 1 | Pump Replacement (planning)                                 | Wet Well | \$4,000   | EA   | 2                  | \$8,000        | Medium   | 2022 |         |         |      | \$8,000  |      |      |      |          |      |      |      |
| Electrical/Instrumentation Improvements |   |   |          |           |      |                    |                |          |      |         |         |      |          |      |      |      |          |      |      |      |
|   | 1 | Upgrade Electrical Distribution Enclosure/Equipment (M      | Exterior | \$40,000  | LS   | 1                  | \$40,000       | Low      | 2022 |         |         |      | \$40,000 |      |      |      |          |      |      |      |
|   | 2 | Install intrinsically safe barrier for wet well instruments | Controls | \$2,000   | LS   | 1                  | \$2,000        | Medium   | 2020 |         | \$2,000 |      |          |      |      |      |          |      |      |      |
|   | 3 | Install utility power bypass circuit for UPS                | Controls | \$2,500   | EA   | 1                  | \$2,500        | High     | 2019 | \$2,500 |         |      |          |      |      |      |          |      |      |      |
|   | 4 | Control Panel/Starters Upgrade (planning)                   | Controls | \$15,000  | LS   | 1                  | \$15,000       | Low      | 2026 |         |         |      |          |      |      |      | \$15,000 |      |      |      |

|                          |          |
|--------------------------|----------|
| High Priority Projects   | \$2,500  |
| Medium Priority Projects | \$11,000 |
| Low Priority Projects    | \$55,000 |

|  |                 |                |                |            |                 |            |            |            |                 |            |            |            |
|--|-----------------|----------------|----------------|------------|-----------------|------------|------------|------------|-----------------|------------|------------|------------|
| Subtotal                                 | \$68,500        | \$2,500        | \$3,000        | \$0        | \$48,000        | \$0        | \$0        | \$0        | \$15,000        | \$0        | \$0        | \$0        |
| Contingencies (20%)                      | \$13,700        | \$500          | \$600          | \$0        | \$9,600         | \$0        | \$0        | \$0        | \$3,000         | \$0        | \$0        | \$0        |
| Estimated Construction Cost              | \$82,200        | \$3,000        | \$3,600        | \$0        | \$57,600        | \$0        | \$0        | \$0        | \$18,000        | \$0        | \$0        | \$0        |
| Engineering and Administrative Allowance | \$16,400        | \$600          | \$700          | \$0        | \$11,500        | \$0        | \$0        | \$0        | \$3,600         | \$0        | \$0        | \$0        |
| <b>Estimated Total Project Cost</b>      | <b>\$98,600</b> | <b>\$3,600</b> | <b>\$4,300</b> | <b>\$0</b> | <b>\$69,100</b> | <b>\$0</b> | <b>\$0</b> | <b>\$0</b> | <b>\$21,600</b> | <b>\$0</b> | <b>\$0</b> | <b>\$0</b> |





C

---

|                 |  |                     |            |
|-----------------|--|---------------------|------------|
| <b>TO:</b>      | Appendix C   | <b>DATE:</b>        | 10/12/2018 |
| <b>FROM:</b>    | Paige Howard, Michael Curry  | <b>PROJECT NO.:</b> | 13969A     |
| <b>SUBJECT:</b> | Portsmouth, New Hampshire<br>Pump Station Master Plan<br>Coastal Resiliency Assessment |                     |            |

---

This memorandum is to present the findings from the City of Portsmouth’s 2013 Coastal Resiliency Initiative Climate Change Vulnerability Assessment and Adaptation Plan as they relate to the City’s twenty public wastewater pumping stations. The 2013 plan provides a broad overview of risk and vulnerability of the City’s assets as a result of projected climate change and resulting sea level and flood elevations rise. The conclusions from the plan will be used as a basis for flood protection and pump station siting recommendations in the Pump Station Master Plan.

The 2013 assessment evaluated impacts of tidal flooding in Portsmouth as a result from sea level rise and coastal storms. The study evaluated various sea level rise scenarios using a range of greenhouse gas emission scenarios and projected flood elevations for the years 2050 and 2100. Modeling efforts used two baseline flood conditions including:

- Mean Higher High Water (MHHW): The higher average high tide
- Mean Higher High Water Flood (MHHW Flood): The higher average high tide with coastal storm surge from a 100-year coastal storm

The modeled scenario results are described in detail below:

**SCENARIO 1:** A *7.5-foot* elevation model correlates to a predicted MHHW in the year 2100 given a low climate change estimate.

**SCENARIO 2:** An *11.5-foot* elevation correlates to the present-day 100-year coastal flood elevation (11.2 ft.) and to two future conditions: the 2050, 100-year coastal flood elevation at

MHHW under a low greenhouse gas emission scenario (12.2 ft.), and the MHHW in 2100 given a high greenhouse gas emission scenario (10.7 ft.).

**SCENARIO 3:** A *13.5-foot* elevation correlates to the 100-year coastal flood elevation at MHHW given the 2050 high greenhouse gas emission scenario (12.9 ft.) as well as the 100-year coastal flood elevation at MHHW with the 2100 low emission scenario (13.7 ft.).

**SCENARIO 4:** An *18.0-foot* modeled elevation corresponds to the 100-year coastal flood at MHHW given the 2100 high emission scenario (17.5 ft.).

Using the elevations developed as part of the Climate Change Vulnerability Assessment, the City's twenty public wastewater pump stations were analyzed for impacts due to each of the four flooding scenarios. **Table 1** provides a summary of the pump stations which would be potentially affected by flooding scenarios 1 through 4.

Pump stations within the area of impact for each scenario are depicted in **Figures 1 through 4**, which are attached. Recommendations for flood impact mitigation is included in Section 2 – Section 4 of the Pump Station Master Plan.


**TABLE 1 – PORTSMOUTH PUMP STATION POTENTIAL FLOOD IMPACTS**

| Pump Station          | Address                  | Lowest Impacted Flood Elevation (ft) above NAVD | Pump Station Elevation (ft) above NAVD |
|-----------------------|--------------------------|---|--|
| Atlantic Heights      | 134 Preble Way           | Not impacted                                    | 49.0                                   |
| <b>Clough Dr.</b>     | <b>210 Clough Dr.</b>    | <b>18.0 (Scenario 4)</b>                        | <b>14.0</b>                            |
| Constitution Ave.     | 278 Constitution Ave.    | Not impacted                                    | 49.0*                                  |
| Corporate             | 215 Corporate Dr.        | Not impacted                                    | 30.0                                   |
| <b>Deer St.</b>       | <b>2 Deer St.</b>        | <b>13.5 (Scenario 3)</b>                        | <b>13.0</b>                            |
| Griffin               | 205 Griffin Park         | Not impacted                                    | 37.75                                  |
| Gosling Rd.           | 120 Gosling Rd.          | Not impacted                                    | 42.0*                                  |
| Heritage Ave.         | 329 Heritage Ave.        | Not impacted                                    | 50.0                                   |
| <b>Lafayette Rd.</b>  | <b>630 Lafayette Rd.</b> | <b>18.0 (Scenario 4)</b>                        | <b>14.0</b>                            |
| <b>Leslie Dr.</b>     | <b>590 Market St.</b>    | <b>11.5 (Scenario 2)</b>                        | <b>9.5</b>                             |
| <b>Marcy St.</b>      | <b>535 Marcy St.</b>     | <b>11.5 (Scenario 2)</b>                        | <b>10.2</b>                            |
| <b>Marsh Ln.</b>      | <b>4 Marsh Ln.</b>       | <b>7.5 (Scenario 1)</b>                         | <b>5.9</b>                             |
| <b>Mechanic St.</b>   | <b>113 Mechanic St.</b>  | <b>11.5 (Scenario 2)</b>                        | <b>8.7</b>                             |
| <b>Mill Pond Way</b>  | <b>131 Mill Pond</b>     | <b>13.5 (Scenario 3)</b>                        | <b>11.8</b>                            |
| <b>North West Rd.</b> | <b>221 North West</b>    | <b>11.5 (Scenario 2)</b>                        | <b>11.0</b>                            |
| Ryeline               | 3618 Lafayette Rd.       | Not impacted                                    | 44.3                                   |
| Tuckers Cover         | 91 Gosport Rd.           | Not impacted                                    | 19.5                                   |
| West Rd.              | 280 West Rd.             | Not impacted                                    | 43.8                                   |
| Woodlands I           | 307 F.W. Hartford        | Not impacted                                    | 32.0*                                  |
| Woodlands II          | 516 F.W. Hartford        | Not impacted                                    | 35.8                                   |

\*Elevations derived from GIS.



Flood elevations displayed are from the Portsmouth Coastal Resiliency Initiative Report, using GIS data delivered to Wright-Pierce by the City of Portsmouth.



**Flood Elevation 11.5 ft (350cm)**  
**DN**

|  |   |
|--|---|
|  | 1 |
|  | 2 |

**SCENARIO 2**




**Flood Elevations from Coastal Resiliency Initiative**  
 Portsmouth, NH

|                                  |                |               |
|----------------------------------|----------------|---------------|
| PROJ NO: 13969                   | DATE: 3/5/2018 | FIGURE:       |
| <b>WRIGHT-PIERCE</b>             |                | <b>3-11.5</b> |
| Engineering a Better Environment |                |               |

KZ: W:\GIS\_Development\Projects\NH\Portsmouth\1115177\_WRI\_Maps\Final\Map\FloodElevation\_350.mxd

Source: Esri, DigitalGlobe, GeoEye, Earthstar, GeoGrid


Flood elevations displayed are from the Portsmouth Coastal Resiliency Initiative Report, using GIS data delivered to Wright-Pierce by the City of Portsmouth.



**Flood Elevation 13.5 ft (410cm)**  
**DN**

|  |   |
|--|---|
|  | 1 |
|  | 2 |

**SCENARIO 3**



**Flood Elevations from Coastal Resiliency Initiative**  
 Portsmouth, NH


|                |                |                |
|----------------|----------------|----------------|
| PROJ NO: 13969 | DATE: 3/5/2018 | FIGURE: 2-13.5 |
|----------------|----------------|----------------|

**WRIGHT-PIERCE**  
 Engineering a Better Environment


KZ: W:\GIS\Development\Projects\NH\Portsmouth\111517 - WRI\_Maps\Final\Map\FloodElevation\_410.mxd

Source: Esri, DigitalGlobe, GeoEye, Earthstar, GeoEye

Flood elevations displayed are from the Portsmouth Coastal Resiliency Initiative Report, using GIS data delivered to Wright-Pierce by the City of Portsmouth.



**Flood Elevation 18.5 ft (550cm)**  
**DN**  
 1  
 2  
**SCENARIO 4**



**Flood Elevations from Coastal Resiliency Initiative**  
 Portsmouth, NH

|                |                |                |
|----------------|----------------|----------------|
| PROJ NO: 13969 | DATE: 3/5/2018 | FIGURE: 1-18.5 |
|----------------|----------------|----------------|

**WRIGHT-PIERCE**  
 Engineering a Better Environment

KZ: W:\GIS\Development\Projects\NH\Portsmouth\111817 - WWT MasterPlan\MDC\FloodElevation\_550.mxd


Source: Esri, DigitalGlobe, GeoEye, Earthstar, GeoEye

D

**Legend**


- ▲ Other / Septic / Grease Trap
- Pump Station
- Treatment Plant
- Sewer Manhole
- Force
- ATLANTIC HEIGHTS PS
- CLOUGH DRIVE PS
- CONSTITUTION AVE PS
- CORPORATE DRIVE PS
- DEER ST OVERFLOW/CSO
- DEER ST PS
- GOSLING RD PS
- GRIFFIN ROAD PS
- HERITAGE RD PS
- LAFAYETTE RD PS
- LESLIE DRIVE PS
- MARCY ST PS
- MECHANIC ST PS
- MILL POND WAY PS
- NONE/UNKNOWN
- NORTHWEST ST PS
- PEASE OUTFALL
- PEASE WWTP
- PEIRCE ISLAND OUTFALL
- PEIRCE ISLAND WWTP
- RYE LINE PS
- TIDEWATCH PS
- TUCKER'S COVE PS
- WEST RD PS
- WOODLANDS 1 PS
- WOODLANDS 2 PS

- ### Legend
- Other / Septic / Grease Trap
  - Pump Station
  - Treatment Plant
  - Sewer Manhole
  - Force
  - ATLANTIC HEIGHTS PS
  - CLOUGH DRIVE PS
  - CONSTITUTION AVE PS
  - CORPORATE DRIVE PS
  - DEER ST OVERFLOW/CSO
  - DEER ST PS
  - GOSLING RD PS
  - GRIFFIN ROAD PS
  - HERITAGE RD PS
  - LAFAYETTE RD PS
  - LESLIE DRIVE PS
  - MARCY ST PS
  - MECHANIC ST PS
  - MILL POND WAY PS
  - NONE/UNKNOWN
  - NORTHWEST ST PS
  - PEASE OUTFALL
  - PEASE WWTP
  - PEIRCE ISLAND OUTFALL
  - PEIRCE ISLAND WWTP
  - RYE LINE PS
  - TIDEWATCH PS
  - TUCKER'S COVE PS
  - WEST RD PS
  - WOODLANDS 1 PS
  - WOODLANDS 2 PS



0 250 500 1,000  
Feet

### Sewer System Portsmouth, NH



**Corrosivity - Concrete**

- Moderate
- High


**Force Mains**

- Unknown Material
- Asbestos Cement
- Polyethylene
- Polyvinyl Chloride
- Vitrified Clay Pipe
- Cast or Ductile Iron
- Gravity Main



**Sewer Pipe Materials and Soil Corrosivity**  
Portsmouth, NH

|  |       |         |            |
|--|-------|---------|------------|
| PROJ NO:   | 13969 | DATE:   | 11/14/2018 |
| <b>WRIGHT-PIERCE</b><br>Engineering a Better Environment |       | FIGURE: | 1          |



**Corrosivity - Steel**


- Low
- Moderate
- High

**Force Mains**

- Unknown Material
- Cast Iron
- Ductile Iron Pipe
- Other
- Gravity Main

**Sewer Pipe Materials and Soil Corrosivity**  
Portsmouth, NH

|  |       |         |            |
|--|-------|---------|------------|
| PROJ NO:   | 13969 | DATE:   | 11/14/2018 |
| <b>WRIGHT-PIERCE</b><br>Engineering a Better Environment |       | FIGURE: | 2          |



230 Commerce Way, Suite 302  
Portsmouth, NH 03801  
603.430.3728 | [www.wright-pierce.com](http://www.wright-pierce.com)