

There is excessive damage to the corners of the house caused by failed gutters. The water also caused damage to underlayment preventing a nailing surface for the new clapboards. Removing the clapboards, fixing the corners and then zip taping/tyvek to prevent future issues was deemed the best solution. So many of the clapboards were cracked and split allowing more weather damage beneath. When preparing the surface for paint, it was evident that paint and caulking was holding a lot of the exterior together. Many boards disintegrated upon contact.



























