



33/35 Richmond Street, Portsmouth NH 03801

Unified Builders of Barrington NH was employed by Gregory Bolton, owner of 33/35 Richmond Street, to manage the repair of the exterior siding and windows in disrepair. While both the siding and windows have been replaced through the years and no longer represent the building's original appearance, Mr. Bolton tasked Unified to make every effort to restore the visible sections of the building as close to the original facade as is possible.

With the initial counsel from Mr. Cracknell regarding the guidelines governing the historical commission's rubrics for maintaining the visual integrity of the period it was erected, we sought further support from other property owners and builders experienced in renovations in the district. Our charge was to propose a solution that was visually appropriate for the historical district's character, do so with sustainable materials, revive the "look" of the original building, and consider the property values of the neighboring parcels.

We established that there are no original materials on the exterior of the building to preserve or restore. Repairing the existing façade is not feasible, so replacement is our only option. The exterior trim and siding is rotted through, and perhaps beyond the sheathing. The exterior window trim on all windows is dry-rotted and in need of replacement. There is no way to repair any of the sills.

The windows on the portion of the house visible from the street, are generally in good shape, or can be repaired. The windows on the remaining portion of the building are not reparable and must be replaced. (See window study).

The existing windows in the front and the siding were replaced in 1992. The windows in the back were replaced in the 1970's.



Owner: Thirty-Three Richmond Real Estate, LLC

We propose to repair the wood trim and sills on the visible portion of the building with smooth finish pressure treated wood stock and field paint, tinted to match existing, using Sherwin Williams Historical Exterior Color paint.

We propose to replace the existing rotted siding with smooth finish Hardie Board product as installed on several other buildings in the Historical District (See list).

We further propose to replace the windows in disrepair on the structure not visible from the street.

There are several areas of the façade facing the street that are in need of repair. We propose to repair, as best as can be done, the rotted sections with wood, and wood repair materials, and paint with the same tint as currently exists.

We have spoken to Penelope and Christopher
Merrow, the abutters directly across Richmond
Street. They expressed their desire to see the
renovation move forward with renovations that will, in
the spirit of the historical look and feel, improve their
property value and aesthetics of the neighborhood.


Our proposal for new windows and siding would improve the aesthetics, provide sustainability, provide a Class A fire rating that is NAHB Green Approved, and has a Class 5 flood resistance approval for 220 mph ultimate wind speed zones.



The finish has superior fade resistance which surpasses commercially grade exterior paints 3 to 1. Our power point presentation illustrates this data.

We pray the Historical Commission will lend guidance to, and approval for the proposed improvements of 33/35 Richmond Street property in the spirit of restoring the essence of the time period this building was erected and preserving property values in the neighborhood.

Our trade partners, and property owner are present to discuss our proposed solutions and answer any questions the commission may have.































James Hardie Siding and Historical District Use







138 Maplewood Ave





James Hardie Fiber Cement Siding and Historical District / Use



Our Business – Fiber Cement Bldg. Products Management James Hardie







James Hardie by the numbers

- 127 Year Operating History
- US Operations began 1988
- 10 Operating US Manufacturing sites
- 2 Research and Development sites
- 2 billion square ft. sold in 2017
- 3500+ employees worldwide
- More than 8 million homes in US
- #1 brand of siding in US



Our Business – Fiber Cement Bldg. Products 🥝 James Hardie





Fiber cement

- Cement/silicate matrix reinforced with cellulose fiber
 - Layered construction for maximum toughness and flexibility
 - Can be cut/nailed using standard construction tools
 - 2x more dimensionally stable than wood
 - 5x more dimensionally stable than vinyl
 - Non-combustible (ASTM E136)
 - Class A fire rating (ASTM E 84)
- James Hardie invests ~\$20 million annually in fiber cement research and development:
 - Durability
 - Coatings research
 - Building science
 - Materials research

Electron micrograph of fiber cement siding in cross section



Approvals



FIRE

- California Office of State Fire Marshall approved cladding for Wilderness/Urban Interface Areas
- Underwriters Laboratories, Warnock Hersey
 - · Approved component of 1 and 2 hour fire wall assemblies

RESILIENCY

- FEMA Class 5 flood resistant material, approved for Special Flood Hazard Areas under NFIP
- Florida Dept. of BPR
 - · 220 mph Ultimate Wind Speed zones
- Miami-Dade County High Velocity Hurricane Zone
 - · Rated for large and small missile impact

SUSTAINABILITY

- LEED credits for locally sourced materials
- NAHB Green Approved

GOOD HOUSEKEEPING SEAL OF APPROVAL











Building a stronger shore

When Hurricane Sandy slammed into Freeport, New York, one building withstood the six-foot storm surge – the Long Island Harbor Master's Quarter clad in James Hardie* siding. Chosen for its classic look, durability and resistance to sea air, the exterior held up beautifully while buildings nearby experienced heavy damage.

Watch a video about this and other real-world testimonials at jameshardie.com





James Hardie® Products with ColorPlus® Technology Finishes

- Increase the value of your homes
- · Gain efficiencies managing your business
- Receive unparalleled support including installation guidance

Performs better. Lasts longer. Stays colorful.

The ColorPlus® Technology process applies finishes in a fully controlled environment that results in better performance than field applied paint.



Finish Adhesion

Our proprietary coating is engineered for exceptional adhesion to our substrate and applied to the surface, edges and features for durable performance.



Color Retention

Our finish is cured onto boards for a stronger bond, which allows for exceptional resistance to cracking, peeling and chipping.



UV Resistance

ColorPlus* Technology finishes retain vibrancy longer when compared to vinyl siding and typical field paints on other siding products.


"James Hardie with ColorPlus, it's all one uniform color. It's just a much more attractive look."

- Terry S., Owner Twin Cities Siding Professionals




Superior Fade Resistance

When considering the cost of siding, think about long term performance. To demonstrate the value of superior fade resistance, we put our ColorPlus® Technology finish head-to-head against siding painted with commercially available exterior grade paint. We exposed these boards to the same 5,000 hours of UV light to replicate the effects of sunlight over five years.



See the Difference

ColorPlus® Technology finishes experiences less fade over time when compared to paint applied on the job site.



"All samples exposed to 5000 hours accelerated QUV-B weathering per ASTM G154-12s, which approximates 5 years exposure in Fjorida surs.





Highly Engineered to Outperform Competitive Siding and Trim

Only James Hardie® siding and trim are Engineered for Climate® to perform beautifully, even after years of wet or freezing conditions, blistering sun, sea air, high winds and more.



Weather

Resists shrinking and swelling in the face of shifting heat and humidity which leads to better paint or finish adhesion.



Won't burn and is recognized by fire departments nationwide*.



Won't be eaten by animals



Water

Water resistant to protect against swelling, warping and cracking.

Liarnes Hardie siding compiles with ASTM E136 as a noncombustible cladding and is reco departments across the U.S. including Marietta, GA, Flagstaff, AZ and Orange County, CA



Unified Unified Builders
688 CALEF HIGHWAY, BARRINGTON, NH 03825
603.905.9004

Window Assessment






MARK	QTY	DESCRIPTION	PANES	NARRATIVE
1	1	WINDOW	6 x 6	Ext rotted trim and sill - replace trim in kind. Window reparable
2	1	WINDOW	6 x 6	Ext rotted trim and sill - replace
3	1	WINDOW	6 x 6	trim in kind. Window reparable Ext rotted trim and sill - replace trim in kind. Window reparable
4	1	WINDOW	6 x 6	Ext rotted trim and sill - replace trim in kind. Window reparable Ext rotted trim and sill - replace
5	1	WINDOW	6 x 6	Ext rotted trim and sill - replace trim in kind. Window reparable Frame, trim, jamb rotted Window
6	1	WINDOW	6 x 6	Irreparable
7	1	WINDOW	9 x 6	Frame, trim, jamb rotted Window Irreparable
8	1	WINDOW	9 x 6	Frame, trim, jamb rotted Window Irreparable
9	1	WINDOW	9 x 6	Frame, trim, jamb rotted Window Irreparable Rotted frame,trim,jamb,aluminum
10	1	WINDOW	6 x 6	channel deteriated - Irreparable Rotted frame,trim,jamb,aluminum
11	1	WINDOW	9 x 6	channel deteriated - Irreparable Rotted frame,trim,jamb,aluminum
12	1	WINDOW	9 x 6	channel deteriated - Irreparable
13	1	WINDOW	9 x 6	Rotted frame,trim,jamb,aluminum channel deteriated - Irreparable Rotted frame,trim,jamb,aluminum
14	1	WINDOW	9 x 6	channel deteriated - Irreparable
15	1	WINDOW	9 x 6	Rotted frame,trim,jamb,aluminum channel deteriated - Irreparable Rotted frame,trim,jamb,aluminum
16	1	WINDOW	9 x 6	Rotted frame,trim,jamb,aluminum channel deteriated - Irreparable Rotted frame,trim,jamb,aluminum
17	1	WINDOW	9 x 6	channel deteriated - Irreparable
18	1	WINDOW	6 x 6	Rotted frame,trim,jamb,aluminum channel deteriated - Irreparable Ext rotted trim and sill - replace
19	1	WINDOW	6×6	trim in kind. Window reparable
20	1	WINDOW	9 x 6	Ext rotted trim and sill - replace trim in kind. Window reparable

MARK	QTY	DESCRIPTION	ROUGH OPENING	NARRATIVE
21	1	WINDOW	6 x 6	Ext rotted trim and sill - replace trim in kind. Window reparable
22	1	WINDOW	6 x 6	Ext rotted trim and sill - replace trim in kind. Window reparable Ext rotted trim and sill - replace
23	1	WINDOW	6 x 6	trim in kind. Window reparable
24	1	WINDOW	6 x 6	Ext rotted trim and sill - replace trim in kind. Window reparable Frame, trim, jamb rotted Window
25	1	WINDOW	6 x 6	Irreparable
26	1	WINDOW	9 x 6	Frame, trim, jamb rotted Window Irreparable
27	1	WINDOW	9 x 6	Frame, trim, jamb rotted Window Irreparable
28	1	WINDOW	9 x 6	no replacement, repaint existing trim
29	1	WINDOW	9 x 6	no replacement, repaint existing
30	1	WINDOW	9 x 6	hö replacement, repaint existing trim Rotted frame,trim,jamb,aluminum
31	1	WINDOW	9 x 6	channel deteriated - Irreparable Rotted frame,trim,jamb,aluminum
32	1	WINDOW		channel deteriated - Irreparable
33	1	WINDOW	9 x 6	Rotted frame,trim,jamb,aluminum channel deteriated - Irreparable Ext rotted trim and sill - replace
34	1	WINDOW	9 x 6	trim in kind. Window reparable
35	1	WINDOW	6 x 6	Ext rotted trim and sill - replace trim in kind. Window reparable Ext rotted trim and sill - replace
36	1	WINDOW	6 x 6	trim in kind. Window reparable
37	1	WINDOW	6 x 6	Ext rotted trim and sill - replace trim in kind. Window reparable




























































































































































EAST SIDE ELEVATION









Unified Builders



















Unified Builders

















NORTH SIDE ELEVATION




















Unified Builders














































If its red Its Lead







