## Figure 2a. Invasive Species Inventory

North Mill Pond | Multi-use Trail | Portsmouth, NH



## **General Notes**

- 1. Base image from Google Earth, May 2018.
- 2. An inventory of invasive and native plant communities was implemented in October 2018. Notes added by DeRosa Environmental Consulting, Inc. on November 1, 2018.
- 2. The principal strategy will be the selective removal of woody invasive plants within understory using whole plant removal techniques and multiyear maintenance.
- 3. Care is to be taken in removing invasive plant material to minimize disturbance to existing native plant species.
- 4. Disturbed soils to be seeded and hay mulched following removal. Native plants will be installed in these areas and are detailed in the Native Species Planting Plan (Figure 2c).




PWS No. 2250


MJD/aem November 1, 2018





Proposed Park Area | North Mill Pond Multi-use Trail | Portsmouth, NH





**WIRE GABIONS** 



GABIONS WITH OYSTER SHELL (CULTCH)

Figure 2d. Living Shoreline Images



BOULDERS AS SILL STRUCTURE | PROPOSAL WILL BE TO USE WIRE GABIONS FILLED WITH OYSTER SHELL



**JOINED GABIONS** 

